

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC1 200-00000-00 3411111 4 5

CON'T
REPORT SOURCE L605000315 7071983 8081783 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING A SURVEILLANCE TEST ON THE DIESEL GENERATOR LOAD SHEDDING RELAYS, SIX 4-KV LOSS
03 OF VOLTAGE RELAYS (27-1-T11A, 27-2-T11A, 27-3-T11A, 27-1-T11B, 27-2-T11B AND 27-3-T11B)
04 WERE FOUND TO HAVE EXCEEDED THE TOLERANCE ALLOWED BY TECHNICAL SPECIFICATION TABLE
05 3.3-4 ITEM 8.a (3196 VOLTS PLUS OR MINUS 19 VOLTS). THE ACTION REQUIREMENTS WERE MET.
06 PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES OF A SIMILAR NATURE
07 INCLUDE: 50-315/82-059, 316/82-100

08 9

SYSTEM CODE IB 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE RELAYX 14 COMP SUBCODE D 15 VALVE SUBCODE Z 16

09 9

17 LER/RO REPORT NUMBER 83 21 22 23 242526 27 2829 30 31 32

ACTION TAKEN E 13 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G080 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 THIS SITUATION IS ATTRIBUTED TO INSTRUMENT DRIFT. THE DIESEL GENERATOR LOAD SHEDDING
11 RELAYS (MANUFACTURED BY G.E. MODEL NGV-13b) WERE READJUSTED TO WITHIN ALLOWABLE LIMITS.
12 THE DESIGN AND PROCUREMENT OF A REPLACEMENT TYPE UNDERVOLTAGE RELAY IS UNDER STUDY.

13 14

FACILITY STATUS H 28 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION SURVEILLANCE TEST 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

8308260146 830817
PDR ADOCK 05000315
S PDR

NRC USE ONLY

NAME OF PREPARED BY R. A. PALMER

PHONE 616-465-5901