

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 [ ] [ ] 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CONT 01 REPORT SOURCE L 5 0 5 0 0 0 3 6 9 7 0 5 1 0 8 3 8 0 6 0 9 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 5/10/83 (Mode 2) and twice on 5/15/83 (Mode 1, 35 & 50 percent power), cold  
03 leg injection accumulator (CLA) "B" was declared inoperable due to the boron  
04 concentration dropping below 1900 ppm. This violates T.S.3.5.1.1 which is re-  
05 portable per T.S.6.9.1.1(b) and similar to RO's 369/81-55 and 81-70. Reactor  
06 coolant system pressure was maintained at the normal operating parameter, and  
07 unit shutdown was commenced as necessary. These incidents did not affect the  
08 ability to maintain the plant in a safe condition. Health and safety of the  
09 public were unaffected

09 S F 11 E 12 B 13 V A L V E X 14 C 15 X 16  
17 LER/NO REPORT NUMBER 8 3 18 19 A 20 A 21 0 2 0 6 22 23 N 24 N 25 L 26 W 0 3 0 26  
17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 These incidents resulted from leakage into the accumulator from the RCS (boron  
11 conc. 1050-1310 ppm) through check valves INI70 and INI71 (Walworth 10" N6376  
12 +SP1500# swing check) which diluted the concentration of CLA "B". CLA "B" was  
13 restored to specification (1900-2100 ppm) each time by additions from the RWST  
14 (2000-2100 ppm). Unit was shutdown, and the valves repaired and pressure tested  
15 (5/23/83).

15 X 28 0 5 0 29 Modes 2 & 1 B 31 Routine Surveillance  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

16 Z 33 0 34 N/A N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 0 0 0 37 Z 38 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

18 0 0 0 40 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

19 Z 42 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

20 N 44 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

NAME OF PREPARER Phillip B. Nardoci PHONE (704) 373-7432

DUKE POWER COMPANY

F.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

June 9, 1983

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

83 JUN 14 10:59  
USNRC REGION II  
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-29. This report concerns T.S. 3.5.1.1, "Each cold leg injection accumulator shall be operable with:...c. A boron concentration of between 1900 and 2100 ppm". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

*H.B. Tucker*

Hal B. Tucker

PBN:jfw  
Attachment (1)

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

OFFICIAL COPY

IE 22