## LICENSEE EVENT REPORT

*	CONTROL BLOCK:
0 11	M I D C C 1 2 0 0 1 - 10 10 10 10 1 - 10 10 3 4 11 11 11 11 1 1 1 1 1 1 1 1 1 1 1 1
O I I	SOURCE L 6 015 010 10 13 11 15 7 018 12 14 18 13 3 0 19 10 17 18 13 19
012	TO THE PROBABLE CONSEQUENCES (10)
	ON AUGUST 24, 1983 FOLLOWING A DISCUSSION WITH THE NRC REGION III, WE DECLARED OUR CONTROL
0 3	ROOM SMOKE DETECTORS INOPERABLE. THIS IS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL
014	SPECIFICATION 3.3.3.7 TABLE 3.310 ITEM 2. THE DETECTORS WERE DECLARED INOPERABLE
0 [5]	BECAUSE WE HAVE NOT SATISFACTORILY DEMONSTRATED THAT THE DETECTORS WILL PERFORM AS
010	INSTALLED. UPON DECLARING THE DETECTORS INOPERABLE WE IMMEDIATELY INITIATED THE REQUIRED
0 7	TECHNICAL SPECIFICATION ACTION STATEMENT. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
7 8	(SEE ATTACHED SUPPLEMENT).
012	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LERINO EVENT YEAR REPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 ATTACHMENT NORM SUBMITTED FORM SUB SUPPLIER MANUFACTURER PRIME COMP.  ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS (2) ATTACHMENT NORM SUBMITTED FORM SUB SUPPLIER SUPPLIER SUPPLIER MANUFACTURER PE 14 13 15 1
[1]0]	THIS EVENT WAS CAUSED BY THE DIFFERENCE IN THE INTERPRETATION OF WHAT WAS REQUIRED TO MEET
	THE REQUIREMENTS OF UNIT 2 FACILITY OPERATING LICENSE NO. DPR-74, SECTION 2.c.(3) (0) (b).
113	SPECIFICALLY, WE PREVIOUSLY HAD INTERPRETED THE TESTING IN THE INSTALLED CONDITION AS NOT!
1 3	AFFECTING THE OPERABILITY OF THE DETECTORS. AN UPDATED LER WILL BE SUBMITTED FOLLOWING
113	THE SATISFACTORY COMPLETION OF THE CONTROL ROOM SMOKE DETECTION SYSTEM TEST
1   5	STATUS STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1   6	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
1   7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (29)
-	9 PERSONNEL 13 13
	O O O O O O O O O O O O O O O O O O O
119	LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DESCRIPTION  NA  NA  NA  NA  NA  NA  NA
20	PUBLICITY SSUED DESCRIPTION 45  PDR ADDCK 05000315 S PDR  NRC USE ONLY
	NAME OF PREPARER R. A. PALMER PHONE 616-465-5901

ATTACHMENT TO LER# 83-079/01T-0
SUPPLEMENT TO EVENT DESCRIPTION

ON AUGUST 24, 1983 FOLLOWING A DISCUSSION WITH THE NRC REGION III, WE DECLARED OUR CONTROL ROOM SMOKE DETECTORS INOPERABLE. THIS IS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.3.3.7 TABLE 3.3-10 ITEM 2. THE DETECTORS WERE DECLARED INOPERABLE BECAUSE WE HAVE NOT SATISFACTORILY DEMONSTRATED THAT THE DETECTORS WILL PERFORM AS INSTALLED, FOLLOWING THE INITIAL TESTING AND ENGINEERING MODIFICATIONS THAT RESULTED FROM THAT TESTING. TESTS HAVE BEEN PERFORMED WHICH DEMONSTRATE THAT THE INDIVIDUAL DETECTORS WILL FUNCTION. WE ARE NOW DEVELOPING A TEST TO DEMONSTRATE THAT THE DETECTORS WILL PROPERLY FUNCTION IN THE MODIFIED CONDITION. UPON DECLARING THE DETECTORS INOPERABLE WE IMMEDIATELY INITITATED THE REQUIRED TECHNICAL SPECIFICATION ACTION STATEMENT.

WE BELIEVE THAT THERE HAS BEEN NO ADVERSE CONSEQUENCE AS A RESULT OF THE DETECTORS NOT BEING TESTED IN THE INSTALLED OR MODIFIED CONDITIONS. THIS CONCLUSION IS BASED ON THE FACT THAT THE CONTROL ROOMS HAVE BEEN CONTINUOUSLY INHABITED.

DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

September 7, 1983

Mr. J.G. Keppler, Regional Administrator United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

> Operating License DPR-58 Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 83-079/01T-0

Sincerely,

for W.G. Smith, Jr. Plant Manager

/cbm

cc: J.E. Dolan

M.P. Alexich

R.F. Kroeger

H. Brugger

E. Swanson/N. DuBry RO: III

R.C. Callen, MPSC

G. Charnoff, Esq.

J.M. Hennigan

R.O. Bruggee

INPO

PNSRC

J.F. Stietzel

E.L. Townley

Dir., IE (40 copies)

Dir., MIPC (4 copies)

SEP 0 1083

IEZZ