

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [C] [A] [S] [O] [S] [3] [2] [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [4] [] [] [5]
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49

CONT
[01] REPORT SOURCE [L] [6] [0] [5] [0] [0] [0] [3] [6] [2] [7] [0] [6] [2] [8] [8] [3] [8] [0] [7] [1] [2] [8] [3] [9]
7 8 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] We were advised by Combustion Engineering Inc. (CE), through Bechtel Power Corpo-
[03] ration, that RCS hot leg sampling nozzle loads were determined to exceed stress
[04] limits considered acceptable by CE. It was concluded that two (2) sampling lines
[05] on Unit 2 and one (1) on Unit 3 required corrective actions to prevent the
[06] development of an unsafe condition. Since this unsafe condition was bounded by
[07] existing FSAR Accident Analyses, there was no impact on the public health and
[08] safety.

[09] SYSTEM CODE [C] [B] (11) CAUSE CODE [B] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [P] [E] [N] [E] [T] [R] (14) COMP. SUBCODE [E] (15) VALVE SUBCODE [Z] (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20
(17) LER/RO REPORT NUMBER [8] [3] (21) EVENT YEAR [] [] (22) SEQUENTIAL REPORT NO. [0] [4] [0] (23) OCCURRENCE CODE [] [] (24) REPORT TYPE [T] [] (25) REVISION NO. [0]
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION TAKEN [F] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] (22) ATTACHMENT SUBMITTED [N] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [N] (25) COMPONENT MANUFACTURER [C] [4] [9] [0] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] This event was caused by a design error. As corrective action, shims were
[11] installed to reduce nozzle loads to within acceptable limits. No further
[12] corrective actions are necessary since this is considered an isolated
[13] event.

[14] FACILITY STATUS [B] (28) % POWER [0] [0] [0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [D] (31) DISCOVERY DESCRIPTION [Vendor Notification] (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[15] ACTIVITY CONTENT RELEASED OF RELEASE [Z] (33) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [NA] (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[16] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[17] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION [NA] (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[18] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

[19] PUBLICITY ISSUED DESCRIPTION [N] (44) (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

8307250479 830712
PDR ADOCK 05000361
S PDR

[20] NAME OF PREPARER [H. B. RAY] (44) PHONE: [714/492-7700] (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32