

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

SOUTH CAROLINA ELECTRIC & GAS COMPANY

USNRC
ATLANTA
POST OFFICE 764
COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

83 JUL 1 A10: 28

July 29, 1983

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 83-073

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-073 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement (a) of Technical Specification 3.3.3.5, "Remote Shutdown Instrumentation," on July 3, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

CJM:OWD/mac
Attachment

cc: V. C. Summer	C. L. Ligon (NSRC)
E. H. Crews, Jr.	G. J. Braddick
T. C. Nichols, Jr., /O. W. Dixon, Jr.	J. C. Miller
E. C. Roberts	J. L. Skolds
H. N. Cyrus	J. B. Knotts, Jr.
Group/General Managers	I&E (Washington)
O. S. Bradham	Document Management
R. B. Clary	Branch
C. A. Price	INPO Records Center
A. R. Koon	NPCF
D. A. Lavigne	File (Lic./Eng.)

~~CONFIDENTIAL~~
IE22

Mr. James P. O'Reilly
LER No. 83-073
Page Two
July 29, 1983

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

On July 3, 1983, with the Plant in Mode 1, a discrepancy of 6% was observed between the Main Control Board and Control Room Evacuation Panel (CREP) indication for Boric Acid Tank Level. The discovery was made during a routine channel check performed in accordance with Surveillance Requirement 4.3.3.5. The CREP instrumentation channel was subsequently declared inoperable in accordance with Action Statement (a) of Technical Specification 3.3.3.5.

There were no adverse consequences resulting from this event since the Plant was in compliance with the Action Statement of Technical Specification 3.3.3.5.

CAUSE AND CORRECTIVE ACTIONS

The cause of the discrepancy was determined to be the result of instrument drift on Boric Acid Tank Level Transmitter LT-163A which provides indication to the CREP. The transmitter was calibrated and returned to operable status on July 3, 1983, after the satisfactory completion of a channel check.

The licensee plans no additional action in reference to this event other than normal surveillance testing.