

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

August 22, 1983
ANPP-27604-BSK/RQT

RECEIVED
NRC
1983 SEP -1 PM 1:17
REGION V USE

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Interim Report - DER 83-55
A 50.55(e) Potentially Reportable Deficiency Relating to
Thermal Liner In Safety Injection System Line Is Missing.
File: 83-019-026; D.4.33.2

Reference: Telephone Conversation between P. Narbut and R. Tucker
on August 1, 1983.

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the referenced telephone conversation. At that time, it was estimated that a determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim Report is attached. It is now expected that this information will be finalized by November 9, 1983, at which time a complete report will be submitted.

Very truly yours,

E. E. Van Brunt, Jr.

E. E. Van Brunt, Jr.
APS Vice President,
Nuclear Projects Management
ANPP Project Director

EEVBJr./RQT:sn

Attachment

cc: See Attached Page Two

11
18-27

U. S. Nuclear Regulatory Commission
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway - Suite 1500
Atlanta, Georgia 30339

INTERIM REPORT - DER 83-55
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNIT 1

I. Potential Problem

During visual inspection of piping, after disassembly of Unit 1 pump tag no. 1-RCE-P01A, it was revealed that the thermal liner for line number SI-A207-BCCA-14 was missing. Preliminary determination is that the liner broke loose during hot function testing and was flushed into the Reactor Vessel.

II. Approach To and Status Of Proposed Resolution

Bechtel engineering is corresponding with C-E to provide reportability disposition and technical justification for corrective action.

III. Projected Completion Of Corrective Action and Submittal of The Final Report

Evaluation of this condition and submittal of the Final Report is forecast to be completed by November 9, 1983.