

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	6	7	0	8	1	7	8	3	8	0	8	2	6	8	3	9
60	61									68	69					74		75						80
DOCKET NUMBER										EVENT DATE								REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During refueling operations a liquid discharge from the aerated

waste monitor tank was made. During the discharge radiation

monitor recorder RJR 9129 failed. The release was not recorded for

approximately 1 hour. The plant was in ETSAS 2.4.1.3.C for 3 hours

while the recorder was fixed. Similar events: LER 83-001

SYSTEM CODE M C 11		CAUSE CODE E 12		CAUSE SUBCODE G 13		COMPONENT CODE I N S T R U 14				COMP SUBCODE R 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 0 3 24 26		OCCURRENCE CODE 0 4 28 29		REPORT TYPE T 30		REVISION NO. 0 32									
ACTION TAKEN B 18		FUTURE ACTION H 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB N 24		PRIME COMP SUPPLIER Z 25		COMPONENT MANUFACTURER L 1 3 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Vibration of the recorder caused an amplifier circuit card to back

out of its connector. The card backed out because the holding

screw had fallen out. The card was inserted the holding screw was

tightened and the unit was calibrated and returned to service.

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	H	28	0	0	0	29	N/A	B	31	Operator Observation	32	
ACTIVITY CONTENT		RELEASED OF RELEASE			AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	L	33	M	34	0.04098 curies	35	Discharge Canal					36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION							
1	7	0	0	0	37	Z	38	N/A					
PERSONNEL INJURIES		NUMBER		DESCRIPTION									
1	8	0	0	0	40	N/A							
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION									
1	9	Z	42	N/A									
PUBLICITY		ISSUED		DESCRIPTION									
2	0	N	44	N/A									

8309230380 830826
PDR ADOCK 05000336
S PDR

NRC USE ONLY

NAME OF PREPARER Steve Stadnick

PHONE 203-447-1791 x 4427

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
THE HARTFORD ELECTRIC LIGHT COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
NEW YORK WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

P.O. BOX 270
HARTFORD, CONNECTICUT 06101
(203) 666-6911

August 26, 1983

MP-5331

Dr. Thomas E. Murley
Regional Administrator, Region 1
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-65
Docket No. 50-336
ETS-NR 50-336/83-3/4T-0

Dear Dr. Murley:

This letter forwards Prompt Licensee Event Report 83-3/4T-0 required to be submitted within ten days pursuant to Millstone Unit 2 Appendix B Environmental Technical Specifications, Section 5.6.2.a (1), concerning an inoperable liquid radwaste discharge radiation monitoring recorder (ETS 2.4.2.3.A).

An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

FOR: E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

A handwritten signature in cursive script, reading 'R. J. Herbert'.

BY: R. J. Herbert
Station Services Superintendent
Millstone Nuclear Power Station

EJM/SS:ejl

Attachment: ETS-NR 50-336/83-3/4T-0

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30)
Director, Office of Management Information and Program Control, Washington, D.C. (3)
U.S. Nuclear Regulatory Commission, c/o Document Management Branch, Washington, D.C. 20555

IE22
||