

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 S C V C S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 0 0 0 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

SCNT
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 9 5 7 0 7 0 7 8 3 8 0 1 1 8 8 3 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On July 7, 1983, at 0300 hours, with the Plant in Mode 1, Pressurizer Power
0 3 Operated Relief Valve PCV-444B-RC would not fully stroke when operated from the
0 4 Main Control Board. The low pressure Nitrogen reservoir for PCV-444B-RC would
0 5 not charge up to normal pressure. There were no adverse consequences as the
0 6 Plant was in compliance with Technical Specification 3.4.4, Action Statement (a),
0 7 and the Pressurizer Code Safety Valves were OPERABLE.
0 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
C B 11 E 12 B 13 V A L V O P 14 D 15 Z 16
17 LER/RO REPORT NUMBER 8 3 18 SEQUENTIAL REPORT NO. 0 7 6 19 OCCURRENCE CODE 0 3 20 REPORT TYPE X 21 REVISION NO. 1
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFRD-N FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
C 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 W 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the occurrence has been attributed to low operating pressure for
1 1 PORV PCV-444B-RC. The Nitrogen Supply Header Pressure Control Regulator (IPV-6307B)
1 2 for PORV PCV-444B-RC was replaced. Before being returned to service on November 24,
1 3 1983, at 2101 hours, a valve operability surveillance test was satisfactorily per-
1 4 formed. No further action is planned other than normal surveillance testing.

FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 0 9 6 29 N/A A 31 Operator Observation 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 N/A N/A 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 N/A 39
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 N/A 41
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 N/A 43
PUBLICATION DESCRIPTION
N 44 N/A 45

8401260081 840118
PDR ADDCK 05000395
S PDR

IE 22

NRC USE ONLY

NAME OF PREPARED L. E. Koib (803) 345-5209

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

84 JAN 23 A 8:31
January 18, 1984

Mr. James P. O'Reilly
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N.W.
Atlanta, Georgia 30303


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Thirty Day Written Report
LER 83-076, Revision 1

Dear Mr. O'Reilly:

Please find attached Revision 1 to Licensee Event Report #83-076 for the Virgil C. Summer Nuclear Station. This revision provides the final report as described in the original report dated August 1, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

LEK:OWD/mac/fjc
Attachment

cc: V. C. Summer
T. C. Nichols, Jr./O. W. Dixon, Jr.
E. H. Crews, Jr.
E. C. Roberts
W. A. Williams, Jr.
D. A. Nauman
Group Managers
O. S. Bradham
C. A. Price
D. A. Lavigne
J. F. Heilman

C. L. Ligon (NSRC)
G. J. Braddick
D. J. Richards
NRC Res. Inspector
J. B. Knotts, Jr.
I&E (Washington)
Document Management
Branch
INPO Records Center
NPCF
File

OFFICIAL COPY

IE 22

1/1