

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [C] [T] [H] [N] [P] [1] [2] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [5]

CON'T [0] [1] REPORT SOURCE [L] [6] [0] [5] [0] [0] [2] [1] [3] [7] [1] [2] [0] [7] [8] [3] [8] [0] [1] [0] [4] [8] [4] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] While performing rod motion checks on December 7, 1983, Bank "A" control rods  
[0] [3] were inserted from the full out position of 320 steps to 310 steps. When an  
[0] [4] attempt to withdraw rods was made, the subgroup 2 rods failed to move out.  
[0] [5]  
[0] [6]  
[0] [7]  
[0] [8]

[0] [9] SYSTEM CODE [R] [B] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [C] [K] [T] [B] [R] [K] (14) COMP. SUBCODE [E] (15) VALVE SUBCODE [Z] (16)  
[17] LER/RO REPORT NUMBER [8] [3] (21) YEAR [ ] (22) SEQUENTIAL REPORT NO. [0] [2] [5] (23-26) OCCURRENCE CODE [ ] (27) REPORT TYPE [L] (28-31) REVISION NO. [0] (32)  
ACTION TAKEN [A] (33) FUTURE ACTION [Z] (34) EFFECT ON PLANT [B] (35) SHUTDOWN METHOD [Z] (36) HOURS [0] [0] [0] [0] (37-40) ATTACHMENT SUBMITTED [N] (41) NFRD-4 FORM SUB. [Y] (42) PRIME COMP. SUPPLIER [N] (43) COMPONENT MANUFACTURER [W] [1] [2] [0] (44-47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] Salve cyler motor starter switch was found to be faulty. Faulty switch  
[1] [1] was replaced. Load was reduced until repairs were completed to satisfy  
[1] [2] technical specifiations for minimum rod height.  
[1] [3]  
[1] [4]

[1] [5] FACILITY STATUS [E] (28) % POWER [1] [0] [0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION [During surveillance test] (32)

[1] [6] ACTIVITY CONTENT RELEASED OF RELEASE [Z] (33) AMOUNT OF ACTIVITY [NA] (34) LOCATION OF RELEASE [NA] (35-36)

[1] [7] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)

[1] [8] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION [NA] (41)

[1] [9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)

[2] [0] PUBLICITY ISSUED [N] (44) DESCRIPTION [NA] (45)

8401270404 840104  
PDR ADOCK 05000213  
S PDR

NAME OF PREPARER G. H. Bouchard

PHONE (203) 267-2556

IF 22



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

January 3, 1984

Dr. Thomas E. Murley  
Regional Administrator, Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Reference: Facility Operating License No. DPK-61  
Docket No. 50-213  
Reportable Occurrence LER 83-25/3L

Dear Dr. Murley:

This correspondence forwards the Licensee Event Report for Reportable Occurrence LER 83-25/3L, required to be submitted within 30 days, pursuant to the requirements of Connecticut Yankee Technical Specifications, Section 6.9.2.b(2).

An additional three copies of the report are enclosed.

Very truly yours,

Richard H. Graves  
Station Superintendent

RHG:GHB/jhb

Attachment: LER 83-25/3L

cc: Dir., Office of Inspection and Enforcement, Washington, D. C. (30)  
Dir., Office of Management Info. & Program Control, Wash., D. C. (3)  
USNRC c/o Document Management Branch, Washington, D. C. (1)

IE22  
||