

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	6	1	5	8	3	8	0	7	1	2	8	3	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
0	9	S	C	E	A	C	K	T	B	K	R	X	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		83		061		03		L		0							
21		22		23		24		25		26							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A		Z		Z		Z		0000		Y		N		L		X999	
33		34		35		36		37		40		41		43		44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

FACILITY STATUS (E) (28) % POWER (0 9 9) (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT RELEASED OF RELEASE (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	41 NA

PUBLICITY
 ISSUED (45) DESCRIPTION (44) NA
 2 0
 7 8 9 10
 8307250191 830712
 PDR ADCK 05000321
 S PDR
 NRC USE ONLY
 68 69 70

PHONE: (912) 367-7851

NARRATIVE REPORT
FOR LER 50-321/1983-061

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-321

Tech. Specs. section(s) which requires report:

This 30 day LER is required by Tech. Specs. Section 6.9.1.9.b due to the event's showing that the Unit was not meeting the requirements of Unit 1 Tech. Specs. Section 3.7.B.1. and Unit 2 Tech. Specs. Section 3.9.5.3.

Plant conditions at the time of the event(s):

This event occurred on 6/15/83 with the reactor mode switch in the run position and reactor power at 2410 MWT (approximately 99%).

Detailed description of the event(s):

On 6/15/83, when the "1B" standby gas treatment system was started, it was discovered that 1T46-F001B (SBGT filter inlet damper) and 1T46-F002B (SBGT exhaust fan discharge damper) would not open. The "1B" standby gas treatment system was declared inoperable.

Consequences of the event(s):

Plant operation was not affected by this event. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The Unit 1 "A" standby gas treatment system and the Unit 2 "A" and "B" standby gas treatment system were proven operable within 4 hours as required by Tech. Specs. Section 3.7.B.1

Justification for continued operation:

Unit 1 was placed in a 7 day LCO as required by Tech. Specs. Section 3.7.B.1. Unit 2 was not formally placed in a 30 day LCO as required by Unit 2 Tech. Specs. Section 3.9.5.3 due to the short time period of the LCO (i.e., approximately 3 hours)

If repetitive, number of previous LER:

This event is non-repetitive.

Impact to other systems and/or Unit:

This event had no impact on any other Unit 1 systems or on Unit 2.

Cause(s) of the event(s):

The cause of this event is component failure due to a blown fuse in the power supply for 1T46-F001B and 1T46-F002B.

Immediate Corrective Action:

The blown fuse was replaced. The "1B" standby gas treatment system was satisfactorily functionally tested per the "STAND BY GAS TREATMENT VENTILATION AND VALVE OPERABILITY" procedure (HNP-1-3655) and returned to operable status on 6/15/83.

Supplemental Corrective Action:

There is no supplemental corrective action required.

Scheduled (future) corrective action:

No scheduled future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

None required.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

USNRC REGION II
ATLANTA, GEORGIA



Georgia Power

Edwin I. Hatch Nuclear Plant

83 JUL 19 AIO: 29


July 12, 1983
GM-83-624

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-321/1983-061. This report is required by Hatch Unit 1 Technical Specifications Section 6.9.1.9.b.


H. C. Nix
General Manager

SES
HCN/SBT/djs

xc: R. J. Kelly
J. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

OFFICIAL COPY

IE 22.11