

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE (205) 899-5156

Licensee Event Report  
LER 83-068/03L-0  
Page 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

Main Control Board position indication and a plant operator failing to perform a required verification. Valve Q2P16V536 was manually opened and the 2B diesel generator was declared operable at 1420 on 12/30/83. Subsequently, the motor operator was inspected and cleaned. The probable cause for the excessive current draw was a buildup of grease caused by the unique valve operator installation. A design change is under evaluation to provide positive MCB position indication for this valve. The individual involved has been counseled concerning this event.