

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL LOCK 10:26 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

83 AUG 2

01 02 03 04 05 06 07 08 09 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T

REPORT SOURCE L 0500025107058380729839

DOCKET NUMBER 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal full power operation, a low pressure alarm was received for the 4B

03 accumulator. The nitrogen fill valve 853B was opened to align the system for

04 nitrogen addition. Subsequently, the 4B accumulator pressure dropped below the

05 minimum required pressure of T.S.3.4.1.a.3. After 4 hours, reactor shutdown was

06 commenced as directed by T.S.3.0.1. This is reportable in accordance with

07 T.S.6.9.2.b.2. The health and safety of the public was not affected. A similar event

08 was reported as LER 251-82-011.

09

SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE VALVE EX 14 COMP SUBCODE F 15 VALVE SUBCODE L 16

17 LER/RO REPORT NUMBER 83 21 22 23 24 25 26 27 28 29 30 31 32

REVISION NO. 0 32

ACTION TAKEN B 18 X 19 EFFECT ON PLANT A 20 SHUTDOWN METHOD A 21 HOURS 0010 22 ATTACHMENT SUBMITTED N 23 NPD-4 FORM 5B N 24 PRIME COAL SUPPLIER L 25 COMPONENT MANUFACTURER C 63 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Valve HCV-4-936 on the accumulator vent line was found partly open (although

11 control room indication showed it as closed) and the downstream ball valve 937 was

12 also leaking. The ball valve was replaced and the local valve positioner on

13 HCV-4-936 was zeroed, closing the valve.

14

FACILITY STATUS E 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

% POWER 100 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 Operator observation 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE 37

PERSONNEL EXPOSURES NUMBER 0 38 TYPE Z 39 DESCRIPTION N/A 40

PERSONNEL INJURIES NUMBER 0 41 DESCRIPTION N/A 42

LOSS OF OR DAMAGE TO FACILITY TYPE Z 43 DESCRIPTION N/A 44

PUBLICITY ISSUED Y 45 DESCRIPTION 46

July 6, 1983 Miami Herald, AP, UPI

NAME OF PREPARER Z. E. Berry

PHONE (305) 245-2910 Ext. 353

USNRC REGION II
ATLANTA, GEORGIA

83 AUG 2 AIO: 01



July 29, 1983
PNS-LI-83-521-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-6

TURKEY POINT UNIT 4


DATE OF OCCURRENCE: JULY 5, 1983

TECHNICAL SPECIFICATION 3.4.1.a.3

4B ACCUMULATOR

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,


J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

An official stamp with the words "OFFICIAL COPY" is visible. Below it, the number "1622" is handwritten. At the bottom right, there are handwritten marks that appear to be "1/1".
PEOPLE... SERVING PEOPLE