

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

August 8, 1983

ANPP-27536-RQT/BSK

RECEIVED
NRC

AUG 22 PM 1:41

REGION V IAE

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Interim Report, Revision 1 - DER 82-73
A 50.55(e) Potentially Reportable Deficiency Relating to
ITT Grinnel Pipe Support Clamps In Unit 2 MSSS Have Excess
Gap, May Not Properly Secure Pipe.
File: 83-019-026, D.4.33.2


Reference: (A) Telephone Conversation between P. Narbut and G. Duckworth
on November 24, 1982
(B) ANPP-22589, dated December 23, 1982 (Interim Report)
(C) ANPP-23222, dated March 10, 1983 (Time Extension)
(D) ANPP-23428, dated April 5, 1983 (Time Extension)
(E) ANPP-24002, dated June 8, 1983 (Time Extension)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B), and
Time Extensions were requested by References (C), (D), and (E). In
Reference (E), it was estimated that a Final Report would be available
by September 1, 1983.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by December 13, 1983,
when a complete report will be submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/RQT:sn

cc: See Attached Page 2

8308300742 830808
PDR ADOCK 05000529
S PDR

11
IE-27

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway - Suite 1500
Atlanta, Georgia 30339

REVISED INTERIM REPORT - DER 82-73
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNIT 2

I. Potential Problem

During a template check on pipe clamps supplied by ITT Grinnell per Purchase Order 10407-13-PM-209, it was found that an excessive gap existed between the pipe and pipe clamp across the width of the clamps. This condition resulted in a sliding fit rather than the required secure fit necessary for the associated snubber or sway strut to function as designed.

II. Approach To and Status Of Proposed Resolution

Grinnell has identified the sliding fit as correctable by appropriate shimming and tightening of the outer bolts. Grinnell has confirmed that the clamps are acceptable for use with two or four area contact. However, specific corrective measures are being requested from Grinnell.

III. Projected Completion of Corrective Action and Submittal Of The Final Report

Evaluation of this condition and submittal of the Final Report is forecast to be completed by December 13, 1983.