

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | J | A | F | L | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 | REPORT SOURCE | L | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 3 | 0 | 6 | 0 | 7 | 8 | 3 | 0 | 9 | 0 | 1 | 8 | 3 | 9  
7 8 80 81 88 89 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During a visual exam in preparation for performing a U.I.  
03 | examination, water seepage was discovered from a weld in the  
04 | stainless steel pipe section of the control rod hydraulic  
05 | return line.  
05 |  
07 |  
07 |

09 | SYSTEM CODE | 03 | CAUSE CODE | B | CAUSE SUBCODE | A | COMPONENT CODE | PIPEXX | COMP. SUBCODE | A | VALVE SUBCODE |  
7 8 9 10 11 12 13 18 19 20  
17 | LER RO REPORT NUMBER | 83 | EVENT YEAR | 83 | SEQUENTIAL REPORT NO. | 023 | OCCURRENCE CODE | 01 | REPORT TYPE | X | REVISION NO. | 1 |  
7 8 21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN | F | FUTURE ACTION | Z | EFFECT ON PLANT | Z | SHUTDOWN METHOD | Z | HOURS | 000 | ATTACHMENT SUBMITTED | N | NPRD-4 FORM SUB | N | PRIME COMP. SUPPLIER | A | COMPONENT MANUFACTURER | Z9P9 |  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | A surface and volumetric exam were conducted to verify the through  
11 | wall crack. The exam substantiated the seepage source. During the  
12 | refueling outage, the control rod drive hydraulic return line was cut  
13 | and capped at the vessel nozzle. Metallurgical analysis is to be  
14 | conducted on the subject pipe segment crack to help determine the  
7 8 9 80

15 | FACILITY STATUS | H | % POWER | 000 | OTHER STATUS | N/A | METHOD OF DISCOVERY | B | DISCOVERY DESCRIPTION | Routine test/inspection  
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY CONTENT | Z | RELEASED OF RELEASE | Z | AMOUNT OF ACTIVITY | NA | LOCATION OF RELEASE | NA  
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES | 0 | NUMBER | 0 | TYPE | Z | DESCRIPTION | NA  
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES | 0 | NUMBER | 0 | DESCRIPTION | NA  
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY | Z | TYPE | NA | DESCRIPTION | NA  
7 8 9 11 12 43 80

20 | PUBLICITY ISSUED | N | DESCRIPTION | NA  
7 8 9 10 45 80

8309190228 830901  
PDR ADOCK 05000333  
S PDR

IE 22 11

NAME OF PREPARER William Fernandez

PHONE: (315) 342-3840

NRC USE ONLY

James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342.3840



Corbin McNeill  
Resident Manager

September 8, 1983  
JAFP 83-0922

Dr. Thomas E. Murley  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Reference: DOCKET NO. 50-333  
LICENSEE EVENT REPORT: 83-012/03L-1

Dear Dr. Murley:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. William Fernandez at (315) 342-3840, extension 220.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'Corbin A. McNeill, Jr.', with a stylized flourish at the end.

CORBIN A. McNEILL, JR.  
RESIDENT MANAGER

CAM:WF:nan  
Enclosure

CC: USNRC Document Control Desk (1)  
INPO Records Center, Atlanta, Ga. (1)  
Internal Power Authority Distribution  
NRC Resident Inspector  
Document Control Center  
LER/OR File

IE22  
||