

## LICENSEE EVENT REPORT

CONTROL BLOCK:                      (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4		5
7	8	LICENSEE CODE				14	15	LICENSE NUMBER				25	26	LICENSE TYPE				30	57	CAT		58						

CON'T

0	1	L	6	0	5	0	0	0	3	3	3	7	0	8	3	0	8	3	8	0	9	0	7	8	3	9
7	8	REPORT SOURCE				60	61	DOCKET NUMBER				68	69	EVENT DATE				74	75	REPORT DATE				80		

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 The Power Authority was informed by it's Architect Engineer that the

0 3 Emergency Diesels may not remain operable if the diesel exhaust systems

0 4 were subjected to tornado wind loads. (T.S. Paragraph 3.9.B.1). This

0 5 event did not have any effect on public health and safety. (See att-

0 6 ached)

0 7

0 8

0	9	E	E	11	B	12	A	13	E	N	G	I	N	E	14	X	15	2	16	17	8	3	21	22	0	3	0	23	24	25	0	3	26	27	0	3	28	29	L	30	31	0	32	F	18	Z	19	Z	20	Z	21	0	0	0	0	33	34	35	36	37	38	39	40	41	Y	42	N	43	A	44	8	4	8	5	45	46	47	48	49	50
7	8	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIA REPORT NO.		OCCURREN CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																				

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Power Authority modified the exhaust system rather than do a costly

1 1 study to determine if the instruments would remain operable (See att-

1 2 ached)

1 3

1 4

1	5	H	28	0	0	0	29	N/A	30	D	31	NOTIFICATION BY ARCHITECT ENGINEER				32		
7	8	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						80		
1	6	Z	33	Z	34	AMOUNT OF ACTIVITY				35	LOCATION OF RELEASE				36			
7	8	ACTIVITY RELEASED		CONTENT OF RELEASE		PERSONNEL EXPOSURES				37	PERSONNEL INJURIES				41			
1	7	0	0	0	37	Z	38	DESCRIPTION				39	LOSS OF OR DAMAGE TO FACILITY				43	
7	8	PERSONNEL EXPOSURES		TYPE		PERSONNEL INJURIES				41	LOSS OF OR DAMAGE TO FACILITY				43			
1	8	0	0	0	40	DESCRIPTION				41	PUBLICITY				45			
7	8	PERSONNEL EXPOSURES		TYPE		PERSONNEL INJURIES				41	PUBLICITY				45			
1	9	Z	42	DESCRIPTION				45	ISSUED				44	NAME OF PREPARER				80
7	8	PERSONNEL EXPOSURES		TYPE		PERSONNEL INJURIES				41	ISSUED				44			

8309190297 830907  
PDR ADOCK 05000333  
S PDR

NRC USE ONLY

NAME OF PREPARER R. J. ConversePHONE: (315) 342-3840

James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342.3840



Corbin McNeill  
Resident Manager

September 7, 1983  
JAFP 83-0929

Dr. Thomas E. Murley  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region 1  
631 Park Avenue  
King of Prussia, PA 19406

REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 83-030/03L-0

Dear Dr. Murley:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. R. J. Converse at (315) 342-3840, Extension 202.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'C. McNeill', followed by a horizontal line.

CORBIN A. McNEILL, JR.

CAM:RJC:fah

Enclosure

CC: USNRC Document Control Desk (1)  
INPO Records Center, Atlanta, Georgia (1)  
Internal Power Authority Distribution  
NRC Resident Inspector  
Document Control Center  
LER/OR File

TE22  
11

POWER AUTHORITY OF THE STATE OF NEW YORK  
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 83-030

PAGE 2 of 2

The Power Authority has identified a potential deficiency in the design of the diesel generator exhaust piping. As designed and installed, a portion of the exhaust piping and the muffler are mounted on the roof of the diesel generator building. This piping was not designed to withstand tornadoes or other extreme atmospheric conditions. If the piping were subjected to such a condition, it could be damaged and result in the discharge of diesel gases directly into the diesel building. The exhaust gases might result in degradation of the diesel generator instrumentation and controls located in the building.

The existence of an actual design deficiency can only be determined by a detailed and expensive environmental equipment qualification analysis. For economic reasons, in lieu of performing this analysis, the Authority has modified the exhaust piping. The piping was modified to preclude failure due to tornado wind load conditions. This modification was completed during the 1983 refueling outage and permanently resolves the potential design deficiency.