## LICENSEE EVENT REPORT

	CONTROL BLOCK:
O :	FILISILIS 2 3 0 0 - 0 00 0 0 - 0 0 0 0 0 1 1 1 1 1 1
CON'T	ARPORT L 6 0 5 0 0 0 3 8 9 0 0 8 1 0 8 3 8 0 9 0 9 8 3 9 EVENT DATE 30
0 2	While at 100% power the plant data processing computer and backup
(013)	computer tripped off line. This rendered the pulse counting CEA position
04	indication and incore power detection system inoperable. These systems
0]5	Lare required per Tech. Specs. 3.1.3.2b and 4.2.1.4. respectively. The
0]6	data system was restored to operation within 18 minutes. The health and
0 7	safety of the public were not affected. This is the first event of this
0 3	type.
09	SYSTEM CAUSE COMPONENT GODE SUBCODE SU
	TAKEN ACTION FUTURE SEPECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORMSUS SUPPLIER MANUFACTURER TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORMSUS SUPPLIER MANUFACTURER MANUFACTURER TO THE COMPONENT MANUFACTURER MANUFACTURER MANUFACTURER TO THE COMPONENT MANUFACTURER TO THE
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The cause of the failure of computer #1 was disc errors. The cause of the
10	The cause of the failure of computer #1 was disc errors. The cause of the
10	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.
	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within
	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.
13	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within 18 minutes.
13	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.  In a cause of the series of the series computer #1 was disc errors. The cause of the series are cause of the series of t
131	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within  The Fisher Porter 3000 series computers were reset and on line within
131	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.    18 minutes.
131	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.    18 minutes   18 minutes   18 minutes   19 mi
131	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.    NA
1 1 2 1 3 1 5 7 8 A 1 6 7 3 1 7 7 3	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.    18 minutes.
13 13 14, a 15, a 16, a 17, a	The cause of the failure of computer #1 was disc errors. The cause of the failure of computer #2 (backup) to come on line could not be determined.  The Fisher Porter 3000 series computers were reset and on line within  18 minutes.    18 minutes.



September 9, 1983 PNS-LI-83-600

Mr. James P. O'Reilly Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta Street N.W., Suite 2900 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-47

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: AUGUST 10, 1983

TECHNICAL SPECIFICATION 3.1.3.2b AND 4.2.1.4

## PLANT DATA PROCESSING COMPUTER

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr. Vice President

Nuclear Energy

JWW/NWG/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)

Harold F. Reis, Esquire

File 933.1 SL

OFFICIAL COPY

PEOPLE ... SERVING PEOPLE