NRC FORM 366 (12.81) 10 CFR 50	LICENSEE EVENT REPORT	APPROVED BY OMB
CONTROL BLOCK	1) IPLEASE PRINT OR TYPE ALL REC	
O 1 A L B R F 1 2 0	0 -0 0 0 0 0 - 0 0 3 4 1 1 1	1 1 1 4 5
CON'T O 1 REPORT L 6 0 5 0	0 0 2 5 9 0 1 2 1 2 8 3 8 0	0 1 1 1 0 8 4 6
EVENT DESCRIPTION AND PROBAB	thile performing SI 4.8.B.2-1b and 4.8.B.	.2-2a an analyst
	acuum pump belt on 1-RM-90-250 (reactor	
0 4 building vent monitor). The CAM may have been inoperable for	r a maximum of 24-
The state of the s	There was no effect on public health and	
	onitors for units 2 and 3 showed no incr	rease in activity
Processor Commenced Commen	nt. There are no redundant systems.	
0 8		
M C 11 E	SUBCODE COMPONENT CODE SUBCODE	SUBCODE SUBCODE
(7) REPORT EVENT YEAR	REPORT NO.	
TAKEN ACTION ON PLANT M	Z 2 2 0 0 0 0 V 2 23 N 24	ME COMP. COMPONENT (26) L (25) S (0 9 3 43
The cause was normal	wear due to continuous operation. The	standard V-belt
	el 325 Series air pump was replaced. No	
franchise to the second	ired. The drive belts are checked perio	dically for wear
1 3 by SI 4.8.B.4.2.a.		1
1 4 FACILITY		
1 5 H (28 0 0 0 0) NA	HER STATUS (30) METHOD OF DISCOVERY DE DISCO	
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF A	ACTIVITY (35) LOCATION OF HI	ELEASE (36)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 1 7 0 0 0 0 37 Z 38 NA	N (19)	80
PERSONNEL INJURIES OF SCRIPTION (41)	1887	60
1 9 Z (42) NA	8402140218 244	#0
PUBLICITY INSUED DESCRIPTION (45)	8402140218 840110 PDR ADDCK 05000259 S PDR	80
20 N 4 NA	FDR	NRC USE ONL
NAME OF PREPARER T.	I. Sharpe PHONE (20	05)729-0621

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 83071 Technical Specification Involved 3.8.B.8

Reported Under Technical Specification 6.7.2.b(2) * Date Due NRC 1/11/83

Event Narrative:
Units 1 and 3 were shut down for refueling, unit 2 was at 91-percent power.
Only unit 1 was affected. During a routine response check of the 1-RM-90-250 continuous air monitor (CAM) the radiochemical laboratory analyst discovered that the drive belt for the Schwitzer Model 325 Series vacuum pump had broken. 1-RM-90-250 monitors the unit 1 reactor and turbine building vents for the presence of radioactivity. The radiochemical lab began taking hourly samples immediately, and operations personnel were notified.

The cause was due to the normal wear expected of continuous operation. A preventive maintenance program to periodically replace these belts is being established and no additional recurrence control is necessary. Hourly samples showed no increase in radiation levels and similar reactor and turbine building vent monitors on units 2 and 3 were operable and also showed no increase in radiation levels. There was no effect on public health and safety.

* Previous Similar Events:

BFRO-50-259/81051, 82008, 82061, 83051, 83059 260/82036, 83003 296/81063, 81067

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision:

NRC FCHM 31 (12-84)	6 0 :	NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB
TO CHA SO	THOL BLOCK	LICENSEE EVENT REPORT	3150.0011
		PCEASE PHINT OR TYPE	ALL REQUIRED INFORMATION)
CONT	L B R F 1 0 0 0	- 0 0 0 0 0 - 0 0 0 4	LICENSE TYPE 30 ST CAT 35
01	SOURCE L 6 0 5 0 0 0	0 2 5 9 0 1 2 1 2 8 3	3 8 0 1 1 1 0 8 4 6
0 2 1 D	aring unit outage, while	performing SI 4.8.B.2-1b and	
0 3 d	Iscovered a broken vacuum	pump belt on 1-RM-90-250 (re	eactor and turbine
0 4 b	uilding vent monitor). T	he CAM may have been inoperat	ble for a maximum of 24-
0 5 h	ours (T.S. 3.8.B). There	was no effect on public heal	ith and safety. Hourly
		rs for units 2 and 3 showed r	
-	evels during the event.	There are no redundant system	ns.
0 8			
0 9	M C 10 E 12	F 13 P U M P X X 14	SUBCODE SUBCODE [X] (15) [Z] (16)
(17)		0 7 1 0 3	TYPE REVISION NO.
A CTIO	FUTURE EFFECT SHUTDOWN METHOD 18 Z 19 Z 20 Z 2	HOURS (22) SUBMITTED FORM	
TO T	E DESCRIPTION AND CORRECTIVE ACT Ne cause was normal wear	due to continuous operation.	The standard V-belt
11 1	or the Schwitzer Model 32	5 Series air pump was replace	ed. No further recur-
12 r	ence control is required.	The C. ive belts are checked	periodically for wear
1 3 b	SI 4.8.B.4.2.a.		
1 4 L			80
1 5 H	28 0 0 0 0 0 NA	DISCOVERY Lab Analys	OVERY DESCRIPTION (32)
	CONTENT OF RELEASE AMOUNT OF ACTIVITY (3) Z (14) NA	NA	TION OF HELEASE (36)
1 7 0 NO	O O O Z Z OB NA	* * * * * * * * * * * * * * * * * * * *	80
	O O A NA		20
LOSS OF	OR DAMAGE TO FACILITY (43)		IE22
1 1 1	10		
20 N	DESCRIPTION (45)		NRC USE ONLY
	NAME OF PREPARER T. J. S	harpe	one (205)729-0621

×

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 83071 Technical Specification Involved 3.8.B.8

Reported Under Technical Specification 6.7.2.b(2) * Date Due NRC 1/11/83

Event Narrative:
Units 1 and 3 were shut down for refueling, unit 2 was at 91-percent power.
Only unit 1 was affected. During a routine response check of the 1-RM-90-250 continuous air monitor (CAM) the radiochemical laboratory analyst discovered that the drive belt for the Schwitzer Model 325 Series vacuum pump had broken. 1-RM-90-250 monitors the unit 1 reactor and turbine building vents for the presence of radioactivity. The radiochemical lab began taking hourly samples immediately, and operations personnel were notified.

The cause was due to the normal wear expected of continuous operation. A preventive maintenance program to periodically replace these belts is being established and no additional recurrence control is necessary. Hourly samples showed no increase in radiation levels and similar reactor and turbine building vent monitors on units 2 and 3 were operable and also showed no increase in radiation levels. There was no effect on public health and safety.

* Previous Similar Events:

BFRO-50-259/81051, 82008, 82061, 83051, 83059 260/82036, 83003 296/81063, 81067

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision:

1750 Chestnut Street Tower II

January 10, 1984

Mr. James P. O'Rellly, Director U.S. Nuclear Regulatory Commission Sulte 2900 101 Marletta Street, NW. Atlanta, Georgia 30303

Dear Mr. O'Rellly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFR0-50-259/83071

The enclosed report provides details concerning a continuous air monitor that was inoperable because of a broken drive belt. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Coffey Director of Nuclear Power

GTJ:MLG
Enclosure
cc (Enclosure):
 Document Control Desk
 U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

DESIGNATED ORIGINAL

Certified By 10

TEZZ III

Mr. James P. O'Reilly

cc (Enclosure):

NUC PR ARMS, 1520 CST2-C

E. A. Belvin, 109 MPB-M

Alvan Bruch, 201 SPB-K

C. W. Crawford, 670 CST2-C

C. H. Crowell, El2A4 C-K

H. N. Culver, 249A HBB-K

J. P. Darling, 546 CST2-C

R. J. Johnson, POTC (Attention: N. S. Catron)

R. L. Lumpkin, 401 UBB-C (2)

D. E. McCloud, 1530 CST2-C

L. M. Mills, 400 CST2-C

J. A. Raulston, W10C126 C-K

F. A. Szczepanski, 220 4018-C

D. L. Williams, WIOB85 C-K

TVA 64 (05-9-65)

UNITED STATES GOVERNMENT

Memorandum

TENNESSEE VALLEY AUTHORITY

T. G. Campbell, Manager, Nuclear Production, 1760 CST2-C

G. T. Jones, Power Plant Superintendent, Browns Ferry Nuclear Plant

DATE

: JAN 1 0 1984

SUBJECT: REPORTABLE OCCURRENCE REPORT - BFRO-50-259/83071 - BROWNS FERRY

NUCLEAR PLANT

Attached is the Plant Operations Review Committee's report of the subject reportable occurrence. This occurrence is reportable under Browns Ferry Unit 1 Technical Specifications, Section 6.7.2.b.(2). This occurrence has been evaluated for reportability under 10 CFR 21 and is not reportable.

This report is due NRC January 11, 1984.

A.T. Jan

TLC:SSH Attachments cc (Attachments): NUC PR ARMS, 1520 CST2-C T. L. Chinn, BFN W. C. Thomison, BFN

JAN 1 1994 Div. Or house a runed

This was principally prepared by C. J. Rozear

