NRC FO (12-81) 10 CFR		AR REGULATORY COMMISSION	APPROVED BY OMB
10 07 10	CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL REQUIRED	NFORMATION)
0 1	C A S O S Z 2 O O - O O C C C C C C C C	NSE NUMBER 25 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4 L 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 6	0 1 7 0 8 0 9 8 3 8 0 9 0	7 8 3 9
0 2	On August 9, 1983, at 1545, with	unit 2 in Mode 1, Purge/Vent Stac	k Monitor
2RI-7865 was discovered to have low flow during a routine visual inspection and			
0 4	was declared inoperable. Purge/V	ent Stack Monitor 3RI-7865 remaine	ed operable.
0 5	In accordance with LCO 3.3.3.6,	Table 3.3-10 Action Statement 22,	action was
o 6 commenced to restore the monitor to operating condition within 72 hours. Public			
0 7 health and safety were not affected by this event. See also LER 83-051 (Docket			
0 8	[No. 50-362).		60
0 9	SYSTEM CAUSE CAUSE SUBCODE M C 11 A 12 X 1. 9 10 11 SEQUENT REPORT N	13 16 19 20	(6)
	17) REPORT 8 3 22 23 24 ACTION FUTURE EFFECT SHUTDOWN METHOD E 18 Z 19 Z 20 Z 21	26 27 28 29 30 31 HOURS 22 ATTACHMENT NPRD-4 PRIME COM SUBMITTED FORM SUB. SUPPLIES 1 0 0 0 Y 23 N 24 N (43	
cause description and corrective actions (27) 1 0 2RI-7865 low flow was due to an apparent unauthorized value manipulation by			
unknown personnel. The valve was opened and proper flow was restored. The			
monitor was declared operable on August 9, 1983, at 2020. (See Attachment.)			
1 3			
1 4			80
	FACILITY POWER OTHER STATUS (3	METHOD OF DISCOVERY DESCRIPT	
1 6	9 10 12 13 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35)	LOCATION OF RELEAS	
7 0	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 37 N 38 NA	44 45	90
7 0	PERSONNEL INJURIES NUMBER DESCRIPTION 41		**
7 8	DESCRIPTION NA	9309260175 830907 PDR ADDCK 05000361 S PDR	n
2 0	PUBLICITY ISSUED DESCRIPTION (45) N (44) NA		NRC USE ONLY
	NAME OF PREPARER H. B	PHONE 714/4	

ATTACHMENT TO LER 83-104
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTION

To prevent future unauthorized valve manipulation, the radiation monitor isolation/bypass valves have been secured in their proper positions with seals. No further corrective action is considered necessary.

SEP 14 PH 12: 34

TELEPHONE

(714) 492-7700

Southern California Edison Company 1983 SEP 14

SAN ONOFRE NUCLEAR GENERATING STATION P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

September 7, 1983

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region V 1450 Maria Lane, Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361

30-Day Report

Licensee Event Report No. 83-104

San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix 2, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for an occurrence involving Limiting Condition for Operation (LCO) 3.3.3.6 associated with accident monitoring instrumentation. Enclosed LER 83-104 addresses this event, including corrective actions and measures to prevent recurrence.

If you have any further questions, please so advise.

Sincerely,

Enclosure: LER No. 83-104

IE-22

- cc: A. E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
 J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)
 - U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement
 - U. S. Nuclear Regulatory Commission Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)