NRC For	. 364			LIC	ENSEE EVEN	T REF	ORT	(LER)	U.S. RU A E	CLEAR REGULA	TORY COMMINE 99
ACILITY	Sal	em Gene	erating S	tation	- Unit 2	2		0	OCKET NUMBER	(0) [0]3[1]	PAGE (3)
Read	tor	Coolan	t System-	-RTD By	ypass Lin	e -	22RC	17 & 231	RC24 Val	lve Fai	lures
EVE	INT DATE	(6)		6)	REPORT DATE	(7)		OTHER	ACILITIES INVO	LVED (B)	
MONTH	DAY	YEAR YEAR	SEQUENTIAL	REVISION	MONTH DAY YEAR FACILITY NAN				ES	DOCKET NUMB	ER(S)
						H				0 19101	
0 1	1 2	8 4 8	4 0 0 1	-00	0 2 0 9	8 4		inite at		0 15 10 1	010111
OPE	RATING	THIS R	EPORT IS SUBMITTE	D PURBUANT	TO THE REQUIREMENT	NTE OF 10	CFR & 10	Check one or more o	f the following) (1	5)	
POWL LEVE (10)	č _o		0.406(a)(1)(i) 0.406(a)(1)(ii) 0.406(a)(1)(iii) 0.406(a)(1)(iv) 0.406(a)(1)(v)		50.36(e)(1) 50.36(e)(2) 50.73(e)(2) 50.73(e)(2)(i) 50.73(e)(2)(ii) 50.73(e)(2)(iii)			50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A 50.73(a)(2)(viii)(8 50.73(a)(2)(x)	0 0	73.71(e) X OTHER (below and 366.4)	Specify in Abstract I in 7ext, NRC Form
					ICENSEE CONTACT	THIS I	ER (12)				
AME	J.	L. Rup	p						AREA CODE	TELEPHONE NU	MBER
			COMPLETE	ONE LINE FOR		FAILURE	DESCRIBE	D IN THIS REPOR	151019	313191	-141319
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	•
В	A B	494	R 3 4 4	Y				111			
	1	111	1 1 1 1				1	111		1.15	
			SUPPLEME	NTAL REPORT	EXPECTED (14)				EXPECT	ED MON	TH DAY YEA
VE	(11 yes, c	mpiete EXPECTE	D SUBMISSION DATE	y .	X NO				DATE (1	ION 151	
In 3 14 H The the LER, occu RTD Sale simi of t RTD deci avai of t Line dis} occu this faci	A lumin of lumin of lumin of lumin of lands are served and and are served and are	ary 198 tor Coo nt was be USNRC nce, and ss lind ceived problem stem and to rad le oppo Reactor lves (in n 22RC1 ndetecto port is ies of	3, Salem lant Loop attribute documents issued 1 d recomme e low flo a messag m (which d disc or es low fl iograph a rtunity. Coolant n Unit 2) 7 and 23F ed. This being su	Unit Unit Ded in D Ded in Ded in D Ded in Ded in	A species of the second	nced mper caus 3-00 Noti uti nts. uti lin have val and nce t th d be rs t ify	a 1 atur ed b 7/03 ce N liti As lity ed) e va bee ves 13, Temp e st not o be the	ow flow e Detect y corros L. As a o. 83-61 es perio a resul , inform was caus lve. Al n experi in both 1984, n erature ems were ed that generic Commissi	condit. tor Bypa sion pro- a resul 5, desc: odically lt of the ning us sed by a lthough ienced, units a cadiogra Detector this fa c in nation and	ion in ass Lin oducts, t of th ribing y verif he IE n that a a separ no add it was at the aphy re or Bypa hed fro ailure ture, a other	No. e. and at this y the otice, ation itional next sults ss m the can nd
		840211 PDR AI	56010 840 DDCK 0500	209 0311 PDR					Ie	E22	

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Salem Generating Station	DOCKET NUMBER	LER NUMBER	PAGE
Unit 2	05000311	84-001-00	2 OF 5

PLANT AND SYSTEM IDENTIFICATION:

Westinghouse - Pressurized Water Reactor

Energy Industry Identification System (EIIS) codes are indentified in the text as [XX].

IDENTIFICATION OF OCCURRENCE:

Reactor Coolant System [AB] - Resistance Temperature Detector (RTD) Bypass Line - 22RC17 and 23RC24 Valve Failures

When Discovered: 01/12/84 01/13/84

Report Date: 02/09/84

This report was initiated by Incident Reports 84-011 and 84-012

CONDITIONS PRIOR TO OCCURRENCE:

Mode 5 - Rx Power 000 % - Unit Load 0000 MWe

DESCRIPTION OF OCCURRENCE:

On January 29, 1983, during routine shutdown operation, a low flow alarm was received in the Unit 1 control room from the No. 14 Reactor Coolant Loop RTD Bypass Line. Investigation of the problem, by alternately isolating the hot-leg and cold-leg sides of the flowpath, indicated that the hot-leg flowpath was obstructed. The No. 14 Reactor Coolant Average Temperature Channel was therefore declared inoperable and a limiting condition for operation was entered, retroactive to the time of discovery. All bistables associated with the channel were immediately placed in the tripped condition. The redundant loop Tave channels remained operable throughout the occurrence. In an attempt to dislodge the obstruction from the hot leg bypass loop, its isolation valve was cycled, and bypass flow was restored to normal. No other problems with the channels were evident, and the occurrence was assumed to involve an isolated instance of corrosion products restricting flow in the bypass line.

Unit 1 Licensee Event Report (LER) 83-007/03L documented the above listed occurrence. As a result of that LER, the NRC issued IE Information Notice No. 83-65 (dated October 7, 1983) to all Westinghouse nuclear power reactor facilities holding on operating license (OL) or a construction permit (CP). This information notice recommended calibration of the flow sensors on a refueling outage basis and verification of the alarm setpoint on a monthly basis, to assure the operability of this monitoring function, since no previous surveillance requirements existed.

•	LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION	
Salem Gene Unit 2	rating Station	n	DOCKET 0500	NUMBE	R	LER NUMBER 84-001-00	PAGE 3 OF 5

DESCRIPTION OF OCCURRENCE; (cont'd)

As a result of that information notice, Salem received a notice (dated October 19, 1983) from another utility, via the Site Westinghouse Representative, informing us of a similar problem which they had experienced with reduced flow through the RTD bypass loops. The message explained that their problem was caused by a stem-to-disk separation of a pypass line isolation valve. The valve disk had fallen, resulting in restriction of the flow. Given the right conditions, the valve disk could lift and flow would be reestablished; this type of failure could easily be mistaken for an obstruction caused by crud.

Although the occurrence in January 1983 was the only one of its kind ever experienced at either of the Salem units, it was decided to radiograph all RTD bypass line valves in all reactor coolant loops of both units during their next refueling outages. When the present maintenance shutdown of Unit 2 was extended, the decision was made to radiograph the valves associated with that unit at that time, rather than wait for the next refueling outage.

Five values in each of the four bypass lines (for a total of twenby values) were radiographed. On January 12, 1984, radiography results of No. 22 Reactor Coolant Loop RTD Bypass Line values revealed that the disk was separated from the stem on 22RC17. On January 13, 1984, a similar failure was discovered on 23RC24, located in No. 23 Reactor Coolant Loop RTD Bypass Line. All other bypass line values were satisfactory.

ANALYSIS OF OCCURRENCE:

The reactor coolant loop temperature instruments are utilized in the Reactor Protection System [JC]. Operability of the temperature instruments is required to provide the overall reliability, redundancy, and diversity available in the facility design for the mitigation of accidents. The Reactor Coolant System [AB] hot-leg and cold-leg RTDs are located in reactor coolant bypass loops. A bypass loop from upstream of the steam generator to the reactor coolant pump inlet is used for the hot-leg RTD, and a bypass loop from degnstream of the reactor coolant pump to the pump inlet is used for the cold-leg RTD.

The bypass loop flowrate affects the overall time response of the temperature signals provided for reactor protection. These response times are considered in performing FSAR accident analyses and are included in plant Technical Specification surveillance requirements. Westinghouse Functional Specification CE CPA-978 requires a bypass flowrate of fifty to three-hundred gallons per minute (50-300 GPM). Flowrate within this band will ensure the required time response for thermal overpower and overtemperature protection. The Salem Generating Station design enables a normal flowrate of three-hundred (300) GPM. The RTD bypass loops have low flow alarms whose setpoint

•	LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION	
Salem Genera	ting Station		DOCKET	NUMBE	R	LER NUMBER	PAGE

ANALYSIS OF OCCURRENCE: (cont'd)

is ninety percent (0%) of the normal flow. This setpoint corresponds to a flowrate of two-hundred and seventy (270) GPM, and is well above the minimum required flowrate of fifty (50) GPM.

Unit 2 has never received this alarm during plant operation, which indicated that the bypass line flow has held these valve disks in the open position. As previously stated, the unit is shutdown. To verify proper operation, the flow sensor calibration was checked, the reactor coolant pumps were started, and flow measurements verified flow to be greater than two-hundred and ninety (290) GPM in the bypass lines containing the defective valves. This indicates that the disks are, in fact, lifting off of their seat. The low flow alarm setpoints were checked. They were satisfactory, and the alarms functioned properly, which confirms that flow in these bypass lines has always been greater than two-hundred and seventy (270) GPM.

Unit 1 RTD bypass flow sensors were also calibrated. Flow measurements greater than two-hundred and seventy (270) GPM was confirmed. The low flow alarm setpoints were also verified to be functioning properly.

A safety evaluation was performed. The physical dimensions of these detached disks precludes the possibility of them being dislodged from the inlet or outlet ports of the valves. Because of the valve design, the stems cannot be physically backed out of the valves by overtravel. They also cannot be forced out by the system pressure; this has been confirmed by the vendor. Flow in the bypass lines has been confirmed to be greater than two-hundred and seventy (270) GPM. The low flow alarms have been verified to be set at 270 GPM and functioning properly; they will alert operators in the control rooms if flow decreases below this value. Corrective action will be taken if the alarm is received. Because only one valve in each loop is affected, the RTDs may be isolated (if necessary) at any time. Flow direction through these valves has been verified to be in the direction that tends to lift the valve disks off of their seats. There are no unreviewed safety questions or problems associated with Unit 2 startup because of these valve failures. There are also no safety problems with continued operation of Unit 1, even if simila. failures should This occurrence involves no undue risk to the health or safety occur. of the public. This problem appears to be generic in nature, and this report is being submitted to notify the Commission and other facilities to the possibility of similar undetected failures.

FAILURE DATA:

Rockwell-International Globe Valve 1500 S 2 Inch, Stainless Steel Type 3624 F316 Mark No. FA-17

•	LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION	
Salem Ger	nerating Station	n]	DOCKET	NUMBE	R	LER NUMBER	PAGE
Unit 2			0500	0311		84-001-00	5 OF 5

FAILURE DATA: (cont'd)

Although the problem has been identified in 2" valves, other size valves of a similar design may also be subject to this type of failure. The separation of the stem from the disk is apparently caused by the force exerted on this joint when the valve is backseated.

CORRECTIVE ACTION:

The Station has identified all two inch (2") valves of this type. Installation has been verified to be such that the system flow (for valves which are in the normally open position) is in the direction which will tend to lift the disk off of the seat, if such a failure should occur. Corrective action will be taken upon receipt of a low flow alarm. The Station is working on plans to replace these valves with ones of a different design. As an added precaution, the handwheels of 22RC17 and 23RC24 have been removed, to prevent further operation and overtravel of the stems. Operators have been advised to use caution while backseating these type of valves.

Prepared By J. L. hupp

In Jupps &

General Manager-Salem Operations

SORC Meeting 84-016



Public Service Electric and Gas Company P.O. Box E. Har.cocks Bridge, New Jersey 08038

Salem Generating Station

February 9, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

SALEM GENERATING STATION LICENSE NO. DPR-75 DOCKET NO. 50-311 UNIT NO. 2 LICENSEE EVENT REPORT 84-001-00

This Licensee Event Report is being submitted to notify the Commission and other facilities of a possible undetected generic problem associated with Reactor Coolant Loop RTD Bypass Line values.

Sincerely yours,

mushok

J. M. Zupko, Jr. General Manager -Salem Operations

JR: k11 808

CC: Distribution

IE22