

3150-0011

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)NRC USE ONLY

PHONE

714-492-7700

ATTACHMENT TO LER 83-110
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNIT NO. 2, DOCKET NO. 50-361

SUPPLEMENTAL INFORMATION FOR EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

The loss of Train B Emergency chiller renders two inverters inoperable in each unit. Since LCO 3.8.3.1. requires all four inverters and their associated busses to be operable in Mode 1 through 4 in each unit and since the associated Action Statement only addresses the loss of one such inverter and its associated bus, LCO 3.0.3 was invoked at 1415.

Public health and safety were not affected as a result of this event. See also LER 83-048 (Unit 3).

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The correct size fuse was installed and the chiller declared operable, at 1514 restoring operability to the two inverters in each Unit and associated A. C. vital busses, and LCO 3.0.3 was exited. As a precaution the fuse in the other chiller E-336 (Train A) was checked and verified to be of the correct size. Since: (1) use of the correct fuse is provided by replacement of failed fuses with like kind fuses, (2) verification with design requirements is periodically accomplished when post maintenance testing (which includes validation with design drawings) is performed, and (3) this is the first discovery of an incorrectly sized fuse, no further corrective action is considered necessary.