

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 0 A S O S 3 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

01 0 5 0 0 0 3 6 2 7 1 0 1 7 8 3 8 0 1 3 1 8 4 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 10/17/83, with Unit 2 in Mode 1, the undervoltage (UV) armatures for

03 Reactor Trip Breakers (RTB's) 4 and 8 were found not to be fully picked-

04 up. On 10/28/83, with Unit 3 in Mode 3, RTB's 5 and 8 were observed to

05 be in the same condition. On 10/31/83, with both Units 2 and 3 in

06 Mode 1, Unit 2 RTB 4 and Unit 3 RTB's 5 and 8 were found in this con-

07 dition. (See attachment.)

08

09 I A 11 E 12 B 13 C K T B R K 14 A 15 Z 16

17 LER/RO REPORT NUMBER 18 8 3 19 0 9 1 20 0 1 21 X 22 1

23 24 25 26 27 28 29 30 31 32

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

10 E 11 X 12 Z 13 Z 14 0 0 0 0 15 Y 16 N 17 N 18 G 19 0 20 8 21 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 UV armatures not being fully picked-up is the result of interference

11 between the UV armature and the copper shading ring around the coil core.

12 All affected RTB's were reset. As corrective action, visual verification

13 and manual adjustment of proper closed air gap position is required

14 following energization of the UV device. Diode elimination is being

15 investigated.

16 B 28 0 0 0 29 NA 30 B 31 Surveillance Testing 32

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 Z 33 Z 34 NA 35 NA 36

18 0 0 0 37 Z 38 NA 39

40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

19 0 0 0 40 NA 41

42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL INJURIES NUMBER DESCRIPTION

20 Z 42 NA 43

44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

21 N 44 NA 45

46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER

J. G. HAYNES

PHONE

714/492-7700

ATTACHMENT TO LER 83-091, REVISION 1
SOUTHERN CALIFORNIA EDISON COMPANY
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 AND 50-362

SUPPLEMENTAL INFORMATION FOR EVENT DESCRIPTION AND PROBABLE
CONSEQUENCES

Based on vendor tests, the abnormal armature position has little or no detectable effect on the ability of the UV trip device to trip the breaker on loss of voltage. Public health and safety were unaffected since the shunt trip feature functioned properly. See LER 83-125 (Docket No. 50-361).

Southern California Edison Company

SCE

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

January 31, 1984

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Licensee Event Report No. 83-091, Revision 1,
(Docket No. 50-361)
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, J. G. Haynes (SCE) to J. B. Martin (NRC),
"14-Day Follow-Up Report, Licensee Event Report 83-091
(Docket No. 50-362)," dated November 18, 1983

The referenced letter provided the 14-Day Follow-Up Report and a copy of the Licensee Event Report (LER) form for an occurrence involving operation of Reactor Trip Breakers (RTB's) on their undervoltage (UV) trip devices. (As in the past, the breakers continue to function acceptably using the shunt trip device.) As stated in that letter, our investigation into UV armatures not fully picking up as a result of interference between the UV armature and the copper shading ring around the core of the coil was continuing with the assistance of SCE and CE organizations and the vendor.

Based on tests conducted by the vendor (General Electric), it has been concluded that the armature in this abnormal position has little or no detectable effect on the ability of the UV trip device to trip the breaker on loss of voltage, therefore, no immediate changes to the UV device settings or configuration of parts was recommended. As stated in the referenced letter, we have implemented their recommendation that following energization of the UV device on the RTB's, the position of the armature should be visually inspected and, if necessary, manually assisted to the proper closed air gap position before closing the breaker, in order to assure the armature is in the optimum position for subsequent tripping.

22
IE-20 11

Mr. J. B. Martin

-2-

January 31, 1984

Revision 1 to LER 83-091 is enclosed. If you require any additional information, please so advise.

Sincerely,

JG. Haynes

Enclosure: LER No. 83-091, Revision 1, (Docket No. 50-361)

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)