U.S. NUCLEAR REGULATORY COMMISSION NRC FORM 366 (7.77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: 0 (4) R E 0 (3) 0 17 P (2 (5) 1 LICENSE NUMBER LICENSEE CODE CON'T REPORT (7) 0 | 8 | 2 | 4(8) 0 9 21 1 8 3 (9) 0 1 15 (6 0 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) Routine surveillance during unit power operation revealed that RWCU System differential 0 2 flow indicator 2-G31-R615 was indicating high. R615 provides an indiciation for one of 0 3 two parallel outputs from RWCU System summer circuit 2-G31-K604 which receives its 0 4 input from three RWCU System flow transmitters, 2-G31-FT-N012, N036, and N041. This 0 5 event did not affect the health and safety of the public. 0 6 0 7 6.9.1.9b Specifications Table 3.3.2-1. Item 3a. Technical 8 COMP SYSTEM CAUSE VALVE CAUSE SUBCODE COMPONENT CODE CODE BI A (13) SI RUU T (15) Z (16) DI (12 N TI (14 0 9 18 REVISION OCCURRENCE REPORT SEQUENTIAL CODE REPORT NO. TYPE NO. EVENT YEAR LER/RO REPORT 8 13 0 3 NUMBER 26 28 NPRD-4 PRIME COMP. COMPONENT ATTACHMENT METHOD ACTION FFFFCT TAKEN (22) HOURS FORM SUB. ON PLANT 19 (23) (24) N X X (21 (25) (18)(19 (20 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The design of the sensing lines to FT-N041 allowed air to become entrapped in high 1 0 points of the lines and cause a calibration shift in the transmitter. The sensing 1 1 lines to FT-N041 were vented and the transmitter, Model No. 555, was returned to 1 2 service. Plant Engineering has been requested to evaluate modifying the sensing lines to all three transmitters to eliminate the air-entrapment problem. 1 4 80 METHOD OF FACILITY (30)(32)DISCOVERY DESCRIPTION OTHER STATUS % POWER Surveillance NA A Operator E (28) 0 0 (31 (29)80 9 10 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE NA NA Z (33) 2 (34) 6 45 80 4.4 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE (38 01 0 A 8310030422 830921 PDR ADDCK 05000324 PERSONNEL INJURIES DESCRIPTION (41) UMBER 0 0 PDR (40 80 E22 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA (42 80 NRC USE ONLY PUBLICITY DESCRIPTION (45) N 44 NA 11111 80 ä 919-457-9521 M. J. Pastva, Jr. PHONE .. NAME OF PREPARER.

LER ATTACHMENT - RO #2-83-73

Facility: BSEP Unit No. 2

Event Date: August 24, 1983

This event occurred when the instrument indication of RWCU System differential flow indicator 2-G31-R615, General Electric Model No. 180, went high. Three RWCU System flow transmitters, 2-G31-FT-N012, N036, and N041, one on the RWCU System suction line and one each on the two RWCU System discharge lines, feed an RWCU System summing circuit, 2-G31-FY-K604. The summing circuit takes the system suction flow and compares it with the combined system discharge flow to produce a differential flow signal to the RWCU System isolation circuits. 2-G31-R615 is a uirect reading indicator off one of the two parallel signals from the summer.

This event resulted from a shift in the calibration of the FT-NC41 caused by entrapped air in the sensing lines of the transmitter. Due to the design of the sensing lines to the NO41, air can be entrapped in high points of the lines during periods when the RWCU System is depressurized for routine RWCU System filter demineralizer precoating or during maintenance of the system. This condition can also affect the FT-NO12 and FT-NO36 transmitters, as their respective sensing lines are similarly designed; although, in this case, air was not entrapped in their sensing lines.

The entrapped air in the sensing lines of FT-N041, General Electric Model No. 555, was removed and the transmitter was returned to service. As a result of this event, plant Engineering has been requested to evaluate modifying the instrument sensing lines of the FT-N012, N036, and N041 transmitters to eliminate the sensing line high point air-entrapment problem.



Carolina Power & Light Company

83 SEP 26 A8: 49

Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429

September 21, 1983

FILE: B09-13510C SERIAL: BSEP/83-3129

Mr. James P. O'Reilly, Administrator U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta Street N.W. Atlanta, GA 30303

> BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-324 LICENSE NO. DPR-62 LICENSEE EVENT REPORT 2-83-73

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

2ling

C. R. Dietz, General Manager Brunswick Steam Electric Plast

RMP/clh/LETJ03

Enclosure

cc: Mr. R. C. DeYoung NRC Document Control Desk

DESCRIPTION COPY