

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	R	A	N	0	2	12	0	0	-	0	0	0	0	0	-	0	0	13	4	1	1	1	1	4	1	1	15	
7	8	LICENSEE CODE					14	15	LICENSE NUMBER					25	26	LICENSE TYPE					30	57	CAT	58						
0	1	REPORT SOURCE					16	0	5	0	0	0	3	6	8	17	0	8	0	2	8	3	18	0	9	2	2	8	3	19
7	8	SOURCE					60	61	DCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 8/2/83, while in Mode 1 at 100% full power (FP), fire door 274, which is the entrance to the cable spreading room, was found to have a gap of greater than 3/4" at the bottom. Our procedures, which are utilized in determining the operability of fire barriers in accordance with ANO-2 Technical Specification (T.S.) 3.7.11, state that there will be no greater than a 3/4" air gap at the base of fire doors. This occurrence was discovered during a fire barrier visual inspection. This occurrence is reportable per T.S. 6.9.1.9.b. No previous occurrences regarding excessive fire door gap have been reported. Other LER's regarding fire barriers include (50-368) 80-081, 81-029, 81-042, 82-029, 82-039, 83-004, 83-008, 83-020, 83-021 and 83-032.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE		REVISION NO	
0 9		A B 11		E 13		Z Z Z Z Z Z 14		Z 15		Z 16		1	
7 8		9 10		11 12		13 18		19		20		32	
17	LER/RO REPORT NUMBER	EVENT YEAR 8 3		---		SEQUENTIAL REPORT NO. 0 3 3		OCCURRENCE CODE /		REPORT TYPE X		REVISION NO 1	
		21 22		23		24 26		27 29		30 31		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		ATTACHMENT SUBMITTED		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
F 18		Z 19		Z 20		Z 21		N 23		Z 25		Z 9 9 9 26	
33		34		35		36		41		43		44 47	
						HOURS 0 0 0 22		FORM SUB N 24					
						37 40		42					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1	0	1	The fire door was previously installed and inspected by procedures that did not contain guidance relating to
1	1	1	maximum allowable clearance. Immediate action was to post a fire watch until repairs could be made. A new
1	2	1	threshold plate was installed to decrease the gap to 3/8" or less. The fire barrier visual inspection of the
1	3	1	cable spreading room is continuing.

7 | 1 | 4 | 8 | 9 | 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	1	NA
7	8	9	10	11	12	13	14	15	16
17	18	19	20	21	22	23	24	25	26
27	28	29	30	31	32	33	34	35	36
37	38	39	40	41	42	43	44	45	46
47	48	49	50	51	52	53	54	55	56
57	58	59	60	61	62	63	64	65	66
67	68	69	70	71	72	73	74	75	76
77	78	79	80	81	82	83	84	85	86
87	88	89	90	91	92	93	94	95	96
97	98	99	100	101	102	103	104	105	106
107	108	109	110	111	112	113	114	115	116
117	118	119	120	121	122	123	124	125	126
127	128	129	130	131	132	133	134	135	136
137	138	139	140	141	142	143	144	145	146
147	148	149	150	151	152	153	154	155	156
157	158	159	160	161	162	163	164	165	166
167	168	169	170	171	172	173	174	175	176
177	178	179	180	181	182	183	184	185	186
187	188	189	190	191	192	193	194	195	196
197	198	199	200	201	202	203	204	205	206
207	208	209	210	211	212	213	214	215	216
217	218	219	220	221	222	223	224	225	226
227	228	229	230	231	232	233	234	235	236
237	238	239	240	241	242	243	244	245	246
247	248	249	250	251	252	253	254	255	256
257	258	259	260	261	262	263	264	265	266
267	268	269	270	271	272	273	274	275	276
277	278	279	280	281	282	283	284	285	286
287	288	289	290	291	292	293	294	295	296
297	298	299	300	301	302	303	304	305	306
307	308	309	310	311	312	313	314	315	316
317	318	319	320	321	322	323	324	325	326
327	328	329	330	331	332	333	334	335	336
337	338	339	340	341	342	343	344	345	346
347	348	349	350	351	352	353	354	355	356
357	358	359	360	361	362	363	364	365	366
367	368	369	370	371	372	373	374	375	376
377	378	379	380	381	382	383	384	385	386
387	388	389	390	391	392	393	394	395	396
397	398	399	400	401	402	403	404	405	406
407	408	409	410	411	412	413	414	415	416
417	418	419	420	421	422				

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	34	NA	35	NA	36
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES										
NUMBER					TYPE		DESCRIPTION			
1	7	0	0	0	37	2	38	NA		
7	8	9	11	12	13					

PERSONNEL INJURIES										80
NUMBER					DESCRIPTION					
1	2	3	4	5	6	7	8	9	10	
1	8				0	0	0	40	1	NA
7		8			9			11	12	
										141

11 12		80
LOSS OF OR DAMAGE TO FACILITY		
TYPE	DESCRIPTION	
1 9	Z 142 NA	43

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	44	NA			
7	8	9	10			45	68
							69
							80

NAME OF PREPARER: Patrick Rogers


PHONE: (501) 964-3100

8310040206 830922
PDR ADCK 05000368
S PDR



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 22, 1983



2CAN098314

Mr. W. C. Seidle, Chief
Reactor Project Branch #2
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-033/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning an excessive fire door gap. This LER is being reissued due to an incorrect Technical Specification reference in the previous revision.

Very truly yours,

John R. Marshall
John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555