


The Light company

Houston Lighting & Power P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

September 22, 1983
ST-HL-AE-1006
File Number: G12.167

Mr. John T. Collins
Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Dear Mr. Collins:

South Texas Project
Units 1 & 2
Docket Nos. STN 50-498, STN 50-499
First Interim Report Concerning the
Reactor Containment Building Post-Tensioning System Tendons

On August 26, 1983, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P) notified your office of an item concerning the Reactor Containment Building (RCB) post-tensioning system tendons. Attached is the first interim report concerning this item. The next report will be submitted to your office by February 29, 1984.

If you should have any questions concerning this item, please contact Mr. Michael E. Powell at (713)877-3281.

Very truly yours,

A handwritten signature in cursive script, reading "G. W. Oprea, Jr.", written in dark ink.

G. W. Oprea, Jr.
Executive Vice President

MEP/mg
Attachment

8310040289 830922
PDR ADOCK 05000498
S PDR

IE-27
1/1

Houston Lighting & Power Company

September 22, 1983
ST-HL-AE-1006
File Number: G12.167
Page 2

cc: G. W. Oprea, Jr.
J. H. Goldberg
J. G. Dewease
J. D. Parsons
D. G. Barker
M. R. Wisenburg
R. A. Frazar
J. W. Williams
R. J. Maroni
J. E. Geiger
H. A. Walker
S. M. Dew
J. T. Collins
A. Vietti
W. M. Hill, Jr.
M. D. Schwarz
R. Gordon Gooch
J. R. Newman

(NRC)
(NRC)
(NRC)
(Baker & Botts)
(Baker & Botts)
(Lowenstein, Newman, Reis, & Axelrad)

STP RMS

Director, Office of Inspection & Enforcement
Nuclear Regulatory Commission
Washington, D. C. 20555

G. W. Muench/R. L. Range
Central Power & Light Company
P. O. Box 2121
Corpus Christi, Texas 78403

Charles Bechhoefer, Esquire
Chairman, Atomic Safety & Licensing Board
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

H. L. Peterson/G. Pokorny
City of Austin
P. O. Box 1088
Austin, Texas 78767

Dr. James C. Lamb, III
313 Woodhaven Road
Chapel Hill, North Carolina 27514

J. B. Poston/A. vonRosenberg
City Public Service Board
P. O. Box 1771
San Antonio, Texas 78296

Mr. Ernest E. Hill
Lawrence Livermore Laboratory
University of California
P. O. Box 808, L-46
Livermore, California 94550

Brian E. Berwick, Esquire
Assistant Attorney General
for the State of Texas
P. O. Box 12548
Capitol Station
Austin, Texas 78711

William S. Jordan, III
Harmon & Weiss
1725 I Street, N. W.
Suite 506
Washington, D. C. 20006

Lanny Sinkin
Citizens Concerned About Nuclear Power
5106 Casa Oro
San Antonio, Texas 78233

Citizens for Equitable Utilities, Inc.
c/o Ms. Peggy Buchorn
Route 1, Box 1684
Brazoria, Texas 77422

Robert G. Perlis, Esquire
Hearing Attorney
Office of the Executive Legal Director
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Revision Date 07-05-83

First Interim Report Concerning the
Reactor Containment Building Post-Tensioning System Tendons

I. SUMMARY

Post-tensioning system tendons in long term storage at the vendors warehouse have been identified as exhibiting corrosion (e.g., rust and pitting). Evaluations are underway to determine if the condition impairs the strength of the tendons such that the required tensile strength cannot be met.

II. DESCRIPTION OF DEFICIENCY

On August 26, 1983, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P) notified the NRC Region IV of an item concerning the Reactor Containment Building (RCB) post-tensioning system tendons.

The tendons for the post-tensioning system of the RCB (Units 1 & 2) have been fabricated and held in storage at the fabricator's (Prescon Corporation) warehouse in San Antonio, Texas. The project specification requires that the fabricated tendons be periodically dipped in a corrosion inhibiting compound and visually inspected to ensure that no corrosion has developed. The specified care of the tendons is periodically surveyed in accordance with project procedures.

Visual inspection of some tendons has revealed rust and pitting of tendon wires. This was further investigated by a team of engineers through a visit to the storage facility. A program was implemented to assess the extent and nature of corrosion with the ultimate objective of determining the suitability of the tendons to perform their intended function for the lifetime of the plant. The basic approach for the evaluation of the tendon corrosion was to investigate a representative sample of the tendons for suitability and then extend the findings by statistical projections to the entire tendon population.

Currently, two randomly selected tendons have been completely examined by Pittsburgh Testing Laboratory. Results indicate that the corrosion pitting condition prevails in most of the wires, and it is not restricted to certain locations within the tendons. In some cases, pit depths exceeding 15 mils have been measured. Tensile test results indicate that the pitted wire material strength and ductility exceed the minimum specified limits. Further evaluation of the test results is presently under way to establish homogeneity of the tendon population, to determine the final sample size, and to validate a statistical approach.

III. CORRECTIVE ACTION

It is anticipated that the investigation of the corrosion of tendons will be complete enough by the end of January 1984 to reach a final decision to either use the existing fabricated tendons or procure replacement tendons.