	EXHIBIT A
	CONTROL BLOCK:
7 8	9 LICENSEE CODE 14 15 0 - 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0
7 8	SOURCE 60 61 0 0 1 0 1 0 1 0 1 0 1 0 1 8 1 1 1 8 1 8
10121	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 [On 8/18/83, while in Mode 1 at 24% full power (FP), Core Protection Calculator (CPC) Channel "A" was placed in [
10131	"bypass" and Channel "D" was tripped thereby entering the action statement of Technical Specification (TS)
10141	[3.3.1.1. This action placed the CPCs in 1 out of 2 logic with Channels "B" and "C" operable and is reportable [
10151	Iper TS 6.9.1.9.b. The above action was taken as a precautionary measure following observation that a CPC
10161	addressable constant (point identification number 064 - Thermal Power Calibration Constant) was reading less
10171	Ithan the minimum unrestricted value allowed by the Technical Specifications without prior PSC approval. There
10181	were no potential adverse affects associated with this event since the values of the constant were subsequently!
7 8 1 0 1 9 1 7 8	SYSTEM CAUSE CAUSE COMPONENT CODE COMPONENT CODE SUBCODE SUBCO
17	REPORT 1 8 3 1 1 1 0 3 8 1 1 1 0 1 3 1 1 1 1 1 1 1 1
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
	ICPC Channels "A" and "D" were removed from service because point identification number 064 for these channels _
1 1 2 1	I was found to be reading less than the minimum unrestricted allowable value without previous Plant Safety
	Committee (PSC) review and concurrence. The affected constants had been inserted into the CPCs the previous
1 1 3 1	Iday. Following observation that the values were less than the unrestricted allowable value, the PSC reviewed
1 1 4 1 8	The calculated values and concurred that they were correct and appropriate, and the CPCs were returned to $\frac{9}{9}$ FACILITY METHOD OF STATUS METHOD OF STATUS DISCOVERY DISC
1 6 8	RELEASED OF RELEASE Z 33
171	NUMBER TYPE DESCRIPTION 1 0 0 0 37 Z 38 NA 9 11 12 13
	PERSONNEL INJURIES NUMBER DESCRIPTION 0 0 0 40 NA 9
2101	PUBLICITY ISSUED DESCRIPTION N 144 NA
	228 83919

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-368/83-038/03L-0

Occurrence Date: __08/18/83

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (Continued)

reviewed by the PSC and found to be correct.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

normal status the same day. In order to prevent recurrence, related procedures have been revised to r quire specific compariso of calculated values to TS limits and signoff provisions have been added to the procedures. Also, clarification has been made to better define the differences between software limits and TS limits.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000.

September 19, 1983

SFP 2 6 1983

2CANØ983Ø8

Mr. W. C. Seidle, Chief Reactor Project Branch #2 U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6 Licensee Event Report No. 83-038/03L-0

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning problems with the Core Frotection Calculator Channels "A" and "D".

ery truly yours,

John R. Marshall Manager, Licensing

JRM: RJS: s1

Attachment

cc: Mr. Richard C. DeYoung Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> > 12/1