MPDATE REPORT-ORIGINAL REPORT DATE 8/26/83

4

.

	RM 344	LICENSEE EVENT REPORT	3136-00-1 EXPIRES 4-30-42
	CONTROL BLOCK.	DELEASE PRINT OR TYPE ALL REQ	UIRED INFORMATION
1		0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1	1 1 0 1 3
DN T			9 2 1 8 3
3 2	EVENT DESCRIPTION AND PROBABLE		
3 3	level switch's setpoints	were out of tolerance. This violates	T.S.3.5.1.2 (switc
14	assumed to have been out	of tolerance during power operation)	which is reportable
3 5	per T.S.6.9.1.11(a) and s	similar to RO's 369/82-38 and 83-13, T	he UHI system was
) jā	not challenged during the	e period of inoperability. Had the UH	I system been chal-
7	Construction of the second sec	ume delivered to the core would not ha	
3	unaffected	afety analysis. Health and safety of	valve
e i c			
	TAKEN ACTION ON PLANT MET		1 32 31 32 ME COMP. COMPONENT JPPLIER MANUPACTURER L 23 B 0 44
0	CAUSE DESCRIPTION AND CORRECTIV This is attributed to Des	sign Deficiency, since there is eviden	ce indicating that
		-1 2004 differential excession indianti	
<u> </u>		el 288A differential pressure indicati	
2	capable of consistently a	actuating within the required toleranc	e. The switches
3	capable of consistently a were recalibrated. Calibr	actuating within the required toleranc ration Frequency will be increased unt	e. The switches
3	were recalibrated. Calibrated Cal	actuating within the required toleranc ration Frequency will be increased unt is implemented.	e. The switches il a modification
3	capable of consistently a were recalibrated. Calibrated. Calibrated. to replace the switches to replace the switches X 28 0 0 X 28 0 0 X 28 0 0 X 28 0 0 0 0 X 28 0 0 0 0 X 28 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 </td <td>actuating within the required toleranc ration Frequency will be increased unt is implemented. t. Outage</td> <td>e. The switches il a modification scription 32 ance scription 33</td>	actuating within the required toleranc ration Frequency will be increased unt is implemented. t. Outage	e. The switches il a modification scription 32 ance scription 33
3	capable of consistently a were recalibrated. Calibrated. Calibrated. to replace the switches : 'acitity' 'status' 'status' <td>actuating within the required toleranc ration Frequency will be increased unt is implemented. t. Outage B T Routine Surveill Training Structure Surveill</td> <td>e. The switches il a modification </td>	actuating within the required toleranc ration Frequency will be increased unt is implemented. t. Outage B T Routine Surveill Training Structure Surveill	e. The switches il a modification
3	capable of consistently a were recalibrated. Calibrated. Cali	actuating within the required toleranc ration Frequency will be increased unt is implemented. t. Outage B T Routine Surveill Truity 35 LOCATION OF A NA	e. The switches il a modification ance ****** (33)
3	capable of consistently a were recalibrated. Calibrated. Calibrated. Calibrated. to replace the switches to replace the switches Actility status Actility Status Activity Value Image: Status Image: Stat	actuating within the required tolerance ration Frequency will be increased unt is implemented. t. Outage B (3) Routine Surveill NA NA NA	e. The switches il a modification ance ****** 33
	capable of consistently a were recalibrated. Calibrated. Calibrated. Calibrated. to replace the switches : 'acility' 's replace the switches : 'acility' 's replace the switches : 'acility' 's replace the switches :	actuating within the required tolerance ration Frequency will be increased unt is implemented. . Outage B (1) Routine Surveill . Outage NA . NA	e. The switches il a modification

DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER VICE PRESIDENT NUCLEAR PRODUCTION

83 SEP 30be A 91: 1883

TELEPHONE (704) 373-4531

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street NW, Suite 2900 Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 2 Docket No. 50-370 LER/RO-370/83-35

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-370/83-35 which was transmitted by my letter of August 26, 1983 concerned an incident involving Upper Head Injection (UHI) level instrumentation found out of calibration. This letter is a followup to the original report.

Two of four level switches which actuate to automatically close the UHI isolation values following a LOCA were set so that the values would close later than designed. The two values affected are in series on one of the two injection lines on the UHI accumulator discharge. The allowable setpoint tolerance is \pm 3.3 inches; the two switches would have actuated at -3.34 inches and -4.56 inches later than the nominal secpoint. The remaining switches would have actuated at +0.89 inches and -2.34 inches. The potential safety concern was whether the maximum UHI water volume delivered to the core (1,011 ft³) would have been exceeded if a LOCA had occurred. (The UHI water volume at the nominal setpoint is 898.5 ft³.)

The UHI Uncertainty Analysis allows for single train failure and for certain random uncertainties. Single train failure assumes one valve on each parallel injection line does not close. The remaining valves close against a greater differential pressure resulting in more water delivered to the core. Thus, an additional 42 ft³ is assumed. The random uncertainties are statistically combined by the Root Sum Square method; setpoint repeatability of 3.3 inches (66 ft³) is the dominant term.

Because of the rapid closure times of the UHI isolation valves, the valves set at -4.56 and -2.34 would have had little effect on the delivered water volume and, therefore, can be conservatively assumed to have failed open. This is comparable, in terms of delivered water volume, to single train failure. The remaining valves (one on each injection line) would have actuated at -3.34 inches and +0.89 inches. In our judgement, the effect on delivered volume of one valve actuating 4.2 inches above the lowest allowable setpoint (3.3 + 0.89inches) would have been enough to offset the effect of one valve actuating 0.04 inches low and the effects of the remaining uncertainties. Therefore if a LOCA had occurred, the UHI water volume delivered to the core would not have exceeded the maximum of 1,011 ft³.

SEFECIAL COPY

James P. O'Reilly September 21, 1983 Page 2

Additionally, McGuire Unit 2 had not operated above 30% rated power level during the period that the instruments were out of calibration. The effect of a LOCA on peak clad temperature would have been much less severe than assumed in the LOCA analysis, and operation of the system would have been within calculated limits.

Please advise if there are any questions.

Very truly yours,

Val D. Tucke

Hal B. Tucker

REH:jfw Attachment

cc: Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

Mr. W. T. Orders NRC Resident Inspector McGuire Nuclear Station