NRC FORM 366 **U.S. NUCLEAR REGULATORY COMMISSION** (7.77) LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) (1)12 0 0 0 0 0 0 0 10 3 4 1 1 1 1 3 4 1 1 1 3 57 CAT IE II 1H (2) 5 LICENSEE CODE CON'T 16 0 9 2 75 REPORT REPORT 10 10 10 13 13 EVEN 18 16 0 1 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On 08/31/83, during performance of the "DRYWELL FISSION PRODUCTS 0 2 MONITORS OPERATION AND CALIBRATION" procedure (HNP-7408), it was deter-0 3 mined that the drywell particulate fission products monitor's(2D11-K631) 0 4 counts per minute were continually increasing which gave a main control 0 5 room alarm. The monitor was declared inop., and an LCO was established. 0 6 This event is contrary to T.S. section 3.4.3.1. The health and safety of 0 7 the public were not affected by this non-repetitive event. 0 8 CAUSE SYSTEM CAUSE COMP VALVE CODE COMPONENT CODE CODE SUBCODE S | T | R | U | 14 Z 13 E 115 C II х II N (16 0 9 SEQUENTIAL OCCURRENCE REVISION REPORT REPORT NO CODE EVENT YEAR TYPE NO. LER/RO 0 3 8 3 0 | 5 | 2 L 0 | REPORT NUMBER 30 32 PRIME COMP. COMPONENT METHOD SUBMITTED NPRD-4 TAKEN FUTURE EFFEC (22) ON PLANT FORM SUB SUPPLIER HOURS MANUFACTURER A 25 Y 23 G | 0 | 8 10 E (18)Z Z Z N 1(24) (20) (19) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event is the result of the failure of the monitor's (2D11-K631) 1 0 filter paper drive motor. The filter paper's drive motor was replaced, and 1 1 the monitor was satisfactorily functionally tested per the "DRYWELL 1 2 FISSION PRODUCTS MONITORS OPERATION AND CALIBRATION" procedure (HNP-7408) 1 3 and returned to service on 08/09/83. (Refer to attached narrative) 4 80 METHOD OF FACILIT (30) DISCOVERY DESCRIPTION (32) OTHER STATUS % POWER 9 9 (29) B (31) NA Technician's Observation 01 5 (28 80 CONTENT ACTIVITY LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE Z 33 Z (34) NA NA 6 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 0 0 37 Z 38 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER NA 000 0 (40) 80 OSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION Z (42) NA. 8310040409 830927 PUBLICITY NRC USE ONLY PDR ADOCK 05000366 DESCRIPTION (45) PDR N (44) NA 69 68 (912)367-7851 S. B. TIPPS NAME OF PREPARER PHONE:.

NARRATIVE REPORT FOR LER 50-366/1983-052

LICENSEE : GEORGIA POWER COMPANY FACILITY NAME : EDWIN I. HATCH DOCKET NUMBER : 50-366

.....

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9 b, because it showed that the unit was not meeting the requirements of Tech. Specs. section 3.4.3.1.

Plant conditions at the time of the event(s):

The plant was in steady state operation at 2419 MWt (approximately 99% power) when this event occurred.

Detailed description of the event(s):

On O8/31/83, during performance of the daily "DRYWELL FISSION PRODUCTS MONITORS OPERATION AND CALIBRATION" procedure (HNP-7408), technicians determined that the drywell particulate fission products monitor's (2D11-K631) counts per minute indication continuously increased, and gave an alarm in the control room. Grab sampling showed that the monitor was at fault. The monitor was declared inoperable; thus, the plant could not meet the requirements of Tech. Specs. section 3.4.3.1.

Consequences of the event(s):

This event did not affect plant operations. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The grab sampling system was operable during this event.

Justification for continued operation:

A 30 day LCO was established and grab samples were taken every 4 hours as permitted by Tech. Specs. section 3.4.3.1, ACTION.

If repetitive, number of previous LER:

This event is non-repetitive.

Narrative Report for LER 50-366/1983-052 Page Two

Impact to other systems and/or Unit:

This event had no impact upon other systems in Unit 2, or on Unit 1.

Cause(s) of the event(s):

After an investigation, technicians determined that the monotor's filter paper was not advancing. This allowed the monitor's vacuum pump to deposit a concentration of radioactive particulates in a very small area on the monitor's filter paper which caused the monitor's sensor to give an alarm.

Immediate Corrective Action:

The monitor's filter paper drive motor was replaced, and the drywell particulate fission products monitor (2D11-K631) was satisfactorily functionally tested per the "DRYWELL FISSION PRODUCTS MONITORS OPERATION AND CALIBRATION" procedure (HNP-7408) and returned to service on 09/08/83.

Supplemental Corrective Action:

No supplemental action was required.

Scheduled (future) corrective action:

No future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

N/A

. . .

Georgia Power Company Post Office Box 439 Baxley', Georgia 31513 Telephone 912 367-7781 912 537-9444

٠

83 SEP 30 A 9: 17



Edwin I. Hatch Nuclear Plant

September 27, 1983 GM-83-942

FLANT E. I. HATCH Licensee Event Report Docket No. 50-366

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II Suite 3100 101 Marietta Street Atlanta, Georgia 30303

ATTENTION: Mr. Jumes P. O'Reilly

Attached is Licensee Event Report No. 50-366/1983-052. This report is required by Hatch Unit 2 Technical Specifications Section 6.9.1.9.b.

Frein

H. C. Nix General Manager

HCN/SBT/djs

XC:

R. J. Kelly

G. F. Head J. T. Beckham, Jr. P. D. Rice K. M. Gillespie S. B. Tipps R. D. Baker Control Room Document Control

DEFICIAL COPY!