

James W Cook Vice President - Projects, Engineering and Construction

84-01 #1

General Offices: 1945 West Parnall Road, Jackson, MI 49201 e (517) 788-0453

February 3, 1984

Mr J G Keppler, Regional Administrator US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER PROJECT DOCKET NOS 50-329 AND 50-330 EXCESSIVE VOLTAGE DROP -AUXILIARY FEEDWATER VALVE ACTUATORS FILE: 0.4.9.88 SERIAL: 28001



On January 6, 1984 Consumers Power Company notified your staff of a potential 10CFR50.55(e) condition involving excessive voltage drop in power cables supplying auxiliary feedwater system DC valve actuators.

This letter is an interim lOCFR50.55(e) report. The attachments to this letter describe the concern and summarize the investigation and corrective action taking place.

Another report, either interim or final, will be sent on or before April 13, 1984

James W. Cook

JWC/cd

Attachments: (1) MCAR-1, Report 80, Revision 1, dated January 23, 1984 (2) MCAR-80, Interim Report 1, Revision 1, dated January 31, 1984

CC: Document Control Desk, NRC Washington, DC

> RJCook, NRC Resident Inspector Midland Nuclear Plant

DSHood, USNRC Office of NRR

INPO Records Center



FEB 1 5 1984

TEJ

2 Serial 28001 84-01 #1

#### OM/OL SERVICE LIST

Mr Frank J Kelley Attorney General of the State of Michigan Ms Carole Steinberg, Esq Assistant Attorney General Environmental Protection Division 720 Law Building Lansing, MI 48913

Mr Myron M Cherry, Esq Suite 3700 Three First National Plaza Chicago, IL 60602

Mr Wendell H Marshall RFD 10 Midland, MI 48640

Mr Charles Bechhoefer, Esq
Atomic Safety & Licensing
Board Panel
U S Nuclear Regulatory Commission
Washington, DC 20555

Dr Frederick P Cowan 6152 N Verde Trail Apt B-125 Boca Raton, FL 33433

Mr Fred C Williams Isham, Lincoln & Beale 1120 Connecticut Ave, NW, Suite 325 Washington, DC 20036

Mr James E Brunner, Esq Consumers Power Company 212 West Michigan Avenue Jackson, MI 49201

Mr D F Judd Babcock & Wilcox PO Box 1260 Lynchburg, VA 24505

Mr Steve Gadler, Esq 2120 Carter Avenue St Paul, MN 55108

September 6, 1983 OC0184-0066A-MP01 Atomic Safety & Licensing Appeal Board U 3 Nuclear Regulatory Commission Washington, DC 20555

Mr C R Stephens (3) Chief, Docketing & Services U S Nuclear Regulatory Commission Office of the Secretary Washington, DC 20555

Ms Mary Sinclair 5711 Summerset Street Midland, MI 48640

Mr William D Paton, Esq Counsel for the NRC Staff U S Nuclear Regulatory Commission Washington, DC 20555

Atomic Safety & Licensing Board Panel U S Nuclear Regulatory Commission Washington, DC 20555

Ms Barbara Stamiris 5795 North River Road Rt 3 Freeland, MI 48623

Dr Jerry Harbour Atomic Safety & Licensing Board Panel U S Nuclear Regulatory Commission Washington, DC 20555

Mr M I Miller, Esq Isham, Lincoln & Beale Three First National Plaza 52nd Floor Chicago, IL 60602

Mr John DeMeester, Esq Dow Chemical Building Michigan Division Midland, MI 48640

Ms Lynne Bernabei Government Accountability Project 1901 Q Street, NW Washington, DC 20009

	50			Serie	1 2800
6	QUALIT	Y ASSURANCE PR	OGRAM	84-03	1 #1
	MANAGEMENT	CORRECTIVE A	CTION REPORT		
BECHTEL POWER		MCAR-1	REPORT NO.	80 Rev. 1	
JOB NO. 7220	Q NO.		DATE	1/23/84	
* DESCRIPTION (Inclu	ding references):				
The voltage drop reversing motors considered when now been calcula results indicate the allowable li (continued on pa • RECOMMENDED AC 1) Determine r action to p	o in the power consisting the cable sizing the cable ted [Calculation that voltage a mits for proper uge 2) TION (Optional)	ables for the a e page 2) is ac es for this app n QPE-18(Q) app t the associate operation. e design defici ce.	euxiliary feedwate tually greater to olication. The ve oroved December 2. ed motor operated	er system d han the val oltage drop 1, 1983], a valves is corrective	c ue has nd below
2) Determine t deficiencie	the extent of rests for all Class	view necessary 1E circuits.	to identify simi	lar voltage	drop
(continued on pa	ge 2)				
REFERRED TO	NGINEERING		QA MANAGEME	NT 🗆	
□ P *This deficiency as potentially r	ROCUREMENT was reported to eportable under	the NRC by the 10CFR 50.55(e)	ISSUED BY client Project QA on 1/6/84.	Engineer	1-23-84 Date
I REPORTABLE DEFICI	ENCY		NOTIFICIENT		Date
	10	* 🐼 YES	Project Manager	ses low	124/8 Date
				-/ (	1
III CAUSE					
III CAUSE	N TAKEN				
II CAUSE	N TAKEN	AUTHORIZED BY			Date
III CAUSE CORRECTIVE ACTIO	N TAKEN	AUTHORIZED BY	re		Date
II CAUSE CORRECTIVE ACTIO STANDARD DISTRIBUTION DIVISION QA MANAGER MANAGER OF QA - BPC GPD - QA MANAGER LAPD QA MANAGER SFPD QA MANAGER	ADDITIONAL DISTRIBU ENGINEERING MANAG PROJECT ENGINEER QE SUPERVISOR CONSTRUCTION MAN	AUTHORIZED BY	FORMAL REPOR (If Section II App	T TO CLIENT plies)	Date Date
II CAUSE CORRECTIVE ACTIO STANDARD DISTRIBUTION DIVISION QA MANAGER MANAGER OF QA - BPC GPD - QA MANAGER LAPD QA MANAGER SFPD QA MANAGER SFPD QA MANAGER PROJECT MANAGER CLIENT	ADDITIONAL DISTRIBU ADDITIONAL DISTRIBU ENGINEERING MANAG PROJECT ENGINEER QE SUPERVISOR CONSTRUCTION MAN PROJ SUPT/PROJ CO CHIEF CONSTR QC EN DIVISION PROCURENT PROJ I ROCUREMENT PROJ I ROCUREMENT	AUTHORIZED BY	FORMAL REPOR (If Section II App CORRECTIVE AC	T TO CLIENT olies)	Date Date
III CAUSE CORRECTIVE ACTIO STANDARD D'STRIBUTION DIVISION QA MANAGER MANAGER OF QA - BPC GPD - QA MANAGER LAPD QA MANAGER SFPD QA MANAGER SFPD QA MANAGER PROJECT MANAGER CLIENT	ADDITIONAL DISTRIBU ADDITIONAL DISTRIBU ENGINEERING MANAG PROJECT ENGINEER QE SUPERVISOR CONSTRUCTION MAN PROJ SUPT/PROJ CO CHIEF CONSTR QC EN DIVISION PROCURENT PROJ FROCUREMENT SUPPLIER QUAL	AUTHORIZED BY	FORMAL REPOR (If Section II Ap) CORRECTIVE AC	T TO CLIENT blies)	Date Date MENTED

MCAR 80, Rev. 1 Page 2

. . . .

### 140586

### DESCRIPTION continued:

The Class lE redundant safety dc valve actuator motors may fail to operate under anticipated plant conditions because of insufficient voltage. The net result could be loss of feedwater to the steam generators and the inability to safely cool down the reactor coolant system.

If this deficiency were to remain uncorrected, it could have adversely affected the safety of operations at the Midland plant.

Valve Number	Cable N Dist Pa Local S	umber nel To tation	Local Control Station Number (Starter)	Cable N Loc. Actuato	umber stion To Motor
1M03177A	1BD2114	A	1NM03177A	1BFW081	R.S.T.II
1M03177B	1BD2115	A	1NM03177B	1BFW082	R.S.T.U
2M03277A	2BD2114	A	2NM03277A	2BFW081	R.S.T.U
2M03277B	2BD2115	A	2NM03277B	2BFW082	R.S.T.U
1M03865A	1AD1114	A	1NM03865A	1AFW082	AG.H
1M03865B	1BD2116	A	1NM03865B	1BFW083	AG .H
2M03965A	2AD1114	A	2NM03965A	2AFW082	AG H
2M03965B	2BD2116	A	2NM03965B	2BFW083	AG,H
1M03831(ING05)	1BD2117	A	1C266	18FW088	AC AF
2M03931(2NG05)	2BD2117	A	2C266	2BFW088	AC,AF

NOTE: 1M03177A through 2M03965B (Dwg. E-158(Q)) are steam generator auxiliary feedwater isolation valves. 1M03831 and 2M03931 (Dwg. E-153(Q)) are auxiliary feedwater turbine 1/2C05 stop valves.

### **RECOMMENDED ACTION continued:**

- Perform a detailed review as determined from (2) above and document results.
- 4) Provide remedial corrective action for the discrepant cables listed herein and for any other deficiencies noted from investigative review; initiate NCRs and safety evaluations as required.
- 5) Issue first report, interim or final, by 1/20/84.

. . .

Bechtel Associates Professional Corporation

Attachment 2

Serial 28001 84-01 #1

SUBJECT: MCAR 80, Rev 1 (issued January 24, 1984) Auxiliary Feedwater DC Reversing Valve Actuator Excessive Power Cable Voltage Drop

INTERIM REPORT 1

DATE: January 31, 1984

PROJECT: Consumers Power Company Midland Plant Units 1 and 2 Sechtel Job 7220

### Introduction

This report provides the interim status and course of corrective action required pursuant to MCAR 80.

#### Description of Deficiency

The voltage drop in the power cables for the auxiliary feedwater system dc reversing valve actuator motors is greater than the value considered when the cables were sized. The voltage drop has now been calculated [Calculation QPE-18(Q), approved December 21, 1983], and the results indicate that voltage at the associated motor-operated valves is below the allowable limits for proper operation.

#### Probable Cause

Voltage drop resulting from the total circuit length between the starter and actuator motor was not considered in the design.

### Summary of Investigation and Historical Background

The investigation into the adequacy of dc reversing valve actuator circuits was initiated as a result of TPO Problem Alert 82-02, Revision 0 (DC Power Circuit Starters and Sizes of Cables for Motors and Valve Actuator Motors). The problem alert identified a voltage deficiency in these types of circuits at the Susquehanna Steam Electric Station, Units 1 and 2. During the investigation, 10 dc reversing valve actuators in the auxiliary feedwater system have been identified that will have voltage below the allowable limits for proper operation (see the attachment). Nonconformance Report (NCR) D-00007 has been written on the Midland project as a result of this investigation to identify and track the corrective action.

### Analysis of Safety Implications

The power cable voltage drop concerns associated with this MCAR have been analyzed for impact on the safety of operations at the Midland plant. If this deficiency were to remain uncorrected, it could have adversely affected the safety of operations at the Midland plant.

# 141453

1.8

Bechtel Associates Professional Corporation

MCAR 80 Interim Report 1

Page 2

### Corrective Action

The following corrective actions have been or will be initiated.

- A design calculation has been issued to provide the criteria for sizing power cables for dc reversing motor-operated valves (MOVs). All future designs including rework will use these criteria for cable sizing. All design personnel in the electrical group have been instructed regarding this requirement.
- A detailed review of Class 1E power and control circuits at the various plant voltage levels will be performed to confirm circuit adequacy with regard to voltage drop. The voltage levels to be reviewed are as follows:
  - a. Medium Voltage
    - 1) 4.16 kV feeds
    - 2) 4.16 kV motors
  - b. Low-Voltage Power
    - 1) 480 V load center feeds
    - 2) 460 V motor control center feeds
    - 3) Distribution panels feeds (120 V ac and 125 V dc)
    - 4) 120 V ac electrohydraulic valve actuators
  - c. Low-Voltage Control
    - 1) 120 V ac from motor control transformers
    - 2) 125 V dc control

As a result of this review, additional NCRs will be initiated to identify and track any nonconformances found, and appropriate process corrective action will be implemented to preclude recurrence. The scope and schedule for the review will be provided in the next report.

All Class 1E dc valve actuators have been reviewed [reference Calculation QPE-18(Q)]. There are no additional dc valve actuators other than the 10 identified in the MCAR.

# 141453

### **Bechtel Associates Professional Corporation**

MCAR 80 Interim Report 1

Page 3

3. To correct the insufficient voltage condition for the dc valve actuators, the power cables will be replaced with larger cables, and/or the starter will be relocated closer to the motors. This will reduce the voltage drop within acceptable limits as defined in Calculation QPE-18(Q). The forecast date for issuance of the design is March 16, 1984.

### Reportability

This deficiency was reported to the NRC by Consumers Power Company as potentially reportable on January 6, 1984.

Submitted by:

021 E.B. Poser Project Engineering Manager

Approved by

Castleberry

Electrical Chief Engineer

Smith

Engineering Manager

Concurrence by:

M.A. Dietrich Project Quality Assurance Engineer

Attachment: List of DC Valve Actuators with Excessive Voltage Drop

	141453	Cable Number	Local Control	Cable Number
8	Valve Number	Dist. Panel to Local Station	Station Number (Starter)	Local Station To Actuator Motor
	1M03177A	1BD2114A	1NM03177A	18FW081 R, S, T, U
	1M03177B	1BD2115A	1NM03177B	18FW082 R, S, T, U
	2M03277A	2BD2114A	2NM03277A	2BFW081 R, S, T, U
	2M03277B	2BD2115A	2NM03277B	28FW082 R, S, T, U
	1M03865A	1AD1114A	1NM03865A	1AFW082 AG, H
	1M03865B	1BD2116A	1NM03865B	1BFW083 AG, H
	2M03965A	2AD1114A	2NM03965A	2AFW082 AG, H
	2M03965B	2BD2116A	2NM03965B	2BFW083 AG, H
	1M03831 (1NG05)	1BD2117A	1C266	1BFW088 AC, AF
	2M03931 (2NG05)	2BD2117A	2C266	2BFW088 AC, AF

### LIST OF DC VALVE ACTUATORS WITH EXCESSIVE VOLTAGE DROP

NOTES :

., •

4146

.

ŝ.

10.

- 1M03177A-2M03965B [E-158(Q)] are steam generator auxiliary feedwater isolation valves.
- 1M03831-2M03931 [E-153(Q)] are auxiliary feedwater turbine 1/2G05 stop valves.