

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | N | P | I | N | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 2 | 7 | 0 | 8 | 3 | 0 | 8 | 3 | 8 | 0 | 9 | 2 | 7 | 8 | 3 | 9
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPRCT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During surveillance test, MV-32035, Cooling Water Header Isolation Valve B,
0 3 | failed to close. No effect on public health and safety since redundant equipment
0 4 | was operable. Tech 3.3.d.l.b. applies. Not repetitive.
0 5 | _____
0 6 | _____
0 7 | _____
0 8 | _____

0 9 | W | A | 11 | E | B | 13 | I | N | S | T | R | U | 14 | S | 15 | Z | 16 |
7 8 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP. SUBCODE 15 VALVE SUBCODE 16
17 | LER/RO REPORT NUMBER | 8 | 3 | 21 | 22 | 23 | SEQUENTIAL REPORT NO. | 0 | 2 | 1 | 24 | 25 | 26 | OCCURRENCE CODE | 0 | 3 | 27 | 28 | 29 | REPORT TYPE | L | 30 | 31 | REVISION NO. | 0 | 32 |
ACTION TAKEN | C | 18 | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 38 | 39 | ATTACHMENT SUBMITTED | N | 23 | 40 | 41 | NPRD-4 FORM SUB. | Y | 24 | 42 | PRIME COMP. SUPPLIER | A | 25 | 43 | COMPONENT MANUFACTURER | G | 0 | 8 | 0 | 44 | 45 | 46 | 47 | 48 | 49 | 50 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Failure of a General Electric auxiliary switch Part No. CR105X100P.
1 1 | Switch was replaced and valve tested satisfactorily.
1 2 | _____
1 3 | _____
1 4 | _____

1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance Test | 32
7 8 9 FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 14

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 ACTIVITY CONTENT 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY 12 LOCATION OF RELEASE 13

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 PERSONNEL EXPOSURES 10 NUMBER 11 TYPE 12 DESCRIPTION 13

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 PERSONNEL INJURIES 10 NUMBER 11 DESCRIPTION 12

1 9 | Z | 42 | NA | 43
7 8 9 LOSS OF OR DAMAGE TO FACILITY 10 TYPE 11 DESCRIPTION 12

2 0 | N | 44 | NA | 45
7 8 9 ISSUED DESCRIPTION 10 PUBLICITY 11

8310120102 830927
PDR ADDCK 05000282
S PDR

NRC USE ONLY

NAME OF PREPARER A. A. Hurstad

PHONE 612-388-1121



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

September 27, 1983


Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Failure of Cooling Water Header Isolation Valve

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(b) since it placed the plant in a degraded mode as permitted by the Limiting Conditions for Operation.


David Musolf
Manager - Nuclear Support Services

DMM/dab

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

Attachment

SEP 30 1983
FEJ 41