

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T 0 1 REPORT SOURCE L 6 0 5 0 0 0 0 3 1 5 7 0 8 2 9 8 3 8 0 9 2 8 8 3 9

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 DURING REFUELING OUTAGE, MODE 6, THE FIRE DOOR LEADING TO THE CONTRACTOR ACCESS

0 3 AREA WAS INADVERTANTLY DAMAGED WHEN THE DOOR WAS CLOSED WITH A PIECE OF STEEL

0 4 BETWEEN THE DOOR JAM AND THE EDGE OF THE DOOR. THE TWO BOTTOM HINGES BROKE. THE

0 5 DOOR HAD BEEN PROPPED OPEN FOR VENTILATION PURPOSES AND WAS UNDER CONTINUOUS FIRE

0 6 WATCH BY A SECURITY OFFICER. THE FIRE WATCH WAS CONTINUED UNTIL THE DOOR WAS

0 7 REPAIRED. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

0 8

0 9

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

A B 11 A 12 E 13 X X X X X X 14 Z 15 Z 16

17 LER/RO REPORT NUMBER 18 8 3 19 20 21 22 23 24 25 26 27 28 29 30 31 32

EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 40 NPD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44

3 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 Z 25 X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 THE INDIVIDUALS INVOLVED DID NOT NOTICE THE DOOR BLOCK. THEY WERE ADMONISHED TO

1 1 USE GREATER CAUTION. THE DOOR WAS IMMEDIATELY REPAIRED AND RETURNED TO OPERABLE

1 2 STATUS.

1 3

1 4

1 5

FACILITY STATUS 28 % POWER 29 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32

H 28 0 0 0 29 N/A 30 B 31 SECURITY OFFICER OBSERVATION 32

ACTIVITY CONTENT 33 RELEASED OF RELEASE 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 6 Z 33 Z 34 N/A 35 N/A 36

PERSONNEL EXPOSURES 37 NUMBER 38 TYPE 39 DESCRIPTION 39

0 0 0 37 Z 38 N/A 39

PERSONNEL INJURIES 40 NUMBER 41 DESCRIPTION 41

0 0 0 40 N/A 41

LOSS OF OR DAMAGE TO FACILITY 42 TYPE 43 DESCRIPTION 43

Z 42 N/A 43

PUBLICITY 44 ISSUED 45 DESCRIPTION 45

N 44 N/A 45

8310120260 830928  
PDR ADOCK 05000315  
S PDR

NRC USE ONLY

NAME OF PREPARER D.K. Welcher

PHONE (616) 465-5901

000 917.226



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

September 28, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report is submitted:

RO 83-091/03L-0

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/clm

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee  
INFO  
PISRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

SEP 30 1983

IE2211