LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1 7 8	M I D C C 2 2 0 0 0 0 0 0 0 0
O 1 7 8	SOURCE L 6 0 5 0 0 0 3 1 6 0 0 9 0 2 8 3 8 0 9 2 8 8 3 9
0 2	DIRING START-UP WITH THE REACTOR AT 20% POWER, THE TURBINE GENERATOR WAS PARALLELED
0 3	WITH THE SYSTEM GRID. IMMEDIATELY AFTER PARALLEL GENERATOR LOAD WAS INCREASED TO
0 4	PREVENT MOTORING. THIS INITIAL LOAD INCREASE CAUSED TAVG TO DROP WHICH RESULTED IN
0 5	A PRESSURIZER PRESSURE DROP TO 2215 PSIA WHICH IS 5 PSI BELOW THE 2220 PSIA MINIMUM
0 6	PRESSURE REQUIRED BY TECH SPEC 3.2.5.b, TABLE 3.2-1. THE PRESSURE WAS BELOW 2220
0 7	PSIA FOR ONE MINUTE. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. SIMILAR
0 8	OCCURRENCES INCLUDE 50-316/78-72, 78-97, 80-001 AND 81-188.
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	LER/RO EVENT YEAR REPORT NO. 17 REPORT 8 3 22 23 24 26 27 28 29 30 31 1 0 32 ACTION FUTURE COMPLANT METHOD HOURS (22) ATTACKMENT FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER 2 9 9 9 9 9 9 9 9 9
10	THE PRESSURE TRANSIENT WAS WORSENED DUE TO PROBLEMS WITH THE PRESSURIZER HEATER
111	BREAKERS TRIPPING. A DESIGN CHANGE HAS BEEN PROCESSED TO INSTALL HEAVIER DUTY
1 2	PRESSURIZER HEATER BREAKERS. THE AVAILABILITY OF MORE PRESSURIZER HEATERS WILL AID
13	THE OPERATOR IN MAINTAINING PRESSURIZER PRESSURE DURING START-UP.
1 4	9 80
1 5	
1 6 R	CTIVITY CONTENT SLEASED OF RELEASE AMOUNT OF ACTIVITY 35 LZ 33 Z 34 NA
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
1 8	9 PERSONNEL INJURIES 13 80 NA 9 11 12 13 NA 8310120448 830928 80 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA S NA S
2 0	PUBLICITY SSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA
/ 8	NAME OF PREPARER C. E. MURPHY PHONE (616) 465-5901