

ATTACHMENT 2

8310170107 831005
PDR ADOCK 05000338
S PDR

TRANSFORMER REPORT
ON
EVENTS AT NORTH ANNA POWER STATION

June 16, 1983

POWER TRANSFORMER DIVISION
WESTINGHOUSE ELECTRIC CORPORATION
GREENTREE, PA 15220

PRINCIPAL REPORTERS

J. Cossaart
E. Petrie
J. Skooglund
A. Sletten
J. Templeton
L. Wagner
D. Yannucci

TABLE OF CONTENTS

		<u>Page No.</u>
I.	Scope	1
II.	Executive Summary	2
III.	Introduction	10
IV.	Conclusions	17
V.	Correlation Analysis	25
VI.	Summary of Areas of Investigation	32
VII.	System Investigation	33
VIII.	Transformer Processing Record Review	39
IX.	Gas Evolution Causes	42
X.	Oil Electrification Effect	53
XI.	Dielectric Analysis of Line Lead Configuration	58
XII.	Impulse Distribution and Resonant Frequency Analysis	70
XIII.	Sensitivity Tests of P.D. Waveguide System	73

APPENDICES

Appendix A:	Trip Reports	75
Appendix B:	Transformer Report on Events	88
Appendix C:	Processing Records	169
Appendix D:	Calculation of Tank Vacuum	214
Appendix E:	Oil Characteristics and Gas Analysis of Serial 7001965 and C-O-6459-5-1	231
Appendix F:	Gas-In-Oil Analysis Results	236
Appendix G:	Trip Report on Hydraulic Experiments in HAM 707	266
Appendix H:	Blue Ribbon Committee Organization	269
Appendix I:	Transformer Evaluation Committee Organization	271

I. SCOPE

This report covers the investigation of the transformer events at VEPCO's North Anna power station from November of 1980 through March of 1983. The report is applicable to shor order HAM707 on which 7 units were manufactured.

Included are dielectric, fluid flow, gas evolution and processing considerations relating to the transformer. Also included is a system analysis relating to the event occurring on December 5, 1982.

II. EXECUTIVE SUMMARY

Seven transformer failures occurred at VEPCO's North Anna power station from November of 1980 to December of 1982. This report covers the investigation of these failures.

None of the failures could be reproduced in the laboratory, thus no definitive conclusions can be reached as to the exact cause of any of the failures.

The following statements can be made on each failure:

FAILURE #1: NORTH ANNA #2 - HV LEAD TO LV COIL
(2099)

Rebuilt ship: 1/77
Processed last: 2/79
Failed at N.A.: 11/80
Phase 'A'

- . Additional transportation involved prior to rebuild.
- . Unit involved in failure at Bowen and rebuilt at Muncie.
- . No factory test difficulties on original or rebuilt unit.
- . Unit did have overexcitation.
- . Processing of main unit was done for a considerable length of time before the failure.
- . Mis-operation of inertiaire system did occur.
- . Gas bubbles do occur in the oil under this condition.
- . Dielectric strength degradation of lead configuration due to gas bubbles in the oil does occur.
- . Simulated lead configuration withstood 400 kV for 48 hours with and without bubbles present -- corona was observed for large bubbles.
- . No other source of bubbles found.

FAILURE #2: NORTH ANNA #2 - HV BUSHING
(2100)

Original ship: 2/74
Processed last: 2/79
Failed at N.A.: 6/81
Phase 'C'

- . No factory test problems.
- . Additional transportation was involved.
- . In bank at Georgia Power when 2099 failure occurred.
- . Unit overexcited.
- . In bank when 2099 failure occurred at N.A.
- . Failure involved bushing only.
- . Processing was done a considerable length of time before failure.
- . HV bushing was not stored properly.

FAILURE #3: NORTH ANNA #2 - HV BUSHING, LV COIL AND TANK
(2098)

Original ship: 2/74
Processed last: 6/81
(Energized)
Failed at N.A.: 7/81
Phase 'B'

- . No factory test difficulties
- . In bank at Georgia Power when 2099 failure occurred.
- . Additional transportation was involved.
- . Unit processed one month prior to failure.
- . In bank when 2100 and 2099 failures occurred.
- . Lead configuration changed 6/81.
- . HV bushing was not stored properly.

FAILURE #4: NORTH ANNA #2 - G.P. UNIT - HV LINE COIL, LV COIL, TANK
(1527)

Original ship: 5/70
Processed last: 6/81
Energized: 7/81
Failed at N.A.: 7/81
Phase 'C'

- . No factory test difficulties.
- . In bank when two other transformer failures occurred at G.P.
- . Dielectrically tested above rated design level at Muncie plant.
- . In bank when 2098 difficulty occurred.
- . Failed immediately after energizing subsequent to 2098 failure at N.A.
- . Large quantities of carbon observed during failure observations.

FAILURE #5: NORTH ANNA #2 - HV BUSHING, CORONA SHIELD AND LV WINDING AND TANK
(2100 Repaired at Muncie)

Rebuilt ship: 10/81
Processed last: 3/82
Energized: 3/82
Failed at N.A.: 8/82
Phase 'B'

- . Bushing transportation.
- . At Muncie, lead configuration changed to present practice during rebuild.
- . No factory test difficulties.
- . Processed five months prior to failure -- factory tested bushing installed 1/82 -- unit was final processed 3/82 -- energized at intervals for five months.
- . Mechanically fatigued bolt in bushing assembly found -- failure location in bushing correlates with physical evidence of bolt and washers.
- . Possible physical evidence of oil electrification in coil assembly.

FAILURE #6: NORTH ANNA #1 - HV BUSHING SHIELD AND LV COIL
(1995)

Original ship: 8/73
Processed last: 8/82
Energized: 11/82
Failed at N.A.: 11/82
Phase 'C'

- . No factory test difficulties.
- . In service since 1978 without difficulty.
- . System configuration changed with addition of generator breaker prior to problem.
- . Pumps removed and refurbished.
- . Processed prior to difficulty.
- . Ambient temperature change of 30°C noted two days prior to energizing.
- . Cooler initiation and operation in accordance with task force report (coolers not operated prior to energization.)
- . To date, gas bubbles have not been produced from the lead or oil in laboratory experiments except under vacuum.
- . Bushing/lead configuration simulation withstood 400 kV for 48 hours with and without bubbles -- corona observed for large bubbles.

FAILURE #7: NORTH ANNA #1 - HV LEAD, LV COIL, TURN-TO-TURN FAILURE
(1994)

Original ship: 7/73
Processed last: 12/82
Energized: 12/82
Failed at N.A.: 12/82
Phase 'B'

- . No factory test difficulties.
- . In service since 1978 without difficulty.
- . System configuration changed with addition of generator breaker prior to problem.
- . Pumps removed and refurbished due to metallic contamination, unit flushed.
- . In bank during 1995 failure.
- . Retrofitted with COPS.
- . Removed barrel barrier,
- . Partial discharge field test with waveguides installed.
- . Pumps run prior to energization per instructions.
- . To date, gas bubbles have not been produced from lead experiment except under vacuum.
- . Bushing/lead configuration simulation withstood 400 kV for 48 hours with and without bubbles -- corona observed for large bubbles.
- . To date, lab tests have not produced high turn-to-turn stresses in area of turn-turn failure observed for a high-low failure mode.

III. INTRODUCTION

Seven single phase generator step up transformers were manufactured and delivered to Virginia Electric Power Company in 1973 and 1974 for operation at the North Anna station. These are identified as S.O. HAM707. The units are rated 330 MVA with a 55°C rise and 369.6 MVA with a 65°C rise. The high voltage winding is 1300 kV BIL on the line end and 150 kV BIL at the neutral. The low voltage is 150 kV BIL. The nominal voltage is 500000 grd. Y/288675 to 22000 volts. There are de-energized taps at 303110, 295890, 281460 and 274240 volts. The cooling system is "FOA" and the oil preservation system is "inertaire" designed to operate between 0.5 and 8.0 psi pressure.

In addition there was involved a spare transformer that Virginia Electric Power Company borrowed from the Georgia Power Company. It is identified as S.O. HAM390. It is a single phase 277 MVA, 500000 grd. Y/288675 to 23800 volts.

The history of each of these units is detailed as follows:

Serial 7001965 S.O. HAM707

1. Tested originally 7/20/73.
 2. Operated commercially.
 3. Installed waveguide and "COPS" system - 11/82.
 4. Removed barrel barriers from H.V. bushing and made general internal inspection -- 11/22/82. See J. B. Templeton's trip report of 12/15/82. (1)
 5. Field corona tests by VEPCO -- 11/30/82 to 12/3/82. See W. J. Carter's trip report of 12/16/82. (2)
- (1) Appendix A - Item 1
(2) Appendix A - Item 2

Serial 7001993 S.O. HAM707

1. Tested originally 7/24/73.
2. Originally the spare for the North Anna Station.
3. Put in place of serial 7002099 which failed on 11/29/80.
4. 500 kV lead changed from wire of coil and brush copper section to cable -- June, 1981. (Muncie Personnel)
5. 500 kV lead rechecked for quality -- July, 1981. (Muncie Personnel).
6. 500 kV bushing removed and replaced with bushing from serial 7002099. Bushing from serial 7002099 tested 7/11/81 in Muncie and returned to VEPCO.
7. Pumps replaced -- July, 1981. New pumps were sent from Muncie. The replaced pumps returned to Muncie were dismantled and two indicated signs of bearing wear.
8. Unit flushed to remove bearing particles -- July, 1981.
9. VEPCO accident -- water introduced inside unit.
10. Unit put on dry out process 7/19/81.
11. Waveguide installed 8/26/82.

Serial 7001994 S.O. HAM707

1. Tested originally 7/26/73.
2. Operated commercially.
3. Installed "COPS" system - 11/82.
4. Removed barrel barriers from H.V. bushing and made general internal inspection -- 11/22/82. See J. B. Templeton's trip report of 12/15/82. (3)
5. Field corona tests by VEPCO -- 11/30/82 to 12/3/82. See W. J. Carter's trip report of 12/16/82. (4)
6. Failed 12/5/82. See W. J. Carter's and D. White's teardown report of 1/10/83. (5)

Serial 7001995 S.O. HAM707

1. Originally tested 8/3/79.
2. Operated commercially starting in 1974 in North Anna #1.
3. De-energized May 1982.
4. Oil drained and refilled with new oil August 1982.
5. Failed 11/16/82 after three hours and six minute after energizing. See H. R. Moore's report of 12/3/82. (6)

- (3) Appendix A - Item 1
- (4) Appendix A - Item 2
- (5) Appendix B - Item 1
- (6) Appendix B - Item 2

Serial 7002098 S.O. HAM707

1. Tested originally 2/20/74.
2. Stored at VEPCO.
3. Loaned to Georgia Power Company for operation at Plant Bowen -- May, 1976.
4. Returned to Muncie on S.O. XDML324 for retest -- tested 9/2/76.
5. Reshipped to VEPCO.
6. Overexcitation reported (140.9% for 42 seconds) -- 2/6/79.
7. 500 kV lead changed from wire of coil and brush copper section to cable -- June, 1982. (Muncie Personnel)
8. Failed while in service at North Anna Station -- 7/3/81.
9. Remains of 500 kV bushing returned to Muncie. See bushing report, serial 6, of 8/3/81 by L. B. Wagenaar. (7)
10. Pumps returned to Muncie.
11. Scrapped in the field - 9/81.

(7) Appendix B - Item 8

Serial 7002099 S.O. HAM707

1. Tested originally 2/22/74.
2. Stored at VEPCO.
3. Loaned to Georgia Power for operation at Plant Bowen -- May, 1976.
4. Failed while in service at Plant Bowen -- May, 1976. See Engineering Lab Report #41-5F by Puri/Hansen - 7/30/76. (8)
5. Returned to Muncie for repair on S.O. XDM1323.
6. XDM1323 tested on 1/31/77.
7. Reshipped to VEPCO.
8. Missing hardware problem. Conclusion it was never shipped. See I. L. Hansen's trip report of 3/24/77. (9)
9. Overexcitation reported (140.9% for 42 seconds) -- 2/6/79.
10. Failed while in service at North Anna Station -- 11/29/80. See trip report by B. W. Hugon of 12/17/80 (10) and disassembly report by L. E. Luke of 6/5/81 (11).
11. Repaired on S.O. XDM1742.
12. Retested on 7/24/81 and reshipped to VEPCO.
13. Waveguide installed - 8/26/82.

- (8) Appendix B - Item 3
- (9) Appendix A - Item 3
- (10) Appendix B - Item 4
- (11) Appendix B - Item 5

Serial 7002100 S.O. HAM707

1. Tested originally on 3/4/74.
 2. Stored at VEPCO.
 3. Loaned to Georgia Power Company for operation at Plant Bowen -- May, 1976.
 4. Returned to Muncie on S.O. XDM1324 for retest -- tested 9/23/76.
 5. Reshipped to VEPCO.
 6. Overexcitation reported (140.9% for 42 seconds) -- 2/6/79.
 7. Failed while in service at North Anna Station -- 6/19/81. See disassembly report of 10/13/81 by B. W. Hugon. (12)
 8. Remains of 500 kV bushing returned to Muncie. See bushing report, serial 7, of 8/3/81 by L. B. Wagenaar. (13)
 9. Pumps returned to Muncie.
 10. Repair order -- XDM1779. Rebuilt with new phase. Tested 10/21/81.
 11. Failed while in service at North Anna Station - 8/22/82. See R&D report 82-7D7-MUNCI-R1, 10/6/82. (14)
 12. Repair order - XDM1867. See teardown report of 2/23/83 by Dale White. (15)
- (12) Appendix B - Item 6
(13) Appendix B - Item 9
(14) Appendix B - Item 10
(15) Appendix B - Item 7

Serial 7001527 S.O. HAM390

1. Tested originally 5/21/70.
2. Operated at Georgia Power Company, Bowen Plant.
3. Removed from service after failure of serials 7001526 and 7001528 -- March, 1976.
4. Returned to Muncie for tests on S.O. XDM1316.
5. Dielectric tests made at 1175, 1300, 1425, 1550 kV BIL.
6. Returned to Georgia Power Company, Bowen Plant, as a spare.
7. Shipped to VEPCO to replace Serial 7002100 -- June, 1981.
8. Failed at VEPCO North Anna Station -- 7/25/81.
9. Unit disassembled in the field and scrapped - 8/81.

A summary of the failure points for each of the incidents is as follows:

FAILURE POINTS

<u>Serial</u>	<u>Shipped</u>	<u>Failed</u>	<u>HV Bushing</u>	<u>HV Corona Shield</u>	<u>HV Lead</u>	<u>HV Line Coils</u>	<u>HV Series Conn.</u>	<u>To LV Wdg.</u>	<u>LV Wdg.</u>	<u>Tank</u>
7002099	1/77	11/80			X			X		
7002100	2/74	6/81	X							
7002098	2/74	7/81	X					X		X
7001527	5/70	7/81				X		X		X
7002100	10/81	8/82	X	X				X		X
7001995	8/73	11/82		X				X		
7001994	7/73	12/82			X			X	X	.
7001993	7/73	---								
7001965	7/73	---								

IV. CONCLUSIONS

The investigation has not been able to simulate or duplicate the failure mechanism observed at the North Anna power station.

In general, the dielectric studies have indicated the following:

1. For large gas bubbles at high velocity oil flow rates, partial discharge was experienced but no flashovers occurred.
2. The high voltage line lead configuration was stressed at 400 kV to ground for a time equivalent to 5.7 years service at nominal operating voltage. This time equivalent is based on a volt-time probability function.
3. The effect of an improper taper joint in the taping of the high voltage line lead did not significantly affect the partial discharge levels.
4. This combination of gas bubbles in the oil system and induced static electrification of the oil did increase the partial discharge levels but no flashovers occurred.
5. No evidence of problems with winding resonance effects could be determined.
6. No evidence of high transient voltage effects could be determined.
7. Gas trapped in taped insulated leads did not evolve into the oil as bubbles unless a negative pressure occurred above the oil.
8. No apparent system related problems have been determined.

A summary of each individual transformer is as follows:

FAILURE #1: NORTH ANNA #2 - HV LEAD TO LV COIL
(2099)

Rebuilt ship: 1/77
Processed last: 2/79
Failed at N.A.: 11/80
Phase 'A'

- . Additional transportation involved prior to rebuild.
- . Unit involved in failure at Bowen and rebuilt at Muncie.
- . No factory test difficulties on original or rebuilt unit.
- . Unit did have overexcitation.
- . Processing of main unit was done for a considerable length of time before the failure.
- . Mis-operation of inertiaire system did occur.
- . Gas bubbles do occur in the oil under this condition.
- . Dielectric strength degradation of lead configuration due to gas bubbles in the oil does occur.
- . Simulated lead configuration withstood 400 kV for 48 hours with and without bubbles present -- corona was observed for large bubbles.
- . No other source of bubbles found.

FAILURE #2: NORTH ANNA #2 - HV BUSHING
(2100)

Original ship: 2/74
Processed last: 2/79
Failed at N.A.: 6/81
Phase 'C'

- . No factory test problems.
- . Additional transportation was involved.
- . In bank at Georgia Power when 2099 failure occurred.
- . Unit overexcited.
- . In bank when 2099 failure occurred at N.A.
- . Failure involved bushing only.
- . Processing was done a considerable length of time before failure.
- . HV bushing was not stored properly.

FAILURE #3: NORTH ANNA #2 - HV BUSHING, LV COIL AND TANK
(2098)

Original ship: 2/74
Processed last: 6/81
(Energized)
Failed at N.A.: 7/81
Phase 'B'

- . No factory test difficulties
- . In bank at Georgia Power when 2099 failure occurred.
- . Additional transportation was involved.
- . Unit processed one month prior to failure.
- . In bank when 2100 and 2099 failures occurred.
- . Lead configuration changed 6/81.
- . HV bushing was not stored properly.

FAILURE #4: NORTH ANNA #2 - G.P. UNIT - HV LINE COIL, LV COIL, TANK
(1527)

Original ship: 5/70
Processed last: 6/81
Energized: 7/81
Failed at N.A.: 7/81
Phase 'C'

- . No factory test difficulties.
- . In bank when two other transformer failures occurred at G.P.
- . Dielectrically tested above rated design level at Muncie plant.
- . In bank when 2098 difficulty occurred.
- . Failed immediately after energizing subsequent to 2098 failure at N.A.
- . Large quantities of carbon observed during failure observations.

FAILURE #5: NORTH ANNA #2 - HV BUSHING, CORONA SHIELD AND LV WINDING AND TANK
(2100 Repaired at Muncie)

Rebuilt ship: 10/81
Processed last: 3/82
Energized: 3/82
Failed at N.A.: 8/82
Phase 'B'

- . Bushing transportation.
- . At Muncie, lead configuration changed to present practice during rebuild.
- . No factory test difficulties.
- . Processed five months prior to failure -- factory tested bushing installed 1/82 -- unit was final processed 3/82 -- energized at intervals for five months.
- . Mechanically fatigued bolt in bushing assembly found -- failure location in bushing correlates with physical evidence of bolt and washers.
- . Possible physical evidence of oil electrification in coil assembly.

FAILURE #6: NORTH ANNA #1 - HV BUSHING SHIELD AND LV COIL
(1995)

Original ship: 8/73
Processed last: 8/82
Energized: 11/82
Failed at N.A.: 11/82
Phase 'C'

- . No factory test difficulties.
- . In service since 1978 without difficulty.
- . System configuration changed with addition of generator breaker prior to problem.
- . Pumps removed and refurbished.
- . Processed prior to difficulty.
- . Ambient temperature change of 30°C noted two days prior to energizing.
- . Cooler initiation and operation in accordance with task force report (coolers not operated prior to energization.)
- . To date, gas bubbles have not been produced from the lead or oil in laboratory experiments except under vacuum.
- . Bushing/lead configuration simulation withstood 400 kV for 48 hours with and without bubbles -- corona observed for large bubbles.

FAILURE #7: NORTH ANNA #1 - HV LEAD, LV COIL, TURN-TO-TURN FAILURE
(1994)

Original ship: 7/73
Processed last: 12/82
Energized: 12/82
Failed at N.A.: 12/82
Phase 'B'

- . No factory test difficulties.
- . In service since 1978 without difficulty.
- . System configuration changed with addition of generator breaker prior to problem.
- . Pumps removed and refurbished due to metallic contamination, unit flushed.
- . In bank during 1995 failure.
- . Retrofitted with COPS.
- . Removed barrel barrier,
- . Partial discharge field test with waveguides installed.
- . Pumps run prior to energization per instructions.
- . To date, gas bubbles have not been produced from lead experiment except under vacuum.
- . Bushing/lead configuration simulation withstood 400 kV for 48 hours with and without bubbles -- corona observed for large bubbles.
- . To date, lab tests have not produced high turn-to-turn stresses in area of turn-turn failure observed for a high-low failure mode.

V. CORRELATION STUDIES

A multidimensional correlation study has been performed on all 500 kV generator step up transformers (GSU) manufactured by Westinghouse and subsequently put into service. The categories selected for the cross correlation are as follows:

- 1) Customer (VEPCO and Others)
- 2) Winding BIL (1300 kV, 1450 kV+)
- 3) Internal work (performed on site) (Yes, No)
- 4) Previous involvement (in a bank during failure) (Yes, No)
- 5) Bushing BIL (1300 kV, 1450 kV+)
- 6) High voltage lead (horizontal, vertical)

Each of the above six categories are subdivided into two classes as indicated, thus creating $2^6 = 64$ cells. One of the two classes in each category is perceived to have possible adverse effects on the failure rate.


(Notes: Three phase transformers are counted as three transformers since each phase has had a chance to fail. Failure of a three phase transformer is counted as one failure. A rebuilt transformer is counted as a new transformer. Internal work is defined as the situation when a transformer is drained and actual physical work is performed inside before reprocessing and reenergization. Initial installation and filling of the transformer on site is not counted as Internal work. The remaining counting rules are self-explanatory).

160 transformers (500 kV GSU) have been manufactured and put into service and of these 16 have failed. The failure rate is therefore 0.1 or 10% of the population. Each of these 160 transformers was classified into one of the 64 cells. Table I shows the number of transformers in the upper left corner and the number of failed transformers in the lower right hand corner. As had been anticipated only a small portion of the cells, actually 11, contain any transformers. These 11 cells are listed in Table II in descending order of the number of transformers in each cell.

Data analysis was carried out on these 11 cells as shown in Table III. Each cell is divided into success and failure. Expected success (90%) and failure (10%) is calculated and the contribution to the X^2 value for each cell calculated.

$$X^2 = \sum_i \sum_j \frac{(O_{ij} - E_{ij})^2}{E_{ij}}$$

where O_{ij} are observed and E_{ij} are expected values. (i designates the column and j the row in Table III).



By definition the degrees of freedom is:

$$D = (i-1)(j-1)$$

which in this case is 11. X^2 is used as a measure of the deviation from a random distribution. If the failures were truly randomly distributed there would be only a 1% chance to obtain X^2 greater than 24.7. The actual calculated value is 83.3. Therefore the probability of the failures coming from a purely random distribution is extremely small. Cell 7 contributes 45 to the X^2 value, but even if cell 7 is disregarded, the value of X^2 is still higher than expected from a random distribution.

If next the elimination of any one of the chosen six categories is considered, cell 7 stays intact in all cases. This can easily be seen by noting that cell 7 in Table I has no non-empty cell in the vertical or horizontal direction. Cell 7 has the combination of all the perceived adverse effects on the failure rate from all the six categories.

Cells 8 to 11 contain only two or one transformers and are therefore statistically not very meaningful. They were therefore next combined into two cells based on whether the transformer has a horizontal or vertical high voltage lead. The first seven cells were kept intact. Table IV shows the result of a similar analysis to that in Table III. Cell 8^x in Table IV is the combination of the original cells 8 and 11, while cell 9^x is the combination of the original cells 8 and 11, while cell 9^x is the combination of the original cells 9 and 10 which also results in losing the category of Customer (VEPCO, Others) in cell 9^x. Cell 9^x now contributes 18 to the X^2 value while cell 8^x is relatively benign.

Similar results are obtained with two other approaches dealing with cells 8 to 11, if cells 8 to 11 are lumped into one new cell or lumped into two new cells based on whether the customer was VEPCO or not. In both these cases one new cell has a substantial contribution to X^2 indicating that cell 7 is not the only contributor to the lack of random behavior of the failure rate.

Eliminating any two of the original categories, similar results are obtained. That is, there remains at least two cells contributing significantly to X^2 . Eliminating three of the categories, cell 7 stays intact with its 100% failure rate in most of the possible combinations of the remaining three perceived adverse effects on the failure rate. One particular case gives an interesting result and is described below:

Of the five non-empty cells, cells A and D contain only VEPCO transformers except on ein cell D. Only cell D has a failure rate which deviates significantly from the average failure rate. Cell A and D are comparable in size and both have a low winding BIL. Cell D contains nearly half the failed transformers. However, cell 7 stays intact with its 100% failure rate if the categories of Previous involvement, Customer and Internal work are the three categories retained. Those are the categories eliminated in cell D. Another example resulting in a cell with 100% failure rate, actually six failures out of six transformers, occurs when the categories of Customer, Bushing BIL and Winding BIL are retained, in which cells 7 and 10 combine. Conversely, if the categories Internal work, Previous involvement and H.V. lead are retained, cell 7 stays intact.

The eliminations of categories described above demonstrates the lack of data for comparison in the available data base. No particular combination of the perceived adverse effects appears to be significantly worse or better than any other combination because cell 7 has such a small amount of neighboring data (Table I).

Discussion

The results of this analysis indicate that there is a significant deviation from random behavior of the failure rate with a strong correlation to a combination of perceived adverse effects on the failure rate. Yet no single one of the perceived adverse effects is needed to show the strong deviation from a truly random failure rate.

It is speculated that a physical reason or reasons for many of the failures have occurred in correlation with many of the perceived adverse effects, but these physical reasons are not known or associated with any particular combination of the initially perceived adverse effects. The extreme deviation from random behavior of the combination of all the perceived adverse effects (cell 7) suggests that one or more unknown adverse physical conditions might have been associated with that group. However, such physical conditions may or may not be associated with any or all the perceived adverse effects on the failure rate.

2

TABLE I

TABLE II

TABLE III

Cell No.	1	2	3	4	5	6	7	8	9	10	11	
Success	80.1 88	29.7 30	8.1 8	7.2 6	5.4 6	4.5 4	4.5 0	1.8 2	0.9 0	0.9 0	0.9 0	144 144
Failure	8.9 1	3.3 3	0.9 1	0.8 2	0.6 0	0.5 1	0.5 5	0.2 0	0.1 1	0.1 1	0.1 1	16 16
No. of Transformers	89	33	9	8	6	5	5	2	1	1	1	160
$\Delta\chi^2$	7.8	0.03	.012	2.0	0.67	0.56	45	0.22	9	9	9	$\chi^2_{.83.3}$

TABLE IV

Cell No.	1	2	3	4	5	6	7	Vert. 8*	Horiz. 9*	Total
Success	80.1 88	29.7 30	8.1 8	7.2 6	5.4 6	4.5 4	4.5 0	2.7 2	1.8 0	144
Failed	8.9 1	3.3 3	0.9 1	0.8 2	0.6 0	0.5 1	0.5 5	0.3 1	0.2 2	16
	89	33	9	8	6	5	5	3	2	160
χ^2 Value	7.8	.03	.012	2.0	0.67	0.56	45.0	1.8	18.0	$\chi^2_{.76.0}$

VI. AREAS OF INVESTIGATION

Subsequent to the seventh failure of the Westinghouse transformers at the VEPCO North Anna power generating station a comprehensive program was initiated to study various aspects of the situation. The Westinghouse study included investigations into the transformers as well as the power system into which it was integrated.

The power system study was conducted by reviewing the data accumulated from the recording devices on the system and through analytical calculations. Calculations of voltages and currents for various scenarios of operation were completed and concentrated on the generator side of the transformer.

Along with the power system study, several investigations were made concurrently concentrating on the internal operation of the transformer. A study of the transformer hydraulic circuit consisted of a review of field processing records, a hydraulic flow analysis, analysis of gas and moisture content in oil samples, and a gas in oil equilibrium analysis. In support of the previous tests, various electrical tests were performed with a high voltage lead configuration as existed in the North Anna transformers. The purpose of the electrical tests was to determine if the insulation integrity degraded as the temperature and pressure changes of the oil produced an equilibrium change in the dissolved gases in the oil thus producing bubbles. Additionally, experiments were performed to determine any electrical effects from static electrification of the oil on the integrity of the high voltage lead insulation.

One of the failures identified in the seventh incident was a turn-to-turn fault in coil 1 of the low voltage winding. In order to determine the sequence as to when the fault occurred, a low voltage impulse distribution test was done to simulate a high voltage to low voltage arc with measurements to quantify the subsequent turn-to-turn stresses. Also, a review was made of the resonant frequency response of the transformer to determine if a low voltage bus duct flashover could result in transient voltages in the high voltage winding.

The transformer involved in the seventh incident had been equipped with an acoustical waveguide inside the transformer to detect incipient electrical problems during the operation of the transformer. A test was performed to determine if the waveguide would have had sufficient sensitivity to detect the turn-to-turn fault in the low voltage if the fault existed prior to the failure of the transformer.

In reviewing the seven incidents at North Anna relative to the field experience of other 500 kV units, the need was identified to conduct a statistical analysis of 500 kV transformers. Thus, a statistical correlation analysis involving multiple variables was completed.

The analysis of the North Anna incidents has entailed a comprehensive investigation. The details of the various studies are included in this report.

VII. SYSTEM INVESTIGATIONS FOR VEPCO NORTH ANNA
TRANSFORMER - GENERATOR FAILURE OF DECEMBER 5, 1982

This report summarizes the results of the system investigations made by T&DSE to determine the possible causes of the VEPCO North Anna transformer and generator failures on December 5, 1983.

Analysis of Oscillograms and Events Records

The oscillograms for the December 5 failure as well as those from the previous August and November failures were examined. The only quantities measured were those from the 500 kV side of the step-up transformer with no generator or low-side quantities monitored. From this limited data nothing unusual could be determined. No external system disturbance was apparent that could have caused the failure.

The handwritten and typed notes on the sequence of events prior to and following the failure prepared by the VEPCO personnel was examined. Certain items from these noted led to the following investigations.

3 E₀ Bus Relay Operation

On Friday, December 3 it was noted that the 3E₀ bus relay operated when the transformer was being backfed from the 500 kV system with the generator breaker open. This relay is connected across the broken delta of a set of potential transformers connected to the low voltage bus between the generator breaker and the low voltage winding of the transformer. A 48 ohm resistor is connected across the relay to stabilize the neutral of the low voltage system. The relay was set to trip at 19 volts which represents an E₀ on the system of 19/208 or approximately 10 percent.

It was originally thought that the relay tripping was due to the unbalanced reactances of the one McGraw single phase unit and the two Westinghouse units which make up the three-phase bank. The setting of the relay was raised and the bank reenergized.

The unbalanced reactances could not have caused the unbalance since there was essentially no load current flowing through the bank. This indicated that something else caused the unbalance, possibly indicative of a turn-to-turn fault existing in the low voltage winding of the transformer. Since these windings are connected in delta, it is impossible to calculate the resulting 3E₀ without knowing the exact loading impedances on the system. Other possible causes were investigated.

A difference in taps on the McGraw unit compared to the Westinghouse units could be significant. It was determined, however, that the difference in tap settings were only .0007 percent, so this should not cause the relay trip.

Since the only ground source on the low voltage bus is this wye-broken delta potential transformer with only a 48 ohm resistor and relay across the broken delta, it is probable that unequal capacitances on the bus could cause the

unbalance. While most of the capacitances (such as that of the iso-phase bus) are relatively equal for each phase, the capacitance of the McGraw unit is lower than the Westinghouse unit. The McGraw unit has a capacitance of 0.02 microfarads while the capacitance of the Westinghouse units is 0.03 microfarads. With this difference it was found that a $3E_0$ of greater than 10% would be obtained.

Figures 1 and 2 show the calculations for this condition. Figure 1 shows that the LV windings of the three single phase step-up units result in phase-to-ground capacitances of 0.025, 0.025 and 0.03 microfarads on phase "a", "b" and "c" respectively. Assuming 100 feet of isolated phase bus adds another 0.002 microfarads to each phase, and the three station service auxiliaries each have 0.005 microfarads per phase, the total would be 0.015 microfarads for each phase. Thus, the total capacitance on two of the phases is 0.042 microfarads with 0.047 microfarads on the third. the capacitances represent .06315 and .0562 megohms capacitive reactance respectively. This compares to the resistance of 0.2 megohms when the 48 ohm broken delta resistor is expressed as R_0 on the primary side of the potential transformer.

Figure 2 shows the symmetrical component solution to this unbalanced capacitance condition. Solving the circuit of Figure 2(c) gives an E_0 value of 0.0366 per unit or a $3E_0$ across the relay of 10.9 percent. This voltage is sufficient to cause the relay to operate.

It can be concluded from this study that it is possible that the $3E_0$ relay operation on December 3 could have indicated a turn-to-turn fault or some other abnormality in the transformer. If such were the case, however, one would have expected that the ultimate failure would have occurred before December 5. It is therefore more probable that the relay operation was caused by the unbalanced capacitance of the low voltage bus system.

$3E_0$ Potential Transformer Resonance

The above calculations clearly indicated that the 48 ohm resistor in the broken delta of the bus potential transformers was not sufficient to stabilize the neutral of the low voltage system with the generator breaker open. A logical question therefore arises, "could ferroresonance have occurred to cause the transformer failure?" A detailed ANACOM study of the North Anna installation would have to be run to determine the actual voltages involved, and whether ferroresonance could occur. As a substitute, the paper "Ferroresonance of Grounded Potential Transformers on Ungrounded Power Systems" by R. F. Karlicek and E. R. Taylor, Jr. (AIEE Power Apparatus & Systems, August 1959) was reviewed for general observations pertinent to the December 5 failure.

From this paper it could be concluded that the ohmic value of the resistor should be considerably less than 48 ohms to absolutely prevent ferroresonance, but the line-to-ground voltage resulting from any ferroresonance (should it occur) would probably not produce high enough voltages to breakdown the transformer insulation.

Distribution Transformer Grounding Bank

The lack of adequate grounding on the low voltage bus suggests another possible failure mode. Assume a line-to-ground fault in the bus between the generator breaker and the transformer. The system is well grounded through the generator neutral resistor and after a certain time delay the relay across this resistor will trip the generator. The ground fault now exists on a system only grounded through the 48 ohm resistor in the potential circuit. This results in a fault current on the order of 0.1 ampere which creates a very unstable arc. This arcing ground fault can cause high transient overvoltages and could cause a failure of the transformer.

This probably did not occur on December 5, since it requires the generator being isolated from the bus which would have protected the generator from damage. It is a real possibility for happening at some time, however, and most people using generator breakers provide a full scale grounding bank on the low voltage bus to protect against this and any other condition where an arcing fault could occur with the breaker open. In fact, the new ANSI standard C37.101-1983 "Generator Ground Protection Guide" contains a section on the relaying for such an installation.


The generally accepted rules for high resistance or distribution transformer grounding states that the grounding resistor size should be such that the resistor kilowatts should be equal to or greater than the capacitive charging kVA or that the ground fault current should be equal to or greater than 5 amperes; whichever gives the lowest resistor ohms. Since with the generator breaker open, the capacitive charging kVA of the bus is quite low, in this case the 5 ampere requirement would hold. Figure 3 shows that for the North Anna application a 1.08 ohm resistor should be used.

Note that when the generator breaker is closed, the generator neutral grounding system will be in parallel with the bus grounding system. Both ground relays should see the bus fault. C37.101 covers this condition with two suggested tripping modes:

1. Set the tripping time of the bus relay at a longer time than the generator relay. The generator will always be tripped and if the fault is in the generator, the integrity of the low voltage bus and thus the station auxiliary bus will be maintained. If the fault is on the bus side of the generator, then the high side transformer breakers will be tripped by the bus relay at some time after the generator breaker. Since in this case, the fault current is only 5 amperes (and no high transient overvoltages are produced) this additional time delay should not be objectionable.
2. An alternative tripping scheme suggested by C37.101 is to supervise the tripping of the bus relay with the auxiliary contacts of the generator breaker. Thus tripping by the bus relay cannot occur unless the generator breaker is open. Note that the operation of this scheme is the same as the one described above.

Generator Breaker

VEPCO has retained Power Technologies, Inc. to perform a detailed analysis of generator breaker performance. The results of that study are not included as part of this report.



$$C_a = .025 \mu f$$

$$C_b = .025 \mu f$$

$$C_c = .03 \mu f$$

Isophase Bus Capacitance = $20 \mu f / ft$
Assume 100 ft of bus

$$C_{bus} = .002 \mu f$$

Station Service Xfmrs = $.005 \mu f$
3 transformers

$$C_{tv} = .015 \mu f$$

Total Capacitance:

$$\phi_A = .025 + .002 + .015 = .042 \mu f$$

$$\phi_B = .025 + .002 + .015 = .042 \mu f$$

$$\phi_C = .03 + .002 + .015 = .047 \mu f$$

$$X_{ca} = .06315 \times 1$$

$$X_{cb} = .06315 \times$$

$$X_{cc} = .0564 \times$$

$$48 \text{ ohm PT Secondary Resistor} = \left(\frac{24,000}{\sqrt{3} \times 120} \right)^2 \times \frac{48}{3} \approx .2 \times 10^6 \text{ } \frac{\mu f}{oh}$$

Figure 1





Figure 2.



$$I_R = \left(\frac{24,000}{\sqrt{3} \times 120} \right) \left(\frac{5}{3} \right) = 192 \text{ amp}$$

$$R = \frac{208}{192} = 1.08 \, \Omega$$

$$E_R = 208 \text{ V.}$$

Figure 3


VIII. TRANSFORMERS PROCESSING RECORDS REVIEW

Processing Procedures

The field processing procedures on Westinghouse transformer units at North Anna in general and on the last failure, 7001994, in particular were reviewed to determine any possible processing-related contributant to failure. The following information was utilized: (1) VEPCO records and verbal information from VEPCO personnel as to the reprocessing of 7001994 in November, 1982, (2) test results of oil samples taken from 7001965, an unfailed unit processed similarly and at the same time as 7001994, and (3) VEPCO records as to the reprocessing of other Westinghouse units at North Anna. Available information does not indicate that the failure of 7001994, or the Westinghouse failures in general, are related to processing conditions or procedures.

Unit 7001994 was retrofitted with a COPS tank, reprocessed with new oil in late November, 1982, and the transformer failed in December. Detailed "EHV Equipment Fill Record" data for all Westinghouse North Anna units were supplied by VEPCO and can be found in Appendix C. Units 7001994 and 7001965 were evacuated for vacuum filling with oil on November 26, 1982. During this process two pressure readings were monitored: (1) at the vacuum pump via a Stokes gauge and (2) by a McLeod gauge separated from the main tank cover by approximately 25 feet of 3/8" i.d. Tygon tubing. The following schematic illustrates the relative position of these gauges and the average pressure readings on both units.

Calculation of Tank Pressure - HAM707



Because of the configuration of the reprocessing system and the fact that a McLeod gauge measures only partial pressure of the non-condensables, the pressure within the tank is different than measured by either gauge. Tank pressure can be calculated based on the Stokes gauge reading and conductance of the 100 feet of 4" vacuum hose.

This calculation (Appendix D) shows that the internal tank pressure was 1.4 mm Hg which is greater than the specification limit of 1.0 mm maximum (per Westinghouse Instruction Leaflet 48-668) prior to oil filling; although the vacuum meets the specification for pressure during oil filling, 2 mm maximum. The 20 hours during which the vacuum pump was on prior to oil filling is sufficient time to evacuate the tank completely and reach equilibrium.

Although the 1.4 mm absolute pressure is greater than the specification requirement prior to oil filling, the insulation should have been effectively impregnated and dried because of circulating hot, de-gassed oil through the system prior to energizing. Moisture in the oil during processing and prior to energization was within specification, 10 ppm maximum. There was very little difference in processing characteristics between 7001994 and 7001965. Unit 7001994 failed in December, 1982, and unit 7001965 did not show any irregular tendency during operation.

After failure of 7001994, samples of oil were taken from 7001965 and a COPS-type McGraw-Edison transformer C-0-6459-5-1 which was processed similarly and run on the same bank (North Anna #1) as the failed unit. These results, shown in Appendix E, indicate that both units have very similar oil characteristics. All tests were performed by Westinghouse in Muncie. The results agreed well with those measured by VEPCO after the 7001994 failure. These oil characteristics are indicative of proper processing and do not show high nitrogen levels which would be expected if the Westinghouse COPS retrofit procedure were not followed accurately or if the units were not processed completely. All tested oil results are what would be expected from normally operating power transformers of this type.

Gas-In-Oil Analysis

Gas-in-oil analysis of the Westinghouse North Anna units were completed by VEPCO on approximately a monthly basis. Oil samples were analyzed by both Doble and VEPCO laboratories, but primarily by VEPCO. These data are included in Appendix F.

It can generally be stated that abnormal transformer conditions would be represented by: (1) total combustible gas content greater than 500 ppm, (2) rate of combustible gas generation greater than 100 ppm for a 24 hour period under relatively constant load or (3) acetylene in excess of 20 ppm. In all cases the North Anna units appear normal. Total combustible gas levels seldom exceeded 100 ppm and were never measured greater than 200 ppm. The following data represent maximum combustible gas levels measured for each transformer regardless of testing laboratory.

Gas-In-Oil Analysis North Anna

<u>Serial</u>	<u>Maximum TCG, ppm</u>	<u>Test Data</u>	<u>Ultimate Failure Date</u>
7002100	152	10/16/80	06/19/81
7002100*	28	06/11/82	08/22/82
7002098	49	11/08/79	07/03/81
7001965	172	09/18/80	--
7001995	147	06/12/81	11/16/82
7002099	133	11/20/80	11/29/80
7002099*	185	10/07/82	--
7001993	103	04/16/81	--
7001994	180	06/12/81	12/05/82

* Unit rebuilt after initial failure

From the recorded data there is no indication of abnormal gas pattern or gas generation rates. In all respects the data are typical of normally operating units.

IX. GAS EVOLUTION CAUSES

Gas Bubble Evolution

The possibility of gas bubble evolution within the transformers at North Anna and within gas-space power transformers in general were investigated as to reliability considerations. Past research has shown that under certain circumstances gas bubbles will lead to reduced electric strength of the insulation system. The extent of strength loss is dependent on the type insulation structure, the condition of oil itself, including its degree of contamination and other factors which may be unpredictable. The presence of gas bubbles is hazardous where the bubbles can collect beneath collars, inverted channels, and other insulation pieces. Gas bubbles in large power transformers can result from the following sources:

- (1) Leak in a low pressure area allowing outside air into the unit
- (2) Gaseous cavitation of supersaturated oil
- (3) Improper processing
- (4) Thermal degradation of oil or insulation resulting from incipient faults.

An analysis of calculated local oil pressures at various locations in the initial HAM707 design (Figure 1) show that gas space pressures less than 0.7 psig would result in negative pressures in the top cooler assembly. Under these conditions should there be a leak in the upper valve assembly or packing gland, air would be sucked into the unit rather than oil being forced out. The resulting air bubble would be circulated with the oil until it dissolved or entered the gas space. If the oil was saturated with nitrogen such as would be expected of a gas-space transformer, the introduced air bubble would not dissolve. However, the probability of air entering the unit is very small since the transformer is pressure tested at the factory and indirectly pressure tested during shipment and processing. Furthermore, with the COPS retrofit design (such as was on the December 1982 failure of 7001994), the oil head caused by the height of the COPS tank generates sufficient static pressure so that all locations within the transformer are under positive pressure, preventing air from leaking into the unit.

The possibility of reduced reliability in large power transformers due to supersaturated transformer oil and the release of nitrogen bubbles because of gaseous cavitation has been speculated on for many years. Laboratory test have shown that bubbles can form in gas-space transformers under special circumstances such as after an extraordinary rapid temperature drop, failure of periphery gas regulating equipment and improper maintenance procedures.

Gases dissolve in all transformer oils, but the amount of gas which is dissolved at equilibrium will depend on the gas, the chemical nature of the oil (both its source and condition) and on the temperature and applied gas pressure. Figure 2 illustrates the effect of temperature on the solubility of nitrogen in a new transformer oil prior to aging or conditioning. At higher temperatures the amount of nitrogen that the oil absorbs will increase. If the gas pressure on the space over the oil is increased above atmosphere, the equilibrium gas content rises in direct proportion to the absolute pressure (Henry's Law) as shown in Figure 3. Thus, to determine the gas concentration in oil at any temperature and pressure it is necessary to apply the nitrogen solubility curve and Henry's Law.

For example, if a unit is at stable load at 6.5 psig gas-space pressure and 80°C, the amount of gas dissolved in the oil is (9.7%) $(14.7 + 6.5)/14.7 = 14.0\%$. This condition is the maximum theoretical gas content at an oil temperature of 80°C because the relief device will bleed out at pressures over 6.5 psig.

As long as equilibrium conditions are maintained, the gas content of the oil is not a problem since only free bubbles will affect the dielectric strength of the oil. However, when the oil temperature is reduced (e.g. decrease in load, loss of excitation, reduced ambient), the gas pressure is also reduced. If the temperature drop is substantial and it occurs over a fast rate (several hours or less), the gas dissolved in the oil cannot escape through the oil-gas space interface fast enough to maintain equilibrium. The result is a condition of supersaturation in the oil.

Using the previous example, suppose the unit is deenergized and that there is no oil circulation (FOA equipment) and rapid cooling to 25°C. The pressure in the gas space would likely be in the range of 0.5 to 3 psig (we will assume 2 psig). The maximum gas content that the oil can hold is (8.9%) $(14.7 + 2.0)/14.7 = 10.1\%$. However, the oil has 14.0% gas because sufficient time was not allowed for orderly diffusion. The saturation level then at the new equilibrium is $14.0/10.1 = 139\%$, and oil can be said to be supersaturated by a factor of 39%.

Supersaturated oil is not a problem in itself. However, when the local oil pressure is reduced below the gas saturation pressure, gas bubbles will be found. Local pressures within a transformer can be calculated knowing the static and dynamic head of oil and pressure drop incurred by circulating the oil through the cooling equipment. Figure 1 illustrates local pressures, P_L , that may exist in the HAM707 design. The data are based on a gas-space pressure of one atmosphere, and the localized pressures can be adjusted for various gas-space pressures by moving up or down the X-ordinate. Low-pressure regions could also occur by transients such as the mechanical shock of short circuit, electrical shock of transient voltages, and vibration. Gas-saturation pressure (pressure of the gas-in-oil) can be calculated using a derivation of Henry's Law:

$$\text{Gas Saturation Pressure} = P_G = (C/C_s)(14.7) - 14.7$$

Where C = measured gas content in oil

C_s = gas content in oil at equilibrium (100% saturation)

and $C/C_s \times 100\%$ = percent saturation

To determine the percent gas saturation necessary for the first theoretical indication of gas bubbling:

$$P_G = P_L$$

$$(C/C_s)(14.7) - 14.7 = P_L$$

$$(C/C_s) = (P_L + 14.7)/14.7$$

Table I shows the value of C/C_s to just begin forming bubbles at various gas-space pressures and locations within a typical transformer tank. Values of C/C_s greater than those presented in Table I will lead to spontaneous generation of gas bubbles.

Table I

For the first bubble to form $P_G = P_L$ Pressures and saturation levels where first bubble will form at locations F, l, m, n are indicated on Figure 1.

Gas Space Pressure psig	P_L	$\frac{F_C}{C_S}$	P_L	$\frac{l_C}{C_S}$	P_L	$\frac{m_C}{C_S}$	P_L	$\frac{n_C}{C_S}$
0.0	-1.2	92	9.0	161	2.7	118	0.6	104
0.5	-0.7	95	9.5	165	3.2	122	1.1	107
1.4	0.2	101	10.4	171	4.1	128	2.0	114
6.5	5.3	136	15.5	204	9.2	162	7.1	148

Note that supersaturation is not needed to generate bubbles. Only the criteria P_G greater than P_L need be satisfied. However, bubbles forming in undersaturated oil will quickly redissolve in the oil. Bubbles forming in supersaturated oil cannot dissolve but will expand and rise. Should these bubbles migrate to a high-stress region of the transformer, the dielectric characteristics may be seriously impaired. Prior investigations have shown as much as a 40% reduction in dielectric strength of oil (measured with VDE electrodes, 80 mil gap) due to the presence of gas bubbles evolving from supersaturated oil.

Gas bubbles could be found anywhere in the transformer depending on the level of saturation and the local pressure. However, they are not likely to evolve in a large power transformer unless:

1. The pumps are on causing low-pressure regions.
2. The gas-saturation level is such that the gas pressure in the oil exceeds the local pressure.
3. Temperature and pressure changes are rapid (i.e. allowing no or very little diffusion through the interface).

Such conditions would most likely be possible if: (1) a gas-space, FOA transformer is deenergized after establishing equilibrium, and ambient conditions are such that temperature drop of the oil is rapid, and the unit is reenergized before a new equilibrium condition could be established or (2) the gas-space regulation system malfunctions or the nitrogen supply is exhausted in which case a negative pressure could develop in the gas space. The only method found to prevent the possibility of bubble formation due to supersaturated oil is by using a constant pressure oil preservation system (COPS) which essentially removes the gas space (insuring continued low gas content in the oil) and does not allow pressure variation.

Gases may also be trapped in the insulation structures after draining and refilling of the transformer with oil. Figure 4 represents a cross section of trapped gas in an insulation structure and between layers of insulation. Attention thus far has focused on spontaneous formation of free gas bubbles in the bulk oil. But potential also exists for reduction of dielectric strength of major insulation structures from bubbles which are trapped in a gas pocket (Figure 4a) or between paper wraps and conductors (Figure 4b). In these places they may be effectively prevented from escaping during draining and filling operations. To eliminate these pockets one must rely on good vacuum treatment, good vacuum-filling procedures, and the circulating of oil with very low gas content through the transformer to dissolve the bubble prior to energizing. It must also be realized that the rate of dissolution of the gas in the bubble to the oil is very temperature dependent.

A high-voltage transformer is generally vacuum filled with oil after draining. Then the oil is circulated through a degassing plant which removes gases and moisture from the oil. Manufacturer's suggested gas content has been 1% or less, and moisture content maximum has been 10 ppm, for EHV units. However, these parameters are measured from the average bulk oil. Insulation areas could have high gas or moisture values yet not be large enough to affect the bulk oil properties. Since the solution of gas and moisture into oil is time and temperature dependent, it is best to adjust processing (circulation) time for oil temperature. After a unit has been sitting deenergized for a long period of time, the temperature of the core and coils are affected by the ambient. Processing in winter months should as a result continue longer, or the temperature of the circulating oil should be increased. Hot oil is usually obtainable from standard degassing plants, and the processing time should take into consideration the temperature of the oil being circulated. Figure 5 describes suggested temperature-dependent processing conditions for filling transformers. These new procedures have been developed primarily as a guide for draining and filling in cold weather months, but they are generally useful independent of the season.

VEPCO claims to have followed these procedures during reprocessing of the COPS retrofit units in November, 1982. To determine whether the processing procedures were adequate to impregnate the insulation around the HV lead in 7001994, a full size model lead was taped, processed and visually observed in a 350 gallon test tank equipped with an observation window. The results of various processing condition with respect to bubble evolution are shown in the following table.

- . Lead processed using processing information supplied -- 2.4 MM Hg
- . Internal heater was implanted adjacent to copper
- . Geometric configuration same as HAM707
- . System brought to equilibrium to simulate inertiaire
- . Internal temperature raised in 10° steps to 136°C
- . No bubbles were observed
- . Drained oil and processed with poor vacuum -- 20 MM Hg
- . Internal temperature raised in 10°C increments to 136°C - no bubbles observed
- . Gas pressure over the oil system was reduced, but no bubbles observed until pressure went negative
- . Lead processed poorly -- 20 MM Hg vacuum
- . Heated to 70°C
- . No bubbles observed
- . Gas pressure over the oil system was reduced, but no bubbles until pressure went negative
- . Number of bubbles was profuse when generated, and continued for a long period of time while under vacuum


The only cases in which bubbles evolved from the lead insulation was when the gas space was under vacuum. Under positive or atmospheric pressure, bubbles were not noticed at the HV lead even when the insulation was grossly underprocessed.

Another possible source of gas bubbles is due to an incipient fault. In 7001994 a turn-turn fault was discovered in coil #1. An analysis was made to determine if gases generated from this fault could find there way to the HV lead to precipitate a breakdown to coil #21. Gas bubbles will dissolve in oil depending on their size, temperature and degree of oil saturation. It is likely that if gas bubbles were generated at coil #1 they would not dissolve for at least one period of circulation through the unit. Figure 5 shows the relative position of coil #1 and the HV lead. The pumps that were operating during the period immediately prior to failure are also noted. It would appear that due to the flow of oil a bubble found at the fault in coil #1 would move directly up through the windings and then transverse across the top of the coils toward the HV lead. However as shown in Figures 6 and 7, a bridge structure compartmentalizes the top of the unit so that the bubbles would have to creep under the bridge section supports and then come up inside the HV lead section of the bridge structure.

To determine the actual flow characteristics in the HAM707 design, field experiments were made on 7001965 which was not energized at the time. The Trip Report attached as Appendix G describes these tests and their results. The following was observed:


- . On turning on the pumps no bubbles were noticed in the circulating oil.
- . When bubbles were purposely injected through one of the pumps, they were found to progress straight up through the windings and then straight-up through the bridge structure.
- . The quantity of injected bubbles were at least twice as great around the core and coils as opposed to through the coils.
- . Calculations indicate that a given volume of gas, if present, will take seven minutes to complete one cycle through the main tank and cooling system.
- . Reference data indicates that if the bubble size is greater than 1/4" in diameter, it would not dissolve in the oil before one cycle of circulation.

It was not likely that a bubble generated at coil #1 would approach the HV lead unless it was circulated through the cooling system and then come up through the HV lead bridge section.




Local Pressures Throughout a Standard Large Power Transformer with Cooling Equipment On

FIGURE A



Nitrogen Solubility in Transformer Oil
As a Function of Oil Temperature

FIGURE 2



Nitrogen Solubility in Transformer Oil
As a Function of Gas-Space Pressure

FIGURE 3





FIG. 4(A)



FIG. 4(B)

Various Methods of Gas Entrapment in Transformer
Insulation Structures on Draining and Filling

FIGURE 4



Circulation Time Versus Oil Temperature Measured Either in Transformer
Tank or at the Inlet to Degasser. Based on Westinghouse Large Power
Transformer Insulation.

FIGURE 5




Figure 6 - Relative Position of Winding Coils and Lead




Figure 7 - Bridge Structure

X. OIL ELECTRIFICATION EFFECTS

Static Electrification

Static electrification phenomena in large power transformers has been studied (notably by Japanese researchers) with regard to reliability of high voltage, larger capacity units. The distribution of electrostatic charges in a transformer is fundamentally similar to that produced by oil flowing through a plain pipe. In a large power transformer, positive and negative charges in oil are separated by the flow of oil on the surface of paper insulation. The charges, positive or negative, are accumulated when the charges generated by oil flow exceed leakage charge to ground. The charges accumulated in the oil (generally positive) or on the solid insulation (generally negative) cause an electric field, and if it proceeds beyond a certain level may cause electrostatic discharge or creepage discharge in oil. Charging tendency in a power transformer is a complex interaction of a number of factors some of which follow.

Primary Factors Which Influence Flow Electrification

- . Oil flow rate
- . Bulk oil properties (temperature, conductivity, etc.)
- . Surface conditions and structure of solid insulation
- . Oil flow paths
- . Moisture content of oil and paper
- . Nature of ionic content of oil

We have examined the charging tendency of various commercial sources of transformer oil during various stages of oil processing and aging. The charging tendency is closely associated with the amount of substances such as ions or polar material that are in the oil. These substances can come from a number of sources such as: (1) products of thermal decomposition, (2) outside sources of contamination, or (3) the refining operation relative to a specific supplier. We had found that the concentration of these ions or polar substances need not be very great to significantly increase charging tendency. In fact the presence of such substances cannot be detected by standard analytical chemical methods, standard transformer oil specification tests, or any other known test other than by directly measuring charging tendency via a laboratory device specifically designed for the purpose (Exxon mini-static tester, Figure 8).

In experiments conducted at Muncie in 1982, various commercial sources of transformer oil were analyzed for charging tendency with the Exxon mini-static tester. The investigation was initially to determine if hydro-refined oil had greater charging tendency than acid refined oil. (Texaco the last and only domestic supplier of acid refined oil is a chief source of supply for the Muncie plant.) The results of the investigation did not show correlation between acid or hydro-refined oil and charging tendency, but it did show that one source of supply (Gulf Trancrest H) exhibited significantly greater charging tendency than any other source, Figure 9.

Further investigation has shown that the higher charging tendency of the Gulf oil is likely to be due to organic sulfur compounds in the oil. These contaminants can be removed from the oil and the charging tendency reduced to normal levels by clay filtering.

Figure 10 illustrates the trend of Gulf Trancrest H IFT (interfacial tension values) as measured by the semi-annual Doble oil survey. Although the degree of contamination required to provide significant charging tendency may not lower the IFT below the specification limit (40 dynes/cm), it would lower IFT somewhat. Figure 10 shows that the IFT values of Trancrest H dropped significantly after changing to the hydro-refining process, and an indication of a drop in IFT also occurs in mid-1980 through 1981. Oil produced in this time period was likely to have been used during factory testing or field filling some of the North Anna units.

The above data only indicate that Trancrest H has a relatively higher static charging tendency than most other oils. To determine whether this factor would have a significant bearing on the reliability of power transformers would require a great expenditure in resources. The complex interaction of parameters which effect charge generation is not fully understood and possibly could only be reliably reproduced in an actual transformer.




Figure 8 - Exxon Mini-Static Tester




Figure 9 - Charging Tendency of Gulf and Texaco Transformer Oils




Figure 10 - IFT Values for Gulf Oil, 1971-81 taken from Doble Semi-Annual Oil Survey

XI. DIELECTRIC ANALYSIS OF LINE LEAD CONFIGURATION

Purpose


The project was undertaken to provide experimental data for the investigation of dielectric phenomenon around the HV line lead and bushing of the North Anna transformers. The effects of gas bubbles, lead taping, and electrification of oil were studied individually and in combination (gas bubbles/poor lead taping, gas bubbles/electrification of oil).

Experimental Assembly

To simulate the HV line lead assembly in the laboratory, a 500 kV bushing was mounted in a test tank. Attached to this bushing was a simulated lead consisting of two parts -- 1) the vertical section is composed of thin copper sheets that are soldered together at each end; this lead section is bolted to the bottom of the bushing; 2) the horizontal portion is made of solid copper bar; both items 1) and 2) were the same as existed in the North Anna units. Refer to Figure 1 for side and front elevation views of the experimental assembly. To simulate the LV coils and insulation, taped copper strap was placed inside pressboard angles; eight coils were simulated by this assembly. All dimensions were the same as the actual transformer. Gas bubbles were introduced into the experimental assembly using a tygon line positioned directly underneath the lead simulation.

Experimental Results (Standard Transformer Oil)

For correlation purposes, tests were performed before doping at 400 kV for the duration listed in Table 6. Three separate tests were performed -- 1) no oil flow/no bubbles; 2) oil flow/no bubbles; and 3) oil flow with bubbles. After doping, tests 2 and 3 were repeated. As shown in Table 7, the partial discharge increased when the oil was flowing with bubbles flowing past the lead. Although the extent of partial discharge increase with the combination of bubbles and electrification was not large, a qualitative trend does exist indicating an increase in partial discharge with the combination. No flashovers occurred during any of these tests.



HV LINE CONFIGURATION WITHOUT TAPE (BARE)

NO BUBBLES

b, c, e

TABLE 1

HV LINE CONFIGURATION (INSULATED)

b, c, e

TABLE 2

HV LINE CONFIGURATION (TAPED)

EFFECT OF BUBBLES

b, c, e

TABLE 3

HV LINE CONFIGURATION TAPED WITH
OVERLAPPING JOINT HAVING LESS THAN NORMAL TAPER

WITHOUT BUBBLES

b.c, e

TABLE 4

HV LINE CONFIGURATION TAPED

VARYING BUBBLE SIZE




TABLE 5

STATIC CHARGE TEST RESULTS

NO OIL FLOW/NO BUBBLES/NO AEROSOL OT

0.00, e

TABLE 6

STATIC CHARGE TEST RESULTS

TESTS WITH AEROSOL OT ADDITIVE IN THE OIL

OIL FLOW WITHOUT BUBBLES

b,c,e

TABLE 7

VEPCO FAILURE SIMULATION TEST IN HIGH VOLTAGE LAB

Figure 1

STATIC CHARGE TEST




Figure 2

XII. IMPULSE DISTRIBUTION AND RESONANT FREQUENCY ANALYSIS

The seventh incident at the VEPCO North Anna station involving a Westinghouse generator step-up transformer exhibited a flashover from the high voltage line lead to low voltage coil 21. In addition, there were multiple flashovers in the isolated phase bus duct connecting the generator to the transformer. Similar flashovers in the isolated phase bus duct were also evident in the sixth incident. The seventh incident involved transformer serial number 7001994, which was also in the same three phase bank with transformer serial 7001995 which was involved in the sixth incident.

Serial 7001994 was completely disassembled and inspected at the Muncie Plant. The evidence from the disassembly included failure points on the HV line lead and low voltage coil 21 which were presumably the two endpoints to a flashover and a turn-to-turn fault in LV coil 1. Figure 1 shows a winding schematic of the coil arrangement with the arrow signifying a flashover to coil 21 and the "X" indicating the turn-to-turn failure in coil 1. The HV winding consists of the series combination of coils 5-14 and 23-34. All other coils are in the LV winding and are connected in four parallel paths. Coils 21 and 1 are in different parallel paths, however, both coils are approximately at the electrical midpoint of their respective parallel paths.

Upon finding the turn-to-turn fault in coil 1, the objective was to investigate as to whether the fault was a result of the high-low flashover or if the fault was incipient to the high-low flashover. Therefore, a test was devised to simulate the application of a transient voltage on the last turn of coil 21 and measure the subsequent turn-to-turn stresses in other parts of the low voltage winding. To accomplish this, transformer serial 7002100 was used. The transformer core and coil assembly was still intact and thus modelling of the windings was not required. A low voltage recurrent surge generator was used to inject a transient voltage into the LV winding with the last turn of coil 21 being the injection point. Measurements of the resulting turn-to-turn voltage were taken on coil 2 since the edge of coil 1 was inaccessible. However, the voltages in coil 2 should be approximately equivalent to the voltages in coil 1.

The waveshape of the voltage applied to coil 21 during the seventh incident is unknown, however, the recurrent surge generator was used to apply a full wave, a chopped wave, and a steep front wave in three separate tests. The results of the turn-to-turn voltages on coil 2 are as follows:

Full Wave	3.5% of applied voltage
Chopped Wave	7.5% of applied voltage
Steep Front Wave	5.5% of applied voltage

With these results and assuming the most pessimistic situation in which the chopped wave voltage is used and that no voltage drop exists in the high-low flashover arc, one would calculate the crest value of the voltage on coil 21 as 424 kV (2×300 kV line to ground for the 500 kV system). The resulting turn-to-turn voltage would be $(.075)(424) = 32$ kV.

The turn-to-turn insulation for the LV consists of paper tape on the conductor with an additional strip of pressboard located in the turn-to-turn space. One of the observations from the disassembly was that the pressboard between turns was shifted out of place thus leaving only the paper tape on the conductors for insulation. The design value for the electrical strength of the specified paper insulation on the conductors was 45 kV. Therefore, the 32 kV turn-to-turn was well below the design level of the paper alone which leads to the low probability of the turn-to-turn fault occurring as a result of the high-low flashover.

From this analysis the probability of the turn-to-turn fault being in existence prior to the high-low flashover is much greater than existing after the high-low flashover. A possible mechanism for producing the turn-to-turn fault involved the sixth incident with serial 7001995. As stated previously, the isolated phase bus ducts flashed over in the sixth incident. It is possible that when the C phase bus duct flashed over a negative impulse wave was applied to the terminal to which the parallel path containing coil 1 was connected. The magnitude of the wave would have been approximately equal to the crest flashover value of the bus duct. This situation was not modelled because it involves a complex interaction between two transformers and the associated isolated phase bus ducts. However, the point to be made is that serial 7001994 (seventh incident) was involved in another incident by being connected to another transformer which failed in a manner that transient voltages could have been applied to serial 7001994.

In summary, it is most probable that the turn-to-turn fault in coil 1 of serial 7001994 was the result of an event prior to the seventh incident.

Another aspect to the transfer of transient voltages involves the concept of producing voltage transients as the result of a resonant frequency condition. This may occur if a dynamic forcing function with a frequency component the same as the resonant frequency of the winding was applied to the winding. In the specific cases analyzed at North Anna in which the isolated phase bus ducts flashed over, the objective was to determine if a low side arc could produce potential differences between the HV and LV of sufficient magnitude to cause the high-low flashover.

One of the North Anna units was tested to determine the resonant frequency at which the HV line voltage is maximum when excited by a sinusoidal voltage on the low voltage terminals. This test produced results for determining as to whether a low side arc in the isolated phase bus duct could produce voltages in the HV in excess of the withstand high-low. Two resonant frequencies were identified for the HV line terminal; 9 kHz and 40 kHz. A flashover in the bus duct could produce a voltage approximated by a square wave with a period dependent on the reflection time from the fault location to the transformer terminal. Assuming an approximate 100 feet of bus duct length with a capacitance of 0.002 microfarads per phase, the voltage wave would be a square wave with a frequency of 2.5 MHz. The 2.5 MHz square wave would not contain any frequency components at or near the 9 kHz and 40 kHz resonant frequencies. Therefore, the conclusion is that the low side isolated phase bus duct flashovers did not produce the high-low flashovers in the transformer but rather the opposite occurred.




Figure 1

XIII. SENSITIVITY TESTS OF ACOUSTIC WAVEGUIDE SYSTEM

— a, c

[

] a, c

APPENDIX A - ITEM 1

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

ENGINEER'S TRIP REPORT
WESTINGHOUSE FORM 2611 G

For Westinghouse Representatives only.

DATE 12/15/82

ORIGINAL TO ISSUING DEPARTMENT'S FILE NO.

DATE OF ARRIVAL AT PROPERTY	DATE OF LEAVING PROP

COPY TO: (FOR REPORT DISTRIBUTION GUIDE - REFER TO REVERSE SIDE OF THIS SHEET)

[illegible]

VISIT - NAME VERCO NEG.

LOCATION	North Anna #1	G.C.	S.O.	SER. O.
----------	---------------	------	------	---------

PURPOSE OF TRIP Remove barrel barriers from H.V. bushing and make general internal inspection.

CONFERENCE HELD AT North Anna Nuclear Plant DATE 11/22/82

THOSE PRESENT Mr. J. Markins and Mr. J. Templeton, Westinghouse; Mr. J. Macgregor, VEPCO.

SUMMARY: See attached.

TRIP REPORT TO VEPCO NORTH ANNA
POWER STATION ON 11/22/82

Mr. Joe Markins and Mr. Jim Templeton of the Muncie Westinghouse Plant and Mr. Joe Macgregor of VEPCO removed the barrel barriers from the HV bushing in serials 7001994 and 7001965 on 11/22/82. The two transformers were part of the transformer bank connected to the North Anna #1 generator. The third transformer in the bank was a McGraw Edison unit.

VEPCO had already prepared both transformers for inspection by draining all of the oil but they had not broken the seal of the manhole covers. With each unit, VEPCO placed a tent over the manhole which maintained a humidity level of about 20-30% above the open manhole.

The phase B unit, serial 7001994, was entered first. The only personnel to enter the transformer were J. Markins and J. Templeton of Westinghouse and J. Macgregor of VEPCO. The first operation completed was to remove the barrel barrier from the internal end of the HV bushing. This was accomplished rather simply by removing the permali nuts and bolts connecting the barrel barrier to the bridge walls. The pressboard barrier was then slipped from around the bushing without any cutting or tearing of the material required. However, as a precautionary measure the phase was packed with cloth material in the area where work was being performed.

After the barrel barriers were removed a general inspection of the transformer was made. The HV line lead and bushing shield were closely examined. The tape on the lead was firm with no soft spots. The bushing shield was in the proper orientation with no evidence of any abnormalities. The top end of all coils, both HV and LV, appeared acceptable.


In the HV line group four insulation items were pounded back into place. The items were the outermost angles for coils 23-28. The items were only raised about 1/2" and located approximately at the centerline of the phase. This condition was not identified as being critical.

In summary, the phase B transformer was in satisfactory condition. The total open time for the transformer was approximately two hours.

The phase A transformer, serial 7001965, was then worked upon in order to remove the barrel barrier and conduct a general inspection. The same procedures were followed with the second unit as used with the first. That is, the humidity was controlled, the phase was packed, the barrier removed without cutting any material, and the windings inspected. Here again, the barrier was removed with no difficulty. The HV line lead and bushing shield were examined and were satisfactory. One point to note about the configuration of the line lead is that the copper bar comprising the horizontal section of the lead was positioned flat in the serial 7001994 whereas it was on edge for the serial 7001965. Again, there was no evidence of any abnormalities with the HV line lead in either unit. The top end of all coils was satisfactory and minor corrections were made with the LV bus bar

connections in that about 70% of the bolted connections were tightened. The connections were not excessively loose but were tightened in order to fully compress the lockwashers.

As with the phase B unit, the phase A transformer was open for approximately two hours. Nothing was found out of the ordinary and the VEPCO representative was satisfied with both units and subsequently instructed the crew on-site to pull vacuum on both units. At the time of leaving the power plant, both units were being processed under vacuum with the plan to refill the units per the instruction book vacuum filling procedure.



J. B. Templeton, Manager
Electrical & Programs Development

APPENDIX A - ITEM 2

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

ENGINEER'S TRIP REPORT
WESTINGHOUSE FORM 3611 G

2 - For long reports give a summary of important points and recommendations.

DATE 12-16-82

DATE OF ARRIVAL AT PROPERTY	DATE OF LEAVING PROPE
-----------------------------	-----------------------

[illegible]

LOCATION Richmond, VA G.O. _____ S.O. HAM 707 SER. O. 7001994

CONFERENCE HELD AT VEPCO - North Anna Station DATE 11/30 - 12/3/78

THOSE PRESENT Joe McGreggor, Ron Barker and Haden Keafauver of VEPCO; John Haubert of (W)

Richmond; W. J. Carter of (W) Muncie

See attached.

SIGNED (ENGINEER)

William J. Carter
DIVISION

APPROVED

APPROVED *[Signature]*
LOCAL

DEPARTMENT

DIVISION

LOCATED

10

Trip Report Summary

The purpose of the trip was to observe the corona tests made on two units of shop order HAM707.

Vepco was having problems obtaining the required oil breakdown voltage and was not ready to make tests when I arrived. After reviewing their procedures, it was observed that:

1. Their test set was being operated on a low line voltage.
2. The oil samples were being tested at about 10-15°C temp. where a 20°C minimum temperature is required by the ASTM procedure.
3. The oil samples may have been taken using dirty fittings.

These problems were corrected and acceptable breakdown voltages were obtained. The moisture contents measure in serial 7001994 were 5.01 ppm in the bottom sample, 8.44 ppm in the top sample and 10.95 ppm in the COPS tank. The gas in oil was 1.05% in the top and .4% in the bottom. The measured moisture contents in serial 7001965 were 6 ppm top and bottom and 17 ppm in the COPS tank. The gas in oil results were .48% top and .6% bottom. Since the measurements in both COPS tanks were above the limit of 10 ppm, several gallons of oil was drained from the bottom of the COPS and new samples were tested. These tests gave similar results. No free water was observed in the samples. Clearance was obtained from Muncie to accept these levels.

During the tests on unit 7001994 difficulties were encountered which resulted in high corona levels at about 50% voltage and higher. The corona levels were apparent on the RIV meters and on both acoustic detection systems. The acoustic signals were characteristic of conducted interference and not acoustically detected corona internal to the transformer. The corona would disappear with time and would then reappear at higher voltages. It was then determined that the source was corona observed and heard on the test set. The acoustic meter on the waveguides measured approximately 45 during these events.

The weather during the entire test period was rainy and foggy. The moisture caused the problems encountered during the test. The final test results are tabulated on the attached page. These results were accepted by all parties. The corona levels were stable during these tests and no corona was detected by either acoustic system.

An attempt was made during the evening of 12/3 to back feed the unit. Before the unit was energized, the waveguide detected several switching events in the 500 kV yard. These events caused a response of about 2,000 to 20,000 on the meter. When the transformer was energized the meter jumped momentarily from 40 to about 45. After about five seconds, relaying on the low voltage bus caused the unit to trip off. The low voltage bus was meggered and a problem at the generator breaker was found and corrected. The transformer was re-energized from the high voltage side at 4:08 a.m. on 12/4/82. As the unit

was energized the meter indicated a level of about 200 units on both waveguides. This signal remained steady for seven minutes and then suddenly decreased to 40 on each waveguide. The 40 reading represented an ambient level present without voltage. The waveguide meters remained steady for over one hour after energization.

Interviews with people in the area of the transformer during the period of energization disclosed that in the interval corresponding with the 200 unit reading on the waveguide meter, severe external corona existed on the 500 kV bus. This external corona probably caused the 200 reading.

At this point, problems with the generator breakers were discovered, and it was decided that it would be several hours before the unit would start carrying load.

B. 7001994

<u>%</u>	<u>Time</u>	<u>H1</u> <u>V</u>	<u>H2</u> <u>V</u>	<u>Acoustic</u> <u>Waveguide</u>	<u>GP</u>
0	0	12-14	25-30	40	-
100	-	12-14	30-35		
125	-	12-14	35-40		
135	0	20-25	35-40	146% max. voltage	
135	5	20-25	35-40		
120	5	20-25	30-35		
	10	20-25	30-35	40	
	20	20-25	30-35	40	
	30	14-18	30-35	39	
	40	18-22	30-35	39	
	50	15-18	40-45	39	
	55	14-16	30-35	39	
135	55	14-16	40-45	39-42	
	56	18-20	35-40		
	57	16-18	30-35	38	
	58	18	30-35	38	
	59	16-18	30-35	38	
135	60	16-18	30-35	38	
120	60	20-25	30-35		

ALL CORONA READINGS ARE STABLE.

Weather conditions: Fog with light rain at end of test.

A. 7001965

<u>%</u>	<u>Time</u>	H1 <u>V</u>	H2 <u>V</u>	Acoustic <u>Waveguide</u>	<u>GP</u>
0	0	18-20	7-8	40	OK
100		30-32	8-10	40	
135	0	25-30	12-14	40	
	2	20-25	8-10	40	
	5	20-25	7-8	40	
120	5	25-30	6-8	40	
	10	20-25	6-8	40	
	15	20-25	12-14	40	
	20	22-27	14-16	40	
	25	30-35	14-16	40	
	30	20-25	16-18	40	
	35	20-25	14-16	40	
	40	20-25	20-25	40	
	45	20-25	16-18	40	
	50	20-25	14-16	40	OK
	55	25-30	20-25	40	
135	55	20-25	25-30	40	OK
	56	20-25	25-30	40	OK
	57	20-25	30-35	40	
	58	20-25	25-30	40	OK
	59	20-25	25-30	40	OK
	60	20-25	25-40	40	OK
120	-	20-25	16-18	40	OK
100	-	20-25	10-12	40	OK

STEADY

Weather Conditions: Heavy Fog

APPENDIX A - ITEM 3

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

NOTE 1 - The Engineer reporting is responsible for the prompt delivery of his reports to all interested persons and for seeing that all points requiring action are cleared up without delay.

2 - For long reports give a summary of important points and recommendations.

For Westinghouse Representatives only.

DATE 3/24/77

ORIGINAL TO ISSUING DEPARTMENT'S FILE NO. HAM707-08

DATE OF ARRIVAL AT PROPERTY	DATE OF LEAVING PROPERTY
3/22/77	3/23/77

COPY TO: (FOR REPORT DISTRIBUTION GUIDE - REFER TO REVERSE SIDE OF THIS SHEET)

[illegible]

VI.	NAME	Virginia Electric Power Company
-----	------	---------------------------------

NEG. _____
(Original S.O. HAM707)

LOCATION Fredericksburg, Virginia

G.O.

S.O. XDM1323 SER. O. 7002099

PURPOSE OF TRIP To search for missing hardware used in the shipping braces.

CONFERENCE HELD AT North Anna Power Station

DATE 3/23/77

THOSE PRESENT Alfred Moore and "Smiley" Francis of VEPCO and C. F. Millis, V. A. Holford, and

I. L. Hansen of Muncie.

SUMMARY:

A bolt in the shipping braces was minus a nut and washer upon arrival at the site. Several investigations by VEPCO and one by Muncie personnel failed to locate the missing hardware. It was the conclusion of the personnel from Muncie that the hardware was never on the bolt.

SIGNED (ENGINEER)

6-7 12222222

APPROVED

3/24/77

Amant

DEPARTMENT

Engineering

DIVISION

Large Power Transformer

LOCATION

Muncie, Indiana

PAGE

1

TRIP REPORT

Virginia Electric & Power Company
S.O. XDM1323 (Originally HAM707)
Serial #7002099

When this unit was received at the North Anna Generating Station an internal inspection was performed with no discrepancies noted. After the unit was placed in an upright position and during the removal of the laydown shipping braces, a bolt was found with no nut or washer on it. Using the attached portion of Drawing HAM707-75 as reference, the location of the missing nut and washer is indicated. There are three bolts through this particular post and wall, and the one without a nut or washer was located near the bottom (or nearest the side member). The missing nut and washer were not discovered in the earlier inspection because of its inaccessibility.

The crew that discovered the missing hardware searched for several hours, but failed to locate it. Mr. Alfred Moore of VEPCO also spent several hours on each of three different occasions searching for the hardware with no success. Mr. Moore and the crew also searched the tank bottom by inserting a magnet through the cooler valves. Since it is impossible to see into the tank bottom, there are undoubtedly large areas that were not covered.

On 3/22/77 V. A. Holford, C. F. Millis, and I. L. Hansen from Muncie inspected the shipping braces and hardware that were removed from the transformer. There was no indication of this bolt ever being tightened because neither the post nor wall had any indentations. All bolts were in one large bag so there was no way of locating and inspecting the bolt of interest to determine whether it had ever had a nut on it. Since it was raining the transformer was not examined internally until 3/23/77. This inspection revealed no loose hardware. Wedges between the shielding and phase were not removed, but gaps in the corners were examined with a boroscope.

In the final discussion with Mr. Moore, I. L. Hansen stated that he was satisfied that the nut and washer were never placed on the bolt at Muncie. Mr. Moore asked about the possibility of cutting into the tank bottom to determine whether anything had fallen into it. Mr. Hansen acknowledged the possibility of doing this, but attempted to discourage it. Mr. Moore said they would not cut into the tank without discussing it first with Muncie.

I. L. Hansen

I. L. Hansen
Design Engineer

3/24/77

APPENDIX B - ITEM 1

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

Teardown Report
VEPCO North Anna Unit
500/22 GSU S# 7001994
S.O. XDM1888 (HAM707)
1/10/83

Summary

This transformer failed on December 5, 1982 and was returned to Muncie for teardown and inspection. Visual examination of the phase indicated that the greatest damage occurred in the area of coil 21 located approximately below the HV bushing flexible connector. The edge of coil 21 was burned and the outermost layers of the coil displaced. The corners of washers 66, 67 and 68 were broken and missing. Arc burning was also found on the edge of the HV bushing flexible connector. Detailed inspection of the coils confirmed the assumption that an arc had occurred between the HV bushing flexible lead and the edge of coil 21.

The detailed inspection also uncovered an electrical failure between turns 7 and 8 of coil 1.

Detailed Inspection

- Tank: The top section of the tank was distorted and ruptured in several places.
- Bridge: Nearly all fiber studs in the bridge structure were broken and the bridge fell off the phase when the tank top section was removed.
- Core Steel: The core steel stack was straight and undamaged.
- Coil Support: The coil supports were undamaged.
- Phase: Coil 1 - Had a turn-to-turn failure between turns 7 and 8 on the HV side 36 inches above the centerline. The turn-to-turn pressboard fill was displaced at the point of failure.
- Coil 15 - A "S" shaped piece of copper wire was found near the start-start connection. No damage to this coil was found.
- Coil 19 - The coil insulation directly adjacent to the damaged area of coil 21 was charred.
- Coil 21 - The outer edge of the coil was burned and bare copper pitted on the A end, HV side. The outer layer of the coil was displaced.
- Coil 22 - The insulation of the "A" end coil edge was skinned in 3 places.
- Coil 38 - The insulation on the "A" end coil edge was skinned in 1 place.

Washers 66, 67, 68 - The "A" end HV side corners of the washers were broken off and missing.

HV Lead - There was electrical burning on the edge of this HV bushing flexible connection at about mid-length.

Conclusion

It is concluded that an electrical arc occurred between the HV bushing flexible lead and the edge of coil 21.

W. J. Carter
D. White
Engineering Operations

APPENDIX B - ITEM 2

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

APPENDIX B - ITEM 2

VEPCO TRANSFORMER
HAM 707, SERIAL 7001995, VEP CO PHASE C
FAILED NOVEMBER 16, 1982

BACKGROUND DATA

- Shipped 1973.
- Went into service 1974 (limited, full service 1975).
- Taken off line, May 1982.
- Drained, refilled with new oil, August 1982.
- Re-energized for first time on November 16, 1982.
- Failed 3 hours, 6 minutes after re-energizing.
- Weather reported to have been mild through the fall season until two nights before the failure.
- Failure occurred while unit was being back fed from the 500 kV system.
- Pump bearing wear had occurred in pumps on other two serials (7001965 and 7001994). These units cleaned, flushed and refilled with new oil. Harley Pump Co. report states that there was no bearing wear in pumps from serial 7001995.

DATA FROM VEP CO RECORDS AND OBSERVATIONS

- Fault Currents
 - Phase C - 16200 amperes
 - Phase A - 5250 amperes
 - Phase B - 5250 amperesNormal 120° Apart
- Breakers cleared fault in three cycles.
- No unusual occurrences or observations prior to failure.
- One stage of coolers initiated when unit was energized.
- Pipes to disconnected gas relay broken and distorted on Phase A and B tanks. Condition prior to Phase C failure thought to be normal.
- No failure on HV bushing.

FAILURE DAMAGE AND FAILURE PATH

- 1-1/2" diameter hole in lower edge of HV bushing shield. See Figure 1.
- Flashover from this hole across the surface of the cylindrical barrier down to the edge of L.V. coil #21 about 18" from the centerline of the phase. The damage on coil 21 was erosion of the strand surfaces for a depth of about 1/32". See Figure 1.
- Smoked area on insulation around failure on coil 21 was small.
- Insulation in good condition with exception of mechanical damage caused by broken porcelain and bridge walls.
- Both upper and lower porcelains on H.V. bushing broken. No evidence of a bushing failure.
- One small arc mark on tank wall opposite the corona shield which was felt to be a low energy secondary failure.
- Tank cover had some minor distortion and the welds at the ends of some cover braces were partially ruptured.

- . No ruptures in tank so that there was no loss of oil.
- . Turn ratio correct after failure.
- . Meggar values in air 1000 megohms minimum indicating no failures to ground within the transformer insulation system.
- . Flashovers reported in bus duct for phases A and C. See Figure 2.
- . Found flashover in Phase A bus duct 8 feet from transformer. Did not find where Phase C flashed over as of 11/18/82.

HYPOTHESIS OF FAILURE CAUSE

The oil became saturated with nitrogen during the period between August and November. The saturation level would be the equilibrium values for ambient temperatures that existed. It appears that a maximum ambient of 30°C occurred during the period. Ambient temperatures dropped to -3° during two nights preceeding the re-energization. The temperature of the oil in coolers, piping and pumps would decrease rather rapidly resulting in super saturation of this oil and possibly formation of some small gas pockets.


When the pumps were started, nitrogen bubbles were evolved in the oil. Gas bubbles collected around the lower edge of the corona shield on the H.V. bushing. Corona was initiated by these gas bubbles which ultimately resulted in a flashover from the shield to the edge of L.V. coil #21.

The potential of the L.V. winding was elevated when the flashover from the H.V. bushing occurred. The potential became high enough to cause flashovers to ground in phases A and C bus duct. The bus duct was the weak link since it was insulated for 110 HV BIL while the transformer LV winding and bushings were insulated for 150 kV BIL. See Figures 1 and 2 for sketches of the failure paths.


This failure sequence agrees with the magnitudes and phase angle relationships of the fault currents.

H. R. Moore
H. R. Moore
12/3/82

WESTINGHOUSE ELECTRIC CORPORATION



WESTINGHOUSE ELECTRIC CORPORATION



SCHEMATIC OF 500 KV

WESTINGHOUSE ELECTRIC CORPORATION

FIGURE 1

APPENDIX B - ITEM 3

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

ENGINEERING LABORATORY REPORT #41-5F

DEVELOPMENT ENGINEERING

MUNCIE PLANT

TITLE: FIELD FAILURE IN S.O. HAM707

ABSTRACT: One of the single phase units (Ser. #7002099), built on S.O. HAM707 failed in the field as a result of flashovers across the ducts between H.V. coils #31, #32 and #33. Flashovers also occurred to the L.V. series connections. This report describes teardown of this unit and outlines a probable sequence of flashovers.

PREPARED BY:

J. L. Puri 7/30/76
(Date)
J. L. Puri
Development Engineer

I. L. Hansen 7/30/76
(Date)
I. L. Hansen
Design Engineer

APPROVED BY:

L. S. McCormick 7/30/76
(Date)
L. S. McCormick
Supervising Engineer
Electrical Development

H. R. Moore 7/27/76
(Date)
H. R. Moore, Manager
Electrical Development

DESCRIPTION OF UNIT

S.O.: Ham707
Customer: VEPCO
Type: Shell Form, Single Phase, 60 Hertz, 4 H-L Generator
Rating: 330 MVA (FOA)
H.V. - 288675 V (1300 kV BIL)
L.V. - 22000 V (150 kV BIL)

FAILURE EVENTS

The tranasformer was brought up to full voltage level and it carried full load only for a few Hertz and failed. Heavy flow of ground currents was also recorded.

Various cases and events that resulted in the failure is still under investigation.

TEARDOWN OBSERVATIONS

The phase was removed from the tank bottom July 12, 1976. No evidence was found of a failure to the tank bottom, core, T-beam, or corona shields.

The bridge was removed; nothing unusual was noted except for the obvious failure which will be described later.

Customer representatives arrived at the Muncie Plant July 13, 1976. Dismantling of the phase began with coil 38. All items were inspected prior to being scrapped -- no evidence of corona was found anywhere.

Initial observations prior to dismantling were that the phase was very dirty with carbon deposits everywhere and copper shot in most of the A end. Channels were not intact in the A end of the phase over coils 30 through 33. A fault with apparently heavy currents had destroyed all but 1 strand of the outside turn on coil 33, burned through the edge strip on coil 32, and completely burned open the outside turn in 31 plus about 80% of the second turn. Burn marks were detected on the series connections between coils 35 - 1 and coils 38 - 4.

Coil 38

This coil had no burn marks on it; however, the series connection between coils 38 - 4 did. The crepe paper over the series connection had been burned through just above the washer line. The resulting cavity in the copper was approximately 1/4" in diameter and approximately 1/8" deep.

Coils 37 and 36

These coils were removed with no evidence of failure except for heavy carbon deposits resulting from the fault in the H.V.

11 35

This coil had burned spots all along the outside turn at the A end (see sketch). There were 14 cavities approximately 1/4" in diameter & 1/8" - 1/4" deep on Coil 36 side and 1 cavity at the 45° on Coil 34 side. In addition one of the outside strands were burned through just beyond the 45°. Most of the cavities were in the outside 4 layers of the turn, but two cavities were detected in the 5th and 6th layers. The series connection was burned in two places just above the washer level. The series connection split in three parts in the turn height direction (Fig. 22, 5 layers each split); only two of the three parts had cavities in them corresponding to the layers that had cavities on the coil. The washers above & below Coil 35 were badly discolored but not "burned" through. The severe discoloration occurred wherever a cavity was formed.

The high-low insulation was dismantled with no evidence of any arcing or corona.

Coil 34

This HV line coil and it's associated static plate were free from unusual markings. The washers between Coils 34 & 33 were badly charred, but did not indicate any coil to coil punctures.

Coil 33

This coil had all but 1 strand of the outside turn burned out. This was located about 2 feet from the coil center line on the HV side of the coil. The failure also burned open several strands of the second turn on the Coil 32 side. This coil also had two cavities on Coil 32 side much like the cavities on Coil 35; they were located near the center line.

Coil 32

This coil had it's edge strip burned away in the area of the fault. In addition there were two cavities on the first layer & one cavity on the second layer; they were located at the 45° line at the A end on the LV side of the center line. Another cavity was noted on the 2nd layer at the tie. Washers between Coils 32 & 33 were burned open at the area of the fault.

1 31

This coil had it's outside turn burned open plus 3 strands in layers 1 and 2 and 1 strand in layers 3 of the second turn. The burned out area was in the A end on the HV side of the coil. There were four cavities on the outside turn also. One was under the tie on Coil 32 side; two were on Coil 30 side on the LV side 90° line; and one was on the coil center line on Coil 32 side.

The finish-finish connection between Coils 30 - 31 was burned nearly open. The burn was located approximately 1 foot toward the HV side of the braze; the burned out area was between and on the outside of the two figure 15 parts. The paper covering this area was not blackened as one might expect from a heating problem; rather, it appeared to have happened in a very short time.

The washers between Coils were burned through at the fault location.

Coil 30

This coil did not have portions of the turn burned open, but there were two cavities on the outside two layers about center line on the Coil 31 side. There was also one cavity on the third layer about center line on Coil 29 side.

Coil 29


This coil had one cavity on the third layer on Coil 30 side at the edge of the tie. Another cavity was located on the Coil 30 side 1-1/2" toward tie from center line. On Coil 30 side, third strand, 10" from edge of tie another cavity was detected. A cavity was noted between the first and second layer of the third turn at about the center line; this was the deepest penetration of cavities noted. There were no cavities noted on Coil 28 side; however, a cavity was located on Coil 28 side of the finish-finish connection.

The remaining coils did not have any unusual marks or distortions evident.


Conclusion

In the area of the failure across the second duct from the HV line, Coils 31 & 33 are "closed" and 32 is "open". Consequently the failure path from Coil 31 to 33 and over the top of 32 is essentially a straight line. The heavy currents that flowed during the coil-to-coil fault apparently generated a great deal of gas. The gas was distributed over most of the A end due to channels over the faulted coils and general gas expansion. The ionized gas then provided a low impedance path for multiple secondary failures from the HV, over the high-low washers, to the LV (Coil 35).


There were a total of 15 cavities on the LV Coil 35 plus one burned open strand. There were also three cavities in the LV series connections. An estimate of the current flowing between high and low would be marginal at best since it is difficult to estimate the current required to form the cavities and impossible to know how many paths were faulting simultaneously.



I. L. Hansen
Design Engineer




J. L. Furi
Development Engineer




"X" INDICATES CAVITIES


WESTINGHOUSE ELECTRIC CORPORATION



BLOCK DIAGRAM OF WINDINGS.



SKETCH OF CONNECTIONS AS VIEWED FROM TOP END OF WINDINGS.



APPENDIX B - ITEM 4

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

1

TRIP REPORT

Virginia Electric and Power Company
S.O. XDM 1323 (originally HAM 707)
Serial 7002099

VEPCO reported that subject unit tripped off the line on November 29, 1980 during normal weather conditions. The SPR, mechanical relief device and differential relays had operated and the fault was cleared within 3-1/2 cycles. There was also a flashover to ground in the L.V. isolated phase bus duct and H.V. arrester damage which VEPCO feels was mechanical rather than electrical failure. VEPCO also reported that the unit will ratio correctly but the Doble readings are slightly low.

An internal inspection was made by Messrs. W. Birckhead and R. Barker of VEPCO and B. W. Hugon of Muncie LPTD on 12/15/80.

The H.V. line coil wire of coil comes up vertically through a clamp and then turns 90° and brazes to a horizontal run of copper bar. Brush copper bolts to the end of this bar and goes vertically upward to the H.V. line bushing which is located on the tank centerline.

There was a flashover from the bottom of the end of the horizontal run of the H.V. line lead to the radius of L.V. coil #16. This coil is 6" beyond rather than directly below the end of the horizontal run of the H.V. line lead. Bare copper was exposed for approximately one square inch on the H.V. line lead. The four conductors of the outside layer of coil #16 were severely pitted for about 12" and the strand adjacent to coil #15 was burned open. The free end of the open strand toward the coil centerline remained essentially in its normal position. The other free end projected upwards 4 or 5 inches and then turned downwards for about 2 inches.

No arc pits could be seen on L.V. coil #15, however, it appeared that the washer between coil #16 and #15 may have been ruptured, and there was considerable carbon on the coil #15 side of this washer. In this area the outside edge of coil #16 is approximately 5" higher than that of coil #15 since #16 is a "closed" coil while #15 is an "open" coil.

The round barriers around the H.V. line lead and the bridge walls supporting these barriers were broken.

The hanger straps for the lower half of the double do-nut corona shield on the H.V. bushing were distorted so that the side of the lower shield toward the L.V. side of the tank was lower than its normal position.

Many of the fiber studs in the bridge walls supporting the L.V. series connections were broken.

No arc to ground was observed during this inspection. It is, of course, possible that one or more L.V. coils may have flashed to the core in a location not visible at this time.

The amount of copper particles and carbon was fairly small for a field failure but still of sufficient magnitude that we would recommend the installation of complete new phase (coils, insulation and bridge). The tank, bushings, coolers and most core steel should be reusable.

BW Hugon 12/17/80

B. W. Hugon
Design Engineer

BWH:sjt:0154E

APPENDIX B - ITEM 5

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

DISASSEMBLY REPORT

SUBJECT

Disassembly of transformer serial number 7002099, built originally on shop order HAM707. The transformer is a single phase, 330MVA, 500kV generator step-up transformer and was located at the North Anna Station of Virginia Electric and Power Company.

HISTORY

This unit failed in service on November 29, 1980. An internal inspection was performed on December 15, 1980 by Mr. W. Birckhead and R. Barker of Virginia Electric and Power Company and by Mr. B. Hugon of Westinghouse LPTD. This inspection indicated there had been an arc between the HV line lead and the center low voltage coil group. It was determined at that time, due to the contamination present, a new phase would be manufactured for re-assembly of this transformer.


REPORT OF DISASSEMBLY

The transformer was untanked and the core was removed. On May 17, 1981 the phase was dismantled by LPTD personnel in the presence of Mr. W. Birckhead and Mr. R. Barker of Virginia Electric and Power Company, Mr. J. Mechler of the Hartford Boiler Insurance Company, and Mr. E. Luke of Westinghouse. The phase assembly was split at the high-low space between coils 14 and 15. The entire group of coils, 1 through 14, was removed intact. Low voltage coil group 15 through 22 was then dismantled coil by coil. The only coil in this group that showed evidence of failure was coil 16. The other coils and their associated insulation were darkened as a result of the carbon and smoke from the arc.

The HV line lead was designed to come vertically up from coil number 34 and then make a 90° bend. Wire of coil was then brazed to a rectangular copper plate which had four holes for connection to a flexible lead which connected to the HV bushing. The failure was an arc from the corner of the copper plate to the edge of low voltage coil 16. The arc burned one strand of the outer layer of coil 16 conductor apart. The other three strands of this outside layer were pitted but had not burned open. There were also arc marks on the second layer of this turn on coil 16, but it is believed this occurred when the outer strand burned open. The arc had melted a small crater in the corner of the HV copper plate connector. Particles of copper from this arcing were observed on the phase. Coil washers in coil 15 to 22 group and some of the high-low washers between coils 22 and 23 were broken along the top edge by bridge items that collapsed as a result of the arc energy.

Attached is a portion of drawings HAM707-48 and HAM707-50 and Page 6 of L-HAM707-08. Drawing HAM707-50 shows that relative position of the HV lead with respect to the coil groupings.

This unit is being re-assembled utilizing a new phase which contains all new coils and insulation. The H.V. line lead has been redesigned such that the rectangular copper plate has been eliminated and the connection, from the coil wire to the H.V. bushing, will be made with insulated cable.



L. E. Luke, Manager
Design Applications

0406E

6/5/81

POINTS TO BE BROUGHT OUT AS FOLLOWS:

T10 SLEW ON _____ HAM010748
 LEAD TEST * 8 M _____ HAM010749
 BRIDGE DET * 8 M _____ HAM010750
 STOP DATA _____ HAM010752


I. ALL SHIPPING SUPPORTS MUST
BE ASSEMBLED IN PLACE BEFORE
UNIT IS LAID DOWN

II. ALL BOLTS USED TO ASSEMBLE THE SHIPPING SUPPORTS MUST BE METAL. THESE ARE DESIGNATED BY 93 M ON THE INSIDE DISCS.

III. ALL BOLTS MARKED 5/8" M-ON
INSIDE WINGS ARE TO HAVE THE
HEADS PAINTED YELLOW. THESE
WILL BE REMOVED IN THE FIELD.

SHOP NOTE
ALL BRIDGE LOADS TO BE
PER EXCEPT WHERE INDICATES
OF VARIOUS OTHER "P"

- NOTCH EARRIER
TO SUN ALSO DO
IN EARRIER AT A



APPENDIX B - ITEM 6

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

DISASSEMBLY REPORT

SUBJECT

Disassembly of transformer, serial number 7002100, built originally on shop order HAM707 and returned to Muncie for repair on shop order XDM1779. This transformer is a single phase, 330 MVA, 500KV generator step-up transformer and was located at the North Anna Station of Virginia Electric and Power Company.

HISTORY

This unit failed in service on June 19, 1981. An investigation at that time indicated it was a high voltage line bushing failure and did not involve the windings.

REPORT OF DISASSEMBLY

The complete phase was disassembled coil by coil on October 7th and 8th, 1981. with Mr. Joe McGregor and Mr. Robby Bridges of VEPCO present. There was a very large amount of carbon deposited on both the coils and the insulation, but no failure was found. The termination of the tape, on the high voltage line lead from the coil to a point just below it's horizontal run, had essentially no taper rather than the specified 7" taper. There was, however, no evidence of tracking or any other electrical difficulty at this point. No other irregularities were found.

Prepared by:

B. W. Hugon 10/13/81
B. W. Hugon (Date)
Design Engineer

Approved by:

L. E. Luke 12/14/81
L. E. Luke (Date)
Manager Design Applications

APPENDIX B - ITEM 7

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

Teardown Report
 VEPCO North Anna Unit
 500/22 GSU S# 7002100
 S.O. XDM1867 (HAM707)
 2/22/83

Summary

This transformer failed August 22, 1982 and returned to Muncie for teardown and inspection. Visual inspection of the phase indicated greatest phase damage occurred in the LV coil 22 located approximately below the HV bushing and next to a H-L space. Several arc spots could be seen on the edge of coil 22 and the outer layers of the coil were displaced. Many arc spots were observed on the HV bushing shield and also on the HV ground plane located on the tank cover. Detailed inspection of the phase confirmed that arcing occurred between the HV bushing shield and the edge of the LV coil 22.

Detailed Inspection

Tank: The top section of the tank was distorted and ruptured in several locations (at brace ends). Several arc spots were observed on the HV bushing ground plane.

The bottom section was dirty but otherwise undamaged.

Bridge: The bridge structure was broken into several pieces. Nearly all fiber bolts connecting the bridge structure were broken.

Core Steel: The core was straight and undamaged.

Coil Supports: The coil supports were in place and undamaged.

Phase: Coil 22 - The coil outer edge was burned and the copper pitted at seven locations on the A end and spaced between the A end centerline and the tangent between the HV leg and the corner radius. The largest burned spot occurred at about the end of the corner radius (HV side) on the A end.

A large charred area (18" x 36") was located on the face of the coil at the tangent between the HV leg and the A end radius. The area included parts of the outer three turns. No turn-to-turn failures were found in the charred area. Three very small spots showing pitting of the copper were found on the outer turn: One between layers 3 and 4, and two between layers 8 and 9. One additional small area showed bare copper free of pitting.

Layers of the outer turn were distorted perpendicular to the plane of the coil. These distortions were located in the charred area. Spacer blocks on washer 69 (under coil 22) were found to be overlapping under the distorted area.

Coils 5, 6, 7, 9, 12, 23, 24, 26, 27, 29, 30, 31, 33 and 34 - Carbon deposits in the form of branching streamers were on the B end light pressboard channels.

Coils 5, 9, 23 and 26 - Carbon deposits in the form of branching streamers were found on tight pressboard channels on the HV leg.

Coils 5, 23 and 26 - Carbon deposits in the form of branching streamers were on the tight, pressboard channels on the LV leg.

HV and LV side sheets - Carbon deposits in the form of branching streamers were found originating from the string ties and along the vertical pressboard strips. Streamers were also found along a crack in the HV side sheet.

Coil Washers - Several of the coil washers had carbon deposits in the form of branching streamers. They were especially noticeable on the following:

Washer 6 had streamers on the A end originating at the coil spacer blocks on the side facing coil 36. The opposite side of washer 6 (facing coil 35) was uniformly dark outside the coil perimeter.

Washer 7 had streamers along the A end edge originating at the edge. Also, a very long streamer at the B end HV corner.

Washer 56 had streamers between spacer blocks on coil 23 side on both HV and LV legs.


Washer 97 located between tap coils 9 and 8 had streamers on the bottom side (facing coil 8) instead of the top side.

Washer 99, between coils 7 and 8, had streamers on both sides.

Washer 109 had streamers between spacer blocks on both legs on the coil 4 side.

H-L Space Washers - Streamers between the spacer blocks and top and bottom edges were on all washers in the H-L space between coils 14 and 15, coils 22 and 23 and coils 34 and 35. The streamers occurred on one side with the other side uniformly dark.

HV Bushing - Chips of porcelain found on top of the phase show signs of arcing on the inside surface and inside the porcelain cross-section. These chips are from the upper half of the oil side porcelain.



Dale White
Engineering Operations

APPENDIX B - ITEM 8

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

REPORT ON FAILED BUSHING

August 3, 1981

Bushing 255D500, Group 2
500 kV System Voltage, 1300 kV BIL
Built as HAM 707, Serial 6 in 1974

The remains of the bushing were received in Muncie on July 16, in a VEPSCO shipping crate. Parts received were the condenser, flange, expansion cap assembly, lower porcelain assembly, lower shields, flexible cable to the transformer winding and broken pieces of the upper porcelain. Broken pieces of the lower porcelain were received in a separate shipping crate.

The bushing was disassembled on July 22 and the condenser was unwound on July 23. The lower 24 inches of the straight portion of the condenser; i.e., the paper area over approximately the lower half the ground foil layer (No. 55), was burned and torn for about one half the circumference. Both tapers had mechanical gouges due to broken porcelain and a few singled areas. The support sleeve had shifted upward about 2.88 inches relative to the condenser. The voltage top insulating board was firmly in its correct position.

After about five layers of paper, the burned and torn paper ended. Parts of the circumference of the condenser paper appeared to have spots which were impregnated but void of oil between layers of paper. Those regions were from about foil layer 52 to foil layer 53.

The entire condenser was unwound to the lead. No other damage or irregularities were found.

The 2 inch shield was still partially attached to the lower porcelain support. The lower shield was complete dislocated from the support, both of the support bolt heads having pulled through the copper material. Both shields had several arc marks on their sides, some of the holes burned completely through the material. The upper 2 inch shield also had five 0.5 to 1.5 inch semi-circles burned out on its top surface where it meets up with the top surface of the lower support. The lower support also had pock marks adjacent to the areas.

The bottom end of the expansion cap was domed inward. The spanner nut securing the spring assembly had some stripped threads and had cracked. Some of the matching threads on the lead tube had also stripped.

L. B. Wagenaar

0608E

APPENDIX B - ITEM 9

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

APPENDIX B - ITEM 9

REPORT ON FAILED BUSHING

August 3, 1981

Bushing 255D500, Group 2
500 kV System Voltage, 1300 kV BIL
Built as HAM707, Serial 7 in 1974

The remains of the bushing were received in Muncie on July 16 in a VEPCO shipping crate. Parts received were the condenser, flange, expansion cap assembly, lower support assembly, lower shield, have terminal and flexible cable to the transformer winding; neither of the porcelains was received.

The bushing was disassembled and the condenser was unwound on July 22. The exterior of the condenser was burned, wrinkled and fluffed up on the entire circumference on about the bottom 41 inches of the 56 inch long straight portion. About 16 inches of the ground layer foil (No. 55) between the top of the support sleeve and the ground layer groove was exposed. About 14 inches of the bottom of the foil was also exposed. About 0.144 and 0.308 inches of paper originally covered the ground and tap foil layer, respectively. The voltage tap insulation board was firmly in its correct position.

The lower taper of the condenser had a surface burn 4 to 24 inches wide running the full length of the taper, the burn getting wider as it progressed up the taper. The remainder of the taper surface was singed, but not badly burned. The top taper had a few singed areas, all of which were only on the surface.

The support sleeve has been shifted upward about 1.75 inches relative to the condenser. The outer 5.74 inches of the condenser had shifted about 0.31 inches upward relative to the lead.

The lead tube showed several burned marks from electrical arcing just below the bottom of the condenser for about one half of its circumference. Some of the burned marks formed a continuous 2 inch long crater. Some of the marks were just below the burned area on the condenser taper, but most were within a 90 degree arc to one side of the darkest area on the taper.

There was also evidence of arcing on the lower porcelain support and the lock nut located on top of the former. These marks generally lined up with the burned area on the lower taper of the condenser. There were also arcing marks in both lower shields. Both shields had been dislocated from the lower support, the heads of the screws attaching them to the support having pulled either off or through the copper material.

The condenser was completely unwound. Burning was found through foil layer 53 (about 0.39 inches of paper thickness) and the amount of such decreased as this foil was approached. About 70% of the approximately 49 inch circumference of the lower ends of the last two foil layers (Nos. 54 and 55) had been burned away for 8 to 9 inches in length. The areas burned away from the foils were generally aligned and extended about 6.5 inches beneath the flange. The surface burn on the lower taper had progressed to within an inch of the bottom end of foil layer 53, but was only on the tapered surface below this point. No other damage or irregularities were found beyond foil layer 53.

APPENDIX B - ITEM 10

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

R&D REPORT 82-7D7-MUNCI-R1

INVESTIGATION OF FRACTURE OF A POWER TRANSFORMER CAP
SCREW FROM VEPCO'S NORTH ANNA NUCLEAR STATION

A. Madeyski
Materials Engineering Department

October 6, 1982

APPROVED

R. C. Bates

R. C. Bates, Manager
Materials Engineering Department

G. W. Wiener

G. W. Wiener, Manager
Materials Science Division



Westinghouse R&D Center
1310 Beulah Road
Pittsburgh, Pennsylvania 15235

CONTENTS

1. INTRODUCTION.....	1-1
2. EXPERIMENTAL PROCEDURES AND RESULTS.....	2-1
2.1 Optical Examination.....	2-1
2.2 Fractography.....	2-1
2.3 Energy-dispersive X-ray Spectrometry (EDS).....	2-1
2.4 Hardness Tests.....	2-1
3. DISCUSSION.....	3-1
4. SUMMARY OF THE OBSERVATIONS AND CONCLUSIONS.....	4-1
5. ACKNOWLEDGEMENTS.....	5-1

October 6, 1982

INVESTIGATION OF FRACTURE OF A POWER TRANSFORMER CAP SCREW
FROM VEPCO'S NORTH ANNA NUCLEAR STATION

A. Madeyski
Materials Engineering Department

ABSTRACT

A forced outage of the main generator stepup transformer at VEPCO's North Anna nuclear power station occurred on August 22, 1982. One hypothesis is that this was caused by the fracture of a cap screw supporting the insulator bushing. An investigation revealed that the final overload fracture of the screw started from a very deep crack produced by a low stress, high cycle bending fatigue. The fatigue cracking may have occurred earlier when the bushing was transported by truck several times. In transport to and from the factory, the bushing laid in a horizontal position in a crate, exerting a bending moment on the screw. Vibrations of the truck made the stress variable, resulting in the fatigue cracking of the screw.

1. INTRODUCTION

A recent forced outage of the main generator step-up transformer at the Virginia Electric and Power Company's North Anna nuclear station was found to have been caused by the fracture of a cap screw. The cap screw was part of the support structure of an insulator bushing, as shown schematically in Figures 1 and 2.* The 500 kV bushing assembly (Drawing No. 255D500) was manufactured in 1965 by the Westinghouse transformer plant in Sharon, Pennsylvania. The bushing was shipped to the customer when originally built. In 1976 the bushing was sent to the Westinghouse Power Transformer Division (PTD) plant in Muncie, Indiana, to correct an electrical connection, after which it was returned to the customer. In 1981 the bushing made another round trip to Muncie for electrical testing.

The broken cap screw was submitted by PTD to the Materials Engineering Department of the Westinghouse R&D Center for investigation. It was stipulated that the method used in the investigation should be non-destructive, if possible. Fortunately, we have succeeded in determining the causes of the cracking in the screw by non-destructive procedures, and the screw will be returned to PTD essentially as received.

The investigation consisted of macro-examination, optical and scanning electron microscope (SEM) fractography, energy-dispersive X-ray spectrometric (EDS) analysis of the material, and hardness testing.

Following is a report on the methods of investigation, the results obtained, and the conclusions reached.

*This design is not used anymore in presently built transformers.

2. EXPERIMENTAL PROCEDURES AND RESULTS

2.1 Optical Examination

The broken cap screw was carefully examined with unaided eye, and using a low power optical microscope. Figures 3 through 6 show the general appearance and details of the screw.

2.2 Fractography

The fracture of the screw was examined using an optical microscope and an SEM. The results are shown in Figures 7 through 10, and 13 through 21.

2.3 Energy-dispersive X-ray Spectrometry (EDS)

While inside the SEM chamber, the fracture face on the shorter piece of the cap screw was analyzed using the EDS attachment. The results are shown in Figures 11 and 12.

In interpreting these results it must be remembered that the EDS technique cannot detect any elements with the atomic number lower than 11. This includes hydrogen, helium, lithium, beryllium, boron, carbon, nitrogen, oxygen, fluorine, and neon. However, all the other elements, including important alloying additions such as chromium, nickel, molybdenum, vanadium, etc., can be detected and measured.

2.4 Hardness Tests

The side of the shank was used for hardness testing (Figure 4). Both Rockwell C and B scales were used. The results shown below were in agreement with each other:

RC 21-23;

RB 98-101;

The corresponding ultimate tensile strength is 112-120 kN/m² approximately.

3. DISCUSSION

Fractography has shown that the screw cracked very deeply in high cycle fatigue (Figure 9, areas 1 through 11), before it finally broke completely in shear overload (Figure 9, area 14). The fatigue crack started from multiple origins on the side of the screw marked 0° in Figure 9, and gradually moved across the screw to area 14. At this point the remaining cross-section carrying the load was very small, and eventually some relatively minor load produced the final catastrophic fracture. The overload fracture of this remaining ligament was of the "dimpled rupture" type (Figure 19), indicating that the screw material was fully ductile.

The "primary" origins of the fatigue fracture were all located at the same side of the screw (Figure 8), but it is interesting to note that there was also a very shallow "secondary" fatigue crack which started from the 180° location (Figure 9). This crack propagated only to the depth of about 0.01 in (Figure 20) before the screw finally broke completely.

The type of fatigue in which the fracture traverses the cross-section from one side to the other almost in a straight line is characteristic of bending in a single plane. In a normal operation of the transformer each cap screw acts only as a guide between the clamp ring and the cylindrical flange (Figures 1 and 2). Therefore, the cap screws are not expected to be subjected to any major bending moments. Furthermore, there is no obvious source of cyclic loading on the bushing support to produce fatigue cracking of the screws in normal service. However, when the bushing is shipped to and from the factory, it is crated in a horizontal position, and part of its weight rests on the center portion of a cap screw. Vibrations of the truck provide the

variability of the load necessary for fatigue. A close examination of the broken screw provided additional evidence substantiating the hypothesis that the cracking occurred in transport. Figure 6 illustrates the wear areas in the middle of the screw. The wear area at the 0° location shows heavy peening and burnishing of the steel, indicating that a high transverse load acted at this point. This load provided the bending moment at the screw thread. A variable bending stress was thus superimposed on the constant tensile stress due to the tightening of the screw in the threaded hole. The resultant stress range apparently exceeded the fatigue threshold level and initiated the crack. The fact that this particular bushing was shipped 5 times prior to its forced outage, makes this explanation even more plausible.

A smaller amount of peening and burnishing in the middle of the screw at the 180° location (Figures 4 and 6) was presumably caused by an upward load due to bouncing of the truck on uneven roads. This load apparently started the secondary fatigue crack.

The hardness test indicated that the screw had a tensile strength in the vicinity of 115 ksi which is quite acceptable for a grade 2 screw (74 ksi min.). The EDS analysis has shown that the steel was of plain carbon grade, presumably middle carbon. There was also no fractographic evidence of any material or manufacturing defects which would have started fatigue cracking at an unusually low stress level. Thus, the quality of the screw does not seem to have been a contributive factor in the cracking.

The second cap screw did not break, but was severely bent, presumably after the first screw broke. The second screw was not submitted to the R&D Center for examination.

4. SUMMARY OF THE OBSERVATIONS AND CONCLUSIONS

1. The screw cracked deeply in high cycle, low stress fatigue before it eventually broke in shear overload at some minor load.
2. In normal operation of the transformer the bushing support cap screws are not expected to be subjected to any significant bending, or to cyclic stresses.
3. The evidence suggested that the screw cracked when the bushing was being shipped in the horizontal position, with its weight bending the screw. Bouncing of the truck on uneven roads provided the variable load necessary for fatigue cracking. The bushing was in transport 5 times before its forced outage.
4. The bushing was made in 1965. This design of the bushing suspension system is not used in transformers currently produced by Westinghouse.

5. ACKNOWLEDGEMENTS

The background information and the excellent cooperation provided by J. Templeton of the Power Transformer Division in Muncie, Indiana, is gratefully acknowledged. Thanks are also due to the following members of the Research and Development Center staff: R. C. Bates and J. W. Cunningham - general guidance and technical discussions; J. P. Yex - macrophotography; T. J. Mullen - SEM fractography and EDS analysis. J. Selchan - typing and assembling of the report before printing.

Dwg. 7771A75




Fig. 1 - Schematic sketch showing the location of the two cap screws in the bushing support assembly. Not to scale.






Fig. 2 — Schematic sketch showing the central detail from Fig. 1 . Not to scale




Mag. 0.95X



Mag. 1.5X

Figure 3. General view of the broken cap screw.



Mag. 3.5X

Figure 4. Details from Fig. 3. Note the wear marks under the head and in the middle of the screw. This side of the screw is located 180° from the main fracture origins (see Fig. 9). The indentations visible in the bottom photograph were produced in the hardness tests.



Mag. 6.3X

Figure 5. Wear area under the head of the screw at a higher magnification. Note that the wear was mainly in the form of scratches. Location at 180° from the main fracture origins.




Mag. 6.3X




Mag. 6.3X

Figure 6. Details of the wear areas in the middle of the screw, 180° from the main fracture origin and 0° from the main fracture origins (see Fig. 9). The 180° photograph (upper) shows heavy peening and burnishing mostly in the central part of the wear area. The 0° wear area (lower photograph) is practically all heavily burnished.




Mag. 6.3X




Mag. 6.3X

Figure 7. Fracture face on the head side (upper photograph) and on the thread side (lower photograph). Note the "beach marks" characteristic of fatigue.




Mag. 12.5X




Mag. 20X

Figure 8. Details of the main origin areas of the fracture. The fracture had multiple origins located at the root of the thread visible on the right hand side of the photographs. Note also the beach marks.




Mag. 6.3X

Figure 9. Fracture face on the thread side. The area numbers refer to the photograph numbers in the SEM fractography.




Mag. 12.5X



Mag. 100X

Figure 10. Area 1 from Fig. 9. Some of the primary fracture origins.



Mag. 1050X




Figure 11. Energy-dispersive x-ray spectrum (EDS) of the fracture area 3 from Fig. 10, next to one of the origins. Numerical results of this analysis are shown in Fig. 12.

SPECTRUM TRANSFORMER SCREW

SEP. 20. 1982


FRACTURE NEAR ORIGIN

STANDARDLESS EDS ANALYSIS
(ZAF CORRECTIONS VIA MAGIC V)


ELEMENT & LINE	WEIGHT PERCENT	ATOMIC PERCENT	PRECISION 2 SIGMA	K-RATIO	ITER
CR KA	0.24	0.26	0.06	0.0032	
MN KA	1.04	1.06	0.09	0.0107	
FE KA	98.38	98.37	0.39	0.9841	
NI KA	0.34	0.32	0.12	0.0031	2
TOTAL	100.00				

NORMALIZATION FACTOR: 1.001

Figure 12. Semi-quantitative EDS analysis of the fracture from Fig. 11. The analysis indicates that the cap screw was made of plain carbon steel.




Mag. 525X




Mag. 1050X

Figure 13. One of the primary origins of the fracture, shown at two magnifications (area 4 from Fig. 10). Note the fracture topography characteristic of fatigue from the very beginning.




Mag. 525X




Mag. 2100X

Figure 14. Bottom of the thread groove at the primary crack origins. Note the spalling of the oxide due to metal strain, and a number of small cracks, marked with arrows. The lower photograph (No. 7) shows one of the cracks at a higher magnification.




Mag. 1050X

Figure 15. The first major beach mark of the fracture (marked No. 8 in Fig. 10). The crack probably stopped here for some time, and then resumed the propagation.



Mag. 1050X




Mag. 2100X

Figure 16. Fracture areas 9 and 10 from Figs. 9 and 10. Note the topography characteristic of fatigue at a moderately high stress intensity range.




Mag. 15X




Mag. 105X

Figure 17. Fracture area 11 from Figs. 9 and 10. Note the side cracking characteristic of a high stress intensity fatigue fracture.




Mag. 1050X

Figure 18. Fracture area 13 from Fig. 17.



Mag. 2100X




Mag. 5000X

Figure 19. Fracture area 14 from Figs. 9 and 17. Note the typical "dimpled rupture" topography, characteristic of an overload fracture in a ductile material. Since the dimples are all oriented in the same direction, there must have been a strong shear component in the final load.




Mag. 210X



Mag. 2100X

Figure 20. Fracture area 16 from Fig. 9. When the cap screw broke in the final overload, the area marked "A" was rubbed and smeared. However, small portions of this area, such as "B" in the photograph 16, which were left undamaged, show that this was originally a fatigue crack that started from the "180°" side (Fig. 9), but did not propagate as far as the crack which started from the "0°" side. The rubbing of area "A" must have produced enough heat to create oxide "C".



Mag. 1100X



Mag. 2100X

Figure 21. Appearance of the bottom of the thread when viewed in the direction of the arrow 18 in Fig. 20. Note the spalling of the oxide, indicating strain, and some small original fatigue cracks marked with arrows.

APPENDIX C

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

EHV EQUIPMENT FILL RECORD

Substation N. J. TRINA
 Equipment 22 ST. VP. CO
 Manufacturer WESTINGHOUSE
 Serial Number 7001527

Readings to be taken every half hour.

Probe # Oil In _____
 Probe # Oil Out 2721H

6-30-81

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks		Probe Temp. °C	Probe Reading	Dew Point	P	Ps	Cs	PPM
				Temp. °C	KV										
6-30	5:10					Start Temp	Start Vac	IN							
	1:00	1.5				82°	24 hrs Hold	OUT							
	1:30	.5				82°		IN							
	5:00	.5				82°		OUT							
	5:30	.5				81°		IN							
	6:00	.5				81°		OUT							
	6:30	.5				81°		IN							
	7:00	.5				81°		OUT							
	7:30	.55				81°		IN							
	8:00	.60				81°		OUT							
	8:30	.70				79°		IN							
	9:00	.73				77°		OUT							
	9:30	.75				75°		IN							
	10:00	.75				78°		OUT							
	10:30	.70				75°		IN							
								OUT							

C = Moisture concentration in sample in PPM.
 Cs = 100% saturation of moisture in sample at temperature of measurement.
 P = Water vapor pressure measured by prob
 Ps = Saturated water vapor pressure at _____

$$C = C_s \frac{(P)}{(P_s)}$$

APPENDIX C

EHV EQUIPMENT FILL RECORD

Substation M. D. D.
 Equipment TX.
 Manufacturer W. H. H. H.
 Serial Number 2001527

Readings to be taken every half hour.

Probe # Oil In _____
 Probe # Oil Out 2721 H

TEMP. °F

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks		Probe Temp. °C	Probe Reading	Dew Point	P	Ps	Cs	PPM
				Temp. °C	KV										
	11:00	.75				75°		IN							
	11:30	.75				74°		OUT							
	12:00	.75				74°		IN							
	12:30	.70				74°		OUT							
7-1-81	1:00	.65				73°		IN							
	1:30	.60				72°		OUT							
	2:00	.65				71°		IN							
	2:30	.60				71°		OUT							
	3:00	.59				71°		IN							
	3:30	.58				72°		OUT							
	4:00	.57				71°		IN							
	4:30	.56				71°	Sal. y	OUT							
	5:00	.56				71°		IN							
	5:30	.60				69°		OUT							
	6:00	.56				69°		IN							
								OUT							

C = Moisture concentration in sample in PPM.

C_s = 100% saturation of moisture in sample at temperature of measurement.

° = Water vapor pressure measured by probe

$$C = C_s \frac{(P)}{(P_s)}$$

EHV EQUIPMENT FILL RECORD

Substation
Equipment
Manufacturer
Serial Number

NANNA Gas 11.5 f

11501

7001527

Readings to be taken every half hour.

Probe # Oil In

Probe # Oil Out

27214

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow- Meter Reading	Remarks	Probe Temp. OC	Probe Reading	Dew Point	P	Ps	Cs	P2X
				Temp. OC	KV									
7-1-81	6:30	.55				70		IN						
	7:00	.55				69		OUT						
	7:30	.55				69		IN						
	8:00	.55				69		OUT						
	8:30	.45				69		IN						
	9:00	.45				69		OUT						
	9:30	.45				69		IN						
	10:00	.44				69		OUT						
	10:30	.43				69		IN						
	11:00	.43				71		OUT						
	11:30	.40				72		IN						
	12:00	.40				74		OUT						
	12:30	.40				76		IN						
	1:00	.40				77		OUT						
	1:30	.45				78		IN						

C = Moisture concentration in sample in PPM.

Cs = 100% saturation of moisture in sample

P = Water vapor pressure measured by probe

P2 = Saturated water vapor pressure at 70

temperature of measure

$$C = C_s \frac{(P)}{(P_s)}$$

EHV EQUIPMENT FILL RECORD

Substation

Equipment

Manufacturer

Serial Number

NANDA

WESTINGHOUSE

7001527

Readings to be taken every half hour.

Probe # Oil In

Probe # Oil Out 27311

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	Temp. °F		Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	Ps	Cs	PPH
				QIL	Meter								
				Temp. °C	Reading								
11/8/81	7:00	.45			10								
	7:30	.48			80								
	8:00	.70											
	8:30												
	9:00	.45											
	9:30	.45		141									
	10:00	.46	.75	140	14700								
	10:30	.50	.80	142	1461		40°	.57	-39	.1081	.55.324	.114	.23
	11:00	.50	.80	148	2400		38°	.51	-41	.0862	.49.692	.110	.19
	11:30	.50	.75	148	3300		35°	.47	-46	.0481	.42.175	.99	.11
	12:00	.50	.80	148	4207		36°	.46	-46	.0481	.44.563	.102	.11
	7:00	.50	.80	148	4711	Changed tank	36°	.46	-46	.0481	.44.563	.102	.11
	7:30	.51	.80	143	5310		36	.43	-47	.0476	.41.820	.102	.09
	8:00	.51	.80	143	15305		36	.42	-48	.0478	.31.504	.95	.10
	8:30	.51	.80	145	1735		37	.41	-49	.0478	.28.391	.82	.09
	9:00	.51	.80	142	8175		37	.41	-49	.0478	.28.391	.82	.09

C = Moisture concentration in sample in PPM.

Cs = 100% saturation of moisture in sample at temperature of measurement.

P = Water vapor pressure measured by barometer.

Ps = Saturated water vapor pressure at temperature of measurement.

$$C = C_s \frac{(P)}{(P_s)}$$

EHV EQUIPMENT FILL RECORD

Substation
Equipment
Manufacturer
Serial Number

N. P. 110
GE
WEST
7001527

Readings to be taken every half hour.

Probe # Oil In
Probe # Oil Out

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks	IN OUT	Probe Reading	Dew Point	P	Ps	Cs	PPM
				Temp. °C	KV									
1-1-8		.5				1370	ch TANKERS	IN						
	10:00	.5				4950		OUT	4	39	-52	.0230	28.74%	82
	11:00					10530		IN	28	39	-52	.0230	28.74%	72
	11:30							OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						
								IN						
								OUT						

C = Moisture concentration in sample in PPM.
Cs = 100% saturation of moisture in sample at temperature of measurement.
P = Water vapor pressure measured by probe.
Ps = Saturated vapor pressure at temperature of measurement.

$$C = C_s \frac{(P)}{(P_c)}$$

John

SHEET 1 OF 3

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation NAT3
 Equipment ATGSD 250
 Manufacturer WEST
 Serial Number 7001994

Probe # Oil In _____
 Probe # Oil Out 41289-PR

11-26-82

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P _s	C _s	PPH
			Temp. °C	KV								
06:00						PULL ROSE	IN					
06:15						PULL TX	OUT					
06:30	150						IN					
06:45	30						OUT					
07:00	11						IN					
07:15							OUT					
07:30	.65	.19					IN					
07:45	.1	.8				HOLD 12 hrs	OUT					
08:00							IN					
08:15	.14	.8	WINDING TEMP 11°C				OUT					
08:30	.14	.8	WINDING TEMP 11°C				IN					
08:45	.14	.75	WINDING TEMP 11°C				OUT					
09:00	.14	.75	WINDING TEMP 11°C				IN					
09:15	.14	.75	WINDING TEMP 11°C				OUT					
09:30	.15	.75	WINDING TEMP 11°C				IN					
09:45	.14	.75	WINDING TEMP 11°C				OUT					
10:00	.13	.75	WINDING TEMP 11°C				IN					
10:15	.13	.75	WINDING TEMP 11°C				OUT					
10:30	.13	.75	WINDING TEMP 11°C				IN					
10:45	.13	.75	WINDING TEMP 11°C				OUT					

SHEET 2 OF 3

EHV EQUIPMENT - ALL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

WESTINGHOUSE
1130

Probe # Oil In
Probe # Oil Out 41289-72

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	KV	Flow. Meter Reading	Remarks	IN	OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PP:1
12:30	.13	.72			WINDING TEMP 12°C		IN	OUT							
13:00	.13	.72			WINDING TEMP 12°C		IN	OUT							
13:30	.12	.72			WINDING TEMP 14°C		IN	OUT							
14:00	.12	.70			WINDING TEMP 15°C		IN	OUT							
14:30	.14	.70			WINDING TEMP 16°C		IN	OUT							
15:00	.13	.70			WINDING TEMP 16°C		IN	OUT							
15:30	.14	.70			WINDING TEMP 16°C		IN	OUT							
16:00	.15	.70			WINDING TEMP 17°C		IN	OUT							
16:30	.14	.70			WINDING TEMP 17°C		IN	OUT							
17:00	.14	.70			WINDING TEMP 17°C		IN	OUT							
17:30	.14	.7			17°C		IN	OUT							
18:00	.18	.72			17°C		IN	OUT							
18:30	.14	.72			17°C		IN	OUT							
19:00	.13	.72			17°C		IN	OUT							
19:30	.09	0.3			17°C	WARM UP OIL	IN	OUT							

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

NAPS
WESTINGHOUSE
15N1K B8

Probe # Oil In
Probe # Oil Out 41289PR

Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL Temp. °F	OIL OUT	Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _g	C _s	Pf
00 .07	.35				START OIL 2015							
30 .01	.65	122°F		995100		30	.310	-40	.09106	31.874	85	.2
60 .09	.60	122		1450		30	.310	-40	.09106	31.874	85	.2
90 .01	.60	122		2446		36	.37	-38	.1209	44.563	102	.2
120 .01	.60	122		3400		42	.39	-34	.1873	61.5	119	.2
150 .09	.55	122		4300		40	.38	-36	.1507	55.324	114	.2
180 .08	.60	121		5080	WINDING TEMP 202	40	.38	-36	.1507	55.324	114	.2
210 .01	.60	121		6200		42	.38	-36	.1507	61.5	119	.2
240 .08	.60	125		6912		45	.38	-36	.1507	71.88	128	.2
270 .01	.60	125		7950	WINDING TEMP 252	45	.38	-36	.1507	71.88	128	.2
300 .01	.60	126		8780	352	46	.38	-36	.1507	75.65	130	.2
330 .01	.60	126		9892	REMOVE VAL HOSE							
360 .01	.60	126		10380	MAIN TANK							
390 .01	.60			11547	#COPS							

TIME	DIL IN °F	DIL IN °C	C °F	DWT °C	
0500	58.4	14.4	128	53	1570
0530	59	15	128	53	2600
0600	61	16.1	130	54.4	3880
0630	61	16.1	130	54.4	4800
0700	61	16.1	131	55	5612
0730	61	16.1	131	55	6950
0800	65	18	134	57	7820
0830	67	19	134	57	8875
0900	69	20.5	135	57.2	9910
0930	70	21	135	57.2	10940
1000	70	21	135	57.2	12100
1030	72	22	136	58	13000
1100	73	23	137	58.3	14160
1130	75	24	138	59	15250
1200	77	25	140	60	16200
1230	78	25.6	142	61	17300
1300	80	26.7	143	62	18400
1330	80	26.7	143	62	19500
1400	82	27.8	146	63.3	20600
1430	84	28.9	147	64	

15-20°C

178

3 hrs @ 20-25°C

3.5 hr @ 25-30°C

C = 5/9 (F - 32)

TIME	OIL IN °F	OIL IN °C	OIL OUT °F	OIL OUT °C	Flow Meter
112782	85	29.4	148	64	21620
1500	86	30	150	65.5	22650
1530	88	31	150	65.5	23800
1600	89	31.6	151	66.1	25130
1630	90	32.2	151	66.1	26000
1700	90	32.2	151	66.1	26920
1730	91	32.7	152	66.6	27963
1800	93	33.8	153	67.2	29340
1830	94	34.4	154	67.7	30360
1900	95	35	154	67.7	31145
1930	95	35	156	68.8	32280
2000	96	35.5	156	68.8	33500
2030	97	36.1	157	69.4	34300
2100	98	36.6	158	70	35800
2130	98	36.6	154	67.7	36627
2200	98	36.6	150	65.5	37285
2230	100	37.7	161	71.6	38650
2300	100	37.7	162	72.2	39782
2330	100	37.7	163	72	4154

TIME	DIL IN OF °C	FIL OUT F° C°	FLOW METER
0100	100 37.7	164 73.3	42655
0130	100 37.7	164 73.3	43840
0200	100 37.7	164 73.3	44380
0230	101 38.3	165 73.9	45475
0300	101 38.3	165 73.9	46520
0330	103 39	166 73.	47850
0400	104 39.6	166 73.9	48880
0430	104 39.6	166 73.9	49790
0500	105 40.1	168 74.8	50780
0530	105 40.1	168 74.8	51850
0600	106 40.7	168 74.8	53000

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

N/A Unit #1 01
WESTINGHOUSE
7001965

Probe # Oil In
Probe # Oil Out

181

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow. Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	Pg	Cs
			Temp. °C	KV								
16:30						START VAC.	IN					
17:11	4.2 mm					LEAK CHECK	OUT					
19:45	1.5 mm					LEAK CHECK	IN					
20:10	8 mm					LEAK CHECK	OUT					
20:20	1.0 mm					LEAK CHECK	IN					
20:30	2.5 mm					LEAK CHECK	OUT					
21:00	2.2 mm	7 mm				LEAK CHECK	IN					
21:30	2.4 mm	8 mm				LEAK CHECK	OUT					
22:00	2.5 mm	7 mm				LEAK CHECK	IN					
22:30	2.3 mm	7 mm				LEAK CHECK	OUT					
23:00	2.4 mm	7 mm				LEAK CHECK	IN					
23:30	2.3 mm	8 mm				LEAK CHECK	OUT					
24:00	2.3 mm	8 mm				LEAK CHECK	IN					
24:30	2.2 mm	8 mm				LEAK CHECK	OUT					
	2.2 mm	9 mm				LEAK CHECK	IN					

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N. ANNADANNA

Equipment #1 850

Manufacturer (W)

Serial Number 7001965 A

Probe # Oil In

Probe # Oil Out

11-27-82

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks	Probe Temp. °C		Probe Reading	Dew Point	P	Pg	Cs
				Temp. °C	KV			IN	OUT					
	0:130	23 mm	9 mm				20°C							
	02:00	23 mm	8 mm				20°C							
	03:45	23 mm	9 mm				19°C							
	05:00	25 mm	9 mm				18°C							
	06:30	25 mm	9 mm				18°C							
	08:00	23 mm	9 mm				18°C							
	09:45	24 mm	9 mm				17°C							
	11:00	24 mm	9 mm				17°C							
	12:15	22 mm	SHUT VALVE TO LOSSIE				17°C							
	01:30	23 mm	—				17°C							
	03:00	24 mm	—				16°C							
	04:30	24 mm	—				16°C							
	06:00	23 mm	—				16°C							
	07:30	23 mm	—				16°C							
	09:00	25	—				16°C							
	10:30	25	—				16°C							
	12:00	22	—				16°C							

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N. ANNA #1
 Equipment #1650 AP
 Manufacturer WESTINGHOUSE
 Serial Number 7001965

Probe # Oil In _____
 Probe # Oil Out _____

11-27-82

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	KV	Flow Meter Reading	Remarks	A	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PPH
10:00	1.5						IN							
11:00	1.6		80°C		(9999400)		OUT							
12:00	.09	1.8	53°C		1890 (0000590)		IN	38.8	.39	-43	.0684	56.2	112	.18
12:30	.1	1.7	57.5°C		7574		OUT	42.2	.425	-39	.1081	61.5	120	.2
13:00	.08	00	58°C		0001111 0001918		IN	42.7	.45	-37	.1351	63.1	120	.25
13:30		00			3912	Loosing vac. stop oil and find	OUT							
14:00	found	Small vac pump tripped			4175	Pressure stabilized	IN							
14:30	.13	1.8	65		4657	Pressure stabilized	OUT	38.3	.66	-27	.389	55.8	110	.7
15:00	.1	1.7	59°C		5400		IN	37.7	.48	-34	.1873	49	109	.4
15:30	.09	1.7	60°C		6100		OUT	37.7	.46	-37	.1351	49	109	.3
16:00	.055	1.7	60°C		6700		IN	37.7	.44	-38	.1209	49	109	.2
16:30	.1	1.7	60°C		7506		OUT	37.7	.43	-38	.1209	49	109	.12
17:00	.1	1.7	60°C		8156		IN	37.7	.42	-39	.1081	49	109	.12
17:30	.1	1.6	59°C				OUT	37.7	.42	-39	.1081	49	109	.2
18:00	.1	1.5	59°C		8850		IN	37.7	.41	-40	.0966	49	109	.2

EHV EQUIPMENT FILL RECORD

184

Readings to be taken every half hour.

Substation N. ANNA
 Equipment 1650 HP
 Manufacturer WESTINGHOUSE
 Serial Number 7001965

Probe # Oil In
 Probe # Oil Out

Appx. 20 HOURS = 6 PM SUNDAY 11/28/82

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL Temp. °C	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	Pg	Cs	Pp
18:30	1.10	1.7	58°C	58°C	9463		105°F	412	40°C	1096			
19:00	1.10	1.7	57°C	57°C	9463	High 99.8 Oil	100°F	325					
19:30	1.10	1.7	57°C	57°C	18500	Main Tank Full							
20:00	1.10	1.2 mm			10608								
20:30	1.10												
21:00	1.10												
21:30	1.10	1.2 mm	65°C	65°C	11725	COPAS tank Full							
22:00	1.10	1.0 mm	74°C	115°C	000	begin circulate	105°F	465					
22:30	1.10	1.0 mm	58°C	125°C	980		105°F	461					
23:00	1.10	1.0 mm	58°C	13°C	1734		110°F	490					
23:30	1.10	.08 mm	60°C	13°C	2709		110°F	490					
24:00	1.10	.8 mm	60°C	14°C	3305	Midnight hour	111°F	500					
24:30	1.10	.75 mm	60.5°C	15°C	4250		113°F	505					
01:00	1.10	.8 mm	61.0°C	15.5°C	5042	11/28/82	114°F	510					

ENV EQUIPMENT FILL RECORD

18

Readings to be taken every half hour.

Substation N. ANNA #1
 Equipment CSU AD TRANSFORMER
 Manufacturer WESTINGHOUSE
 Serial Number 7001965

Probe # 011 In
 Probe # 011 Out

11-23-82

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	IN	OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PP
02:00	80 mm	80 mm	62°C	6784		IN	OUT	105°F	—					
02:30	80 mm	80 mm	62.5°C	7402		IN	OUT	104°F	.485					
03:00	80 mm	80 mm	63.0°C	8092		IN	OUT	101°F	.481					
03:30	80 mm	80 mm	64.0°C	8856		IN	OUT	100°F	.465					
04:00	80 mm	80 mm	64.5°C	9816		IN	OUT	100°F	.475					
04:30	80 mm	80 mm	65.0°C	10514		IN	OUT	100°F	.478					
05:00	80 mm	80 mm	65.5°C	11277		IN	OUT	100°F	.473					
05:30	80 mm	80 mm	66.5°C	12055		IN	OUT	100°F	.479					
06:00	80 mm	80 mm	67.0°C	12916		IN	OUT	100°F	.475					
06:30	80 mm	80 mm	68°C	14251		IN	OUT	100°F	.482					
07:00	80 mm	80 mm	69°C	15205		IN	OUT	100°F	.485					
07:30	80 mm	80 mm	69.5°C	15858		IN	OUT	101°F	.480					
08:00	80 mm	80 mm	70°C	16424		IN	OUT	100°F	.461					
08:30	80 mm	80 mm	70	17150		IN	OUT	100	.461					

EHV EQUIPMENT FILL RECORD

186

Substation NORTH ANNA #1
 Equipment EX-10 AΦ TRANSFORMER
 Manufacturer WESTINGHOUSE
 Serial Number 7001965

Readings to be taken every half hour.

Probe # Oil In _____
 Probe # Oil Out _____

11-28 Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	OIL IN Temp. °C	Flow. Meter Reading	Remarks	IN OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _g	C _s	PP
09:30		.8 mm	71	26.5	187.50		IN							
							OUT	100	.463					
10:00		.8 mm	71	27	17.500		IN							
							OUT	100	.470					
10:30		.8 mm	71.5	27.5	10278		IN							
							OUT	100	.470					
11:00		.8 mm	72	28	21108		IN							
							OUT	100	.465					
11:30		.8 mm	72.6	28.7	21916		IN							
							OUT	100	.468					
12:00		.8 mm	73	29	22656		IN							
							OUT	100	.470					
12:30		.8 mm	73.5	29.5	23450		IN							
							OUT	101	.470					
13:00		.8 mm	74	30	24207		IN							
							OUT	102	.431					
13:30		.8 mm	74.8	30.9	25240		IN							
							OUT	100	.420					
14:00		.8 mm	75	31	25818		IN							
							OUT	100	.435					
14:30		.8 mm	76	31.5	26762		IN							
							OUT	105	.460					
15:00		.8 mm	76	32.5	27533		IN							
							OUT	100	.407					
15:30		.8 mm	76	32.0	28309		IN							
							OUT	98	.405					
16:00		.8 mm	77	32.5	29075		IN							
							OUT	10	.470					
							IN							

ENV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

N/A Unit #1 A
GEV. TRANSEFORMER
WESTINGHOUSE
7001965

Probe # Oil In
Probe # Oil Out

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s
17:00	—	0.8 mm	76.5	33.0	30650	—	1100	.445				
17:30	—	0.8 mm	77	33.5	31518	—	100	.455				
18:00	—	0.80 mm	77.0°C	34.0°C	32263	—	105.9	.457				
18:30	—	0.80 mm	77.5°C	34.0°C	32917	—	100°F	.410				
19:00	—	0.75 mm	78.0°C	34.0°C	33736	—	100°F	.410				
19:30	—	0.75 mm	78.0°C	34.5°C	34640	—	100°F	.425				
20:00	—	0.70 mm	78.5°C	34.8°C	35502	—	100°F	.440				
20:30	—	0.70 mm	78.5°C	35.0°C	36179	—	100°F	.435				
21:00	—	0.70 mm	78.7°C	35.3°C	37242	—	100°F	.431				
21:30	—	0.70 mm	78.9°C	35.5°C	37680	—	100°F	.431				
22:00	—	0.70 mm	79.5°C	36.0°C	38531	—	100°F	.435				
22:30	—	0.70 mm	79.8°C	36.0°C	39180	—	100°F	.420				
23:00	—	0.70 mm	80.2°C	36.2°C	40110	—	100°F	.438				
23:30	—	0.70 mm	80.5°C	36.5°C	40890	—	105	.455				

ENV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

A/A Unit I A
650 TRANSFORMER
WESTINGHOUSE
7001965

Probe # Oil In
Probe # Oil Out

11-29-82
A

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	OIL IN Temp. °C	Flow. Meter Reading	Remarks	A	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PP
24:30		70 mm	82.0°C	37.5°C	42471	—	IN	100°F	432					
01:00		70 mm	82.0°C	37.5°C	43212	—	OUT	100°F	431					
01:30		70 mm	82.5°C	37.5°C	44088	Circulating oil Time 2:00 to 2:30 Total 24 hrs. Avg 42.5°C 0.4% water	IN	100°F	432					
02:00		70 mm	82.5°C	37.5°C	44778	—	OUT	100°F	415					
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							
							IN							
							OUT							

EHV EQUIPMENT FILL RECORD

189

Readings to be taken every half hour.

Substation N.A.P.S.
 Equipment #1 G.S.U. TX C
 Manufacturer NEST
 Serial Number 7001595

Probe # Oil In N/A
 Probe # Oil Out 41289-PR

SHEET 1 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	IN OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	ppm
8-10-92	10:45					WATER PUMP	IN							
	11:10					PULL HOSE	OUT							
	11:15					PULL TX	IN							
	11:30	80					OUT							
	12:00	70				12:15	IN							
	12:30	16				140	OUT							
	13:00	13					IN							
	1:30	1.3					OUT							
	2:00	1.5					IN							
	2:30	2					OUT							
	3:00	2					IN							
	3:30	2					OUT							
	4:00	1					IN							
	4:30	0.90					OUT							
	5:00	0.075					IN							
							OUT							

EHV EQUIPMENT FILL RECORD

190

Readings to be taken every half hour.

Substation N.A.P.S.
 Equipment L.G.S.D. 7X Cφ
 Manufacturer WEST
 Serial Number 7001995

Probe # Oil In Nd
 Probe # Oil Out 41289 PR

SHEET 2 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PP:
10/9/2	5:30	.09					IN						
	6:00	.09					OUT						
	6:30	.1					IN						
	7:00	.07					OUT						
	7:30	.08					IN						
	8:00	.08					OUT						
	8:30	.08					IN						
	9:00	.07					OUT						
	9:30	.07					IN						
	10:00	.07					OUT						
	10:30	.07					IN						
	11:00	.07					OUT						
	11:30	.07					IN						
	12:00	.08					OUT						
	12:30	.08					IN						
							OUT						

PHV EQUIPMENT FILL RECORD

191

Readings to be taken every half hour.

Substation N.A.P.S.
 Equipment LG.S.U.TX CD
 Manufacturer WEST
 Serial Number 2201975

Probe # Oil In N.A
 Probe # Oil Out 4428972

SHEET 3 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	KV	Flow Meter Reading	Remarks	IN	OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _g	PP:
8-11-82	1:00	.08														
	1:30	.08														
	2:00	.08														
	2:30	.06														
	3:00	.25	.9	144	35	375	START OIL	IN	OUT	24	.64	-14	1361	22.377	69	4
	3:30	.15	.9	144		1315		IN	OUT	24	.54	-19	8154	22.377	69	2
	4:00	.15	.9	144		2220		IN	OUT	24	.52	-21	.705	22.377	69	2
	4:30	.15	.9	146		3200		IN	OUT	24	.52	-21	.705	22.377	69	2
	5:00	.15	.9	146		4200		IN	OUT	24	.50	-22	.64	22.377	69	1
	5:30	.15	.9	146		5000		IN	OUT	24	.49	-23	.58	22.377	69	1
	6:00	.15	.9	146		6100		IN	OUT	24	.48	-24	.526	22.377	69	1
	6:30	.15	.9	148				IN	OUT	22	.46	-25	.476	19.827	65	1
	7:00	.15	.9	146		7750		IN	OUT	22	.46	-25	.476	19.827	65	1
	7:30	.15	.9	146		8140		IN	OUT	22	.46	-25	.476	19.827	65	1
	8:00	.15	.9	146		8625		IN	OUT	22	.46	-25	.476	19.827	65	1

Readings to be taken every half hour.

Substation	N. A. P. S. #7
Equipment	TX 134 G.S.U.
Manufacturer	WEST
Serial Number	7001994

Probe #	Oil In	Oil Out
Probe #	41289 PR	

START
8-5-82

SHEET 1 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT <div>Temp. °C KV</div>	Flow. Meter Reading	Remarks		Probe Temp. °C	Probe Reading	Dew Point	P _s	C _s	P
8-5-80	19:00						IN						
Sgt	19:30						OUT						
	20:00	.3					IN						
	20:30	.15					OUT						
	21:00	.1					IN						
	21:30	.35					OUT						
	22:00	.35					IN						
	22:30	.35					OUT						
	23:00	.35					IN						
	23:00	.35					OUT						
	23:00	.35					IN						
	23:00	.35					OUT						
	23:30	.35					IN						
	24:00	.35					OUT						
	:30	.35					IN						
	1:00	.4					OUT						

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N.A.P.S.
 Equipment TX 165U. 3A
 Manufacturer WEST
 Serial Number 7001994

Probe # Oil In _____
 Probe # Oil Out 41289 PR

SHEET 2 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	IN OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	PPH
5-82	1:30						IN							
	2:00						OUT							
	2:30						IN							
	3:00						OUT							
	3:30						IN							
	4:00						OUT							
	4:30						IN							
	5:00						OUT							
	5:30						IN							
	6:00						OUT							
	6:30						IN							
	7:00						OUT							
	7:30						IN							
	8:00						OUT							
	8:30						IN							

Readings to be taken every half hour.

N.W.P.S

Substation

Equipment

Manufacturer

Serial Number

Probe # Oil In

Probe Oil Out

SHEET 3 OF 4

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum		OIL OUT		Flow Meter Reading	Remarks	Probe Temp. OC		Probe Reading	Dew Point	P	P _s	C _s	PH
			mm	hg	Temp. OC	KV			IN	OUT						
8-5-82	9:00	.3														
	9:30	.25														
	10:00	.30	.7		140	35		START OIL	IN	24	.55	-19	.954	22.377	609	1
	10:30	.4	1.0		144		10666		OUT	30	.56	-18	.938	31.821	85	2
	11:00	.4	1.0				1965		IN	30	.52	-21	.705	31.921	85	1
	11:30	.4	1.0		144	35	3000		OUT	30	.50	-22	.64	31.924	85	1
	12:00	.45	1.0		144	35	3902		IN	32	.49	-24	.526	35.663	91	1
	12:30	.37	1.0		146	35	5000		OUT	32	.48	-24	.526	35.663	91	1
	13:00	.35	1.0		144		5670		IN	32	.47	-25	.476	35.663	91	1
	13:30	.35	1.0		145		6585		OUT	36	.49	-24	.526	44.563	102	1
	14:00	.35	1.0		145		7500		IN	36	.48	-24	.526	44.563	102	1
	14:30	.35	1.0		145		8625		OUT	36	.47	-25	.476	44.563	102	1
	15:00						9720	FIN.	IN							
	15:30								OUT							
	16:00								IN							

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Probe # Oil In 19656-PR
 Probe # Oil Out 19652-PR

Substation N. A. 1111A
 Equipment 1122357
 Manufacturer 7002100
 Serial Number

2-1-82

Date	Time	Trans. Vacuum		Streamline Vacuum		Oil Out		Flow Meter Reading	Remarks			Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	P _p
		mm	hg	mm	hg	Temp. °C	KV											
1-1-82	1300								START VAC	IN	OUT							
	1430		.45						2.4	IN	OUT							
	1500		.16							IN	OUT							
	1530		.25							IN	OUT							
	1600		.35							IN	OUT							
	1630		.25							IN	OUT							
	1700		.3							IN	OUT							
	1730		.35							IN	OUT							
	1800		.35							IN	OUT							
	1830		.35							IN	OUT							
	1900		.40							IN	OUT							
	1930		.45							IN	OUT							
	2000		.45							IN	OUT							
	2030		.45							IN	OUT							

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

N. A. N. A.

H. E. C. S. S. S. M. A. C.

W. 3. 7

7002100

Probe # Oil In 19156-PR
Probe # Oil Out 19152-PR

Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow. Meter Reading	Remarks	A	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	P ₂
			Temp. °C	KV										
2100	140						IN							
2130	135						OUT							
2100	135						IN							
2130	135						OUT							
2200	135						IN							
2230	135						OUT							
2300	135						IN							
2330	135						OUT							
2400	135						IN							
2430	135						OUT							
2500	135						IN							
2530	135						OUT							
2600	135						IN							
2630	135						OUT							
2700	135						IN							
2730	135						OUT							
2800	135						IN							
2830	135						OUT							
2900	135						IN							
2930	135						OUT							

EHV EQUIPMENT FILL RECORD

Substation
Equipment
Manufacturer
Serial Number

NANNA
HZ-7 G.S.U
WST
7002100

Readings to be taken every half hour.

Probe # Oil In 19656-PR
Probe # Oil Out 19652-PR

Date	Time	Trans. Vacuum		Streamline Vacuum		OIL OUT		Flow. Meter Reading	Remarks	IN	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s
		mm	hg	mm	hg	Temp. °C	KV									
2-2-82	4:00	1.6							START OIL	IN						
	4:30	.6		.62		128°F		600		OUT	30°C	.61	-17	1.031	5.685	33
	5:00	.9		.75		105°F		1340		IN	2°C	.35	-66	.00349	5.294	32
	5:30	.6		.77		107°F		2220		OUT	30°C	.69	-13	1.490	5.685	33
	6:00	2.6		.77		106°F		3040		IN	30°C	.41	-46	.0481	31.824	85
	6:30	1.7		.7		120°F		4000		OUT	40°C	.71	-11	1.785	6.101	34
	7:00	.55		.75		118°F		4720		IN	32°C	.40	-48	.0378	35.663	91
	7:30	1.0		.75		118°F		5550		OUT	40°C	.72	-10	1.950	6.101	34
	8:00	.94		.79		117°F		6380		IN	34°C	.40	-48	.0378	39.698	97
	8:30	1.1		.79		125°F		7350		OUT	40°C	.71	-11	1.785	6.101	34
	9:00	.85		.79		125°F		8150		IN	34°C	.40	-48	.0378	39.898	97
	9:30	1.1		.79		125°F		8450		OUT	40°C	.72	-10	1.950	6.101	34
	10:00							9671	PINK	IN	36°C	.40	-48	.0378	44.563	102
										OUT	40°C	.74	-9	2.131	6.101	34
										IN	36°C	.38	-54	.0178	44.563	102
										OUT	36	.38	-54	.0178	44.563	102
										IN	36	.38	-54	.0178	44.563	102
										OUT	39	.38	-54	.0178	52.402	112
										IN						
										OUT						
										IN						
										OUT						

Readings to be taken every half hour.

Probe #	Oil In	Oil Out
Probe #	Oil In	Oil Out

Substation	North Anna
Equipment	#2 C.S.V. TX
Manufacturer	WSP
Serial Number	2002100

260 / 13375

Date	Time	Trans. Vacuum		Streamline Vacuum	Oil Temp. °C	KV	Flow Meter Reading	Remarks	Probe Temp. °C		Probe Reading	Dew Point	P	P _s	C _s
		mm	hg						IN	OUT					
3-26-82	4:20							Start Vac							
	4:25							vac							
	5:00							Start Vac							
	5:20							Start Vac							
	5:30							Start Vac							
	6:00	25m						Start Vac							
	6:30	20						Start Vac							
	7:00	10						Start Vac							
	7:30	1						Start Vac							
	8:00	28						Start Vac							
	8:30	07						Start Vac							
	9:00	04						Start Vac							
	9:30	04						Start Vac							
	10:00	09						Start Vac							
	10:30	11						Start Vac							

#2

EHV EQUIPMENT FILL RECORD

N. Anna

Substation
Equipment
Manufacturer
Serial Number

#2-63-VIX
W. J. T.
2002100

Readings to be taken every half hour.

Probe # Oil In

Probe # Oil Out

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks	Probe Temp.		Probe Reading	Dew Point	P	P s	C s
				Temp. °C	KV			IN	OUT					
	11:00	.08	.6	136		2670				44				
	11:30	.08	.6	136		3400				44				
	12:00	.08	.6	136						44				
	12:30	.08	.6	136		14110				44				
	1:00	.08	.6	136		3700				44				
	1:30	.08	.6	136		6700				44				
	2:00	.08	.6	141		7900				44				
	2:30	.08	.6	136		8231				44				
	3:00	.08	.6	140		8019	Collapsed Hose			44				
	3:30	.08	.6	120		8494				44				
	4:00	.08	.6	120		8800				44				
	4:30	.08	.6	90			START CIRCULATION			44				
	5:00	.08	.6	110						44				
	5:30	.08	.6	120						44				

#3

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N. ANNA
 Equipment #2 C.S.V.
 Manufacturer WES
 Serial Number 7002100

Probe # Oil In _____
 Probe # Oil Out _____

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	KV	Flow. Meter Reading	Remarks	IN OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P.s.	C.s.
3/27	6:30			120				IN						
	7:00			120				OUT						
	7:30			120				IN						
	8:00			120				OUT						
	8:30			120				IN						
	9:00			120				OUT						
	9:30			121				IN						
	10:00			121				OUT						
	10:30			123				IN						
	11:00			125				OUT						
	11:30			130				IN						
	12:00			130				OUT						
	12:30			130				IN						
	1:00			135				OUT						

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

ANNA
#26507R
2002100
CIT. OIL

Probe # Oil In NO 72032
Probe # Oil Out 19652-PR

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. OC	KV	Flow. Meter Reading	Remarks	Probe Temp. OC	Probe Reading	Dew Point	P	P _s	C _s
3/27	13:30			135		0.12 IN	Oil	36	.57	-29	317	83.71	140
	14:00			140		OUT		48	.46	-36	1807	68.26	123
	14:30			142			70	44	.45	-38	1209	83.71	140
	15:00			144			70	46	.44	-39	1081	75.65	130
	15:30			142			75	48	.44	-39	1081	83.71	140
	16:00			144			75	48	.48	-32	2318	136.18	172
	16:30			144			77	56					
	17:00			146		INSTALLED 1000 PRESS	80	36					
	17:30			149		.53 IN	81	48					
	18:00			149		.27 OUT	81	44					
	18:30			148		.20 IN	81	46					
	19:00			148		.19 OUT	84	48					
	19:30			160		.18 IN	84	48					
	20:00			164		.19 OUT	85	58					

TCHILL / CORBIN

EHV EQUIPMENT FILL RECORD

Substation NORTH ANNA
 Equipment #2 65.0 TX
 Manufacturer WEST
 Serial Number 7002100

Readings to be taken every half hour.

Probe # Oil In NO 780132
 Probe # Oil Out 1961272

MOPP 3 CIR. OIL

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT		Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	Ps	Cs
				Temp. °C	KV								
3/27	20:30			164		.14	85	55	.41	-39	.081	118.07	161
	21:00			166		.06	87	46	.40	-48	.0378	75.61	130
	21:30			166		.06	87	39	.39	-50	.0246	12.442	112
	22:00			166		.07	89	52	.41	-46	.0481	107.09	150
	22:30			167		.068	90	47	.40	-48	.0378	68.26	123
	23:00			168			90	44	.39				
	23:30			170			90		.41				
	24:00			172			92	57	.43				
	24:30			172			94	46	.41				
	01:00			164			95	42	.37				
3/28	01:30			164			95	42	.37				
	02:00			162			98	43	.38				
	02:30			162			98	52	.42				
	03:00			163			98	33	.42				

#7
MITCHELL/CORBIN

P.P. #7

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation
Equipment
Manufacturer
Serial Number

N. ANNADANNA

W #2 GSU TX

W 7002100

Probe # Oil In N/A
Probe # Oil Out 19652 PR

MOPOP

Date	Time	Trans. Vacuum mm hg	Strandline Vacuum mm hg	OIL OUT TANK °C	KV	Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s
3/28	11:00	START					SEE # ONE REVERSE						
	11:15	27.5"	19 mm/hg	N/A		N/A	SEE # TWO REVERSE						
	11:30	12 Torr	15 mm/hg	N/A		N/A	SEE # 3 REVERSE						
	11:45	SEE NOTE #3	10 mm	TANK TEMP °C									
	12:00	6 mm	1.5 mm										
	12:15	6 mm	1.3 mm			MER GAGE							
	12:30	5.9	1.1 mm	21.4g									
	12:45	5.5	1.05	20.8g									
	13:00	5.5	.95	20.1g									
	13:30	3.0	.92	20.1		1.25	1337 .85		START HOLD TIME				
	14:00	3.0	.85	19.5		.9							
	14:30	2.5	.82	19.5		.95							
	15:00	2.3	.78	19		1.0							

#8

MITCHELL/CARRIN

P.P. # 8

ENV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N. ANNADANNA.

Equipment #2 G.S.U. TX

Manufacturer

Serial Number 7082100

Probe # Oil In N/A

Probe # Oil Out 19652 PR

Outside Air

MOPP # 3 TANK TEMP

MER GAGE TION

Date	Time	Trans. Vacuum		mm hg	Oil Out Temp.		KV	Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P s	C s
		mm	hg	mm	hg	°C									
3/28	16:00	2.3		.78	19.5			1.05							
	16:30	2.3		.75	19.6			1.1							
	17:00	2.3		.75	19.9			1.1							
	17:30	2.2		.71	20.0			1.1							
	18:00	2.2		.71	20.0			1.1							
	18:30	2.2		.71	19.5			1.1							
	19:00	2.2		.70	19.2			1.2							
	19:30	2.2		.70	19.1			1.3							
	20:00	2.2		.69	17.5			1.3							
	20:30	2.2		.68	17.4			1.3							
	21:00	2.2		.68	17.0			1.3							
	21:30	2.2		.68	16.1			1.3	6°C						
	22:00	2.2		.68	11.5			1.3	4°C						

MITCHELL/GARRIN

P.P. #9

EHV EQUIPMENT FILL RECORD

Substation N. ANNADANNA
 Equipment #2 G.S.U. TX
 Manufacturer (W)
 Serial Number 7002100

Readings to be taken every half hour.

Probe # Oil In N/A
 Probe # Oil Out 19692 PR

MOPP #2 TANK
 MER GAUGE OUTSIDE

Date	Time	Trans. Vacuum mm hg	Oil Out Vacuum mm hg	Oil Out Temp. °C	KV	Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s
3/28	23:00	2.2	.68	15.7		1.3	4°C	IN					
	23:30	1.2	.68	15.1		1.2	4°C	OUT					
3/29	24:00	1.2	.68	14.9		1.2	4°C	IN					
	24:30	2.2	.68	14.8		1.3	4°C	OUT					
	01:00	2.2	.68	14.5°		1.2	4°C	IN					
	01:30	2.2	.65	14.4°		1.2	3½°C	OUT					
	02:00	2.2	.65	14.1°		1.2	3°C	IN					
	02:30	2.2	.62	13.7°		1.2	3°C	OUT					
	03:00	2.0	.62	13.1°		1.2	2°C	IN					
	03:30	2.0	.62	13.1		1.2	2°C	OUT					
	04:00	2.0	.62	13.0		1.2	2°C	IN					
	04:30	1.9	.65	12.1		1.2	1°C	OUT					
	05:00	1.7	.65	12.0		1.2	1°C	IN					
	05:30	1.7	.65	11.8		1.2	1°C	OUT					
								IN					

#10

EHV EQUIPMENT FILL RECORD

$$C = C_s \left(\frac{P}{P_s} \right)$$

Substation
Equipment
Manufacturer
Serial Number

N. ANNA
FL 2 GSD TX
WEST
7002100

Readings to be taken every half hour.

Probe # Oil In N/A
Probe # Oil Out 19052 PR

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	TANK TEMP. OUT Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	R
3-29	6:00	2.0	.65	1.2		11.7 12	IN						
	6:30	2.0	.65	1.2		11.7 12	OUT						
	7:00	2.0	.65	1.3		11.8 22	IN						
	7:30	1.9	.65	1.3		11.8 22	OUT						
	8:00	1.9	.9	130	485	16.1 41	IN	7.45 START AIR - 7 YEARS					
	8:30	2.0	.78	130	1350	27.4 7	OUT	18.3 KAS RAC					
	9:00	2.0	.78	130	2300	31.4 8	IN	22	.38	-52	.0230	35.563	71
	9:30	1.6	.80	130	3345	34.6 10	OUT	38	.39	-50	.0296	49.692	110
	10:00	1.6	.92	132	4385	36.1 11	IN	3A	.39	-50	.0296	49.692	110
	10:30	1.9	.95	134	5115	36.6 12	OUT	42	.41	-46	.0481	61.50	119
	11:00	1.8	1.0	136	6180	35.6 12	IN	42	.42	-43	.0527	61.50	119
	11:30	2.0	.85	134	7265	35.6 15	OUT	48	.43	-42	.0767	83.71	140
	12:00	2.0	.85	138	8115	33.4 14	IN	50	.45	-38	.1209	94.86	145
	12:30	2.0	.94	176	9248	30.2 15	OUT	51	.43	-40	.0966	97.20	147
	13:00			138	9580		IN	56	.47	-34	.1876	123.80	163

28/MA 2 07:00

- (INTO TX)
- # 1.)
- a.) OIL OUT OF MAPP. = 166°F.
 - b.) OIL IN (RETURNING TO MAPP.) = 110°F.
 - c.) WINDING TEMP GAUGE INDICATING 78°C (OR 172.4°F)
 - d.) AMBIENT TEMP 24°F
 - e.) WIND CHILL FACTOR = APPROX 4°F
 - f.) DEW POINT RANGE ON N₂ = -47° TO -51°
 - g.) REQUIRED 5 $\frac{2}{3}$ CYLINDERS OF N₂ TO FOLLOW OIL OUT
AND RACE 1 PSI + N₂ PRESS ON TX

START VACUUM

#1.) COOLER VALVES OPENED

- 1) 1 P.S.I. + N₂ PRESS. NO OIL IN TX
- 2) WINDING TEMP. GAUGE INDICATING 40° C.
- 3) LIQUID TEMP. GAUGE INDICATING 36° C.
- 4) OIL BEING CIRCULATED BETWEEN TANKERS WITH G.E. BLOTTER PRESS FOR DURATION OF VACUUM TIME

#2.) a) TX VACUUM TAKEN w/ MCLEOD GAUGE

- b) MOPP. VACUUM TAKEN w/ PENWALT/STOKES VACUUM TUBE GAUGE

#3.) a) R/M MCLEOD GAUGE

- b) INSTALL STOKES RECORDING VACUUM TUBE GAUGE
- c) INSTALL THERMOMETER ON TX TANK

1390

EHV EQUIPMENT FILL RECORD

210

Readings to be taken every half hour.

Substation N. Anna
 Equipment Ad
 Manufacturer WEST
 Serial Number 7001965

Probe # Oil In _____
 Probe # Oil Out _____

7-28-82

Date	Time	Trans. Vacuum		Streamline Vacuum		Oil Out		Flow. Meter Reading	Remarks	IN	OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	P
		mm	hg	mm	hg	Temp. °C	KV											
7-28	1135								START VAC	IN	OUT							
	1200	60		TEST					1.49K	IN	OUT							
	1230								TEST	IN	OUT							
	1300	.2							Hold 14 hrs	IN	OUT							
	1330	.4								IN	OUT							
	1400	.15								IN	OUT							
	1430	.3								IN	OUT							
	1500	.35								IN	OUT							
	1530	.40								IN	OUT							
	1600	.40								IN	OUT							
	1630	.45								IN	OUT							
	1700	.45								IN	OUT							
	1730	.50								IN	OUT							
	1800	.55								IN	OUT							
	1830	.55								IN	OUT							

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N.A.P.S.
 Equipment AF
 Manufacturer WEST
 Serial Number 2001965

Probe # Oil In _____
 Probe # Oil Out _____

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow Meter Reading	Remarks	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	P
7-28	1900	170					IN						
	1930	175					OUT						
	2000	175					IN						
	2030	175					OUT						
	2100	185					IN						
	2130	181					OUT						
	2200	180					IN						
	2230	180					OUT						
	2300	190					IN						
	2330	185					OUT						
	2400	185					IN						
	2430	190					OUT						
	1900	185					IN						
	1930	185					OUT						
	2000	190					IN						
	2030	190					OUT						
	2100	190					IN						
	2130	190					OUT						
	2200	190					IN						

3 of 4

EHV EQUIPMENT FILL RECORD

Readings to be taken every half hour.

Substation N. A. S. V. TX
 Equipment W. S. T.
 Manufacturer 70013
 Serial Number

212


Probe # Oil In 41289-172
 Probe # Oil Out

Date	Time	Trans. Vacuum mm hg	Streamline Vacuum mm hg	OIL OUT Temp. °C	Flow. Meter Reading	Remarks	IN	OUT	Probe Temp. °C	Probe Reading	Dew Point	P	P _s	C _s	P?
	230	.9													
	300	.9													
	330	.72													
	400	.75													
	430	1.0				START OIL			7.1	.83	-5	3.013	22.377	6.9	2.2
	500	1.0													
	530	1.1	0.7	148	5.09				7.7	.52	-21	.705	19.827	6.5	2.2
	600	1.1	0.75	154	1375				2.0	.51	-21	.705	18.050	6.1	2.3
	630	1.1	.07	149	7.000				7.2	.52	-19	.937	35.462	9.1	2.0
	700	1.05	.07	156	2580				8.0	.54	-19	.954	17.535	6.1	2.0
	730	1.05	.07	141	3285				2.0	.54	-19	.854	17.535	6.1	2.0
	800	1.08	.07	142	4035				2.0	.53	-20	.776	17.535	6.1	2.0
	830	1.05	.07	141	11915				2.0	.53	-20	.776	17.535	6.1	2.0
	900	1.1	.07	149	5710				7.7	.53	-20	.705	17.535	6.5	2.0
	930	1.08	.08	148	6600				7.2	.53	-20	.705	17.535	6.5	2.0

APPENDIX D

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

Calculation of Tank Pressure - HAM707



The single phase transformer, HAM707, (retrofitted with a COPS unit) was evacuated to prepare for vacuum filling. During this process, two pressure readings were taken (1) at the vacuum pump and (2) by a McLeod gauge separated from the tank cover by approximately 25 ft. of 3/8 inch I.D. tubing. The question has been raised, what is the total pressure within the tank.

Conditions at the end of evacuation prior to oil filling were:

1. Pressure at pump, .8 mm. This is assumed to be a total pressure reading.
2. Pressure measured by McLeod gauge, .14 mm.
3. Ambient temperature assumed to be approximately 60°F.

Since the McLeod gauge records the partial pressure of the non condensables, the pressure within the tank can be calculated by the following equation.

$$P_1 = P_a + P_o + H_w$$

where

P_1 = Total pressure, mm

P_a = Partial pressure of air, mm

P_o = Partial pressure of oil, mm

P_w = Partial pressure of water, mm

At 60°F, the partial pressure of oil is negligible, therefore,

$$P_1 = P_a + P_w$$

The internal pressure within the tank is determined by applying standard formulas and graphs used in vacuum technology. (Copies of pertinent pages from the Stokes Bulletin 526 and 518-B are attached.)

From the Table on page 12, the conductance of a 100 ft. length of 4 inch diameter pipe is:

$$C = 9 \times 4 \times 800 / 26 = 1108 \text{ CFM}$$

Mass flow, Q, in mm - CFM is defined as

$$Q = \Delta P \times C = (P_1 - P_2) \times C, \text{ mm} - \text{CFM}$$

or

$$P_1 = \frac{Q}{C} + P_2, \text{ mm}$$

For a 1300 CFM blower, similar to the Stokes Model 1721, the pumping speed, S, is 840 CFM (see page 6 from Bulletin 518-B). The value of Q can be evaluated the pump itself.

$$Q = P_2 \times S$$

$$= 840 \times .8 = 672 \text{ mm} - \text{CFM}$$

Finally, the total pressure is

$$P_1 = \frac{672}{1108} + .8 = 1.4 \text{ mm}$$

and partial pressure of water

$$P_w = P_1 - P_a = 1.4 - .14 = 1.26 \text{ mm}$$


P. L. Thiel
Development Engineer

STOKES® Vacuum Equipment

Stokes Vacuum Components Department, Pennwalt Corporation
5500 Tabor Road, Philadelphia, Pa. 19120 • 215-289-0100

The Complete Line of High-Performance Mechanical Booster Vacuum Pumps

multi-stage, high-speed mechanical booster pumps give more pumping performance per dollar



**STOKES OFFERS A COMPLETE
LINE OF MECHANICAL BOOSTER
VACUUM PUMPS FOR YOUR
SYSTEM REQUIREMENTS**

Specifications detailed at the right, and the pumping performance curves on page 6 cover the eleven standard models which are most widely used. Stokes Advisory Service is available to help you select the correct model, or to determine the need for special models or modifications to match your requirements.

MODEL NUMBER	1718	1728	1730	1730 MB	1730 HC	1721	1721 MB
Displacement							
1st Stage Blower, cfm							
2nd Stage Blower, cfm	—	—	—	208	—	—	208
Microvac Forepump, cfm	50	80	150	150	300	150	150
Normal Cut-In Pressure, Torr	15	25	30	35	90	15	20
Pressure Limit for Continuous Operation, Torr	5	10	15	15	40	3	3
Drive							
1st Stage, hp	3	3	3	3	3	7½	7½
2nd Stage, hp	—	—	—	3	—	—	2
3rd Stage, hp	2	3	5	5	10	5	
Connections							
Suction Flange	4"	4"	4"	4"	4"	8"	8"
Discharge	1½" IPS	1½" IPS	2" IPS	2" IPS	3" IPS	2" IPS	2" IPS
Water Requirements							
1st Stage, gpm	½	½	½	½	½	½	½
2nd Stage, gpm	—	—	—	Air Cooled	—	—	Air Cooled
Forepump, gpm	Air Cooled	¾	1	1	2	1	1

**Electrical
Characteristics**

Full Controls Set
460V-3-60 Power With Transformer and 115V Control

Oil Requirements							
1st Stage	.8 Pt.	.8 Pt.	.8 Pt.	.8 Pt.	.8 Pt.	5 Pt.	5 Pt.
2nd Stage	—	—	—	.4 Pt.	—	—	4 Pt.
Forepump	1 Gal.	1.5 Gal.	3 Gal.	3 Gal.	12 Gal.	3 Gal.	3 Gal.
Dimensions*							
Height, In.	43	45	49½	49½	58	51½	51½
Height to inlet, In.	26	36	36	36	36	41	41
Length, In.	48½	48½	48½	62	55	54	68
Width, In.	30	30	30	30	41½	38¾	38¾
Shipping Weight, Lb.	1230	1460	1855	2130	2700	3200	3475
Net Weight, Lb.	1080	1300	1685	1960	2485	2700	2975
Shipped in	1 Pc.	1 Pc.	1 Pc.	1 Pc.	1 Pc.	1 Pc.	1 Pc.

*Dimensions are subject to minor changes. Confirm these prior to construction.

Three new series of Mechanical Booster combinations. MB models provide for blank









1722	1722 MB	1722 HC	1721-S	1722-S	1722 HCS	1724	1723	1725	1726	1719	1720	1727	1729
—	310	—	—	—	—	—	—	—	—	—	—	1300	1300
300	300	600	150	300	600	300	300	600	730	600	730	300	300
25	30	75	10	15	60	15	10	10	15	10	15	1st Stage 3.0	1st Stage 2.0
15	15	25	2	8	20	1.0	0.8	1.2	1.3	1.0	1.1	2nd Stage 25.0 0.6	2nd Stage 25.0 0.45
7½	7½	7½	10	10	10	20	25	30	30	40	40	40	50
—	2	—	—	—	—	—	—	—	—	—	—	7½	7½
10	10	2 @ 10	5	10	2 @ 10	10	10	2 @ 10	30	2 @ 10	30	10	10
8"	8"	8"	8"	8"	8"	8"	10"	12"	12"	14"	14"	18"	18"
3" IPS	3" IPS	3" IPS (2)	2" IPS	3" IPS	3" IPS (2)	3" IPS	3" IPS	3" IPS (2)	5" FLG.	3" IPS (2)	5" FLG.	3" IPS	3" IPS
½	½	½	½	½	½	2	2	2	2	2½	2½	3	3
—	—	—	—	—	—	—	—	—	—	—	—	½	½
2	2	4	1	2	4	2	2	4	5	4	5	2	2


Standard On All Models. Pressure Controls Only Are Optional. All NEMA 12.

Circuit Is Standard. 230V-3-60 Power Is Optional for 10 HP Motors or Smaller. Special Arrangements Available.

5 Pt.	5 Pt.	5 Pt.	5 Pt.	5 Pt.	5 Pt.	5¼ Gal.	5¼ Gal.	5¼ Gal.	5¼ Gal.	7¾ Gal.	7¾ Gal.	10¾ Gal.	15 Gal.
—	.4 Pt.	—	—	—	—	—	—	—	—	—	—	5 Pt.	5 Pt.
12 Gal.	12 Gal.	24 Gal.	3 Gal.	12 Gal.	24 Gal.	12 Gal.	12 Gal.	24 Gal.	20 Gal.	24 Gal.	20 Gal.	12 Gal.	12 Gal.
58	58	56	51½	58	56	67	67	67	67	78	78	85	76
41	41	41	41	41	41	50	50	50	50	60	60	63	45
55	69	71	54	55	71	72	72	91	99	102	112	126	122
41½	41½	70	38¾	41½	70	46	50	70	57	70	60	71	118
4000	4275	6000	3300	4100	6100	5750	5900	8700	10,400	10,000	11,700	11,900	15,300
3500	3775	5300	2800	3600	5400	5250	5400	7900	9600	9200	10,900	10,900	13,300
1 Pc.	1 Pc.	2 Pcs.	1 Pc.	1 Pc.	2 Pcs.	1 Pc.	1 Pc.	2 Pcs.	2 Pcs.	2 Pcs.	2 Pcs.	2 Pcs.	2 Pcs.

Pressures in the 10⁻³ range. HC and HCS series provide for faster and pumpdown capability as compared to standard models.





 **PENNWALT**

**EXCLUSIVE
TWO-YEAR
WARRANTY**




STOKES' MICROVAC' PUMPS






WIDE RANGE OF MODELS FOR



Model 146H
30 cfm displacement



Model 148H
50 cfm displacement




Model 149H
80 cfm displacement

SPECIFICATIONS FOR STOKES MICROVAC PUMPS

	Model 146H	Model 148H	Model 149H	Model 212H	Model 412H	Model 612H	Model 912H
Displacement, Cubic Feet per Min.	30	50	80	150	300	600	728
Pump Speed (RPM)	800	610	490	490	490	490	438
Motor (HP)	1½	2		5	10	2-10 HP Motors	30
Motor Speed (RPM)	1800	1800		1800	1800	1800	1800
Pipe Connections: Suction	2" FLG.	1½" FLG.		3" FLG.	6" FLG.	6" FLG.	6" FLG.
Discharge	1¼" NPT	1½" NPT		2" NPT	3" NPT	3" NPT (2)	5" FLG.
Water Inlet	—	—		1" NPT	½" NPT	½" NPT (2)	1" NPT
Water Outlet	—	—		1" NPT	½" NPT	½" NPT (2)	1" NPT
Oil Capacity (Gal.)	½	1¼		3	12	24	20
Net Weight (Lbs.)	315	345		950	1750	3800	5500
Shipping Weight (Lbs.)	390	435		1075	1975	4500	6000
Height	30"	33"		43½"	51½"	55½"	66½"
Floor Space	14¼"x16¼"	17¼"x18¾"		22"x30¼"	22½"x40½"	44¼"x70"	42½"x50½"
Cooling System	Air	Air		Water	Water	Water	Water
Water Consumption (Max.)	—	—		1 GPM	2 GPM	4 GPM	5 GPM

ALL APPLICATIONS



Model 212H
150 cfm displacement






Model 412H
300 cfm displacement



Model 912H
728 cfm displacement

PERFORMANCE CURVES FOR MICROVAC PUMPS






MICROVAC PUMP SELECTION...

The basic functions of a vacuum pump are, first, to remove air from the system until the desired low pressure has been obtained; and second, to maintain this low pressure... i.e., to pump out non-condensable vapors or gases resulting from decomposition, vaporization, air inleakage and other sources. The size of the vacuum pump that is most efficient and economical for a given application depends primarily on five factors:

1. Degree of vacuum required.
2. Size of the system.
3. Nature and quantity of vapors and gases to be handled.
4. Pump-down time.
5. Frequency with which the system is pumped down to operating vacuum.



Typical Problems and Their Solutions


When these factors are properly evaluated, it is relatively simple to select the correct Microvac pump and to obtain a system that operates with minimum attention and maintenance. The pump-down graph given here makes it possible to determine rapidly (1) the size of pump required to exhaust a given volume to a specified vacuum in a given time; or (2) the time required to exhaust a given volume to a specified vacuum, when the pump to be used is already available or installed. The problems that can be solved with the aid of this graph vary widely in nature. However, these typical cases illustrate its basic uses.



Determine the Microvac pump that will evacuate a 350 cubic foot vacuum dryer to a pressure of 5 mm in 10 minutes.

From the pump-down graph, we find that to reach 5 mm, there are 5.6 cubic feet to be pumped for every cubic foot of system. Multiplying this factor (5.6) by the number of cubic feet in the system (350), gives the total cubic feet to be pumped (1960). Dividing this by the time (10 minutes) determines the cubic feet per minute to be pumped (196). Microvac pump Model 412, having a displacement of 300 cubic feet per minute, has ample capacity to perform the job.


$$\frac{5.6 \times 350}{10} = 196 \text{ cfm}$$



How long will it take a Model 149 Microvac pump (displacement 80 cfm) to evacuate a 225 cubic foot impregnating tank to a pressure of 450 microns?

From the pump-down graph, we find that at 450 microns, 9.0 cubic feet must be pumped for every cubic foot of system. Dividing the product of the pump-down factor (9.0) and the volume of the system (225 cubic feet) by the displacement of the Microvac pump (80 cfm) gives the time required, 25.3 minutes.


$$\frac{9.0 \times 225}{80} = 25.3 \text{ min.}$$



Determine the Microvac pump that will evacuate refrigeration units having a total volume of 9 cubic feet to a pressure of 100 μ in 2 minutes.

From the pump-down graph, we find that at 100 μ there are 12.0 cubic feet to be pumped for every cubic foot of system. Multiplying this factor (12.0) by the number of cubic feet in the system (9) gives the total cubic feet to be pumped (108). Dividing this by the time (2) determines the cubic feet per minute to be pumped (54). Microvac pump Model 149, having a displacement of 80 cubic feet per minute, has ample capacity to perform the job.

$$\frac{12.0 \times 9}{2} = 54 \text{ cfm}$$



A vacuum pump must be selected for an altitude test chamber application. The test chamber has a volume of 15 cubic feet and is to be evacuated to 1 mm, raised to 100 mm, and then re-evacuated to 1 mm. The cycling from 100 mm to 1 mm must take place 10 times per hour.

On the assumption that 2 minutes will be required to increase the pressure from 1 mm to 100 mm by controlled air admission, 20 minutes of each hour are used to increase the pressure. This leaves 40 minutes per hour, or 4 minutes per cycle for re-evacuation. From the pump-down graph, we find that 2.12 cubic feet per cubic foot of volume must be pumped to reach 100 mm; and a total of 7.75 cubic feet per foot of volume to reach 1 mm. Subtracting the former from the latter gives the cubic feet to be pumped per cubic foot of system (5.63) to reduce the pressure from 100 mm to 1 mm. Multiplying this by the volume of the tank gives the total cubic feet to be pumped (84.5). Dividing this by the number of minutes in the re-evacuation cycle (4) gives the cubic feet per minute to be pumped as 21.1. Microvac Model 148, having a displacement of 38 cfm, will do the job.

$$7.75 - 2.12 = 5.63$$

$$\frac{5.63 \times 15}{4} = 21.1 \text{ cfm}$$

VACUUM PROBLEMS AND THEIR SOLUTIONS

The formulas, graphs, constants, conversion factors and other data provided on the following pages can be used to solve a wide variety of vacuum problems. These examples illustrate the solutions of some typical ones. In each case, it is assumed that the chamber is clean, dry, empty and leak-free.

13.1 Calculate the net pumping speed of a vacuum system consisting of a Model 212 Microvac pump (displacement 146 cfm) connected to a tank through 30 feet of 3-inch pipe. The system is operating at a pressure of 250 microns.

From the Conductance Chart on page 12, the conductance of the pipe can be calculated using the method described above the chart. This is found to be 334.6 cubic feet per minute.

$$C_{\text{chart}} = 11.6 \text{ cfm}$$

$$C = \frac{11.6 \times 3 \times 250}{26} = 334.6 \text{ cfm}$$

The pumping speed of the Model 212 Microvac pump at 250 microns can be determined from the performance curve on page 7. At this pressure, the pumping speed is 115 cfm. Using the formula on page 11 for the conductance of the vacuum system, the net conductance is determined as follows:

$$\frac{1}{S} = \frac{1}{115} + \frac{1}{334.6}$$

$$S = 86 \text{ cfm}$$

13.2 How long will it take to remove 1.5 pounds of water from a product at an average pressure of 5 mm. using a Stokes 412-H Microvac pump (displacement 300 cfm), assuming that heat input to the drying product is sufficient to maintain the vapor pressure at 5 mm.?

In this case, water is being removed in the form of vapor which will condense in the pump oil and affect the vacuum attainable unless the water is removed. All Microvac pumps have gas ballast to remove water vapor. Assuming that this will prevent oil contamination, proceed with solution.

From chart on page 13 showing the volume of 1 pound of water at various pressures, the volume of 1 pound of water at 5 mm. is 3250 cu. ft. Therefore, 1.5 pounds will have a volume of 4875 cu. ft. at 5 mm. Dividing this by the net speed of the 412-H pump (per performance curve page 7), 265 cfm, time required = 18.3 minutes, assuming piping is adequately sized and disregarding time required to pump down to 5 mm. initially.

$$t = \frac{4875}{265} = 18.3 \text{ min.}$$

At 5 mm., the use of full gas ballast does not affect pumping speed of the 412-H Microvac pump appreciably, and permits handling up to 7 pounds of water per hour. Only 1.5 pounds of water is handled in 18.3 minutes, so the 412-H operating with full gas ballast is satisfactory.

13.3 A vacuum system is found by test to have a leak rate resulting in a pressure rise of 1 mm. Hg per hour. The volume of the vacuum system is known to be 200 cubic feet. How large a pump will be required to maintain a pressure of 100 microns within the system with this leak rate?

The tank volume is 200 cu. ft. and the observed pressure rise is 1000 μ (1 mm.) per hour. This is a mass of 200,000 μ cu. ft. per hour, or 3300 μ cu. ft./min. To handle this at a pressure of 100 μ requires a pump having a net speed at is pressure of 33 cu. ft. per minute.

$$s = \frac{3300\mu \text{ cu. ft./min.}}{100\mu} = 33 \text{ cu. ft./min.}$$

The speed of a 149-H Stokes Microvac pump (displacement 89 cfm) at 100 μ is 51 cfm. Thus, a 149-H pump is entirely adequate.

13.4 In a low-temperature drying system the condenser has a minimum temperature of -45° F. Assuming that a minimum of 10° temperature differential between the product and the condenser surface is required (product temp. \approx 35° F.), what is the minimum pressure at which the product can be dried efficiently?

It will be seen from the vapor pressure and temperature chart on page 13 that at -35° F. the vapor pressure of water is 140 microns. Operating at this pressure will be satisfactory to maintain efficient drying.

13.5 In a vacuum impregnation system it is found necessary to determine whether or not the piping system will seriously affect the pump-down time. The tank has a capacity of 250 cubic feet and is connected to a Stokes 412-H Microvac pump (displacement 300 cfm) by 25 feet of 3" pipe. The final operating pressure is 1 mm.

As can be seen from the formula for the conductance of a vacuum system on page 11, it is obvious that if the conductance of the piping is sufficiently greater than the pumping speed of the pump, it will have no appreciable effect on the net pumping speed of the system. From the conductance chart on page 12, using the conversion factors in the mechanical pump range, the conductance of the piping system can be determined.

$$C_{\text{chart}} = 14 \text{ cfm}$$

$$C = \frac{14 \times 3 \times 1000}{26} = 1615 \text{ cfm}$$

This figure is sufficiently greater than the speed of the pump (260 cfm at 1 mm. from performance curve on page 7) so that it will have only a slight effect on the net pumping speed of the system, as can be seen from the calculation of the net pumping speed.

$$\frac{1}{S} = \frac{1}{260} + \frac{1}{1615}$$

$$S = 223 \text{ cfm}$$

At higher pressures the conductance of the piping would be greatly increased and thus have correspondingly less effect; or if pipe size is increased, the effect also will be less.

13.6 A manufacturer wishes to remove and recover benzene solvent from his final product. Tests show that the final product will discolor if heated above 123° F. The solvent cannot be extracted at atmospheric pressure, for at this pressure a temperature of 176° F. is required. The plant has cooling water available at a maximum summer temperature of 80° F. Under what vacuum conditions should he operate?

The solvent vapors must be condensed with 80° F. cooling water; therefore, it is easily seen from the graph of Boiling Points of Solvents Under Vacuum (page 13) that the vacuum cannot be higher than 26.25 in. Hg. If a vacuum of 22 in. Hg is used, the benzene will boil at 110° F. This is sufficiently below the 123° F. limiting temperature for satisfactory operation and yet high enough to produce a sufficient temperature differential in the condenser; thus the solvent vapors will readily condense.

VACUUM FORMULAS, CONSTANTS AND CONVERSION FACTORS

Rate of flow of air through an orifice.

For air at 20°C in diffusion pump range

$$S = 158A$$

For air at 20°C in mechanical pump range

$$W = \frac{.533 \times C_v \times A \times P_1 \times 60}{\sqrt{R}} = 1.39 A P_1 \text{ pounds per min.}$$

$$S = W \times 13.3 \frac{\text{Pa}}{P_1}$$

.533 = Critical P_R Ratio

A = Sq. in. of orifice

P_a = Atmospheric Pressure—psia

P_1 = P_1 Upstream Pressure—psia

C_v = Orifice Coefficient (Assumed as 1)

$$\sqrt{R} = \sqrt{\text{Degrees Rankine}} = \sqrt{^\circ\text{F} + 460} = 23$$

S = Speed = cu. ft./min @ P_1

Rate of flow of gases through a tube.

$$Q = \frac{4}{3} \sqrt{2\pi} \sqrt{\frac{RT}{M}} \frac{r^3}{L} (P_1 - P_2)$$

Q = Mass flow in micron-liters per second

R = gas constant = 83.1

T = absolute temperature

M = molecular weight

r = inside radius of tube in cm.

L = length of tube in cm.

P_1 = initial pressure microns

P_2 = final pressure microns

From Knudsen's Equation above the following rule-of-thumb equations have been derived for calculating conductance in various pressure ranges of air at 20°C.

(a) Diffusion pump range, where there is molecular flow and when pressure in microns multiplied by diameter in inches is less than 7.

$$C = 13 \frac{D^3 \text{ inches}}{L \text{ (feet)}}$$

(b) Intermediate range, where pressure in microns multiplied by diameter is greater than 7 and less than 220.

$$C = 0.5 \frac{D^4}{L} \bar{P} + 11 \frac{D^3}{L}$$

(c) Mechanical pump range, where pressure times diameter is greater than 220.

$$C = .5 \frac{D^4}{L} \bar{P}$$

C = conductance in c.f.m.

D = diameter in inches

L = length in feet

$$P = \text{Mean pressure in microns} = \frac{P_1 + P_2}{2}$$

P_1 = Upstream pressure in microns

P_2 = Downstream pressure in microns

Conductance of vacuum system

$$\frac{1}{S} = \frac{1}{S_p} + \frac{1}{C}$$

S = Net pumping speed in cfm

S_p = Speed of pump in cfm

C = Conductance of piping in cfm

Calculating "pump-down" time

(Chart on page 8 is derived from this and includes system factors*)

$$T = \frac{V}{S}$$

T = Time in minutes

V = Cubic feet to be pumped to reach final pressure

S = Speed of pump in cfm

$$V = V_0 \log_e \frac{P_0}{P}$$

V = Cubic feet to be pumped to reach final pressure P

V_0 = Volume of system

P_0 = Initial pressure in mm.

P = Final pressure in system in mm.

*Adequate system factors should be included.

Calculation of velocity of molecules

Average velocity

$$\Omega = \sqrt{\frac{8RT}{\pi M}} = 14,551 \sqrt{\frac{T}{M}} \text{ Cm. per sec.}$$

Most probable velocity

$$W = \sqrt{\frac{2RT}{M}} = 12,900 \sqrt{\frac{T}{M}} \text{ Cm. per sec.}$$

Where

R = Gas Constant = 8.315×10^7 ergs per Mole °K

T = Absolute Temperature, °K

M = Molecular weight

Calculation of mean free path

$$L = 8.524 \frac{\eta}{P} \sqrt{\frac{T}{M}} \text{ Cm.}$$

P = Pressure in mm.

η = Viscosity in c.g.s. units

T = Absolute Temperature

M = Molecular weight

Ω = Average velocity

Mass of gas striking unit area per unit time

$$m = 58.32 \times 10^{-3} P \sqrt{\frac{M}{T}} \text{ gm per Cm.}^2 \text{ per sec.}$$

M = Molecular weight

P = Pressure in mm.

T = Absolute Temperature

Conversion factors for "pumping speed" in various units

To convert from	To	Multiply by
Cubic cm./sec.	Cubic ft./min.	0.0021
Liters/sec.	Cubic ft./min.	2.12
Cubic meter/hr.	Cubic ft./min.	0.589
Cubic ft./min.	Liters/sec.	0.4719
Cubic ft./min.	Cubic meter/hr.	1.699

Calculation of velocity of molecules.

1 micron (μ) Hg	= 1 millitorr
1 micron (μ) Hg	= 0.001 mm Hg = 10^{-3} mm Hg
1 micron (μ) Hg	= 1.33 dynes per sq. cm.
1 μ mercury	= 0.000001 mm Hg = 10^{-6} mm Hg
1 μ mercury	= 1.33×10^{-3} dynes per sq. cm.
1 millibar (International)	= 0.75 mm Hg
1 bar (International)	= 750 mm Hg = 29.93 in. Hg
1 millitorr	= 1 micron (μ) Hg
1 millimeter Hg	= 1 Torr
1 millimeter Hg	= 1000 microns = 10^3 microns
1 millimeter Hg	= 1333 dynes per sq. cm.
1 millimeter Hg	= 1.33 millibar
1 millimeter Hg	= 0.0013 bar
1 millimeter Hg	= 0.03937 in. Hg
1 millimeter Hg	= 0.01934 lbs. per sq. inch
750 millimeters Hg	= 10^6 dynes per sq. cm. = 1 megabar
(All at 0°C., and g = 980.6)	
1 inch Hg @ 32°F.	= 0.4912 lbs. per sq. inch
1 inch Hg @ 58.4°F.	= 0.4898 lbs. per sq. inch
29.921 inches Hg @ 32°F.	= 14.696 lbs. per sq. inch = 760 mm Hg
30.000 inches Hg @ 58.4°F.	= 14.696 lbs. per sq. inch = 762 mm Hg
1 atmosphere	= 760 mm Hg = 14.7 lbs. per sq. inch
1 lb. per sq. inch	= 2.036 in. Hg @ 32°F. = 51.72 mm Hg
1 lb. per sq. inch	= 2.041 in. Hg @ 58.4°F. = 51.85 mm Hg
1 bar (England)	= 10 ⁶ dynes per sq. cm. = 750 mm Hg
1 microbar (England)	= 1 dyne per sq. cm.
1 microbar (England)	= 0.00075 mm = $.75 \times 10^{-3}$ mm Hg
1 bar or harye	= 0.00075 mm = $.75 \times 10^{-3}$ mm Hg
1 Torr	= 1 millimeter Hg

CONDUCTANCE OF PIPES FOR AIR FLOW

This graph can be used to determine the conductance of a pipe in the diffusion pump range. In the intermediate range, use formula (b) on page 11. In the mechanical pump range, the conductance can be calculated by determining the conductance from the graph and multiplying it by the diameter of the pipe in inches and the pressure in microns divided by 26.

$$C = \frac{C_{\text{chart}} \times d \times p}{26}$$

EXAMPLE

Calculate the conductance of a 1" pipe 25 feet long at 1 mm. The conductance from the graph is .52 cfm. Multiplying this by the diameter (1") and the pressure in microns (1000) and dividing by 26 gives a conductance of approximately 20 cubic feet per minute.

$$C_{\text{chart}} = 0.52 \text{ cfm}$$


$$C = \frac{0.52 \times 1 \times 1000}{26} = 20 \text{ cfm}$$

Calculate the conductance of a 3" pipe 40 feet long at 160 μ . The conductance from the graph is 9 cfm. Multiplying this by the diameter (3") and the pressure in microns (160) and dividing by 26 gives a conductance of approx. 166 cfm.

$$C_{\text{chart}} = 9.0 \text{ cfm}$$


$$C = \frac{9.0 \times 3 \times 160}{26} = 166 \text{ cfm}$$

For other examples using the conductance chart, see page 10.




VAPOR PRESSURE OF WATER AT VARIOUS TEMPERATURES

BOILING POINTS OF SOLVENTS UNDER VACUUM



VOLUME OF POUND OF WATER VAPOR UNDER VACUUM at 20° C.



TEMPERATURE C°	TEMPERATURE F°	PRESSURE OR VACUUM
200		
190	380	200
180	360	150
170	340	100
160	320	
150	300	50
140	280	40
130	260	30
120	240	20
110	220	10
100	200	0
90	180	5
80	160	10
70	140	20
60	120	23
50	100	25
40	80	27
30	60	28
20	40	29
10	30	29.5
0	20	29.8
-10	10	3,000
-20	0	1,000
-30		500
-40		200
-50		100
-60		50
-70		20
-80		5
-90		2
-100		0.5
-110		0.1
-120		0.02
-130		
-140		
-150		

PRESSURE
POUNDS PER
SQUARE INCH
GAGE

VACUUM
INCHES
MERCURY

ABSOLUTE
PRESSURE
IN MICRONS
MERCURY

APPENDIX E

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

WESTINGHOUSE ELECTRIC CORPORATION
LARGE POWER TRANSFORMER DIVISION

TRANSFORMER OIL TEST REPORT

Customer: VEPCO
Location: North Anna #1
Sample I.D.: McGraw #1 GSU Lab No.: 146, 147

G.O.: _____
Transformer Shop Order: _____
Transformer Serial No.: C-0-6459-5-1

Dielectric Strength, KV

DISC Electrode:

VDE Electrode:

Power Factor, % 60 Hz @ 25°C:

Interfacial Tension Dynes Per CM:

Neutralization Number, KOH Per Gram:

Color:

Moisture Content, PPM:

TOP BOTTOM

0.0112 0.0086

39.0 39.8

5.5 6.1

I hereby certify the above report is a time record taken from laboratory tests in accordance with current Westinghouse and/or ASTM methods.

P. V. Oommen 1-14-83
Engineer Date

E. M. Polina 1-17-83
Manager Date

0026S

WESTINGHOUSE ELECTRIC CORPORATION
LARGE POWER TRANSFORMER DIVISION
TRANSFORMER GAS-IN-OIL ANALYSIS REPORT

Customer: VEPCO
Location: North Anna #1
Sample I.D.: McGraw #1 GSW Lab No.: _____

G.O.: _____
Transformer Shop Order: _____
Transformer Serial No.: C-0-6459-5-1

Gas	Date Sampled:		TOP		BOTTOM	
			PPM GAS IN OIL		PPM GAS IN OIL	PPM GAS IN OIL
Nitrogen, N ₂			<u>21657 (91%)</u>		<u>11363 (98%)</u>	_____
Oxygen, O ₂			<u>2112 (9%)</u>		<u>275 (2%)</u>	_____
Carbon Dioxide, CO ₂			<u>75</u>		<u>67</u>	_____
*Carbon Monoxide, CO			<u>16</u>		<u>15</u>	_____
*Hydrogen, H ₂			<u>1</u>		<u>1</u>	_____
*Methane, CH ₄			<u>2</u>		<u>2</u>	_____
*Ethane, C ₂ H ₆			<u>1</u>		<u>1</u>	_____
*Ethylene, C ₂ H ₄			<u>0</u>		<u>0</u>	_____
*Acetylene			<u>0</u>		<u>0</u>	_____
Other:			_____		_____	_____
*Total Combustibles			<u>20</u>		<u>19</u>	_____
Total Gas In Oil (Note: 1% = 10,000 PPM)			<u>2.39</u> %		<u>1.17</u> %	_____ %

Remarks:

I hereby certify the above report is a true record taken from laboratory tests in accordance with current Westinghouse and/or ASTM methods.

T. V. Oommen 1-14-83
Engineer Date

S. P. Quinn 1-17-83
Manager Date

0025S

WESTINGHOUSE ELECTRIC CORPORATION
LARGE POWER TRANSFORMER DIVISION

TRANSFORMER OIL TEST REPORT

Customer: VEPCO
Location: North Anna #1
Sample I.D.: WH #1 GSU Lab No.: CS-148
149

G.O.: _____
Transformer Shop Order: HAM707
Transformer Serial No.: 7001965

Dielectric Strength, KV
DISC Electrode:
VDE Electrode:

TOP BOTTOM

Power Factor, % 60 Hz @ 25°C:

0.0090 0.0075

Interfacial Tension Dynes Per CM:

39.0 40.1

Neutralization Number, KOH Per Gram:

Color:

Moisture Content, PPM:

5.1 6.8

I hereby certify the above report is a true record taken from laboratory tests in accordance with current Westinghouse and/or ASTM methods.

T. V. Oommen 1-14-83
Engineer Date

S. W. P. P. P. 1-17-83
Manager Date

0026S

TRANSFORMER GAS ANALYSIS REPORT

TRANSFORMER I.D.: S.O. IX / S/N 7021885

LAB # 3-195

SAMPLE SUPPLIER: VERCOIL, ANNA, UNIT #2

DATE SAMPLED: 1-20-87

SAMPLE I.D.: BOITON
BEFORE/AFTER TEMP RUN
OTHER

DATE ANALYZED 1-20-87

	<u>GAS</u>	<u>PPM GAS</u> <u>IN OIL</u>
H ₂	HYDROGEN	2.0
O ₂	OXYGEN	620.0
N ₂	NITROGEN	9522.0
CH ₄	METHANE	2.0
CO	CARBON MONOXIDE	14.0
CO ₂	CARBON DIOXIDE	155.0
C ₂ H ₄	ETHYLENE	2.0
C ₂ H ₆	ETHANE	1.0
C ₂ H ₂	ACETYLENE	.
C ₃	PROPANE/ACRYLENE	2.0
OTHER		
	TOTAL	10100.0

COLLECTING LAB

ANALYST

TOTAL PPM IN OIL 10100
 TO PPM IN GAS 22.0

APPENDIX F

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

237

	HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG.		X REF. 3204	
	H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	REPORT No.	REMARKS										
SAMPLE DATE: 10-15-81 C 7044 SYRINGE No. TEST DATE: 10-15-81	0	6	2	10	560	1	0	82,579	19	0.00	505A	Resample 1 year										
SAMPLE DATE: 11-6-81 Y 9435 SYRINGE No. TEST DATE: 11-16-81	3	14	29	10	610	2	0	93,412	62	0.03	512C	Resample 1 year.										
SAMPLE DATE: 12-21-81 704 SYRINGE No. TEST DATE: 12-21-81	0	9	23	11	690	2	0	95,935	45	0.02	527A	Resample 1 year										
SAMPLE DATE: 1-25-82 B. 6834 SYRINGE No. TEST DATE: 2-1-82	14	11	30	12	570	4	0	95,041	71	0.05	533B	Resample 1 year										
SAMPLE DATE: 3-9-82 3 3359 SYRINGE No. TEST DATE: 4-7-82	0	8	16	95	520	3	0	92,542	122	.02	544B	Resample 1 year										
SAMPLE DATE: 4-2-82 5-3456 SYRINGE No. TEST DATE: 6-11-82	0	7	23	9	380	4	0	82,923	43	0.02	557E	Resample 1 yr.										
SAMPLE DATE: 6-28-82 B. 3079 SYRINGE No. TEST DATE: 8-23-82	0	5	10	5	210	2	0	50,232	22	.02	580B	Resample 1 year.										
SAMPLE DATE: 8-23-82 D903 SYRINGE No. TEST DATE:	1	8	29	12	580	4	0	102,334	54	0.3	595											
COLOR											PCB (PPM)											
DATE											DATE											
DIE - by 877/1816											WATER CONTENT (PPM)	19	2.56									
DATE											DATE	12/11/81	3/4/82									
I.F.T.											METALLIC ANALYSIS											
DATE											DATE											
NEUT. No											POWER FACTOR %											
DATE											DATE											

North Anna GS2A											
	HYDROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	TOTAL GAS CONTENT	COMBUSTIBLE GAS CONTENT	ESTIMATED TCG	X REF. 3204
	H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	MFG. WH
											S/N- 700 20 99
											LOCATION North Anna GS
											REPORT No - REMARKS
12-1-80 N 8670 12-2-80	3200	980	150	50	220	720	860	108,960	5960	5.44	(393G) Resample 1 year 12-2-81
12-2-80	Post Mortem To be repaired HAW.										
12-2-80	Returned from Factory to North Anna - Replacing failure on GS2 "C"										
1-2-81 2-1-81 8-12-81	0	0	7	0	81	0	0	18,088	7	.03	TOP 494 Resample 3 mo.
8-12-81 Y 9423 9-12-81	0	0	2	0	49	0	0	8151	2	.02%	BOTTOM 484A - Resample 3 months
8-10-81 17164 9-1-81	-	-	7	-	90	-	-	2.0%	7		Visco Lab.
8-12-81 Y 126 9-12-81	-	-	-	-	-	-	-	6.4%	-	-	Visco Lab.
8-9-81 13771 9-10-81	0	7	48	34	413	6	0	82,942	95	.01%	Visco Lab.
9-10-81 13771 9-21-81	0	9	55	12	640	1	0	111,867	77	0.04	497 Resample 6 mo.
COLOR								PCD (PPM)			
DATE								DATE			
DIE - 34 01/10/81 42								WATER CONTENT (PPM)	11	21	
DATE 9/19/81								DATE	12/2/80	4/12/81	
I.F.T. 46.0								METALLIC ANALYSIS			
DATE 9/18/81								DATE			
NEUT No .028								POWER FACTOR %			
DATE 9/18/81								DATE			

Visco Lab.
Visco Lab.
Visco Lab.
200

247

GALLONS OF OIL	ATMOSEAL YES NO	HYDROGEN	OXYGEN	NITROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	COMBUSTIBLE GAS CONTENT	ESTIMATED T.C.B.	3174	
		H ₂	O ₂	N ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	%	REPORT No. - REMARKS	LOCATION NA #1 BGS
10-7-82		0	2500	6500	2	35	3	700	2	0	66242 42	0.04	604 E	Resample 1 year.
11-16-82		17	4765	70650	N/D	32	N/D	552	N/D	N/D	76016 49		G218	
11-17-82		6	1541	485	N/D	24	N/D	372	N/D	N/D	50522 30		G223	
11-17-82		175	7385	925	N/D	49	N/D	N/D	N/D	N/D	999278 224		G225	
11-29-82		3	2368	8110	N/D	N/D	8	8	N/D	N/D	10494 11		G232	
11-29-82		N/D	866	3178	N/D	2	N/D	N/D	N/D	N/D	4046 2		G236	
11-30-82		BEFORE CORONA Test - TOP												
11-30-82		BEFORE CORONA Test - TOP												
11-30-82		BEFORE CORONA Test Bottom												

COLOR	DATE	ONE-TO	DATE	I.P.T.	DATE	HEUT. No.	DATE	PCB (PPM)	DATE	WATER CONTENT (PPM)	DATE	METALLIC ANALYSIS	DATE	POWER FACTOR %/100 ²	DATE
AS	10/6/82	47/34	10/6/82	41	10/6/82	20.01	10/6/82			15	10/6/82	3942	10/11/82	0.54	10/6/82

		HYDROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	TOTAL GAS CONTENT	COMBUSTIBLE GAS CONTENT	ESTIMATED TCG	X REF. 3174	
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	MFGR: 2214	
		S/N-7001994											
		LOCATION: 10A 5501B											
		REPORT No. - REMARKS											
TOP	10-5-81 SAMPLE DATE: T3771 SYRINGE No. 10-19-81 TEST DATE	22	13	11	9	5000	30	0	102,585	85	0.05	506B	Resample 1 year
Bottom	10-5-81 SAMPLE DATE: K 97114 SYRINGE No. 10-15-81 TEST DATE	12	15	0	10	5100	35	0	106,132	72	0.03	505C	Resample 1 year
	11-6-81 SAMPLE DATE: R 4949 SYRINGE No. 11-16-81 TEST DATE	11	12	1	7	3900	26	0	105,357	57	0.02	512	Resample 1 year.
	12-21-81 SAMPLE DATE: Z 8578 SYRINGE No. 12-21-81 TEST DATE	0	16	0	9	4400	35	0	105060	60	0.01	527B	Resample 1 year.
	1-25-82 SAMPLE DATE: X-9975 SYRINGE No. 2-1-82 TEST DATE	6	11	1	7	2900	25	0	79,050	50	0.02	533D	Resample 1 year
	3-9-82 SAMPLE DATE: T 9337 SYRINGE No. 3-9-82 TEST DATE	0	11	0	6	3000	24	0	88041	41	.00	544A	Resample 1 year
	4-2-82 SAMPLE DATE: V-0126 SYRINGE No. 4-2-82 TEST DATE	0	13	0	8	3700	28	0	100,249	49	0.00	557-C	Resample 1 year
	6-11-82 SAMPLE DATE: X 2942 SYRINGE No. 6-28-82 TEST DATE	0	8	1	5	1900	18	0	60,432	32	.01	580C	Resample 1 year.
COLOR										PCB (PPM)			
DATE										DATE			
DIE -rv 877 1816										WATER CONTENT (PPM)		9 18 8	
DATE										DATE		10/8/81 10/8/81 10/11/81	
I.F.T.										METALLIC ANALYSIS		514	
DATE										DATE		10/8/81	
NEUT. No										POWER FACTOR %			
DATE										DATE			

		HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF: 3174	
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM		PPM	%											
SAMPLE DATE	V 4195	2	10	0	8	2300	22	0	95,542		42	0.01	(408C) Resample 1 year										
SYRINGE NO.																							
TEST DATE	1-30-81																						
SAMPLE DATE	2-18-81																						
SYRINGE NO.	A-9997	0	9	8	7	1700	21	0	75,145		45	0.01	(425F) Resample 1 year - 2-18-82										
TEST DATE	3-10-81																						
SAMPLE DATE	3-19-81																						
SYRINGE NO.	A 9094	17	0	4	7	1500	18	0	75,155		52	0.05	(435F) Resample 1 year										
TEST DATE	4-1-81																						
SAMPLE DATE	5-3-81																						
SYRINGE NO.	53484																						
TEST DATE	3-20-81																						
SAMPLE DATE	3-20-81																						
SYRINGE NO.	D 2448	0	12	0	9	4000	28	0	106,649		49	0.00	(434B) Resample 1 year										
TEST DATE	3-21-81																						
SAMPLE DATE	4-12-81																						
SYRINGE NO.	E 5830	60	26	21	38	5700	50	1	117,596		196	0.111	465C Resample 1 year										
TEST DATE	6-30-81																						
SAMPLE DATE	6-12-81																						
SYRINGE NO.	V 6006	27	27	38	47	9310	41	N/D	88%		180												
TEST DATE	7-4-81																						
SAMPLE DATE	9-10-81																						
SYRINGE NO.	Y 9990	19	17	15	11	5300	36	1	106,799		99	0.05	497A Resample 1 year										
TEST DATE	9-2-81																						
COLOR																							
DATE	12/18/81																						
DIE - by	R/T																						
DATE	6/30/81																						
I.F.T.	452																						
DATE	6/30/81																						
NEUT No	0.53																						
DATE	6/30/81																						
PCD (PPM)																							
DATE																							
WATER CONTENT (PPM)																							
DATE																							
METALLIC ANALYSIS																							
DATE																							
POWER FACTOR %																							
DATE																							

GALLONS OF OIL	ATMOSEAL YES NO	ESTIMATED T.C.B.											COMBUSTIBLE GAS CONTENT %	REPORT No.-REMARKS
		H ₂	O ₂	N ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	ACETYLENE	PPM		
SAMPLE DATE 8-27-82		BOTTOM												G139
SYRINGE No. V5097		N/D	2553	888	0	5	0	400	0	0	91765	5		
OIL TEMP														
TEST DATE 8-27-82														
SAMPLE DATE 8-27-82		TOP												G127
SYRINGE No. V5354		N/D	1924	564	N/D	N/D	N/D	299	N/D	N/D	59022	0		
OIL TEMP		Small air bubbles diff. gas in bottle.												
TEST DATE 8-27-82														
SAMPLE DATE 10-7-82		0	2100	97000	7	15	9	1300	1	0	100,432	0.01	604 f	Resample 1 year
SYRINGE No. T-5746											32			
OIL TEMP 60°C														
TEST DATE 10-7-82														
SAMPLE DATE 12-27-82		0	650	110,000	3	0	6	1100	0	0	111,759	0.00	621	Resample 1 year
SYRINGE No. M-0769											9			
OIL TEMP 45°C														
TEST DATE 1-7-83														
SAMPLE DATE														
SYRINGE No.														
OIL TEMP														
TEST DATE														
SAMPLE DATE														
SYRINGE No.														
OIL TEMP														
TEST DATE														
SAMPLE DATE														
SYRINGE No.														
OIL TEMP														
TEST DATE														
COLOR														
DATE														
ONE-WAY														
DATE														
I.P.T.														
DATE														
TEST. No.														

Doble

GALLONS OF OIL	ATMOSEAL YES NO	H ₂	O ₂	N ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	ACETYLENE	COMBUSTIBLE GAS CONTENT	ESTIMATED T.C.B.	REPORT No. - REMARKS
SAMPLE DATE: 2-22-82														
SYNTHESIS NO: 79291		0	1200	85000	1	0	3	630	0	0	86,834/4	0.00	544E	Resample 1 year
OIL TEMP: 210°C														
TEST DATE: 3-9-82														
SAMPLE DATE: 4-7-82		0	2000	80000	1	0	2	410	0	0	82413/3	0.00	557B	Resample 1 year
SYNTHESIS NO: 50296														
OIL TEMP: 40°C														
TEST DATE: 4-23-82														
SAMPLE DATE: 6-11-82		0	2100	98000	0	0	2	360	0	0	100,462/2	.00	580F	Resample 1 year
SYNTHESIS NO: 5385														
OIL TEMP: 37°C														
TEST DATE: 6-22-82														
SAMPLE DATE: 8-23-82		0	1000	95000	1	0	2	580	0	0	96,583/3	0	595C	
SYNTHESIS NO: N1073														
OIL TEMP: 37°C														
TEST DATE: 8-23-82														
SAMPLE DATE: 1-23-82		0	1200	94000	2	0	2	590	0	0	95,794/4	0	595B.	
SYNTHESIS NO: D606														
OIL TEMP: 37°C														
TEST DATE: 2-23-82														
SAMPLE DATE: 4-23-82		N/D	1934	56000	N/D	N/D	N/D	299	N/D	N/D	59022			
SYNTHESIS NO: 10000														
OIL TEMP: 37°C														
TEST DATE: 8-23-82														
SAMPLE DATE: 8-23-82		N/D	1385	69000	N/D	N/D	N/D	371	N/D	N/D	71622/0			
SYNTHESIS NO: N1077														
OIL TEMP: 37°C														
TEST DATE: 8-23-82														
SAMPLE DATE: 1-23-82		34	11553	78000	0	8	0	280	0	0	90229/42		G138	
SYNTHESIS NO: A0553														
OIL TEMP: 37°C														
TEST DATE: 8-23-82														
COLOR														
DATE														
ONE-WAY														
DATE														
I.P.T.														
DATE														
NEUT. NO.														
DATE														
PCB (PPM)														
DATE														
WATER CONTENT (PPM)														
DATE														
METALLIC ANALYSIS														
DATE														
POWER FACTOR %														
DATE														

Asks

Cells

Hydro

Hydro

Hydro

	HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF. 3172	
	H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM		PPM	%										MFG. WH	
																					SIN-7001993	
																					LOCATION: N.A. GS2A	
																					REPORT No. - REMARKS	
8-6-81 SAMPLE DATE: U7309 SYRINGE No.	0	2	1	3	65	0	0	811181	23,961	6	.01	483C	Resample 1 month									
6-12-81 SAMPLE DATE: W8694 SYRINGE No.	17	20	50	N/D	3948	10	N/D	7.2%	97				12 per lb.									
7-29-81 TEST DATE: P. 19-81 SAMPLE DATE:	14	6	15	34	341	13	0	83,779	78	.0170			12 per lb.									
9-16-81 TEST DATE: 9-16-81 SAMPLE DATE:	0	4	8	5	860	0	0	100,857	17	0.01	497C	Resample 1 year.										
10-7-81 SAMPLE DATE: F1584 SYRINGE No.	0	3	0	4	920	0	0	96,027	7	0.00	505B	Resample 1 year										
10-16-81 TEST DATE: 11-6-81 SAMPLE DATE:	0	2	0	3	730	0	0	85,135	5	0.00	512A	Resample 1 year.										
11-16-81 TEST DATE: 12-19-81 SAMPLE DATE:	0	3	0	4	840	7	0	102,354	14	0.00	527C	Resample 1 year.										
1-25-82 SAMPLE DATE: W8196 SYRINGE No.	0	20	0	2	640	0	0	91044	4	0.00	533C	Resample 1 year										
2-1-82 TEST DATE:																						
COLOR	L1.0										PCB (PPM)											
DATE	7/6/81										DATE											
DIE - by 872/815	5/41										WATER CONTENT (PPM) 35 16 5											
DATE	7/30/81										DATE 7/30/81 9/2/81 7/1/81											
I.F.T.	37										METALLIC ANALYSIS											
DATE	7/2/81										DATE											
NEUT. No	20.01										POWER FACTOR % 25C 0.019											
DATE	7/3/81										DATE 7/30/81											

2nd test before
3 after
5 after
6 after
dist.

1/2 in
1/2 in
1/2 in

		HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED ICG		X REF. 3172			
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%											MFGN. WH			
		S/N - 7001993																							
		LOCATION - NAGS2A																							
		REPORT No. - REMARKS																							
SAMPLE DATE: 7-14-81		By phone 7-14-81																							
SYRINGE No. T9241		0	3	14	0	150	2	0	17509	19	.06	466A Resample 1 year													
TEST DATE: 7-30-81		pcl - < 5 ppm - Beahm Lab.																							
SAMPLE DATE: 7-30-81		Hold 100% pure content																							
SYRINGE No. 7-30-81		0	1	0	1	81	0	0	10483	2	.000	474A Resample 1 mo.													
TEST DATE: 7-30-81																									
SAMPLE DATE: 7-30-81		Hold 100% pure content																							
SYRINGE No. 7-30-81		0	2	2	1	57	0	0	18762	5	.001	474B Resample 1 month													
TEST DATE: 7-30-81																									
SAMPLE DATE: 7-30-81		C/L																							
SYRINGE No. 7-30-81																									
TEST DATE: 7-30-81		C/L																							
SAMPLE DATE: 7-30-81																									
SYRINGE No. 7-30-81																									
TEST DATE: 7-30-81																									
SAMPLE DATE: 8-6-81		Rush By phone 8/11/81																							
SYRINGE No. S9964		0	2	6	2	110	2	0	28,422	12	.02	TOP Resample 483A 1 month													
TEST DATE: 8-11-81																									
SAMPLE DATE: 8-6-81		Rush By phone 8/11/81																							
SYRINGE No. V4598		0	2	5	2	160	2	0	29,971	11	.019	TOP Resample 483 1 mo.													
TEST DATE: 8-11-81																									
SAMPLE DATE: 8-6-81		Rush By phone 8/11/81																							
SYRINGE No. X9945		0	2	6	3	68	0	0	26,174	6	.019	BOTTOM Resample 483B 1 month													
TEST DATE: 8-11-81																									
COLOR																				PCB (PPM)		< 5			
DATE																				DATE		7-2-81			
DIE - by 872		41																		WATER CONTENT (PPM)		9 15 5			
DATE		9/18/81																		DATE		7/7/81 7/7/81 7/7/81			
I.F.T.		46.0																		METALLIC ANALYSIS					
DATE		9/19/81																		DATE					
NEUT. No		0228																		POWER FACTOR %					
DATE		9/18/81																		DATE					

TAKEN
Before
AND
AFTER
GE OVER
10kVage
Test

H ₂		CH ₄		CO		C ₂ H ₆		CO ₂		C ₂ H ₄		C ₂ H ₂		PPM		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF. 3172	
HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		PPM		PPM		%		MFG. CCH		S/N-7001993	
H ₂		CH ₄		CO		C ₂ H ₆		CO ₂		C ₂ H ₄		C ₂ H ₂		PPM		PPM		%		LOCATION N. A		G52A	
REPORT No. - REMARKS																							
9-18-80																							
K 2729		14	9	150	11	770	6	0	75,160	190	0.18	(371E) Resample 1 yr 9-18-81. (8% alk)											
SYRINGE No.																							
TEST DATE		Moved to Pos. G52A following failure of 7002099 PCB - types del.																					
12-16-80																							
S 9603		5	4	49	3	800	5	0	80,866	66	0.06	(399E) Resample 1 yr 12-16-80 (51% alk)											
SYRINGE No.																							
TEST DATE																							
1-22-81																							
A 9997		0	10	42	4	1000	6	0	98,962	62	0.03	(408B) Resample 1 year - 1/22/81											
SYRINGE No.																							
TEST DATE																							
2-18-81																							
W 8939		7	9	55	5	1200	5	0	89,781	81	0.06	(425E) Resample 1 year 2/18/82 8% alk											
SYRINGE No.																							
TEST DATE																							
3-10-81																							
A 9293		20	10	58	6	1400	7	0	99,301	101	0.08	(437A) Resample 1 year											
SYRINGE No.																							
TEST DATE																							
4-1-81																							
SYRINGE No.																							
TEST DATE																							
5-19-81																							
Z 1902		0	6	41	4	1400	4	0	69,655	55	0.05	459A - Resample 1 year. 5-19-82											
SYRINGE No.																							
TEST DATE																							
6-30-81																							
R-6853		17	10	43	6	3000	5	0	99,181	81	0.06	465I Resample 1 year											
SYRINGE No.																							
TEST DATE																							
COLOR																							
DATE																							
DIE -rv 877																							
DATE																							
I.F.T.																							
DATE																							
NEUT. No																							
DATE																							
PCB (PPM)																							
DATE																							
WATER CONTENT (PPM)																							
DATE																							
METALLIC ANALYSIS																							
DATE																							
POWER FACTOR %																							
DATE																							

[illegible]

		HYDROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	TOTAL GAS CONTENT	COMBUSTIBLE GAS CONTENT	ESTIMATED TCG	X REF. 3175
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	MFGR: 2014
												S/N- 7001995
												LOCATION: 114 G51C
												REPORT No. - REMARKS
10P	SAMPLE DATE: 7-7-82 SYRINGE No. 42 TEST DATE: 10-19-81	17	20	7	4400	22	0	103,808	108	0.09	506C	Resample 1 year
7501901	SAMPLE DATE: 8-7-82 SYRINGE No. 31 TEST DATE: 10-19-81	16	2	8	3900	19	0	99,576	76	0.06	506A	Resample 1 year
	SAMPLE DATE: 11-6-81 SYRINGE No. N 8233 TEST DATE: 11-16-81	19	19	0	7	3700	24	0	106,669	69	0.04	512E Resample 1 year.
	SAMPLE DATE: 12-21-81 SYRINGE No. T 9192 TEST DATE: 12-21-81	15	16	1	6	3200	21	0	96,459	59	0.03	527D Resample 1 year.
	SAMPLE DATE: 1-25-82 SYRINGE No. W 9623 TEST DATE: 2-1-82	18	20	11	8	3300	27	0	98,184	84	0.05	533A Resample 1 year.
	SAMPLE DATE: 2-22-82 SYRINGE No. C 0919 TEST DATE: 3-4-82	12	19	1	7	3200	23	0	104,962	62	0.03	544D Resample 1 year.
	SAMPLE DATE: 4-7-82 SYRINGE No. S-0450 TEST DATE: 4-2-82	17	17	11	7	3300	19	0	86,371	71	0.05	557D Resample 1 year.
	SAMPLE DATE: 6-11-82 SYRINGE No. D-095 TEST DATE: 6-28-82	15	20	2	8	2800	25	0	95,470	70	0.04	580D Resample 1 year.
COLOR										PCB (PPM)		
DATE										DATE		
DIE - by 877 1916										WATER CONTENT (PPM)		59 29
DATE										DATE		10/8/81 10/8/81 12/11/81
I.F.T.										METALLIC ANALYSIS		H/C 30 514
DATE										DATE		10/20/81 10/22/81
WEUT. No										POWER FACTOR %		
DATE										DATE		

	H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	TOTAL GAS CONTENT	PPM	COMBUSTIBLE GAS CONTENT	%	ESTIMATED TCG.	X REF. 3175
														MFGRI. WH
														S/N-7001995
														LOCATION N.A.-G5IC
														REPORT No -REMARKS
1-22-81 SAMPLE DATE B7289 SYRINGE NO	12	8	12	4	1200	7	0	97,043	43	.03	(408E) Resample 1 year 1.22-82			
1-30-81 TEST DATE														
2-18-81 SAMPLE DATE A14676 SYRINGE NO	19	8	8	3	940	6	0	73,784	44	0.05	(425D) Resample 1 year - 2-18-82 8#OK			
3-10-81 TEST DATE														
3-19-81 SAMPLE DATE W8879 SYRINGE NO	0	8	7	4	850	7	0	66,776	26	0.01	(436E) Resample 1 year			
4-1-81 TEST DATE														
5-31-81 SAMPLE DATE N/A SYRINGE NO														
TEST DATE														
3-1-81 SAMPLE DATE Y9291 SYRINGE NO	By PHONE	12	18	7	3000	16	0	104,162	62	0.03	(434) Resample 1 yr 3-30-82			
3-21-81 TEST DATE														
6-12-81 SAMPLE DATE X-9911 SYRINGE NO	72	16	30	9	4400	19	1	106,147	147	0.14	465-A Resample 1 year. 6-12-82			
6-30-81 TEST DATE														
6-12-81 SAMPLE DATE T7167 SYRINGE NO	34	27	36	9	5650	17	N/O	8.8%	123					
7-29-81 TEST DATE														
9-10-81 SAMPLE DATE K7190 SYRINGE NO	39	19	22	8	4500	21	0	-115,909	109	0.08	467-D Resample 1 year			
9-21-81 TEST DATE	(0	15.5	6.7	5.5	4587	25	0	(wet)						
COLOR									PCB (PPM)					
DATE									DATE					
DIE - sv BIC 43	/	/	/	/	/	/	/		WATER CONTENT (PPM)					
DATE 9/18/81									DATE					
I.F.Y. H.O									METALLIC ANALYSIS					
DATE 9/18/81									DATE					
NEUT NG .028									POWER FACTOR %					
DATE 9/18/81									DATE					

HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG.		X REP. 3175	
H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	REPORT No. - REMARKS											
19	5	0	3	1300	2	0	112,929	29	.02	(386J)											
22	21	11	15	1300	6	0	113,875	75	0.04	(314J) Resample 1 yr. 11/80											
23	9	0	8	1500	10	0	99,050	50	0.05	(348J) Resample 1 yr 5-81 (2wk)											
25	10	22	5	2200	9	0	106,471	71	.06	(371A) Resample 1 yr 9-19-81 (38 wk)											
23	10	15	4	2300	8	0	95,860	60	0.06	(381A) Resample 1 yr 10-16-81 (42 wk)											
<p><i>Page 2</i></p> <p><i>Lab closed - some test sent to</i></p>																					
12	12	21	6	2100	9	0	129,960	60	0.03	(392C) Resample 1 yr 11-26-81											
40	11	14	5	2000	10	0	92,777	77	0.08	(399A) Resample 1 yr 12-16-80 - 51 wk.											

COLOR	1	PCB (PPM)	<5
DATE	4/10/81	DATE	11/12/80
DIE - NV 877	47/32 41	WATER CONTENT (PPM)	8
DATE	10/10/80 6/10/81	DATE	11/20/80
I.F.T.	452	METALLIC ANALYSIS	371H
DATE	4/30/81	DATE	9/19/80
NEUT. No	1025	POWER FACTOR %	.065 .03
DATE	4/30/81	DATE	10/6/80 1/30/81

[illegible]

GALLONS OIL	A/M SEAL YES NO	HYDROGEN H ₂	OXYGEN O ₂	NITROGEN N ₂	METHANE CH ₄	CARBON MONOXIDE CO	ETHANE C ₂ H ₆	CARBON DIOXIDE CO ₂	ETHYLENE C ₂ H ₄	ACETYLENE C ₂ H ₂	COMBUSTIBLE GAS CONTENT PPM	ESTIMATED T.C.G. %	X REF: 373		
													REPORT NO.	REMARKS	
12-3-82		200 -	After Test												
SYNTHESIS NO.		ND	2726	11 3/6	ND	4	3	ND	ND	ND	13969				G250
OIL TEMP											7				
TEST DATE															
12-3-82		Bottom -	After Corona Test												
SYNTHESIS NO.		ND	1585	64 7/8	1	2	ND	3	ND	ND	8069				G249
OIL TEMP											3				
TEST DATE															
12-3-82		Bottom -	After 1" B" failure												
SYNTHESIS NO.		ND	3426	98 6/7	2	12	N/D	21	N/D	N/D	13328				G243
OIL TEMP											14				
TEST DATE															
12-6-82		Top -	AFTER 1" B" failure												
SYNTHESIS NO.		ND	1961	6509	ND	3	ND	21	ND	ND	8494				G253
OIL TEMP											3				
TEST DATE															
1-20-83		Top -	Dable -	Rush -											Phone to R. White.
SYNTHESIS NO.		1	1500	6500	2	8	1	140	1	0	8153				
OIL TEMP											13				
TEST DATE															
1-20-83		Bottom -	Dable -	Rush -											Phone to R. White
SYNTHESIS NO.		1	1900	8100	2	8	1	170	2	0	10184				
OIL TEMP											14				
TEST DATE															
1-20-83		Top -	Veeco -	L.A.B. -											Phone to R. Prefitt
SYNTHESIS NO.		N/D	2300	8486	1	4	N/D	55	N/D	N/D	10935				G299
OIL TEMP											5				
TEST DATE															
1-20-83		Bottom -	Veeco -	L.A.B. -											
SYNTHESIS NO.		22	11635	46047	N/D	11	N/D	114	N/D	N/D	57829				G300
OIL TEMP											33				
TEST DATE															
COLOR															
PCB (PPM)															
DATE															
WATER CONTENT (PPM)															
DATE															
METALLIC ANALYSIS															
DATE															
POWER FACTOR %															
DATE															

GALLONS OF OIL	ATMOSEAL YES NO	HYDROGEN	OXYGEN	NITROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	COMBUSTIBLE GAS CONTENT	ESTIMATED T.C.O.	X REF: 3173	
		H ₂	O ₂	N ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	%	REPORT NO. - REMARKS	REPORT: WA
4-7-82		0	5000	8300	6	0	13	1800	56	0	89.875 / .75	0.01	577-A	Sample 1 year.
6-11-82		0	2300	8900	14	0	14	1600	62	1	91.991 / .91	0.00	580A	Sample 3 mo.
10-7-82		0	1800	6700	3	22	4	360	3	0	69.192 / .32	103	604 B	Sample 1 year.
11-16-82		5	2677	56969	2	28	N/D	223	N/D	N/D	59804 / .35	35	G217	
11-17-82		3	5075	60946	2	26	N/D	330	N/D	N/D	66282 / .31	31	G224	
11-18-82		Bank	614	437	4033	N/D	183	N/D	N/D	N/D	999174 / .336	336	G226	
11-29-82		BEFORE	964	3879	CORONA Test - BOTTOM	N/D	2	N/D	5	N/D	4850 / .2	2	G234	
11-29-82		BEFORE	408	4937	CORONA Test - TOP	N/D	5	N/D	5	N/D	6055 / .5	5	G235	
COLOR		0.5	PCB (PPM)											
DATE		10/5/82	DATE											
OIL TEMP		47/56	1	1	1	1	WATER CONTENT (PPM)							
DATE		10/5/82	DATE											
I.P.T.		40	METALLIC ANALYSIS											
DATE		10/5/82	DATE											
HEAT. NO.		250	POWER FACTOR % 110°C											
DATE		10/5/82	DATE											

Called
11/18/82
1:05 PM
By Phone

MAIN GSI		HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF. 3173	
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	MFG. W.H.											
												S/N-7001965											
												LOCATION N.A. GSI A											
												REPORT No. - REMARKS											
10-18-80 SAMPLE DATE		0	8	0	8	1200	27	0	113,743	43	0.03	(2862)											
SYRINGE No.																							
TEST DATE																							
11-8-80 SAMPLE DATE		6	19	1	13	790	60	1	86,990	100	0.02	(314) Resample 1 year											
SYRINGE No.																							
TEST DATE																							
5-3-80 SAMPLE DATE		0	21	0	13	1000	64	1	83,499	99	0.01	(3483) Resample 1 yr 5/81											
SYRINGE No.																							
TEST DATE																							
4-15-80 SAMPLE DATE		0	30	7	21	2100	110	4	123,272	172	0.02	311 F Resample 3 mo 12-18-80 (50 Fuke)											
SYRINGE No.																							
TEST DATE																							
10-16-80 SAMPLE DATE		0	28	6	16	1500	90	4	86,944	144	0.02	381 C - Resample 1 year - 10-16-81 (42 wk)											
SYRINGE No.																							
TEST DATE																							
10-23-80 SAMPLE DATE																							
11-20-80 SAMPLE DATE																							
11-20-80 SYRINGE No.		Pipes & Cables - Closed - Some that sent to Dahl																					
TEST DATE																							
11-20-80 SAMPLE DATE		4	21	14	20	1400	98	3	79,560	160	0.04	392 B - Resample 1 year 11/20/81											
SYRINGE No.																							
TEST DATE																							
12-16-80 SAMPLE DATE		0	27	0	23	1300	110	2	88,262	162	0.02	(399) Resample 1 yr 12-16-81 - 51 st WK											
SYRINGE No.																							
TEST DATE																							
12-22-80 TEST DATE																							
COLOR												PCB (PPM)											
DATE												45											
DIE - No. 872												11/16/81											
DATE												WATER CONTENT (PPM)											
10/20/81												-26 13											
I.P.T.												DATE											
6/10/81												11/20/80 4/16/81											
DATE												METALLIC ANALYSIS											
6/10/81												371 H 3941											
NEUT No												DATE											
6/10/81												9/18/80 10/11/82											
DATE												POWER FACTOR %											
6/10/81												1.08											
												DATE											
												6/20/81											

	HYDROGEN H ₂	METHANE CH ₄	CARBON MONOXIDE CO	ETHANE C ₂ H ₆	CARBON DIOXIDE CO ₂	ETHYLENE C ₂ H ₄	ACETYLENE C ₂ H ₂	TOTAL GAS CONTENT PPM	COMBUSTIBLE GAS CONTENT PPM	ESTIMATED TCG. %	X REP 3173 MFG: WH S/N: 7111915 LOCATION: 42-2-1A REPORT No - REMARK
SAMPLE DATE: 1-20-81 SYRINGE NO: 1-20-81 TEST DATE: 2-18-81 SAMPLE DATE: Y9070 SYRINGE NO: 3-10-81 TEST DATE: 3-19-81 SYRINGE NO: T9444 SYRINGE NO: 4-1-81 TEST DATE: 4-1-81 SYRINGE NO: N5070 SYRINGE NO: 3-31-81 TEST DATE: 3-31-81 SYRINGE NO: K7547 SYRINGE NO: 3-31-81 TEST DATE: 3-31-81 SYRINGE NO: 5-6-81 TEST DATE: 5-6-81 SYRINGE NO: 5-19-81 SYRINGE NO: 6-4-81 TEST DATE: 6-4-81 SYRINGE NO: 6-12-81 SYRINGE NO: V9896 SYRINGE NO: 6-30-81 TEST DATE: 6-30-81	0	24	0	21	770	100	2	80,417	147	.01	(408A) Resample 1 yr 1-22-82
	0	18	0	17	570	81	1	71,987	117	.001	(425C) Resample 1 yr. 2-18-82 8% alk
	0	20	0	22	620	100	1	81,223	123	.01	439 - Resample 1 year
	By P/H	22	0	29	1400	110	2	100,669	169	.002	(434H) Resample 1 year
											4-16-82
	0	13	5	14	1600	73	2	79,607	107	.01	459B - Resample 1 year
	5	15	0	18	2500	88	3	102,129	129		465J Resample 1 year
COLOR								PCB (PPM)			
DATE								DATE			
DIE - No 07/016								WATER CONTENT (PPM)			
DATE								DATE			
I.F.T.								METALLIC ANALYSIS			
DATE								DATE			
NEUT No								POWER FACTOR %			
DATE								DATE			

Fig. 3

	HYDROGEN								TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT	ESTIMATED TCG	X REF 3173			
	H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%			MPGR-214	S/N-7001965	LOCATION-116 G.S. 1A	REPORT No. -REMARKS
1-2-81 3-3460 SYRINGE No. TEST DATE	32	19	13	N/D	2342	90	N/D	6.80%	154							
9-16-81 SAMPLE DATE M4801 SYRINGE No. 9-21-81 TEST DATE	0	11	4	18	3000	81	2	99,516	116	0.01	497B	Resample 1 year				
10-8-81 SAMPLE DATE 8-6-81 SYRINGE No. 10-15-81 TEST DATE	0	10	0	19	2000	80	1	98,610	110	0.01	505E	Resample 1 year				
10-15-81 SAMPLE DATE 5-3-81 SYRINGE No. 10-15-81 TEST DATE	0	9	0	15	2700	68	1	92,993	93	0.01	505F	Resample 1 year				
11-6-81 SAMPLE DATE K 9703 SYRINGE No. 11-16-81 TEST DATE	0	8	0	13	2100	58	1	87380	80	0.01	512D	Resample 1 year.				
12-15-81 SAMPLE DATE D-156 SYRINGE No. 12-21-81 TEST DATE	0	7	0	15	2000	63	1	97,386	86	0.01	527F	Resample 1 year				
1-25-82 SAMPLE DATE 0-628 SYRINGE No. 2-1-82 TEST DATE	0	7	0	15	1800	61	1	95684	84	0.01	533E	Resample 1 year				
2-22-82 SAMPLE DATE 79549 SYRINGE No. 3-4-82 TEST DATE	0	6	0	11	1600	50	0	85,867	67	0.01	544F	Resample 1 year.				
PCB (PPM)																
DATE																
DIE - by 873 1016 41																
DATE 9/8/81																
I.F.T. 462																
DATE 9/18/81																
NEUT. No 1028																
DATE 9/18/81																
PCB (PPM)																
DATE																
WATER CONTENT (PPM) 12 7 3 14																
DATE 9/10/81 11/15/81 12/15/81 12/14/81																
METALLIC ANALYSIS 5/4																
DATE 10/22/81																
POWER FACTOR %																
DATE																

Nathan G#2B		HYDROGEN H ₂	METHANE CH ₄	CARBON MONOXIDE CO	ETHANE C ₂ H ₆	CARBON DIOXIDE CO ₂	ETHYLENE C ₂ H ₄	ACETYLENE C ₂ H ₂	TOTAL GAS CONTENT PPM	COMBUSTIBLE GAS CONTENT PPM	%	ESTIMATED ICG	X REF. 3203
												MFGR: WH	
												S/N: 70 02098	
												LOCATION: N.A. G#2B	
												REPORT NO - REMARKS	
12-1-82 SAMPLE DATE	0	9	0	7	430	7	0	94,753	23	0	(393F) Resample 1 yr 12-2-81		
31502 SYRINGE NO													
12-5-80 TEST DATE													
12-16-80 SAMPLE DATE	0	9	10	12	660	9	0	106,100	40	0.01	(399E) Resample 1 year 12-16-81 (51st wk)		
B 234 SYRINGE NO													
12-16-80 TEST DATE													
1-22-81 SAMPLE DATE	0	9	0	9	540	8	0	102,466	26	1.00	(408) Resample 1 yr 1-22-82		
Z 8044 SYRINGE NO													
30-71 TEST DATE													
2-18-81 SAMPLE DATE	0	10	0	10	680	8	0	45,238	28	0.01	(425B) Resample 1 year - 2-18-82 8th wk		
Y 9094 SYRINGE NO													
3-9-81 TEST DATE													
3-19-81 SAMPLE DATE	0	10	0	10	740	10	0	113,170	30	1.00	(438E) Resample 1 year 3-19-81		
T 3700 SYRINGE NO													
4-1-81 TEST DATE													
6-12-81 SAMPLE DATE	0	10	10	11	1500	9	0	112,740	40	0.009	465 F Resample 1 year		
K 9101 SYRINGE NO													
6-30-81 TEST DATE													
6-12-81 SAMPLE DATE													
5-3-81 SYRINGE NO	N/D	12	11	N/D	234	N/D	N/D	9.2%	23				
7-29-81 TEST DATE													
8-12-81 SAMPLE DATE													
8-12-81 SYRINGE NO													
8-12-81 TEST DATE													
COLOR								PCB (PPM)					
DATE								DATE					
WATER CONTENT (PPM)								4					
DATE								12/2/80					
METALLIC ANALYSIS													
DATE													
POWER FACTOR %													
DATE													

		HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF. 3203	
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%											MFG: WH	
		S/N- 7002098																					
		LOCATION: N.A. - 4525																					
		REPORT No. - REMARKS																					
10-14-79	SAMPLE DATE	0	9	14	10	180	0	0	93,413	33	.01	(286M)											
	SYRINGE No.																						
	TEST DATE																						
8-2-79	SAMPLE DATE	0	9	18	9	150	3	0	83,989	39	.02	(291E)											
	SYRINGE No.																						
	TEST DATE																						
11-4-79	SAMPLE DATE	9	13	5	15	290	7	0	90,339	49	0.02	(314) Resample 1 yr 11-80											
	SYRINGE No.																						
	TEST DATE																						
	SAMPLE DATE	0	9	0	2	240	5	0	105,361	21	.00	(348M) Resample 1 yr 5-81 (2nd yr)											
	SYRINGE No.																						
	TEST DATE																						
9-13-80	SAMPLE DATE	0	10	9	9	480	8	0	129,316	36	0.01	(371G) Resample 1 yr 9-18-81 (3rd yr)											
9-13-80	SYRINGE No.																						
	TEST DATE																						
10-23-80	SAMPLE DATE	0	10	15	7	660	7	1	102,800	40	0.01	(381-D) Resample 1 yr 10-16-81 (42 wk 81)											
10-23-80	SYRINGE No.																						
	TEST DATE																						
11-20-80	SAMPLE DATE	Vapco Lab closed - some test sent to Dahl																					
11-20-80	SYRINGE No.																						
	TEST DATE																						
11-20-80	SAMPLE DATE	0	10	0	7	380	7	0	79,904	24	0	(392A) Resample 1 yr 11-20-81											
11-20-80	SYRINGE No.																						
	TEST DATE																						
	COLOR											PCB (PPM)										25	
	DATE											DATE										11/10/80	
	DIE - no 872											WATER CONTENT (PPM)										5	
	DATE											DATE										11/20/80	
	I.F.T.											METALLIC ANALYSIS										371H	
	DATE											DATE										9/18/80	
	NEUT No											POWER FACTOR %										.11	
	DATE											DATE										10/16/80	

GALLONS OF OIL ATMOSEAL YES NO	ESTIMATED T.C.O.											REPORT NO.-REMARKS	
	H ₂	O ₂	N ₂	CH ₄	CO	C ₂ H ₂	CO ₂	C ₂ H ₄	C ₂ H ₆	ACETYLENE	COMBUSTIBLE GAS CONTENT	ESTIMATED T.C.O.	REPORT NO.-REMARKS
	<p>Repaired - Relearned from factory - Installed and will be energized GSA 2 "B"</p>												
SAMPLE DATE 4-2-82	0	1300	8500	1	6	1	41	0	0	9849	0.05	557	Resample 1 year.
SYRINGE NO. 11-0766													
OIL TEMP 100													
TEST DATE 4-27-82													
SAMPLE DATE 6-17-82	0	2200	6200	3	22	3	110	0	0	64,338	0.03	588E	Resample 1 year.
SYRINGE NO. 19128													
OIL TEMP 100													
TEST DATE 6-28-82													
SAMPLE DATE	Failed 8/22/82.												
SYRINGE NO.													
OIL TEMP													
TEST DATE													
SAMPLE DATE													
SYRINGE NO.													
OIL TEMP													
TEST DATE													
SAMPLE DATE													
SYRINGE NO.													
OIL TEMP													
TEST DATE													
COLOR													
DATE													
DIR BY													
DATE													
I.P.T.													
DATE													
NEUT. NO.													
DATE													
PCB (PPM)													
DATE													
WATER CONTENT (PPM)													
DATE													
METALLIC ANALYSIS													
DATE													
POWER FACTOR %													
DATE													

		HYDROGEN	METHANE	CARBON MONOXIDE	ETHANE	CARBON DIOXIDE	ETHYLENE	ACETYLENE	TOTAL GAS CONTENT	COMBUSTIBLE GAS CONTENT	ESTIMATED TCG	X REF. 3205
		H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	MFGR. WH
												SIN-7002100
												LOCATION: NAG 52C
												REPORT No - REMARKS
12-16-80	W8510	2	29	2	14	780	39	1	103,467	87	0.01	(399C) Resample 1 year 11/6/80 - 51% alk
12-22-80	V9866	9	26	2	13	600	37	1	98,988	88		(408D) Resample 1 year 1-22-82
2-18-81	A-9142	0	27	2	15	740	40	1	41,415	85	0.02	(425A) Resample 1 year 2/18/82 8th wk.
3-19-81	Y9546	17	26	11	15	720	40	0	47,427	109	0.05	(428E) Resample 1 year.
5-19-81	Y4691	0	20	15	14	670	33	0	72722	82	0.02	459- Resample 1 year -
6-12-81	B-7796	20	26	16	16	1500	40	2	99020	120	0.055	(465G)
6-22-81	C-1886	5100	1600	34	120	1200	1700	2400	96,554	10,954	9.8	464 Severe
7-27-81	S-3456	7	40	40	25	2425	38	N/D	9.2%	150		
COLOR										PCU (PPM)		
DATE										DATE		
DIE - by 31/81										WATER CONTENT (PPM)		21 7.48
DATE										DATE		6/22/81 34/81
I.F.T.										METALLIC ANALYSIS		
DATE										DATE		
NEUT No										POWER FACTOR %		
DATE										DATE		

HYDROGEN		METHANE		CARBON MONOXIDE		ETHANE		CARBON DIOXIDE		ETHYLENE		ACETYLENE		TOTAL GAS CONTENT		COMBUSTIBLE GAS CONTENT		ESTIMATED TCG		X REF. 3205	
H ₂	CH ₄	CO	C ₂ H ₆	CO ₂	C ₂ H ₄	C ₂ H ₂	PPM	PPM	%	REPORT No. - REMARKS	MFG. 014		S/N-7002100		LOCATION: N.A. GESC						
16-18-79	0	11	28	9	200	5	0	92,555	53	.02	(286 I)										
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
2-2-79	7	16	37	18	140	11	0	88,029	89	.05	(291 D)										
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
11-4-79	9	28	31	29	94	13	0	77,604	110	0.06	(314 E) Resample 1 yr					11-80					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
5-2-80	0	29	17	16	200	22	0	93,684	84	0.02	(348 R) Resample 1 yr					5-81 (2 weeks)					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
10-16-80	31	31	46	10	770	32	2	103,422	152	0.09	(381 B) Resample 1 yr					10-16-81 (4276 WR)					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
11-20-80											1/2 up to 1/2 inch closed - Jarre test sent to Lab										
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
11-21-80	20	27	28	11	560	32	1	58,879	119	.11	(392 I) Resample 1 yr										
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-2-80	11	32	31	22	670	54	1	96,421	151	.05	(393 H) Resample 1 yr					12-2-81					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					
SYRINGE No.																					
TEST DATE																					
12-5-80																					
SAMPLE DATE																					

APPENDIX G

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

ENGINEER'S TRIP REPORT
WESTINGHOUSE FORM 3611 G

NOTE 1 - The Engineer reporting is responsible for the prompt delivery of his reports to all interested persons and for seeing that all points requiring action are cleared up without delay.

2 - For long reports give a summary of important points and recommendations.

DATE 1/25/83

[illegible]

- NAME North Anna Nuclear Station

LOCATION _____ G.O. _____ S.O. _____ SER. O. _____

PURPOSE OF TRIP Perform hydraulic experiments on HAM707.

CONFERENCE HELD AT _____ DATE _____

THOSE PRESENT Messrs. Robert Bowman, (W) Field Salesman; John Haubert, District Engineer;
Joe McGregor, VEPCO.

SUMMARY:

See attached.

SIGNED (ENGINEER)
P. L. Thiel
DEPARTMENT
Engineering

P. L. Thiel
DIVISION
PTD

APPROVED
E. M. Petrie *E. M. Petrie* 1-31-33

LOCATION	Muncie, IN
----------	------------

PAGE 1

TRIP REPORT - NORTH ANNA

I traveled to the North Anna Nuclear Station to perform several experiments on their HAM707 unit which was retrofitted with COPS unit in December of 1982.

A summary of these tests and my conclusions follows:

1. Ran pumps #1, 2, 3 together and observed if any bubbles were circulated through the phase. Only pumps #1, 2, and 3 were run because the temporary circuit supplying power to the pumps would trip when all five pumps were operated. No bubbles were observed. The oil was highly illuminated by a special 150 watt light source immersed in the oil.
2. Introduced dry air through a fitting mounted on pump #2 while pumps #1, 2, and 3 were operated. A generous quantity of bubbles passed upward from around the phase and through the phase. The highest velocity area was found to be between the phase and the core directly above the edge of the T-beam. The bubbles traveled with a higher velocity at the perimeter of the phase than within the phase but the interior flow (above the coils) was greater than I expected. All bubbles regardless of the exit location traveled vertically with no sideways movement.
3. The oil was drained from the unit down to the top of the end frames exposing the bridgework. The outside edge of the bridge lined up with the outside of the padding washers on three sides of the phase. On the side adjacent to the HV bushing, the bridge was set back from the outside padding washer approximately 2.5 inches.

The welds joining the side members to the end frames had good appearance. Wedging on all four sides of the phase was tight which reduced the leakage from around the phase more than expected.

I discussed with Mr. J. McGregor about the processing of this unit when it was being retrofitted with the COPS unit. Nitrogen was introduced into the unit as the unit was drained and maintained on the unit prior to opening the unit at the manhole cover. When the manhole cover was removed, the unit was purged with dry air and a tent positioned over the manhole where the relative humidity of the air was measured at under 40 percent. The mechanical relief device was modified to provide a fitting through which vacuum could be drawn for the filling process since the unit was being retrofitted with a COPS tank. The unit was then vacuum filled to within several inches of the cover and vacuum broken by admitting nitrogen into the tank. The COPS was then filled. They used the Vokes #2 streamliner to process the oil down to 5 ppm H₂O.

APPENDIX H

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

APPENDIX H

BLUE RIBBON COMMITTEE ORGANIZATION

George Mechlin - Chairman
Vice President of R&D Westinghouse

Members:

D. Berg	-	Consultant, (_____-Mellow University
W. Emmerich	-	Technical Director, R&D Westinghouse
R. Ratica	-	Westinghouse Power System Customer Service Representative
S. Quick	-	General Manager, Westinghouse Steam Turbine Generator Div.
J. Karnash	-	Westinghouse Law Department

APPENDIX I

TRANSFORMER REPORT ON EVENTS AT N. ANNA POWER STATION

TRANSFORMER EVALUATION COMMITTEE

J. Skooglund - Chairman
 Engineering Manager - Power Transformer Div.

Systems:

J. Bonk	Westinghouse T&D Systems Engr.
C. Wagner	Westinghouse T&D Systems Engr.
E. Taylor	Westinghouse T&D Systems Engr.
D. Shankle	Westinghouse AST
S. Baldwin	Westinghouse Steam Turbine Generator Division (Liaison to Power Generation)

Transformer

Insulation and Field Analysis - A. Sletten
 Westinghouse R&D

Hydraulics - R. Rothmann - Westinghouse R&D
 - E. Petrie - Westinghouse PTD

Design - J. Cossaart - Westinghouse PTD
 - H. Moore - Westinghouse PTD
 - J. Templeton - Westinghouse PTD
 - D. Yannucci - Westinghouse PTD

Consultants:

S. Bennon