

NRC FORM 366  
(12-81)  
10 CFR 50U.S. NUCLEAR REGULATORY COMMISSION  
LICENSEE EVENT REPORTAPPROVED BY OMB  
3150-0011CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 P A S E S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 3 8 7 7 1 2 0 9 8 3 8 0 2 2 8 8 4 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Between December 4 thru 9, 1983, the alarms/indication/records for the sample flow

03 rate of the Standby Gas Treatment Vent Radiation Monitor was lost. A Micropro-

04 cessor analyzing the flow rate data failed; the word "Normal" was printed for the

05 channel output during each daily surveillance. When discovered, LCO per T.S.

06 3.3.7.11 was entered, the microprocessor was replaced and the system returned to

07 service. During the event, sample flow was not lost and all other alarms/indica-

08 tion/printouts functioned properly. There was no effect on public health & safety.

09 SYSTEM CODE S C 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE Y 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 3 1 6 8 1 0 3 X 1

18 ACTION TAKEN A 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 23 ATTACHMENT SUBMITTED Y 24 NPD-4 FORM SUB. N 25 PRIME COMP. SUPPLIER A 26 COMPONENT MANUFACTURER E 0 7 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was the failure of the microprocessor, which was replaced.

11 The daily surveillance procedure is being changed to give the operator more in-

12 formation to interpret the output and to ensure that the word "Normal" is not re-

13 lied upon as the sole indicator of channel condition.

14

15 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NAME OF PREPARER B.L. Wilks

PHONE (717)542-2181, X3239

8403020315 840228  
PDR ADOCK 05000387  
S PDR

NRC USE ONLY

ATTACHMENT

LER # 83-168/03X-1

Pennsylvania Power & Light Company  
Susquehanna Steam Electric Station  
Docket Number: 50-387

On December 9, 1983, it was discovered that the channel monitoring sample flow rate (one of eleven channels on the Eberline Control Terminal) for the Standby Gas Treatment Vent Radiation Monitor was not functioning properly; an LCO was entered in accordance with T.S. 3.3.7.11. At this time, the sample flow rate measured by the Air Monitor Panel was approximately 1 cfm, which was normal for the vent flow rate at the time. The sample flow rates taken in accordance with Technical Specification at four hours intervals were normal.

Investigations of recorded data from December 4 indicated that requests for data from the channel resulted in '0.00 E+00' cfm being printed by the control terminal. The PRINT, ALLSTAT, ENTER command (the command used for daily surveillance) list channel 11 (sample flow rate) as NORMAL. No alarms accompanied the zero flow recorded by the control terminal. All evidence indicates that the particulate, iodine, noble gas and vent flow channels of the SBGTS vent monitor continued to operate properly. History files and data requested from these channels were normal during the time the sample flow channel was inoperable. According to the control terminal printout, alarm functions for the other channels were operable.

Some of the alarms or status changes recorded during this time were:

- a. CK SRCI (check source) on Channels 01,03,05,06,07 and 09.
- b. TRN ALM (trent alarm) on Channel 0603.
- c. ALT ALM (alart alarm) on Channel 0601 (This was an invalid alarm which occurs routinely on +0.00 E+00.
- d. FLUSH on Channels 01,03,04,05,06,07, and 09 (This status change occurred during changeout of iodine cartridge and particulate filter and cleared when flush was stopped.)

The weekly particulate filter and iodine cartridge installed in the monitor on December 2, 1983, and removed on December 9, 1983 showed levels lower than detectable when counted.

Analysis indicates sample flow was not lost between December 2 and 9, 1983 as evidenced by the noble gas concentration recorded during this time for the period during which sample flows are not available, estimated sample flow rates can be calculated based on vent flow rates and will be used for the determination fo release rates from the vent.

The failure of the alarms, indication and records for the Standby Gas Treatment Vent Radiation Monitor sample flow rate was caused by the microprocessor analyzing the data. The microprocessor was replaced and the control terminal was returned to service.

The acceptance criteria for the channel checks has been revised to provide the operator with more information in determining operability. Additional changes to acceptance criteria are being considered and will be implemented as necessary to improve the information available to the operator.

During this event there was no effect on public health and safety.



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

February 28, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 83-168/03X-1  
ER 100450 FILE 841-23  
PLA-2105

Docket No. 50-387  
License No. NPF-14

Attached please find a copy of Licensee Event Report No. 83-168/03X-1. This event was originally determined to be reportable per Technical Specification 6.9.1.9.c on January 6, 1984 in that, alarms and indications for the sample flow rate of the Standby Gas Treatment Vent Radiation Monitor was lost without notification and went undetected between December 4 and 9, 1983. Revision 1 of this Licensee Event Report provides additional information concerning the corrective actions to be taken as a result of the event.

H.W. Keiser  
Superintendent of Plant-Susquehanna

BLW/pjg

cc: Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Mr. R.H. Jacobs  
Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

TE22  
1/1