

CONTROL BLOCK		1		(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																																	
01	C	A	D	C	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5																												
LICENSEE CODE		14		15		LICENSE NUMBER		25		26		LICENSE TYPE		30		57		CAT		58																																	
CON'T		01		REPORT SOURCE		L		0		5		0		0		0		2		7		5		7		0		8		2		6		8		3		8		1		0		2		0		8		3		9	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES		10																																																			
02		Prior to fuel load, while installing support saddles on the Containment Spray																																																			
03		Additive Tank, welding was performed on the additive tank without first draining																																																			
04		the tank of sodium hydroxide solution, contrary to direction given by the Plant																																																			
05		Staff Review Committee. Reportable per Technical Specification Section																																																			
06		6.9.1.13.c. This event has in no way affected the public's health and safety.																																																			
07																																																					
08																																																					
09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE																																									
10		S		A		11		A		12		E		13		A		C		C		U		M		U		14		Z		15		Z		16																	
17		LER/NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																																									
18		8		3		0		1		9		0		3		L		1																																			
19		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-6 FORM SUB		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																			
20		X		X		Z		Z		0		0		0		Y		N		N		W		1		2		0																									
21		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS		27																																																	
22		Caution on draining the additive tank prior to welding was not communicated to																																																			
23		the field. The additive tank has been drained and inspected using dye-penetrant																																																			
24		techniques. No evidence of cracks or corrosion in the weld area was observed.																																																			
25																																																					
26																																																					
27		FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																																											
28		B		0		0		0		C		During non-routine inspection																																									
29		ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																																															
30		Z		Z		NA																																															
31		PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION																																															
32		0		0		0																																															
33		PERSONNEL INJURIES NUMBER		DESCRIPTION																																																	
34		0		0		0																																															
35		LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION																																																	
36		Z		NA																																																	
37		PUBLICITY ISSUED DESCRIPTION																																																			
38		N		NA																																																	
39		8310270376 831020		PDR ADOCK 05000275		S		PDR		NRC USE ONLY																																											
40		NAME OF PREPARER		WILLIAM J. KELLY		PHONE		(805) 595-7351																																													

DIABLO CANYON UNIT 1
DOCKET NO. 50-275
LER 83-019/03L-1

SUPPLEMENTAL INFORMATION

The design change notice (DCN) that proposed adding support saddles to the Containment Spray Additive Tank was approved by the Plant Staff Review Committee (PSRC) with special instructions written on the DCN cover sheet cautioning the personnel performing the work to drain the additive tank prior to welding. Persons responsible for the assignment of work to the field failed to notice the special instructions on the cover sheet of the DCN and they did not transmit those instructions to the personnel performing the work.

To prevent recurrence, a prominent stamp will be placed on applicable DCNs to indicate that special instructions are included that must be followed. Personnel involved in transmitting DCNs to the field have been cautioned to be aware that some DCNs will contain special instructions.

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

October 20, 1983

Mr. John B. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368


Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Licensee Event Report 83-019/03L-1
Tank Welding Error

Dear Mr. Martin:

Pursuant to Section 6.9.1.13.c of the Technical Specifications, Appendix A to the Diablo Canyon Unit 1 Operating License, the enclosed is a revision to the subject Licensee Event Report concerning the welding of support saddles on the Containment Spray Additive Tanks while the tank contained sodium hydroxide in solution.

This event has in no way affected the public's health and safety.

Sincerely,


for James D. Shiffer

Enclosure

cc: G. W. Knighton, Chief

Director, Office of Management Information
and Program Control

Service List

RECEIVED
OCT 21 PM 1:50

RECEIVED
OCT 21 PM 1:50

1/0
JE-22