

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 C A S O S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

01 REPORT SOURCE L 0 5 0 0 0 3 6 1 7 0 9 1 7 8 3 8 1 1 0 1 7 8 3 9
7 8 DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With Unit 2 in Mode 1, CEAC 2 was declared inoperable at 1717 on 9/17/83

03 due to spurious position indication from CEA 20. Repairs were made and

04 CEAC 1 was declared operable at 1840 on 9/23/83. At 2028 on 9/23/83,

05 CEAC 1 was again declared inoperable when it indicated the insertion of

06 Shutdown Bank B subgroups 3 and 4 when only Regulating Group 6 was being

07 inserted. In each event Table 3.3-1 Action Statement 6 of LCO 3.3.1 was

08 invoked and met. Public health and safety were not affected.

09 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 3 21 22 SEQUENTIAL REPORT NO. 1 2 4 24 26 OCCURRENCE CODE 0 3 27 29 REPORT TYPE L 30 31 REVISION NO. 0 32

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 4 9 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A circuit board in CEAC 1 was initially replaced. The 9/23/83 event was

11 caused by the failure of the new board. A defective connector in the

12 position circuit for CEA 20 was then found and was the true cause of the

13 9/17/83 event. The board and connector were replaced and CEAC 1 was de-

14 clared operable at 0820 on 9/28/83.

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED DESCRIPTION N 44 NAME OF OPERATOR J. G. HAYNES PHONE 714/492-7700 NRC USE ONLY

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

October 17, 1983

SCE

RECEIVED
OCT 20 PM 2 14

RECEIVED
OCT 20 PM 2 14

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 83-124
San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 for San Onofre Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for two occurrences involving Limiting Condition for Operation (LCO) 3.3.1 associated with the Reactor Protection System (RPS). Since the two occurrences involved the same components, system, cause and method of discovery, these events have been combined into a single report in accordance with NUREG-0161.

On September 17, 1983, at 1717, with Unit 2 in Mode 1 at 100% power, operators observed spurious indication for Control Element Assembly (CEA) 20 on Control Element Assembly Calculator (CEAC) 1. CEAC 1 was declared inoperable and pursuant to Table 3.3-1, Action Statement 6 of LCO 3.3.1, at least once per 4 hours each CEA was verified to be within 7 inches of all other CEA's in its group. The inoperability of CEAC 1 was initially believed to be due to a problem with the multiplexer circuit board for CEA 20. The circuit board was replaced and CEAC 1 was declared operable at 1840 on September 23, 1983.

At 2028 on September 23, 1983, with Unit 2 in Mode 1 at 100% power, CEAC 1 was again declared inoperable when it indicated the insertion of Shutdown Bank B subgroups 3 and 4 when only Regulating Group 6 was being inserted. Action Statement 6 was again invoked and at least once per 4 hours each CEA was verified to be within 7 inches of all other CEA's in its group.

JB-22

October 17, 1983

Investigation of CEAC 1 determined that the newly installed multiplexer circuit board had failed. This circuit board was replaced. However, a defective connector in the CEA 20 position circuit was discovered. This connector is believed to be the true cause of the first event. The connector was replaced and CEAC 1 was declared operable at 0820 on September 28, 1983. No further corrective action is deemed necessary.

There was no impact on the health and safety of plant personnel or the public associated with these events.

If you require any additional information, please so advise.

Sincerely,

J. G. Haynes / J. G. Haynes

J. G. HAYNES
STATION MANAGER

Enclosure: LER No. 83-124

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)