

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9		C	B	(11)	E	(12)	C	(13)	P	I	P	E	X	X	(14)	E	(15)	Z	(16)	
7		8	9		10	11		12		13					18		19		20		
(17) LER/RO REPORT NUMBER		EVENT YEAR						SEQUENTIAL REPORT NO.				OCCURRENCE CODE				REPORT TYPE				REVISION NO.	
		8 3						0 2 0				0 1				T				3	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		(22)		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
B (18)		Z (19)		Z (20)		Z (21)		0 0 0 0				Y (23)		N (24)		N (25)		D 2 4 0 (26)			
33		34		35		36		37				40	41		42		43		44		47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (H) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) METHOD OF DISCOVERY (C) (31) DISCOVERY DESCRIPTION (32) I.E. Bulletin 83-02 Requirement

ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39)  
1 7 0 0 0 37 Z 38 NA

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)  
1 8 0 0 0 40 NA

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION NA  
1 3 7 8 9 10  
PDR ADOCK 05000265  
S PDR  
PUBLICITY (45)  
ISSUED DESCRIPTION Numerous Loca' Media Reports  
2 0 7 8 9 10  
NRC USE ONLY

NAME OF PREPARER D Clark

PHONE: 309-654-2241, ext 244

- I. LER NUMBER: LER/RO 83-20/01T-3
- II. LICENSEE NAME: Commonwealth Edison Company  
Quad Cities Nuclear Power Station
- III. FACILITY NAME: Unit Two
- IV. DOCKET NUMBER: 050-265
- V. EVENT DESCRIPTION:

On September 4, 1983, Quad Cities Unit Two was shut down in order to begin the Cycle 6 refueling outage. During the outage, numerous inspections of the Primary Coolant System were performed as required by the N.R.C. I.E. Bulletin 83-02. The ultrasonic testing was performed by Lambert, McGill and Thomas, Incorporated personnel and the results were reviewed by the Commonwealth Edison Level III examiner. The results indicated that eleven welds on large bore stainless steel pipe welds were identified to contain linear indications in the heat-affected zone of the welds. Nine of the welds were located on the Reactor Recirculation System, and two were located on the Residual Heat Removal (RHE) Shutdown Cooling suction piping. A complete list of affected welds including a description of the indications and the final disposition can be found on Attachment 1.

An additional eleven welds in the Reactor Recirculation System were also found to contain linear indications. These welds were inspected as part of the IGSCC Inspection Order and are reported under LER/RO 83-21/01T.

VI. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The probable consequences of this occurrence were minimal. Crack indications of this type tend to propagate at a slow rate. Therefore, a 100 percent through-wall crack could be easily detected using existing Primary Containment leakage monitoring systems before a complete failure would occur. During the current Operating Cycle, the allowable containment leakage rate has been reduced in order to expedite the investigation of potential leakage from stainless steel piping. None of the indications discovered extended completely through the weld. Safe operation of the Reactor was not jeopardized as a result of this occurrence.

VII. CAUSE

The exact cause of the crack indications has not been determined; but it is postulated that intergranular stress corrosion cracking is the probable mode of failure. The normal heat generated by welding causes a heat-affected zone at the weld to piping interface. This, combined with coolant impurities, high operating temperatures, and stresses experienced in the weld area are factors encountered in the Reactor Recirculation System which are mechanisms necessary for intergranular stress corrosion cracking to occur.

The stainless steel piping was fabricated by the Dravo Corporation, Type A358, Grade TP 304. The pipe fittings are Type A 403 Grade WP 304. The stainless steel used in all the original Recirculation System pipe and fittings contained carbon contents between 0.05 and 0.08 percent.

#### VIII. CORRECTIVE ACTION

The crack indication evaluation and repair criteria was performed by NUTECH Engineers, Inc. Indications were evaluated based upon indication depth, length, direction, and applied stresses. Induction Heat Stress Improvement (IHSI) was performed on many welds, both with and without crack indications in order to reduce weld residual stress. As a general rule, circumferential indications with a length greater than 120 degrees of the pipe circumference and/or a depth of greater than 25% of the pipe wall thickness were repaired by applying a weld overlay. All axial indications were repaired by weld overlay. All analyses were performed to the guidelines specified in the ASME Boiler and Pressure Vessel Code, Section XI, Paragraph IWB-3640, "Acceptance Criteria for Austenitic Steel Piping." See Attachment 2 for a typical evaluation sequence.

Additional inspections were performed on weld 02BS-S12 to determine the actual size of the indications. Second and third party inspections by Independent Testing Laboratory and Universal Testing Lab. using the Shear Wave technique confirmed the original evaluation. A newer ultrasonic test technique, identified as ID Creeping Wave, was used by UTL.

The results of this inspection indicated that no cracks existed in these welds. A sample plug was cut out of weld 02BS-S12 to perform further analyses. The plug was examined visually and by dye penetrant testing but no evidence of a crack could be found. The plug was then sectioned, polished, etched and examined microscopically. No cracks were found on the sample. The remainder of the weld was examined by radiography and the pipe I.D. was visually inspected with a borescope. Results of the sample plug and weld inspections provided conclusive evidence that no IGSCC cracks existed in this weld.

The repair program consisted of either performing a weld overlay or leaving the weld as-is. All welds containing indications that were left as-is had IHSI performed on them. Five welds were repaired using weld overlay. The length and thickness of each overlay differed, depending upon the indication size, analysed stresses and pipe geometry. A more detailed description of the indication evaluation and repair program can be found in a Commonwealth Edison letter from B. Rybak to Mr. Harold R. Denton, "Quad Cities Station Unit 2 Weld Inspection Results, NRC Docket No. 50-265", dated January 27, 1984.

Each weld overlay was dye penetrant tested; and an ultrasonic examination was performed to verify bonding between the base metal and weld material. A post-examination of each weld treated by IHSI was performed by ultrasonic testing. Prior to the reactor startup, the

entire Recirculation System was hydrostatic tested in conjunction with the reactor vessel hydrostatic test at 1.1 times the system nominal operating pressure.

QUAD-CITIES UNIT TWO


INDICATION DESCRIPTION & REPAIR

<u>WELD ID</u>	<u>LOCATION</u>	<u>PIPE DIAMETER</u>	<u>CRACK TYPE</u>	<u>FLAW CHARACTERIZATION(1)</u>			<u>DISPOSITION</u>	<u>WELD IHSI'd</u>
				<u>MAX DEPTH</u>	<u>LENGTH</u>	<u>LOCATION</u>		
02D-S3	'D' Riser Elbow to Pipe	12"	Circ	25%	0.5"	Pipe Side	Leave As-Is	Yes
02D-F6	'D' Riser Saddle to Pipe	12"	Circ	80%	8.0"	Pipe Side	Overlay	No
02G-S3	'G' Riser Elbow to Pipe	12"	Circ	32%	2.25"	Pipe Side	Overlay	Yes
02AD-F12	'A' Loop Disch Pump to Pipe	28"	Circ	10%	24.0"	Pipe Side	Leave As-Is	Yes
02BS-S3	'B' Loop Suction Elbow to Pipe	28"	Circ	40%	12.0"	Elbow Side	Overlay	No
02BS-S12	'B' Loop Suction Elbow to Pipe	28"	Circ(1)(2)	20%	48.0"	Pipe Side	Leave As-Is	Yes
02BS-F14	'B' Loop Suction Pipe to Elbow	28"	Circ	18%	5.25"	Pipe Side	Leave As-Is	Yes
02BD-S6	'B' Loop Disch Elbow to Pipe	28"	Circ	39%	17.0"	Elbow Side	Overlay	No
			Axial	64%	1.25"	Elbow Side	Overlay	No
02B-S9	Ring Header Pipe to Cap	22"	Circ	15%	17.0"	Cap Side	Leave As-Is	Yes
10S-F1	RHR Shutdown Clg Tee to Pipe	20"	Circ	11%	6.0"	Pipe Side	Overlay	No
10S-F5	RHR Shutdown Clg Valve to Pipe	20"	Circ	18%	3.5"	Pipe Side	Leave As-Is	Yes
			Circ	12%	8.0"	Pipe Side	Leave As-Is	Yes

NOTE: (1) Flaw characterization based on composite of LMT/ITL results.

(2) Additional inspection by UTL and plug sample of 02BS-S12 confirms that no flaw actually exists





TYPICAL FLAW DISPOSITION SEQUENCE



**Commonwealth Edison**

Quad Cities Nuclear Power Station  
22710 206 Avenue North  
Cordova, Illinois 61242  
Telephone 309/654-2241

*DMB*

NJK-84-62

February 21, 1984

J. Keppler, Regional Administrator  
Office of Inspection and Enforcement  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station  
Docket Number 50-265, DPR-30, Unit Two  
Appendix A, Section 6.6.B.1.c

Enclosed please find Reportable Occurrence Number (RO) 83-20/01T-3 for Quad-Cities Nuclear Power Station. Previous revisions to this Reportable Occurrence have identified welds containing linear indications found during the Inservice Inspection required by I.E. Bulletin 83-02. This revision identifies the final disposition of these indications.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.1.c; an abnormal degradation discovered in the Reactor Coolant Pressure Boundary.

Respectfully,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivialis  
Station Superintendent

NJK:DGC/bb

Enclosure

cc B. Rybak  
A. Morrongiello  
INPO Records Center

MAR 5 1984

*IE22 11*