

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PASES 1200-00000-000341111145  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CONT

01 REPORT SOURCE L605000387709218381021839  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While on daily rounds Operations personnel identified damaged seals on the Reactor-

03 Turbine Building airlock doors. This is considered a loss of secondary containment

04 integrity per Technical Specification definitions and Limiting Condition for

05 Operation (LCO) 3.6.5.1 was declared. The building was maintained at the required

06 negative pressure. There were no consequential affects to public health and

07 safety.

08

09

17 LER/RO REPORT NUMBER 83

18 ACTION C

19 FUTURE ACTION X

20 EFFECT ON PLANT Z

21 SHUTDOWN METHOD Z

22 HOURS 0000

23 SEQUENTIAL REPORT NO. 133

24 OCCURRENCE CODE 03

25 REPORT TYPE L

26 REVISION NO. 0

27 ATTACHMENT SUBMITTED N

28 NPRD-4 FORM SUB. N

29 PRIME COMP. SUPPLIER Z

30 COMPONENT MANUFACTURER Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The seals were apparently damaged when equipment was being taken into the Reactor

11 Building. This airlock is the only access to the Reactor Building and is a high

12 traffic area. Some periodic damage can be anticipated. The damaged seals were

13 replaced within the four hour Technical Specification limit (3.6.5.1).

14

15 FACILITY STATUS E 100% POWER 100 OTHER STATUS NA METHOD OF DISCOVERY B Operator Observation

16 ACTIVITY CONTENT RELEASED OF RELEASE Z Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

17 PERSONNEL EXPOSURES NUMBER 000 TYPE Z DESCRIPTION NA

18 PERSONNEL INJURIES NUMBER 000 DESCRIPTION NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

20 PUBLICITY ISSUED DESCRIPTION N

8311010112 831021  
PDR ADOCK 05000387  
S PDR

JEZZ

NAME OF PREPARER A.P. Piemontese

PHONE (717) 542-2181



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

October 21, 1983


Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 83-133/03L-0  
ER 100450 FILE 841-23  
PLA-1917

Docket No. 50-387  
License No. NPF-14

Dear Dr. Murley:

Attached is Licensee Event Report No. 83-133/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that while on daily rounds Operations personnel identified damaged seals on the Reactor/Turbine Building airlock doors. There was no effect on the ability of ventilation systems to maintain the required secondary containment negative pressure. The damaged seals were replaced within the four hour Technical Specification limit (3.6.5.1).

  
H.W. Keiser  
Superintendent of Plant-Susquehanna

APP:pjg

cc: G.G. Rhoads  
Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
11

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 PASES 1200-000000-000341111145  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CONT

01 REPORT SOURCE L605000387709218381021839  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While on daily rounds Operations personnel identified damaged seals on the Reactor-

03 Turbine Building airlock doors. This is considered a loss of secondary containment

04 integrity per Technical Specification definitions and Limiting Condition for

05 Operation (LCO) 3.6.5.1 was declared. The building was maintained at the required

06 negative pressure. There were no consequential affects to public health and

07 safety.

08

09 S A 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 LER/RO REPORT NUMBER 83

18 ACTION TAKEN C

19 FUTURE ACTION X

20 EFFECT ON PLANT Z

21 SHUTDOWN METHOD Z

22 HOURS 00000

23 SEQUENTIAL REPORT NO. 133

24 OCCURRENCE CODE 03

25 ATTACHMENT SUBMITTED N

26 NPRO-4 FORM SUB. N

27 PRIME COMP. SUPPLIER Z

28 COMPONENT MANUFACTURER 999

29 REVISION NO. 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The seals were apparently damaged when equipment was being taken into the Reactor

11 Building. This airlock is the only access to the Reactor Building and is a high

12 traffic area. Some periodic damage can be anticipated. The damaged seals were

13 replaced within the four hour Technical Specification limit (3.6.5.1).

14

15 E 28 100 29 NA 30 B 31 Operator Observation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 4016 Z 33 Z 34 NA 35 NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 4017 000 37 Z 38 NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 4018 000 40 NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 4019 Z 42 NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 4020 N 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

NAME OF PREPARER A.P. Piemontese

PHONE (717) 542-2181

8311010112 831021  
PDR ADOCK 05000387  
S PDR

NRC USE ONLY



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

October 21, 1983


Dr. Thomas E. Murley  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 83-133/03L-0  
ER 100450 FILE 841-23  
PLA-1917

Docket No. 50-387  
License No. NPF-14

Dear Dr. Murley:

Attached is Licensee Event Report No. 83-133/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that while on daily rounds Operations personnel identified damaged seals on the Reactor/Turbine Building airlock doors. There was no effect on the ability of ventilation systems to maintain the required secondary containment negative pressure. The damaged seals were replaced within the four hour Technical Specification limit (3.6.5.1).

  
H.W. Keiser  
Superintendent of Plant-Susquehanna

APP:pjg

cc: G.G. Rhoads  
Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
11