Commonwealth Edison Company Braidwood Generating Station Route #1, Box 84 Braceville, IL 60407-9619 Tel 815-458-2801

N.

ComEd

March 17, 1995 BW/95-0037

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

The enclosed Licensee Event Report from Braidwood Generating Station is being transmitted in accordance with the requirement of 10 CFR 50.73 (a)(2)(i)(B), which requires a 30-day written report.

This report is number 95-001-00, Docket No. 50-457.

To Le

K.L. Kofron U Station Manager Braidwood Generation Station

KLK/BJM/dla o:\corresp\zcsteno

Enclosure: Licensee Event Report No. 457-95-001-00

cc: NRC Region III Administrator NRC Resident Inspector INPO Record Center CECo Distribution Center I.D.N.S.

210135



1/222

NRC FORM	N 366		7.000	U.S.	NUCLEAR	REGULATO	RY COMM	ISSION	ľ	APPROVED BY	(ONS NO. IRES 5/31/	3150-0 95	104	
(See	reveri	LICE	NSEE	EVENT REPO	ORT (LE	IR) s for ea	ach blo	sk)	ESTIMATI THIS IN FORWARD THE INF (MNBB 7 WASHING REDUCTI MANAGEM	ED BURDEN PE IFORMATION CO COMMENTS RE FORMATION AND 714), U.S. NU TON, DC 20555 ON PROJECT ENT AND BUDGE	R RESPON LLECTION GARDING I RECORDS CLEAR REG -0001, AN (3150-0 T, W HIN	SE TO REQUES BURDEN MANAGI ULATORY ID TO T 104), GTON, D	COMPLY WITH 50.0 HRS. ESTIMATE TO MENT BRANCH COMMISSION, HE PAPERWORK OFFICE OF C 20503.	
FACILITY	Y NAME	(1)	+ 2						DOCKET	NUMBER (2)	7	1	PAGE (3)	
DIGIC	ANOUN	27 MG	L Z	ve Accumula	tor Nit	rogen	Drac	harge	Dross	ure Found	Too Hi	ab Du	e To	
Equip	ment	Failu	re	ve Accumula	ICOL MIC	rogen	FIEL	larye	LT699	ure round	100 11	gii Du	10 10	
EVEN	T DATE	(5)		LER NUMBER (6))	REPO	RT DATE	(7)	Γ	OTHER FACIL	ITIES INV	OLVED	(8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY	NAME		DOCKET	NUMBERS	
02	15	95	95 -	001	00	03	17	95	FACILITY	NAME		DOCKET	NUMBER	
OPERA	TING	1	THIS REP	PORT IS SUBMITTE	D PURSUANT	TO THE	REQUIR	EMENTS	OF 10 CF	R §: (Check o	one or mo	·e) (11)	
NODE	(9)	1	20.40	02(b)		20.405	(c)			50.73(a)(2)(i	iv)	73	71(b)	
POW	ER	100	20.40	05(a)(1)(i)		50.36(0	:)(1)			50.73(a)(2)()	()	73.	.71(c)	
LEVEL	(10)		20.40	05(a)(1)(ii)		50.36(0	:)(2)			50.73(a)(2)(v	vii)	OTI	IER	
			20.40	05(a)(1)(iii)	X	50.73(8	i)(2)(i)		50.73(a)(2)(viii)(A) (Special Abstraction			act below	
			20.40	05(a)(1)(iv)		50.73(8	a)(2)(i	i)		50.73(a)(2)(v111)(B) and in T			Text,	
			20.40	05(a)(1)(v)		50.73(8	1)(2)(1	(1)		50.73(a)(2)()	()	NRC Fo	rm 366A)	
energener/a	1	narionan T	COMP	LETE ONE LINE FO	OR EACH CO	PONENT	FAILURE	DESCR	IBED IN T	HIS REPORT (1	3)			
CAUSE	SYST	EM CO	MPONENT	MANUFACTURER	TO NPRD	S	C	AUSE	SYSTEM	COMPONENT	HANUFAC	TURER	TO NPRDS	
Х	SE		V	W165	Y		4							
			SUPPLEMEN	TAL REPORT EXPE	CTED (14)				E	(PECTED	MONTH	DA	Y YEAR	
YES (If	yes, co	mplete	EXPECTED	SUBMISSION DATE).	x	NO		SUE	TE (15)				
ABSTRAC	T (Lim	it to 1	400 space	s, i.e., approx	imately 15	single-	spaced	typewr	itten lin	es) (16)				
On 2, the U blowd Opera Reque 4-way test was a accur Opera Becau	/10// Unit down able est w y val ing p an al mula ation use (95, 0 2 MS on t at t was w lve. revea onorm tor (ns or of th	perat IV's. he 2A he ti ritte On 2/ led t ally 4200 igina e hig	ions perfo At that MSIV Act me due to n to troud 15/95, the hat the b high nitro psi vs. 3 lly though h nitrogen	ormed time t ive Tr the s blesho e blow lowdow ogen p 600 ps ht the n prec	the q hey w ain. ucces ot a down n fun recha i). T blow	uart ere The sful susp 4-wa ctio rge his down	erly unab valv 10% ecte y va pres high fun	MSIV ble to re was valve valve was of pro- sure pre- pre- ction	Partial perform determi e stroke blem wit as repla rable, h found on here is a not	Stro the ned the ced. the the the work	ke T accu be Acti blo Furt r, ti Acti reas cor	est on mulator on wdown her here ve side on that rectly.	

psi was due only to the nitrogen. With the nitrogen pressure at 4200 psi, the Active train was inoperable as there was not a sufficient hydraulic oil volume left in the accumulator to close the MSIV within the required closing time of 5 seconds as required by Technical Specification Surveillance requirement 4.7.1.5. The cause was determined to be leaking of the crosstie valves between the active and standby accumulators. There have been no previous occurrences at Braidwood. NRC FORM 366 (5-92)

NRC FORM 366A (5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95

LICENSEE EVENT REPORT (LEE TEXT CONTINUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORMARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MHBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND REDGET WASHINGTON, DC 20503					
FACILITY NAME (1)	DOCKET NUMBER (2)	l.	LER NUMBER (6))	PAGE (3)	
Braidwood Unit 2	05000457	YEAR	SEQUENTIAL NUMBER	REVISION	2 OF 7	
	05000457	95	001	00		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

A. PLANT CONDITIONS PRIOR TO EVENT:

EVENT DATE: 02/15/95 UNIT: Braidwood Unit 2 EVENT TIME: 1130 MODE: RX POWER: 100% 1 RCS [AB] TEMPERATURE/PRESSURE: NOT/NOP

B. DESCRIPTION OF EVENT:

There was no equipment inoperable at the beginning of this event that contributed to the severity of the event.

On 2/10/95, Operations was performing procedure 2BwOS 0.5.MS.1, Quarterly Main Steam Isolation Valve (MSIV) Partial Stroke Test. When the 10% stroke was performed on the 2A MSIV active accumulator side, all components needed to perform a 100% stroke were verified operable (the open/close circuit 4way valve, "A" solenoid, and the active accumulator). Hydraulic pressure on the accumulator dropped from 5000 psig to 4200 psig, as is expected for this portion of the test. The fact that the 10% stroke worked proved that the open/close 4-way valve was properly aligning the accumulator to the system. The next step of the test required a blowdown of the active accumulator and verification of correct nitrogen precharge pressure (~3600 psig at NOT). However, when the test switch in the Main Control Room was placed in the blowdown position (C and D solenoids energized), nothing was seen, heard, or felt in the field to indicate a blowdown had occurred. Normal expectations are that accumulator pressure will drop to around 3600 psig and the hydraulic oil reservoir level will increase. Accumulator pressure was indicating around 4100 psig. Blowdown did not apparently function properly. However, when the test switch was placed back to "normal" after the blowdown attempt the accumulator began to recharge, verifying that the test 4-way valve was again aligning the accumulator to the system.

An action request was written to address the problem, and troubleshooting by Mechanical Maintenance (non-licensed) and the System Engineer (nonlicensed) began. Items checked included verification that the accumulator outlet valve was open. This was found lockwired open at the appropriate 24 turns. The fact that the 10% valve stroke test functioned properly proved that the outlet valve was properly set. When the active accumulator pumped back to 5000 psi, the installed gauge on that accumulator matched the

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				APPROVED BY ONB NO. 3150-0104 EXPIRES 5/31/95					
LICENSE TE					ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20503					
FACILITY	NAME (1)	DOCKET NUMBER (2)	7	LER NUMBER (6)	PAGE (3)				
Braidwood Unit 2		05000457	YEAR	SEQUENTIAL	REVISION					
		05000457	95	001	00	3 of 7				

B. DESCRIPTION OF EVENT (continued) :

installed pressure gauge on the standby accumulator. Although there may have been error in the active gauge, it would have had to be identical to any error in the standby gauge. Problems with the gauge calibration were discounted at this time. Pilot air pressure was checked and found to be where it should be at 80 psi. Both the C and D solenoids were checked and found to be energized during the blowdown mode as required. Proper venting of air through these solenoids was also verified, showing that the blowdown 4-way valve was receiving a proper air signal to shift it to the blowdown position. When this 4-way valve was given a blowdown signal, pressure in the active accumulator showed about a 100 psig decrease (from 4200 psig to 4100 psig). This is normal when a 4-way valve shifts due to internal leakage as the valve spool slides between ports. Also, the hydraulic pump stalled, indicating that the 4-way valve had shifted to either the mid position (all ports isolated) or to the blowdown (reservoir) position. This left two options as to the cause of the failure. First was a total lack of hydraulic fluid in the accumulator. Second was that the blowdown 4way valve was only shifting 1/2 way and was hanging up in the mid position.

A total lack of hydraulic fluid in the accumulator was first considered as a cause of no blowdown, but this would indicate a very high nitrogen precharge in the accumulator. This abnormally high precharge was not considered as the most likely failure because precharges are accurately and routinely done by Operations via BwOP MS-5, and the oil level in the reservoir was not above the normal level. If the nitrogen precharge in the accumulator was high, not as much oil would be charged into the accumulator and the reservoir level would be abnormally high. Additionally, high nitrogen pressure was discounted as the sole cause of the failed blowdown because Operations had just successfully completed the 10% partial stroke, and if the observed 4100 psi accumulator pressure had been from nitrogen only, then there would have had to be exactly enough oil in the accumulator at the start of the event to perform one 10% stroke with no oil left over. This was considered a very unlikely scenario. All indications pointed to a defective blowdown test 4-way valve, which would not affect MSIV Operability. The System Engineer made the determination that the MSIV was operable, even with a defective blowdown 4-way valve, due to the fact that the valve had performed a 10% stroke successfully and the accumulator pressure was restored to 5000 psig after the test switch was returned to normal. Preparations were made to change out the blowdown 4-way valve.

NRC FORM 366A (5-92)	U.S. N	UCLEAR REGULATORY COMMISSION	APPROVED BY CMB NO. 3150-0104 EXPIRES 5/31/95					
LICE	NSEE EVENT REPOR TEXT CONTINUATI	T (LER) ION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WIT THIS INFORMATION COLLECTION REQUEST: 50.0 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE T THE INFORMATION AND RECORDS MANAGEMENT BRANC (MNBB 7714), U.S. NUCLFAR REGULATORY COMMISSION WASHINGTON, DC 20555-0001, AND TO THE PAPERWOR REDUCTION PROJECT (3150-0104), OFFICE O MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.					
FA	CILITY NAME (1)	DOCKET NUMBER (2)		SR NUMBER (5)	PAGE (3)		
Braidwood Unit 2		05000457	YEAR	SEQUENTIAL	REVISION	4 05 5		
		05000457	001	00	4 OF 7			

B. DESCRIPTION OF EVENT (continued):

On 2/15/95, the blowdown 4-way valve was changed out on the 2A MSIV active side accumulator. The accumulator was charged back up to a pressure of 5000 psig and a 10% partial valve stroke was successfully performed. The pressure in the accumulator dropped to 4300 psig (expected). The blowdown test was then executed. A rag placed on the reservoir breather to prevent hydraulic oil from possibly blowing out of the reservoir during the test was lifted off the vent when the blowdown was performed. This showed that blowdown had definitely occurred, however the indicated accumulator pressure was reading 4200 psig. For the given room temperature, a precharge of 3600 psig would be expected. A 4200 psig accumulator precharge pressure is outside the operability bounds. The operator in the field was directed to bleed off 600 psig of nitrogen to reduce the precharge to within the pressure bounds of procedure BwOP MS-5T2, (Temperature/Pressure Limits). The active side accumulator was allowed to recharge to a pressure of 5000 psig. Both the 10% partial strule and blowdown tests were repeated satisfactorily.

Given the above information, it is evident that the active side accumulator on the 2A MSIV contained too high a nitrogen precharge pressure and was inoperable following the failure of the surveillance run by operations on 2/10/95. This rendered the 2A MSIV inoperable for a period of time which exceeded the 48 hours allowed by Technical Specification 3.3.2.

The design function of the Main Steam Isolation Valve (MSIV) is to close within 5 seconds after receiving an ESF actuation signal. To do this, two safety related, captive nitrogen accumulators provide high pressure hydraulic fluid to the valve actuator ram through two fully redundant hydraulic circuits. A 4-way hydraulic valve is used to control the actuator ram direction to open or close the MSIV. The shifting of this valve is done by air which is controlled by A and B solenoids. All solenoids are normally de-energized with the MSIV open at power.

A second 4-way valve is used to line up the accumulator to either the hydraulic opening and closing circuit, or to the reservoir (blowdown) for testing. The shifting of this second 4-way valve is done by C and D solenoids. With both the C and D solenoids de-energized, air is ported to the 4-way valve such that the accumulator is lined up to the open and close hydraulic circuit. This is the normal configuration when the MSIV is open at power. When the C and D solenoids are energized, air is ported to this 4-way valve such that the accumulator is lined up to the reservoir and all hydraulic fluid in the accumulator is lined up to the reservoir. This allows checking of the remaining nitrogen (precharge) pressure in the accumulator.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION FACILITY NAME (1) Braidwood Unit 2 DOCKET NUMBER (2) DOCKET NUMBER (2) DOCKET NUMBER (2) LICENSEE EVENT REPORT (LER) TEXT CONTINUATION ESTIMATED BURDEN PER RESPONSE TO COMPLY THIS INFORMATION COLLECTION REQUEST: 50.0 FORWARD COMMENTS REGARDING BURDEN ESTIMA THE INFORMATION AND RECORDS MANAGEMENT UNABER 7714,0, U.S. NUCLEAR REGULATORY COMMIN WASHINGTON, DC 20555-0001, AND TO THE PAP REDUCTION PROJECT (3150-0104), OFFIC MANAGEMENT AND BUDGET. WASHINGTON, DC 20500 PAGE 0 10000457 95 001 00	NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY CONST SSICN				APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95					
FACILITY NAME (1) DOCKET NUMBER (2) LER NUMBER (6) PAGE Braidwood Unit 2 YEAR SEQUENTIAL NUMBER REVISION NUMBER 5 OF 05000457 95 001 00	LICENSEE EVENT R TEXT CONTIN	EPORT (LER) NUATION	ESTIMATED BURDEN PER RESPONSE TO COMPLY WI THIS INFORMATION COLLECTION REGUEST: 50.0 HR FORWARD COMMENTS REGARDING BURDEN ESTIMATE THE INFORMATION AND RECORDS MANAGEMENT BRAN (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSIO WASHINGTON, DC 20555-0001, AND TO THE PAPERWO REDUCTION PROJECT (3150-0104), OFFICE MANAGEMENT AND BUDGET WASHINGTON DC 20503								
Braidwood Unit 2 05000457 95 001 00 00	FACILITY NAME (1)	DOCKET NUMBER (2)	1	LER NUMBER (6)	PAGE (3)					
05000457 95 001 00	Braidwood Unit 2	05000457	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 7					
		05000457	95	001	00						

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

B. DESCRIPTION OF EVENT (continued):

A clearly defined temperature-pressure curve is used to determine the required precharge pressure on the accumulators and maintain a correct ratio of nitrogen to hydraulic fluid.

An empty, uncharged accumulator will first be completely filled with nitrogen. This is referred to as the precharge pressure and is determined by the ambient temperature. This precharge pressure is also the minimum pressure available to the actuator to close the MSIV at the end of the close stroke. This is a captive volume and is not withdrawn or mixed with the hydraulic oil during valve operation due to a sealed, floating piston inside the accumulator separating the nitrogen and hydraulic fluid. In order to hydraulically charge the accumulators, a small, non-safety related air driven hydraulic pump is utilized. This is a positive displacement pump and has a given hydraulic output pressure for a given air input pressure.

The input air pressure is adjusted for a hydraulic output pressure of 5000 psig. During normal operations, the accumulator will continue to "charge" until both the hydraulic and nitrogen pressures are at 5000 psig. The internal accumulator piston floats as hydraulic oil is charged into the accumulators. At this point, the pump stalls and the accumulators are ready to close the MSIV within the required 5 seconds.

As the temperature in the MSIV room increases during power operations, the pressure in the accumulators also increases (the mass balance between the nitrogen and hydraulic fluid remains constant). In order to adjust accumulator pressure as temperature increases, a precharge (or blowdown) test is performed. This test releases the accumulator's hydraulic fluid to the reservoir. Nitrogen pressures are then checked and adjusted, if required, based on the accumulator temperature. Maximum and minimum pressure lines found on the precharge graph bound the operability limits for that accumulator and thus, that MSIV's train.

This report is being submitted pursuant to 10CFR50.73(a)(2)(i)(B) - any operation or condition prohibited by the plant's Technical Specifications.

C. CAUSE OF EVENT:

The primary cause of the overpressure in the active accumulator is attributed to Equipment Failure. One or more crosstie valves in the nitrogen header connecting the active and standby accumulators were found to be leaking. This active nitrogen gas space is crosstied via two normally closed manual isolation valves. A check of these valves confirmed that there was indeed leakage past at least one of the normally closed NRC FORM 366 (5-92)

NRC FORM 366A (5-92) LICENSEE EVENT R TEXT CONTIN	APPROVED BY ONE NO. 3150-0104 EXPIRES 5/31/95 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PA OFFICE OF					
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)	
Braidwood Unit 2	05000457	YEAR	SEQUENTIAL	REVISION		
	05000457	95	001	00	6 OI 7	

TEXT (If more space is required, use additional copies of MRC Form 366A) (17)

C. CAUSE OF EVENT (continued):

valves. Each accumulator is normally tested individually for a partial stroke and blowdown test. During this test, a pressure differential is set up for at least 30-45 minutes while the hydraulic pump restores accumulator pressure to normal. It appears that a mass transfer of nitrogen occurred from the standby accumulator to the active accumulator during this test on 11/12/95, as each was found to be exactly 700 psig off the as-left pressure, active high and standby low, that MMD charged them to on 11/02/94.

Numerous other failure modes were investigated following this event. All but the above have been discounted as being the most probable mechanism of failure.

D. SAFETY ANALYSIS :

The safety implications of the high nitrogen precharge is that the valve would not have gone fully closed within the required 5 seconds as specified in Technical Specification Surveillance Requirement 4.7.1.5, if it had received a close signal on the active train only. However, the valve would have closed within the required time limit of 5 seconds if a SSPS train "B" Main Steam Isolation Signal had been received. Train "B", the standby accumulator, remained Operable throughout this event. If a manual closure signal was given to the 2A MSIV using the control switch on 2PM06J in the Main Control Room, the valve would have gone 96% closed within 3 seconds, and would then have pumped fully closed via the air driven hydraulic pump, within 30 seconds. Typically, this manual control switch is only used for opening or closing a MSIV in mode 4, since any abnormal plant condition requiring manual steam line isolation will direct the NSO to verify/actuate the MS Isolation switches on either 2PM05J or 2PM06J. These control switches give an automatic close signal to both the "A" and "B" train of all MSIV's. In addition, should the MSIV fail to close completely, the Emergency Operating Procedures contain contingency actions for the operators to perform to address this event. The safety significance of this event was minimal, since the redundant train "B" hydraulic system on the 2A MSIV would have closed the valve within the required 5 seconds during almost any plausible event, for example, testing of a train.

NRC FORM 366 (5-92)

NRC FORM 366A (5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104 EXFIRES 5/31/95

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO

LICENSEE	EVENT	REPORT	(LER)
TEX	CONT	INUATIO	N

LICENSEE EVENT REPORT (LE) TEXT CONTINUATION	R)	THE IN (MNB8 7 WASHING REDUCTI MANAGEP	FORMATION AND N 7714), U.S. NUCLI STON, DC 20555-0 ION PROJECT MENT AND BUDGET,	RECORDS MAI EAR REGULAT 001, AND T (3150-0104) WASHINGTON	AGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK O OFFICE OF DC 20503.
FACILITY NAME (1)	DOCKET WUMBER (2)		LER HUMBER (6)	PAGE (3)
Braidwood 2	05000457	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	7 OF 7
	05000457	95	001	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

E. CORRECTIVE ACTIONS:

Inspections were performed on all MSIV nitrogen isolation values on both Unit 1 and 2. Leakage was identified on both the 2A and 2D MSIVs. Action requests #950008845, 950008855, 950008856, and 950008858 have been written to inspect and repair/replace all nitrogen cross tie manual isolation valves for the 2A (two valves) and the 2D (two valves) MSIV.

During the investigation, several other enhancements to the MSIV procedure, unrelated to this event, were identified as being warranted. These are being tracked outside of this LER.

F. PREVIOUS OCCURRENCES:

There have been no occurrences of this type previously a' Braidwood Station.

G. COMPONENT FAILURE DATA:

MANUFACTURER	NOMENCLATURE	MODEL	PART NO.		
Whitey Co.	"HN" Series Severe Service Needle	SS-6HNBF8		N/1	A