

DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

October 27, 1983

Mr. J. G. Keppler, Regional Administrator United States Nuclear Regulator Commission Region III, 799 Roosevelt Road Glen Ellyn, Illinois 60137

Operating License DPR-58/DPR-74 Docket No. 50-315/50-316

Dear Mr. Keppler:

On October 20, 1983, we reported to Mr. N. Jackiw and Mr. J. Heller by telephone and confirmed by my letter dated October 20, 1983, a situation that occured with Unit one in which we believed at the time that we had operated in Mode 4 for a period of time with the "Automatic Actuation Logic" of Engineered Safety Features Actuation System inoperable as required by Technical Specification 3.3.2.1, Table 3.3-3, item 1.b. Subsequent review reveals that the "Automatic Actuation Logic" was operable in that any feature required to provide actuation in Mode 4 would have provided Actuation of Safety Injection, Feedwater Isolation, Phase A Isolation, etc., during that time. The "blocks" present on entry into Mode 4 were being provided by the logic and the blocked functions were not required in Mode 4. Therefore, the prompt telephone report advising of this event was unnecessary and is hereby retracted.

Sincerely,

W. G. Smith, Jr.

cc: J. E. Dolan

M. F. Alexich

R. F. Kroeger

H. Brugger

E. R. Swanson/N. DuBry, RO:III

R. C. Callen, MPSC

G. Charnoff, Esq.

J. M. Hennigan

R. O. Bruggee, EPRI

INPO

PNSKC

J. F. Stietzel

E. L. Townley

Dir., IE (40 copies)

Dir., MIPC (4 copies)

8311040079 831027 PDR ADOCK 05000315 S PDR OCT 1 1 1/0