

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
01 N C M G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5										7 8 9 14 15 25 26 30 37 CAT 58									
CON'T																			
01 REPORT SOURCE L 6 0 5 0 0 0 3 6 9 7 1 1 1 1 8 3 8 1 1 2 3 8 3 9										7 8 60 61 68 69 74 75 80									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																			
02 While in Mode 1, Instrumentation and Electrical technicians attempting to repair																			
03 lower personnel air lock (PAL) door pins inadvertently deflated the door seals on																			
04 the reactor building side door while the auxiliary building side door was open.																			
05 (Annulus door was closed.) This violates T.S.3.6.1.3 and is reportable per T.S.																			
06 6.9.1.10.(b). Recent changes on the PALs allow seal deflation if interlocking de-																			
07 vices change state after the doors are closed. This change requires power removal																			
08 prior to working on closed doors; however, the technicians were unaware of this.																			
The health and safety of the public were unaffected.																			
09 S D 11 D 12 Z 13 P E N E T R 14 A 15 Z 16										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32																			
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-1 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER																			
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 Z 9 9 9 26										33 34 35 36 37 38 39 40 41 42 43 44 45 46 47									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																			
10 This incident occurred due to a procedural deficiency. When the technician real-																			
11 ized containment integrity had been lost, he left the PAL and closed and sealed the																			
12 outer door, reestablishing integrity. The loss of contaminated air from containment																			
13 was insignificant. A procedural step was added to require one PAL door to be sealed																			
14 by removing power when work is done on the other door with the unit above Mode 5.																			
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32																			
15 E 28 0 9 9 29 NA A 31 IAE Technician Observation										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36																			
16 Z 33 Z 34 NA NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39																			
17 0 0 0 37 Z 38 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
PERSONNEL INJURIES NUMBER DESCRIPTION 41																			
18 0 0 0 40 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43																			
19 Z 42 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
PUBLICITY ISSUED DESCRIPTION 45																			
20 N 44 NA										7 8 9 10 11 12 13 14 15 16 17 18 19 20									
NAME OF PREPARER W. H. McDowell																			
PHONE: (704) 373-8878																			

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

November 23, 1983

83 NOV 28 8:52
TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
LER/RO-369/83-107

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-107. This report concerns Technical Specification 3.6.1.3, "Each containment air lock shall be operable with: a. Both doors closed except when the air lock is being used for normal transit entry and exits through the containment, then at least one air lock door shall be closed, and..." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

Hal B. Tucker
HBT

Hal B. Tucker

WHM/php

Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

OFFICIAL COPY

IE 22
11