

# NORTHEAST UTILITIES



The Connecticut Light And Power Company  
Western Massachusetts Electric Company  
Holyoke Water Power Company  
Northeast Utilities Service Company  
Northeast Nuclear Energy Company

General Offices: Seiden Street, Berlin, Connecticut

P.O. BOX 270  
HARTFORD, CONNECTICUT 06141-0270  
(203) 665-5000

Re: 10CFR50.73(a)(2)(iv)

September 20, 1991

MP-91-746

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Reference: Facility Operating License No. DPR-21  
Docket No. 50-245  
Licensee Event Report 91-023-00

Gentlemen:

This letter forwards Licensee Event Report 91-023-00 required to be submitted within thirty (30) days pursuant to 10CFR50.73(a)(2)(iv).

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

  
Stephen E. Scace  
Director, Millstone Station

SES/SC:ljs

Attachment: LER 91-023-00

cc: T. T. Martin, Region I Administrator  
W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2 and 3  
D. H. Jaffe, NRC Project Manager, Millstone Unit Nos. 1 and 3

9110020025 910920  
PDR ADOCK 05000245  
S PDR

*Ext No  
P002503677  
IF22  
11*

## LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this information collection request: 50 0 hrs. Forward comments regarding burden estimate to the Records and Reports Management Branch (p-530), U. S. Nuclear Regulatory Commission, Washington, DC 20555, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503.

FACILITY NAME (1)

Millstone Nuclear Power Station Unit 1

DOCKET NUMBER (1)

0 5 0 0 0 2 4 5 1 OF 0 1 2

PAGE (2)

TITLE (4)

Unplanned Standby Gas Treatment System Initiation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
0	8	2	1	9	1	9	1	0	5	0	0
0	8	2	1	9	1	9	1	0	5	0	0
OPERATING MODE (9)			THIS REPORT IS BEING SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)								
N			<input checked="" type="checkbox"/> 20.402(b) <input type="checkbox"/> 20.402(c) <input checked="" type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 73.71(b)								
POWER LEVEL (10)			<input type="checkbox"/> 20.405(a)(1)(i) <input type="checkbox"/> 50.36(c)(1) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 73.71(c)								
0 0 0			<input type="checkbox"/> 20.405(a)(1)(ii) <input type="checkbox"/> 50.36(d)(2) <input type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/> OTHER (Specify in Abstract below and in Ten, NRC Form 366A)								
			<input type="checkbox"/> 20.405(a)(1)(iii) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(viii)(A)								
			<input type="checkbox"/> 20.405(a)(1)(iv) <input type="checkbox"/> 50.73(a)(2)(ii) <input type="checkbox"/> 50.73(a)(2)(viii)(B)								
			<input type="checkbox"/> 20.405(a)(1)(v) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)

NAME

Steve Cohen, Engineer, Ext. 4403

TELEPHONE NUMBER

AREA CODE

2 0 3 4 4 7 - 1 7 9 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	B	H		No					

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

☐ YES (If yes, complete EXPECTED SUBMISSION DATE) ☒ NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On August 21, 1991, at 0833 hours, during plant start-up (246 degrees Fahrenheit and 15 psia) the "A" Standby Gas Train initiated and a partial Group II isolation was received. Operations personnel verified that there were no valid initiation signals and secured "A" Standby Gas and reset the partial Group II isolation. This event occurred two additional times at 0849 hours on August 21, 1991, and at 1311 hours on August 27, 1991, and it was determined to be related to work being performed in the control panel. Investigation revealed a loose connection to be the cause of the "A" Standby Gas Train initiation. The connection was tightened and the Standby Gas Treatment System Operability surveillance was successfully performed. No safety consequences resulted from the event.

NRC Form 365A (6-89)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92 Estimated burden per response to comply with this information collection request: 50.0 hrs. Forward comments regarding burden estimate to the Records and Reports Management Branch (p-530), U.S. Nuclear Regulatory Commission, Washington, DC 20565, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503.																
<b>LICENSEE EVENT REPORT (LER) TEXT CONTINUATION</b>																				
FACILITY NAME (1)  Millstone Nuclear Power Station Unit 1		DOCKET NUMBER (2)  0 5 0 0 0 2 4 5 9 1		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="3">LER NUMBER (6)</th> <th colspan="2">PAGE (3)</th> </tr> <tr> <th>YEAR</th> <th>SEQUENTIAL NUMBER</th> <th>REVISION NUMBER</th> <th></th> <th></th> </tr> <tr> <td></td> <td>0 2 3</td> <td>0 0</td> <td>0 2</td> <td>OF 0 2</td> </tr> </table>		LER NUMBER (6)			PAGE (3)		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				0 2 3	0 0	0 2	OF 0 2
LER NUMBER (6)			PAGE (3)																	
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER																		
	0 2 3	0 0	0 2	OF 0 2																
TEXT (If more space is required, use additional NRC Form 365A's) (17)																				
<p>I. <u>Description of Event</u></p> <p>On August 21, 1991, at 0833 hours, during plant start-up (246 degrees Fahrenheit and 15 psia) the "A" Standby Gas Train initiated and a partial Group II isolation was received. Operations personnel verified that there were no valid initiation signals and secured "A" Standby Gas and reset the partial Group II isolation. This event occurred two additional times at 0849 hours on August 21, 1991, and at 1311 hours on August 27, 1991, and it was determined to be related to work being performed in the control panel. Investigation revealed a loose connection to be the cause of the "A" Standby Gas Train initiation. The connection was tightened and the Standby Gas Treatment System Operability surveillance was successfully performed. No safety consequences resulted from the event.</p>																				
<p>II. <u>Cause of Event</u></p> <p>The cause of the event was determined to be a loose connection, that was disturbed while work was being performed in the control room panel, that caused one of the Group II isolation relays to deenergize resulting in the initiation of "A" Standby Gas and a partial Group II isolation.</p>																				
<p>III. <u>Analysis of Event</u></p> <p>The incident is reportable per 10CFR50.73(a)(2)(iv), "Any event or condition that resulted in an unplanned manual or automatic actuation of any Engineered Safety Feature (ESF)."</p> <p>While a design modification was being implemented in a control room panel the "A" Standby Gas Treatment System initiated and a partial Group II isolation was received. Operations personnel verified that there were no valid initiation signals present and secured Standby Gas and reset the Group II isolation. The modification work continued and "A" Standby Gas initiated for a second time and at this time it was determined to be related to the modification being performed in the control room panel. Investigation revealed that a Group II relay was deenergized and was determined to be the cause of the "A" Standby Gas initiation. The wiring to the coil of this relay was checked and no loose connections were found. On August 27, 1991, at 1311 hours the "A" Standby Gas Treatment System initiated again when the modification work resumed. An indepth look of all the relay wiring was conducted and a loose connection was found on contact 3-4 of the Group II isolation reset. A momentary loss of continuity in this circuit would remove the relay seal-in and deenergize the Group II isolation relay. This relay would not energize until the Group II isolation was reset.</p> <p>The wire was tightened and the Standby Gas Treatment System Operability Surveillance was successfully performed. The Standby Gas Treatment System was determined to be operable, since the loose connection would not prevent standby gas from being initiated on an actual initiation signal. As a worse case, the loose connection would initiate Standby Gas when the loose connection was disturbed in any way.</p>																				
<p>IV. <u>Corrective Action</u></p> <p>Operations personnel verified that no valid initiation signals were present and secured Standby Gas and reset Group II isolation. A work order was created to troubleshoot the cause of the initiation. The cause was determined to be a loose connection. The loose connection was tightened and the standby gas treatment system operability surveillance was performed and successfully completed.</p>																				
<p>V. <u>Additional Information</u></p> <p>None</p>																				