

Report Issued:

AUG 26 1977

Report 411-77.55

PACIFIC GAS AND ELECTRIC COMPANY
DEPARTMENT OF ENGINEERING RESEARCH

FAILURE ANALYSIS OF CRACKED FIELD WELD NO. 212
DIABLO CANYON UNIT 1, STEAM GENERATOR 1-2
NOZZLE-TO-PIPE WELD

Prepared By:

S. F. Friedrich
S. F. FRIEDRICH, Engineer

S. T. Ivy
S. T. IVY, Engineer

Approved By:

W. C. Ham
W. C. HAM, Sr. Metallurgical Engr.

C. J. Reinberg
C. J. REINBERG, Supv. Engineer

TABLE OF CONTENTS

	Page
LIST OF TABLES	11
LIST OF APPENDICES	11
LIST OF FIGURES	111
SCOPE	1
INTRODUCTION	1
FABRICATION AND SERVICE HISTORY	2
Material Specifications	2
Welding and Heat Treating History	2
Service History	3
RESULTS OF METALLURGICAL EXAMINATION	4
CONCLUSIONS	6
RECOMMENDATIONS	8
TABLES AND FIGURES	9
APPENDICES	22

LIST OF TABLES

Table	Page
I Fabrication and Service History (Summary)	9

LIST OF APPENDICES

	Page
I Material Specifications	22
II Hot Functional Module	34
III Analysis of Element Patterns	37

LIST OF FIGURES

Figure	Page
1 Sketch of spool piece and crack path and shape of crack	10
2 Fracture surface, overall view	11
3 Fracture surface, area of SEM examination	12
4 SEM photographs of main fracture surface	13
5 Polished cross-section of the main fracture	14
6 Cross-section of secondary cracks	15
7 Polished cross-section of secondary crack	16
8 Details of polished cross-section	17
9 Opened crack (secondary)	18
10 Microprobe spectrum of steel matrix	19
11 Microprobe spectrum of oxide in crack	20
12 Microprobe spectrum of inclusion stringer	21

SCOPE

This report covers the metallurgical investigation of a crack found in the pipe-to-nozzle weld of feedwater line of Steam Generator 1-2 at Diablo Canyon Power Plant. Based on the findings of this investigation, recommendations are made for modification of the welding procedures, fabrication practices, and inspection of future welds made in P-3 nozzle materials.

INTRODUCTION

On March 17, 1977, during heat-up for hot functional testing of Unit 1, a leak was discovered in the nozzle-to-pipe butt weld joining the 16-inch diameter feedwater pipe to the No. 4 nozzle of Steam Generator 1-2 (Field Weld No. 272, Line K76-555-16IV). The line temperature and pressure at this time was approximately 300°F and 90 psi, respectively. Visual observation at this time revealed an intermittent linear indication approximately 3/8-inch long running in the circumferential direction near the center of the weld. During grinding of the weld crown flush with the pipe surface the length of this linear indication increased to approximately two inches. Subsequent nondestructive examination by radiography and ultrasonics revealed a crack with a total length of approximately six inches.

As a result of the above findings, a spool piece containing a major portion of the weld, a small section of the nozzle I.O. adjacent to the weld root, and several inches of pipe were removed for analysis. Figure 1 is a sketch of the spool piece received for analysis; included is the crack path and a sketch of the shape of the crack.

FABRICATION AND SERVICE HISTORY

Material Specifications

The steam generator nozzle is fabricated of ASME SA508 Class 2 material. A copy of the original Material Test Report and a chemical analysis performed on the nozzle material adjacent to the crack are included in Appendix I. The chemical and physical properties for this material are within the limits for SA508 Class 2 material.

The feedwater line piping is fabricated from ASTM A106 Grade B material. A copy of the chemical analysis performed on this material adjacent to the crack are included in Appendix I. This analysis shows that the pipe material meets the chemical requirements of ASTM A106 Grade B.

Welding was performed using E8018 C-3 electrode. A copy of the original Certificate of Analysis for the three electrode lots used and a check analysis taken adjacent to the crack are included in Appendix I. These analyses show the material to within the chemical requirements of E8018 C-3.

Welding and Heat Treating History

Welding on Field Weld 272 was done in accordance with M. W. Kellogg Procedure 200. The weld traveller and other Q.C. documents were checked along with the temperature records for preheating and postweld heat treatment for compliance with this procedure; no deviations were noted. The weld root was placed using the tungsten inert gas method (TIG) with a consumable insert and inert gas backing. Two TIG fill passes were put in and the weld was completed using shielded metal arc weld. The weld

preparation was preheated to 200°F prior to welding. Welding on FW 212 was done over a time period of several weeks; Table I is an outline of this welding history.

Postweld heat treatment was performed at 1150°F; metal temperatures were monitored on both the pipe and nozzle sides of the weld with a thermocouple placed several inches from the centerline of the weld. The temperature records were reviewed, and during heat-up there was an uneven heating rate between the pipe and the nozzle, resulting in a maximum temperature differential of 260°F, where the pipe was at a temperature of 680°F when the nozzle was at 420°F. This temperature differential was rectified and no further problems were encountered throughout the postweld heat treatment.

Radiography of this weld was performed after completion of welding but prior to postweld heat treatment, an acceptable practice under the governing construction code, USAS 331.1.0-1967. Review of the radiographs showed a slight density gradient in the region where the crack occurred, but it was not judged to be rejectable nor would it be interpreted as such now. If this indication in actuality is a crack, it is at the limit of detectability.

Service History

Prior to making FW 212, a cap was welded onto the feedwater nozzle of SG 1-2, and a hydro test of the steam generator was performed. Subsequently, the piping was attached and two more hydro test cycles were performed, followed by a hot functional test program. A second hot functional was underway when the leak occurred. This sequence of events is summarized in Table I, the hot functional testing summary is in Appendix II.

During the period between the hydro test following weld completion, August 29, 1975, and the time the leak occurred, March 17, 1977, the system was filled with water under chemical control to limit corrosion or other damage to the piping or steam generator internals. The water chemistry records were reviewed and no abnormal conditions were noted.

RESULTS OF METALLURGICAL EXAMINATION

The surface of the main fracture was almost flat, originated along the edge of a weld bead, grew approximately perpendicular to the surface and contained markings that ran parallel to the original edge, Figures 2 and 3. These markings appeared to be "beachmarks" denoting positions of the crack during its growth. The fracture surface appeared to be oxidized and was dark in color near the origin edge. Using SEM, the main fracture surface was found to be oxidized, to exhibit some evidence of mechanical damage (rubbing) and, at a distance from the origin, to contain secondary cracks, Figure 4. The presence of the visual beachmarks and the secondary cracks indicate that cyclic loading had a role in the generation of the fracture.

Examination of several polished cross-sections taken through the crack showed the fracture initiated in small regions of lack of fusion along the fusion zone and in small, up to 0.015-inch deep, cracks at the root of grinding scratches adjacent to the fusion zone on the nozzle side of the weld. The crack propagated through the heat-affected zone and then through the weld metal in the V-shaped section of the weld, Figure 5. The crack cross-section in the heat-affected zone was very flat and straight, indicating little ductility; once into the weld the crack tended to branch

and wander, indicating a material with more ductility. The heat-affected zone in both pipe and nozzle materials was tempered martensite, the pipe material away from the weld was mixed pearlite and ferrite, and the weld material was tempered martensite. Microhardness tests in these various regions, converted to Rockwell hardness values, were as follows: nozzle, away from HAZ, R_g 96; nozzle HAZ, R_c 34; weld root, R_c 23; pipe base material, R_g 88.

Examination of the small cracks adjacent to the main fracture, Figures 6, 7, and 8, illustrated that the cracks originate in slight depressions in the surface, grew perpendicular to the surface and at an oblique angle to the rolling direction (as revealed by the inclusion stringers), were filled with oxide, were transgranular, and exhibited some crack branching. No evidence of plastic deformation was observed. EDXA microprobes verified that the material in the cracks was probably oxide, that the base metal was carbon steel, and that the inclusion stringers were manganese sulfide, Figures 10-12.

Two small cracks were opened up for examination by impacting them at liquid nitrogen temperatures (Specimens 2 and 3). The fracture surfaces had a dark layer of oxide patches along the outer edge, Figure 9, and were in close proximity to weld beads. Each crack was actually the result of the coalescence of many cracks each having its own origin. The origin edges of the fracture surfaces were covered with a relatively uniform oxide layer. The oxide layer was present all the way to the tip of the prior existing crack.

Using the plastic/carbon replica technique, the details of the main fracture surface were examined in the TEM. The surface was again found to be completely oxidized; however, in some areas, the oxide formed parallel ridges which could possibly suggest prior fatigue striations. In some areas, large block-like oxide growth was found.

Extraction replicas were examined in the TEM to obtain the diffraction pattern of the oxide. The patterns obtained were analyzed, Appendix II, and found to be composed of $\alpha\text{-Fe}_2\text{O}_3$. This oxide forms at about 300°C (570°F).

CONCLUSIONS

The characteristics of the small cracks and the major fracture surface are similar in regularity, orientation, oxidation, and degree of crack branching. The oxide extended to the tip of the advancing cracks indicating that oxidation and/or corrosion was an inherent part of the crack growth process. The characteristics of the fracture process; i.e., transgranular, oxidized, no plastic deformation, with some crack branching, indicated that the crack growth mode was either corrosion fatigue or thermal fatigue.

The oxide resulting from corrosion fatigue would probably be hydrated and a lower temperature form than found on the crack surfaces in this study. Based on this and the closely regulated water purity, it is believed that it is more likely that the cracks in the feedwater line of Diablo Canyon Unit 1 steam generator resulted from thermal fatigue. The cracks initiated in elongated depressions in the surface of the steel which are believed to be grinding marks, and apparently acted as local stress risers, and at minor regions of lack of fusion in the weld root.

It is believed that small cracks initiated on the I.O. of the nozzle, weld, and pipe during the thermal cycling that occurred during preheating. These small cracks originated at convenient stress risers such as grinding scratches and regions of lack of fusion and weld bead, rollover. At the time of acceptance radiography, prior to postweld heat treatment, these cracks were below the limits of detectability for radiography. Upon heat-up for the postweld heat treatment thermal stresses from the uneven heat-up between the pipe side and nozzle side of the weld caused several of these small cracks to link up and grow to some substantial size, most likely through the heat-affected zone (HAZ) and into the weld metal. The HAZ at this time, prior to postweld heat treatment (PWHT), would have consisted of untempered martensite, and have a hardness of about $R_c 45$. The HAZ would have quite low ductility in this condition and easily propagate an existing crack when subjected to differential thermal stresses. Once this crack had propagated to a substantial size during PWHT it propagated to failure by fatigue as a result of subsequent hydro test and hot functional test stresses.

Since postweld heat treatment of the weld has tempered the heat-affected zone, this high hardness, low ductility condition no longer exists. The heat affected-zone now has a hardness of $R_c 30-35$, and would not be expected to be subject to the rapid crack growth that is believed to have occurred during PWHT.

RECOMMENDATIONS

Based on the findings of this investigation, following recommendations are made for future welds made in P-3 materials:

1. Specify a minimum preheat temperature of 250° F; a maximum interpass temperature of 550° F should also be specified.
2. Maintain the preheat temperature throughout the weld and until postweld heat treatment can be initiated. If a long delay during welding or between welding and PWHT is unavoidable, maintain the preheat for at least eight hours after welding stops, and then slowly cool to room temperature.
3. Care should be exercised in avoiding large temperature differentials during preheating and postweld heat treatment.
4. Final radiography should be done after postweld heat treatment.

TABLE 1

Fabrication and Service History (Summary)

1-14-73 Preheat to attach lugs
1-14-73 Preheat to weld cap
1-15-73 Preheat to weld cap
2-19-73 Hydro, 1356# at 106°F
4-8-74 Preheat to remove cap
4-9-74 Preheat to remove cap
5-18-74 Preheat for nozzle-pipe weld
5-21-74 Preheat for nozzle-pipe weld
5-22-74 Preheat for nozzle-pipe weld
5-23-74 Preheat for nozzle-pipe weld
5-24-74 Preheat for nozzle-pipe weld
6-15-74 Radiograph finished weld
6-24-74 PWHT weld
7-8-74 PWHT adjacent weld (15" away)
8-29-75 Second hydro, 1320# at 88°F
8-29-75 Third hydro, 1356 at 88°F
12-13-75 First hot functional
2-10-76
3-16-77 Second hot functional




Figure 1. Schematic diagram of failed nozzle illustrating the locations from which samples were removed.



Figure 2. Overall view of fracture surface.




Figure 3 Specimen #1, showing fracture surface with parallel markings originating along one side of weld bead; 3X.




Figure 4. Surface of main fracture which was in the heat affected zone (HAZ) of the nozzle, Specimen #1, showing oxidized surface with crack branching. a. 20x (50595). b. 500x (50594). c. 2000x.






Figure 5. Polished cross section of the main fracture.
The pipe is on the bottom left, the weld root
is bottom center and the nozzle is bottom right.
The bottom of the picture is the pipe I.O. The
small bright dots are micro hardness indentations.
7 x magnification.



a.



b.

Figure 6. Cross section of Specimen #3, Figure 1, which shows small secondary cracks similar to those noted adjacent to the main fracture. The tilted view shows the coincidence of the cracks with grinding marks on the pipe and nozzle I. D., as well as in the unground weld.



Figure 7. Polished cross section from main fracture area showing a crack, filled with oxide, with crack branching and sulfide inclusion stringers; 450X.




Figure 8. Details of polished cross section shown in figure 7. a. 1000X.
(51136). b. 5000X (51130).



Figure 9. Opened crack along weldment on Specimen 2 showing several fracture plateaus indicative of multiple cracks and multiple origins. a. 3X.
b. 12X.

STEEL

FLUORESCENT X-RAY SPECTRUM

Scanning Electron Analysis Laboratories, Inc.

201 WILSHIRE BLVD., LOS ANGELES, CA. 90060 • (213) 390-2720

Sample: STEEL MATRIX
Beam Voltage: 15 kV
Scan Size: 10 μ m
F.S.: 1000

Aperture: 100 μ m
Filter: None
T-X-Ray Tube: None
Area: Ident
Tilt: 111
Angle: 80°
Acquisition Time: 32K/4K
Path: Slant
Scan Rate: 1000

Total X-Ray Photon Counts (Full scale: 32K counts)



Figure 10. EDXA microprobe spectrum obtained from steel matrix in Figure 8.





Figure 12 EDXA microprobe spectrum obtained from inclusion stringer (Figure 8).



Report 411-77.55

APPENDIX I

Material Specifications and Welding Procedure

S.O. No.

411-77-55

Purchase - Westinghouse Electric Corp.

MATERIAL TEST REPORT

DATE

Purchase's Order No.

Distributor - G.I. Metals Co., Inc.

Distributor's Order No.

Wardell Metals & Foundry Inc.

DATE 10-10-69
S-O-N 54-1-1042-890

PRODUCT PO# ITEM NO.	QTY.	PRODUCT SPEC.	HEAT Q. CODE NO.	FORGING NO.	HEAT TREATMENT	SCB CHARTS ATTACHED
1 1	11.75" I.D. Insert Stud Feedwater Hoses Por/Dug. #700G217 T-00784	S1508-2	Q2Q3W	L019	1650°F ± 250°F. 1hr/in Air Cooled. 1560°F ± 250°F. 1hr/in Water Quenched. 1290°F ± 250°F. 1hr/in Air Cooled. 1560°F ± 250°F. 1hr/in Water Quenched. 1290°F ± 250°F. 1hr/in Air Cooled. Toots Stress Relieved At 1125°F ± 250°F. For 20 Hours.	X

CHEMICAL ANALYSIS AND MECHANICAL PROPERTIES

FORGING NO.	HEAT NO.	MECHANICAL PROPERTIES						NOTE REPORTS ATTACHED		
		C	Ni	S	Si	Mn	Mo	V	U.T.	M.P.
L019 L	Q2Q3W	.21	.79	.012	.012	.27	.34	.80	.68	.05
		.209	.79	.005	.015	.29	.37	.80	.57	.04

FORGING NO.	HEAT NO.	TEST TEMP. INSUL. FRI + 1000	TEST TEMP. FRI + 1000	VOL. % FRI + 1000	STRENGTH IN LBS. IN INCHES	A.S. S.H.S.	TESTING IN INCHES	LATERAL STR. IN INCHES	IMPACT TESTS IN INCHES		
									U.T.	M.P.	O.P.
L019 L	Q2Q3W	0°	93.000	72.500	21.5	64.9	92-109-114	.067-.076-.083	80-90-90		
		150°	93.100	73.400	21.5	60.9	108-118-103	.074-.076-.073	85-90-85		

*Steel to be Standardized*The following test results are shown below to be average
of our standard quality materials of the Company

CHEMETRON CORPORATION
WELDING PRODUCTS DIVISION

Certificate of Analysis

447

M. W. Kellogg Co.
c/o Pacific Gas & Elect. Co.
Daiblo Canyon Power Plant
Avila Beach, California 93424

Customer Order No. N/A

Order No. 62853

Shipped 6-6-73

This material conforms to Specification AWS A 5.5-69

Test No. 415

X-Ray Satisfactory Type E 8018 C-3
F-7177-1269 Item #

Trade Name:

Atom Arc 8018

Moisture @ 1800°F. 0.2%

Diameter Size:

1/8"

Concentricity 3%

Lot Number:

C315C3AD

Type Steel A-285

Test Number:

402K9921

	Test No.	Full	Split	Volts	Amps
--	----------	------	-------	-------	------

Carbon	.05				
Manganese	1.01				
Chromium	Nil				
Nickel	.96				
Silicon	.58				
Columbium		Test		AS	
Tantalum		Results:		Welded	
Molybdenum	.12	Yield		76,400	/
Tungsten		Tensile		87,500	/
Copper		Elongation		31%	/
Titanium		Red. of Area		76.7%	/
Phosphorus	.017	Charpy V-Notch Impacts Tested @ -40°F.			
Sulphur	.018				
Vanadium	.02	Impacts		79	/
Iron		Impacts		84	/
Ferrite		Impacts		87	


Date of Penna. |
County of York | SS

Subscribed and sworn to before me
this 22nd day of June

19 73

APPROVED
M. W. KELLING
Q.A.
P.L.E. Shaded Carbon Plate
<u>TM 6-27-73</u>
INITIALS


The undersigned certifies that this report is
correct and that no significant change has
been made in any of the elements described
in the qualification approval.


Name: M.W. Kellogg
Title: Manager Products

Commission expires:

4-12-76

CHEMETRON CORPORATION
WELDING PRODUCTS DIVISION

BY 
R.J. Stallman

CHEMETRON CORPORATION
WELDING PRODUCTS DIVISION

Certificate of Analysis

520

M. W. Kellogg Company
c/o Pacific Gas & Electric
Power Plant
7 Miles N. of Avila Beach
Avila Beach, California 93424
7177-1505

Customer Order No. 6520

Order No. 65365

Shipped 9-21-73

This material conforms to Specification AWS A 5.5-69


Test No. 650

X-Ray Satisfactory Type E 8018-C3

Trade Name:	Atom Arc 8018	Moisture @ 1800°F. 0.2%
Diameter Size:	1/8"	Concentricity 3%
	400 lb.	Type Steel A-285
Lot Number:	/B328C3AD	Test No. Full-Split Volts Amps
Heat Number:	/627233	Tensile & Impacts 1 6 22 130
Carbon	.05 /	Test AS
Manganese	.93 /	Results: Welded
Chromium	.05 /	Yield 72,400 /
Nickel	1.07 /	Tensile 86,000 /
Silicon	.40 /	Elongation 31% /
Columbium		Red. of Area 75.0%
Tantalum		Charpy V-Notch Impacts Tested @ 400°F
Molybdenum	.15 /	Impacts 76
Tungsten		Impacts 77
Copper		Impacts 78
Titanium		Fillet: OK Vertical 1 Overhead
Phosphorus	.014 /	
Sulfur	.022 /	
Vanadium	.02 /	
Iron		
Ferrite		

State of Penna. | SS
County of York |

Subscribed and sworn to before me
this 25th day of Sept.



1973

The undersigned certifies that this report is correct and that no significant change has been made in any of the elements described in the qualification approval.

My commission expires:

4-12-76

CHEMETRON CORPORATION
WELDING PRODUCTS DIVISION

BY J. L. Thompson

27
LABORATORY CERTIFICATE

Report 411-77.55

Anamet Laboratories, Inc.ANALYTICAL
CHEMICAL
METALLURGICALHIGH TEMPERATURE
HIGH PRESSURE
POTENTIAL TESTS

May 25, 1977

LABORATORY NUMBER: 577.329 P.O. No. LO-879806

SAMPLE: One (1) Sample for Chemical Analysis

MARK: P-12 B
DCPP #1 Steam Generator
Nozzle Failure Analysis

DATE SUBMITTED: May 24, 1977

REPORT TO: Pacific Gas & Electric Company
3400 Crow Canyon Road
San Ramon, California 94583
Attn: Mr. Steve Ivy

CHEMICAL ANALYSIS

	(Element)	(Symbol)	Analysis	Requirements	
				A-508 Cl. 2	Min. Max.
Carbon	(C)		0.23%	-	0.27%
Chromium	(Cr)		0.40%	0.25%	0.45%
Manganese	(Mn)		0.81%	0.50%	0.90%
Molybdenum	(Mo)		0.58%	0.55%	0.70%
Nickel	(Ni)		0.80%	0.50%	0.90%
Phosphorus	(P)		0.009%	-	0.025%
Silicon	(Si)		0.28%	0.15%	0.35%
Sulfur	(S)		0.012%	-	0.025%
Vanadium	(V)		0.05%	-	0.05%

Respectfully submitted,

ANAMET LABORATORIES, INC.

By

Siegfried Otto
Manager, TestingJc
jm

29
LABORATORY CERTIFICATE

Report 411-77.55

Anamet Laboratories, Inc.

2927 1/2 STREET

BERKELEY, CALIFORNIA 94710

BENGTSS

May 25, 1977

ANALYTICAL
CHEMICAL
METALLURGICALHIGH TEMPERATURE
APPLIED RESEARCH
PHYSICAL TESTING

LABORATORY NUMBER:

577.329 A

P.O. No. LO-873

SAMPLE:

One (1) Sample for
Chemical Analysis

MARK:

P-1

DCPP #1 Steam Generator
Nozzle Failure Analysis

DATE SUBMITTED:

May 24, 1977

REPORT TO:

Pacific Gas & Electric Company
3400 Crow Canyon Road
San Ramon, California 94583

Attn: Mr. Steve Ivy

CHEMICAL ANALYSIS

	Requirements	
	A-106 Gr. 3	
	Min.	Max.

Aluminum (Al)	0.03%	Information
Carbon (C)	0.25%	- 0.30%
Chromium (Cr)	0.14%	Information
Copper (Cu)	0.10%	Information
Manganese (Mn)	0.90%	0.29% 1.06%
Molybdenum (Mo)	0.04%	Information
Nickel (Ni)	0.07%	Information
Phosphorus (P)	0.015%	- 0.04%
Silicon (Si)	0.25%	0.10% -
Sulfur (S)	0.033%	- 0.058%
Titanium (Ti)	0.003%	Information
Vanadium (V)	0.003%	Information

Respectfully submitted,
ANAMET LABORATORIES, INC.

By

Siegfried Otto
Manager, Testing3c
jm

29
LABORATORY CERTIFICATE

Report 411-77.55

Anamet Laboratories, Inc.

EAST 14TH STREET

BERKELEY CALIFORNIA 94710

SACRAMENTO

May 25, 1977

ANALYTICAL
CHEMICAL
METALLURGICALHIGH TEMPERATURE
APPLIED RESEARCH
PHYSICAL TESTING

LABORATORY NUMBER:

577.329 B

P.O. No. LO-879806

SAMPLE:

Two (2) Samples for
Chemical Analysis

MARK:

Weld - Side and Crown
DCPP #1 Steam Generator
Nozzle Failure Analysis

DATE SUBMITTED:

May 24, 1977

REPORT TO:

Pacific Gas & Electric Company
3400 Crow Canyon Road
San Ramon, California 94583
Attn: Mr. Steve IvyCHEMICAL ANALYSIS

		<u>Side</u>	<u>Crown</u>
Aluminum	(Al)	0.005%	0.004%
Carbon	(C)	0.08%	0.06%
Chromium	(Cr)	0.29%	0.06%
Copper	(Cu)	0.07%	0.08%
Manganese	(Mn)	1.17%	1.08%
Molybdenum	(Mo)	0.15%	0.12%
Nickel	(Ni)	1.00%	1.03%
Phosphorus	(P)	0.012%	0.012%
Silicon	(Si)	0.55%	0.60%
Sulfur	(S)	0.022%	0.022%
Titanium	(Ti)	0.01%	0.01%
Vanadium	(V)	0.03%	0.02%

Respectfully submitted,
ANAMET LABORATORIES, INC.

By

Siegfried Otto
Manager, TestingJc
jm

7.01

PROCEDURE SPECIFICATION FOR: Carbon Steel
to Nickel Steel piping, Insert weld-
GTAW (root) and SMAW (weld out).

BASE METAL: The base metal shall conform
to the specifications for ASME, Section IX,
to P-1 materials.

Filler Metal: The filler metal shall con-
to ASME Filler Metal Specifications Num-
SFA-5.5 and SFA-5.13 for ferrous filler
in Group Number 7-4 and P-6.

Chemical composition of the weld depos-
shall fall within the limits of weld Metal
Classification A-125.

G FOR TORCH SHIELD: Nominal composition
argon, 99.995% minimum purity (for GTAW
process).

G FOR BACKUP PURGE: Argon per Page 5
(TAW process).

WELDS FOR SET-UP: The GTAW process
filler metal type listed on Page 2 may
be used with or without back-up purge in 1/16,
or 1/8 inch diameter.

POSITION: The welding may be done in all
positions.

HEAT AND INTERPASS: 200° F - 300° F pre-
for SMAW weld out only and 200° F minimum
pass.

GT HEAT TREATMENT: 1100° F - 1200° F, 1
per inch minimum (see job specifications
cycle and thicknesses requiring post heat
treatment).

BACKING STRIP: None.

PAVE SPEED: GTAW $\frac{1}{2}$ " = 6" per min.
SMAW $\frac{3}{4}$ " = 8" per min.

WELDING PROCESS: The welding shall be done by
the GTAW insert root and SMAW weldout processes
using manual equipment. The GTAW process may
be used with the filler metal type listed on
Page 2 for intermittent voids, lock-in holes
(peep holes) in the ring, or mismatch in the
root set-up. If necessary, one complete pass
may be made while holding the purge. SMAW
welding shall be done using a non-consumable
electrode of 22 thoriated tungsten, E22H-2.

BASE MATERIAL THICKNESS: This procedure
is qualified to allow welding of material
thickness between 3/16" and 1.5" (heat
treated).

PREPARATION OF BASE MATERIAL: The edges
or surfaces of the parts to be joined by
welding shall be prepared by flame cutting,
plasma arc, grinding, machining, or any
combination of methods to essentially form
the geometry of the weld shown on Page 2
as detailed on the attached sketches and
shall be clean of all oil or grease and
excessive amounts of scale or rust.

ELECTRICAL CHARACTERISTICS: The current
used shall be DC: GTAW Straight Polarity
SMAW Reverse Polarity.

JOINT WELDING PROCEDURE: The welding tech-
nique, such as electrode sizes, and voltages
and currents for each electrode, size of the
welding tip and filler rods, shall be sub-
stantially as shown on Page 2.

APPEARANCE OF WELDING LAYERS: The welding
current and manner of depositing the weld
metal shall be such that there shall be
practically no undercutting on the side
walls of the welding groove or the adjoining
base material. See job specifications for
specific undercutting limitations.


CLEANING: All slag or flux remaining on
any bead of welding shall be removed before
laying down the next successive bead of
welding.

DEFECTS: Any cracks or blow holes that
appear on the surface of any bead of welding
shall be removed by chipping, grinding, or
planing before depositing the next success-
ive bead of welding.

The H. W. Wilson Co., Inc.
A Division of Martin Incorporated
Plating Division
Williamsport, Pa. 17701

32

Report 411-77-55
Page 2 of 4
Weld Procedure Card No. 200
Spec. No. P12b-P1-K1-F4-SIHW-66
Date 1/14/73
Revision Dates: 6-16-76



S. NO. NO. LESS	FILLER METAL TYPE OPTIONAL	FILLER METAL SIZE OPTIONAL	AMPS	MAX. VOLTS	POLARITY	TOUCH SHIELD & FLOW RATE (MIN.)	TUNGSTEN SIZE AND POLARITY
GT TAW	E70S-2, or -6	INSERT 1/8 X 5/32	55-175	21	straight	Argon 20 CFH	1/8 or 3/32 diameter straight
CK TAW	E70S-2, or -6	1/16 3/32 1/8	60-120 70-150 100-140	14 17 20	straight	Argon 20 CFH	1/8 or 3/32 diameter straight
LANCE W	E6018	3/32 1/8 5/32 3/16	65-110 100-165 140-220 180-275	27 31 34 36	reverse	—	—

*NOTE: 1/16", 3/32", or 1/8" E70S-2 or E70S-6 filler metal may be used as necessary for tackling, filling intermittent voids, leak-in holes (pore holes), or mismatch in the root set-up. If necessary, one complete pass may be made while holding the purge.

THE STREAM TEL E.C. LILLEGOD CUTTING
COMPANIES
AND 24 HR INVOICES ELEVEN FIFTEEN SHIFT
ONLY

N/A = NOT APPLICABLE

P. G. C. E.		NO. 6 SYSTEM #	ISOLATING DRAWING NO.		DETAL DRAWING NO.		SHEET NO.	
PREPARED BY	JOB NO.	DATE	CLASS		CLASS	SECTION 1	MARK NO.	N/A
R.B.	7177	1/2/74	ASME	SECTION 1	ESD	500146	N/A	10 of 1
1	CLEANING	1/2/74	AT&S		ESD	926	1/2/74	1/2/74
2	FIT-UP				ESD	215	6X	1/2/74
3	WELD ROOT PASS				CODE	200	6X	1/2/74
4	PREHEAT SMAW ONLY (200° - 300°)				CODE	200	117	30
5	WELD COMPLETE				CODE	200	6X	30
6	GRIND FOR R.T.				ESD	207	117	31
7	VISUAL INSPECTION				ESD	215	117	31
8	R.T. FINISHED WELD				ESD	207	K	1/2/74
9	-STRESS RELIEVE - SEE Chart No - 341				ESD	218	117	2/4/74
10	R.T. FINISHED WELD				ESD	200	117	2-1-5
11	REMOVE DAMS				ESD	214		
12	P.T FINISHED WELD				ESD	211		CL00100 0528
13	FIELD WELD # 212 - 1/2 - 1/2 - 1/2 OUT 5/2/74				ESD	220		
14	CLEANING	1/2/74	AT&S		ESD	220	117	31/74
15	FIT-UP				ESD	215	117	31/74
16	WELD ROOT PASS				CODE	200	117	31/74
17	PREHEAT SMAW ONLY (200° - 300°)				CODE	200	117	31/74
18	WELD COMPLETE				CODE	200	117	31/74
19	GRIND FOR R.T.				ESD	207	415	5/2/74
20	VISUAL INSPECTION				ESD	215	415	5/2/74
21	R.T. FINISHED WELD				ESD	207	ES	5/2/74
22	STRESS RELIEVE	Chart 323			ESD	210	220	5/2/74
23	P.T. FINISHED WELD				ESD	214	92	5/2/74
24	REMOVE DAMS				ESD	214	671	5/2/74

Engineering Dept. Date 6/5/74
A.S.

11/07/1999

T. Spence Friedrich
from: M&T/RD Etcher

PACIFIC GAS AND ELECTRIC COMPANY
STATION CONSTRUCTION DEPARTMENT
DIABLO CANYON PROJECT

Pg. 1 of 2

HISTORY OF STEAM GENERATOR 1-2
DIABLO CANYON PROJECT

March 28, 1977

The following information is provided per your request to indicate tests and transient conditions which influenced temperature and pressure on the secondary side of steam generator 1-2:

STEAM TESTS

- 2/19/74 1st hydro - 1 cycle to 1356 psig & 106° F (main steam and feedwater nozzles capped at generator)
- 2/29/75 2nd hydro - 1 cycle to 1320 psig & 88° F (R/V's lifted and pressure had to be reduced)
- 3/29/75 With Present Piping
- 3rd hydro - 1 cycle to 1356 psig & 88° F

NOT FUNCTIONAL TEST

12/13/75	RCS heatup	100° F to 150° F
12/15/75	RCS heatup	150° F to 240° F
12/21/75	RCS heatup	257° F to 340° F, 62 psig to 103 psig
12/30/75	RCS heatup	350° F to 450° F, 119 psig to 407 psig
12/31/75	RCS heatup	450° F to 571° F, 407 psig to 750 psig
1/1/76	RCS heatup	571° F to 547° F, 750 psig to 1010 psig
1/4/76	pressure dip	1000 psig - 940 - 1000 psig, ΔT < 10° F
1/4/76	pressure dip	1000 psig - 925 - 995 psig, ΔT < 10° F
1/4/76	temperature drop	545° F to 523° F, 980 psig to 870 psig
1/6/76	temperature dip	524° F - 497 - 524° F, 824 psig - 651 - 824 psig
1/7/76	temperature dip	537° F - 505 - 512° F, 900 psig - 695 - 750 psig
1/8/76	temperature increase	508° F to 545° F, 714 psig to 983 psig
1/9/76	temperature dip	545° F - 503 - 547° F, 983 psig - 677 - 1000 psig
1/10/76	temperature dip	548° F - 526 - 542° F, 1000 psig - 829 - 973 psig
1/12/76	RCS cooldown	536° F to 115° F, 908 psig to 0 psig
1/15/76	RCS heatup	139° F to 327° F, 0 to 84 psig
1/17/76	RCS heatup	327° F to 528° F, 84 psig to 360 psig
1/21/76	temperature dip	525° F - 472 - 546° F, 340 psig - 501 - 982 psig
1/22/76	turbine roll	546° F - 475 - 537° F, 1000 psig - 525 - 643 psig
1/24/76	temperature increase	501° F to 545° F, 580 psig - 985 psig
1/25/76	turbine roll	547° F to 482° F, 979 psig to 563 psig
1/26/76	RCS cooldown	482° F to 255° F, 553 psig to 20 psig
1/29/76	RCS heatup	255° F to 546° F, 20 psig to 989 psig
2/4/76	turbine roll	546° F - 477 - 546° F, 986 psig - 537 - 993 psig
2/5/76	turbine roll	546° F - 435 - 532° F, 987 psig - 595 - 837 psig

History of Steam Generator 1-2
Diable Canyon Project

-2-

To: Spence Friedrich
 From: MRT/ED Etzler

Pg. 2 of 2

HOT FUNCTIONAL TEST - continued

2/7/76	tested safeties	956 psig - 864 psig several times AT < 10° F
2/10/76	tested safeties	552° F - 531° F four times 1042 psig - 868 psig
	(S.G.'s 1-3 and 1-4)	
2/10/76	RCS cooldown	549.5° F to 100° F, 1003 psig to 0 psig

NOTE: During the days not listed above, the temperature and pressure were relatively stable. A detailed picture of temperature and pressure is available at the site and a drawing of the entire hot functional program. Steam pressure shown on the drawing is downstream of the main steam isolation valves and does not always agree with steam pressure in the steam generator.

MINI-HOT FUNCTIONAL TEST

3/14/77	RCS heatup	115° F to 165° F
3/15/77	RCS heatup	165° F to 300° F, 0 psig to 52 psig
3/16/77	RCS heatup	300° F to 330° F, 52 psig to 88 psig
3/17/77	RCS cooldown	337° F to 100° F, 88 psig to 0 psig

FEEDWATER TO STEAM GENERATOR

During both Hot Functional and Mini-Hot Functional, the auxiliary feedwater system was used for makeup to the steam generator. Feedwater temperature varied from 50° F to 110° F and flow rate varied from 0 to 300 GPM. We understand you have obtained water chemistry results from the plant chemist.

THERMAL EXPANSION

During Hot Functional, thermal movement and potential component and piping interferences were closely monitored for each steam generator. Movement of steam generator 1-2 was in agreement with the movement of the remaining generators and acceptable by Engineering Department. However, insulation on the feedwater inlet line for steam generator 1-2 did come in contact with the missile barrier penetration, whereas feedwater lines on the other steam generators did not. The insulation cover was slightly indented, but not enough to induce a restriction to the movement of the feedwater line with the steam generator. Results of the thermal expansion test during Hot Functional are on file at the plant and General Office.

R. W. WOOD
 Startup Department

ENCL:for
 cc File

ANALYSIS OF ELECTRON DIFFRACTION PATTERNS

Gold Calibration for Camera Constant

<u>Ring Dia. cm</u>	<u>$d\bar{A}$</u>	<u>K</u>
2.30	2.355	5.42
2.65	2.039	5.40
3.75	1.442	5.41
4.40	1.230	5.41

$$K = 5.41$$

Pattern From Extracted Oxide

<u>Ring Dia. cm</u>	<u>$d\bar{A}$</u>	<u>Intensity*</u>
1.3	4.15	S
1.5	3.60	W
2.0	2.70	S
2.15	2.52	M
2.40	2.25	M
2.70	2.00	W
3.10	1.74	M
3.30	1.63	W
3.50	1.55	VS
4.00	1.35	S
4.40	1.22	W
4.70	1.15	M

*VS - Very Strong

S - Strong

M - Medium

W - Weak

* αFe_2O_3 Hematite

4-3755 MAJOR COMMISSION

443

9-9502