

QUAD-CITIES NUCLEAR FOWER STATION

Address Reply to:

POST OFFICE BOX 216 \* CORDOYA, ILLINOIS \$1242

February 9, 1972

U. S. Atomic Energy Commission Washington, D. C. 20545

Attention: Dr. Peter Morris

Director Division of Reactor Licensing

Reference: Facility Operating License - DPR-29

Appendix A - Section 3.10A

Dear Dr. Morris:

As set forth by the Technical Specifications for Quad-Cities Nuclear Power Station, Section 3.10A - Refueling Interlocks, the following abnorgal occurrence is reported as 1-72-2.

On February 7, 1972 at 4:45 p.m., while moving a fuel assembly out of the Unit 1 - reactor vessel for neutron source removal, operations discovered that a rod withdraw block failed. Operations were following approved step-by-step procedures which did not call for control rod withdrawat. The indication of rod block failure was visual in that the "rod out" permit light remained on with the refueling bridge over the reactor cavity while fuel assembly weight was on the grapple.

Upon discovery of the failure, fuel transfer operation was terminated and the electrical maintenance group was assigned to determine the cause for failure. The bridge position limit switch is a General Electric Model CELISGROT which uses a screwed clam, connection between the roller arm and the switch shaft. The switch shaft had moved with respect to the roller arm came approached raised portion of the track bed. The shaft was

8305200026 720311 PDR ADDCK 05000254 5 PDR

2/23

Dr. Peter Morris -2-February 9, 1972 readjusted with respect to the roller arm and clamped tight. Switch operation was tested, the interlock circuit tested, and fuel transfer operation resumed. Very truly yours, COMMONWEALTH EDISON COMPANY Quad-Cities Nuclear Power Station B. B. Stephenson BBS / zm