

SITE PROBLEM
REPORT TRANSMITTAL

**** CLEARED ****

GP4 EXHIBIT 491 FOR IDENT.
3/23/82 H. A. KUDOLPH

TO: Charge Control For Distribution
S. H. Klein - Quality Assurance
Central Engineering Files
D. Putzke - Task Engineer
J. Lauer - Project Manager

FILE: 13-14-386
CONTRACT NO: 620-00 14
SPR 386
TITLE Electronic
Relief Valve Modification
DATE: 3/27/78
STATUS CODE C

L. C. Rogers - MET. ED.
F. R. Faist - TOLEDO
J. R. Bohart - Intl. Support
J. L. Donnell - OFR
B. A. Karrasch - Plant Integration

0627-

Attached is one copy of Site Problem Report No. 386 which was processed
on Contract 620-00 14. Future contracts have been reviewed for the
potential of a similar problem. This problem ~~is~~ not considered applicable to
other contracts.

REMARKS:

B. H. H.
NUCLEAR SERVICE SUPPORT ENGINEER

CLEARED

CONFIDENTIAL
COUNSEL ONLY

8307060547 780327
PDR ADOCK 05000289
P HOL

7323

017

SITE PROBLEM REPORT

BASCO & WILCOX SPR #386

CUSTOMER Toledo Edison Company	ORIGINATOR F.R. Faist	DATE 11/2/77	DOC. NO. CONT. NO. 13 - 600-0014	SPR NO. 386
VENDOR Crosby	P.A. NO. 023 090 IS		PART NO./IATA NO. 28/041/005	GROUP NO. 1
TITLE (MAX 30 CHARACTERS) Electronic Relief Valve Modification			PROBLEM CONTACT J. E. Anderson	

DESCRIPTION OF PROBLEM:

See attached sheet.

PROBLEM IDENTIFICATION

STATUS-ACTION TO DATE, INCLUDING PERSONS CONTACTED: Lynb. Engineering is aware of this problem. S. A. Lamanna, Lynb., and J. A. Lauer, Proj. Mgr. know of this problem. T. D. Murray and B. R. Beyer, TECo, are also aware of the problem.

FURTHER ACTION RECOMMENDED BY SITE PERSONNEL: 1. Lynb. Engineering should review Crosby installation, operating and maintenance instructions No. I - 1115, Sect. 4.2 with the Crosby vendor to determine if these instructions will give the proper pilot valve stem adjustment when actuated. 2. Engineering to provide additional recommendation and concurrence with action taken.

RESOLUTION: *Reviewing Crosby with recommendations as per comm. with Mr. Dick Ahlstrom. The instruction manual section 4.2 will be revised by Crosby. P. A. Lauer will give copies of the revised pages for the I.M. Steve Lamanna.*

RESOLUTION

PREPARED BY <i>Doug Holsted</i>	DATE 11-4-77	APPROVED BY <i>J. A. Lauer</i>	DATE 11-7-77
<i>P. A. Lauer & K. E. Lauer</i>	DATE 11-7-77		

COST CATEGORY ☐ NORM ☒ OTHER	FIELD CHANGE REQ ☐ YES ☒ NO	F.C.A. NO. 06- N/A	SIGNIF. DEFICIENCY ☐ YES ☒ NO
--	---	-----------------------	---

COMPLETION

SITE COMPLETION REPORT: SOM Letter #352, copy attached was written to TECo. Instruction manual is correct and will not be revised. Additional adjustment check provided. Eng. concurred with Crosby/TECo actions.

DEVIATIONS: ☒ NONE	SPR REV NO. ☐
DATE COMPLETED: 3/21/78	
COMPLETED BY: <i>F. R. Faist</i>	
F. R. Faist	
SHEET 2 of 11	

7323 0180

Description of Problem:

On 10/13/77, the electromagnetic relief valve was tested after the completion of repairs as outlined in SPR #369. The valve was cycled six times successfully. On the seventh test cycle the pilot valve did not close. The ERV was isolated and permitted to cool down while waiting for Crosby representatives.

Crosby rep., Walt Conroy, arrived and the pilot valve assembly was removed from the main valve. Disassembly of the pilot valve revealed that the pilot valve stem had stuck open due to the close tolerance causing a binding condition between the O.D. of the stem and the I. D. of the pilot valve nozzle. Also, a small metal particle was found in the pilot stem/nozzle area. Subsequent cleaning of the inlet piping to the ERV revealed this same type of metal particles.

The Crosby representative furnished a detailed drawing of the pilot valve stem requiring a diameter of .374. This was changed to read .373 diameter .372.

by the Crosby rep., and the stem was modified accordingly by TECO Maintenance under the direction of the Crosby rep. This modification resulted in opening the clearance between the stem and the nozzle thus eliminating the binding. The nozzle was also reamed out with a reamer the same size, no material was removed.

All parts were cleaned and assembled. The solenoid linkage was adjusted to drop the adjustment bolt more squarely on the disc actuator. In addition, the adjustment bolt was positioned to move the pilot valve stem off the seat a maximum of .125". It had been moving off the seat some .375".

The pilot valve was tested without pressure by actuating the solenoid three times. The valve was tested again twice with 5 or 6 seconds between tests. This was followed by testing the valve five more times assuring actuation each time by a one minute delay between tests. The valve was tested with a pressure of 1100 psig on the second and third occasion.

JEA:nlf

CONFIDENTIAL
COUNSEL ONLY

3 of 12

70-23

0181

TITLES

HWXCHINESE
20 SEP 1962
620-0014

Suggested that
give black ink shield LCII
Test extract solvent mint 3 times

Office of the Secretary of the Navy

Open ~~at~~ R.C.S.
Follow twice for 5-6 sec of
before starting again it
R.C.S. & Q. can take it
in R.C.S. &

He not go below 600 ft on RCS if
Ours should be as near 1500 ft as possible
will test at 1150 because of heat stress
limitations -

Stroke 5 times securing retention
during each time - ~~last 5 times~~ at
in between stroke to avoid clamping
~~Right hand~~
Stroke 5 times again same as above

NRC wants one of us at ~~top~~ ~~of~~ ~~the~~ ~~office~~

~~CONFIDENTIAL~~
~~83-25-100-100-1~~
~~CONFIDENTIAL~~
312-82-100-100-1

.. 4 18 32

१०२३

0 1 8 2


Crosby - Bolt Crosby
Ext. L. L. L.

10-15-77

Accomplished things planned and
discussed on 10-11-77.

Walt will include in his
report recommendation to use
method of adjusting solenoid
to get ≈ 0.100 pilot valve stroke.

Crosby ~~will~~ Engineering will
submit letter in charge on
pilot valve stroke diameter.


11/15/77
CONFIDENTIAL
COUNSEL ONLY

6011

7023

0184

NUCLEAR POWER STATION MAINTENANCE WORK ORDER

Continuation sheet for No. 3 and No. 1A 1ED 10/72

FUNCTIONAL ACCOUNT NO. 558 3300 5 EQUIPMENT FILE NO. 77-2120 MWO NO. 77-2120

1. EQUIPMENT/INSTRUMENT NAME AND NO. PRZR ELECTROMAGNETIC RELIEF VALVE RC2A

2. MWO INITIATED BY: ☐ WHI ☐ AIR NO. ☐ NCR No. ☐ MWO NO. ☐ OTHER

3. DESCRIPTION OF PROBLEM/MALFUNCTION
RC2A STUCK OPEN. TROUBLESHOOT AND
REPAIR AS NEEDED. WORK WITH SERVICE MAN
ON REPAIRS

4. WORK CLASSIFICATION
☒ Normal ☐ Immediate ☐ Emergency ☐ Outage ☐ Preventive Maintenance
☒ Routine ☐ Non-Routine ☒ Nuclear Safety Related/ASME ☐ Non-Nuclear Safety Related
Frequency
Scheduled For

5. REP REQUIRED ☒ Yes ☐ No 6. CLEANLINESS INSPECTION REQUIRED ☐ Yes ☒ No 7. NPRD REQUIRED ☐ Yes ☒ No

8. PROCEDURE/INSTRUCTION Number A/C-1 Revision 9. APPROVED BY MAINTENANCE/ISC ENGINEER [Signature] DATE 9/26/77

10. REVIEWED BY QUALITY CONTROL [Signature] DESIGNATED INSPECTOR (Name) [Signature] DATE 9/26/77

11. SPECIAL INSTRUCTIONS Wait for Q.C. order to start work. ASSIGNED RESPONSIBILITY Hessell/MacCallach 12. PERMISSION TO COMMENCE WORK 9/27/77

13. DESCRIPTION OF WORK PERFORMED
IDENTIFIED VALVES REFINED PARTS & GASKETS
VALUES - WAS AT - HDIC TO CYCLE VALVE DUE TO X-10
RA-11 & V.H.H. when valve was cycled with pressure
pilot valve stuck again on the 5th blow.

14. TEST EQUIPMENT I.D. NO. CALIBRATION DUE DATE 1-7-78 15. SPARE PARTS REQUIRED ☐ Yes ☒ No

16. MAINTENANCE COMPLETED AND INSPECTED PER REQUIREMENTS OF AG 15J4C0
DESIGNATED INSPECTOR [Signature] DATE 10/17/77 RESPONSIBLE FOREMAN [Signature] DATE 10-17-77

17. TESTING COMPLETED & TESTED TO SHIFT FOREMAN/FOREMAN CONTROL
TEST NO. SHIFT FOREMAN/FOREMAN [Signature] DATE

18. ACTION ITEMS/FOLLOW UP
☐ NPRD Form Completed (if required) ☐ None Required
☒ Initiated Followup MWO NO. 77-2256 ☐ Other
☐ Initiated AIR/DVR NO.

19. MAINTENANCE/ISC ENGINEER [Signature] MWO REVIEWED AND APPROVED [Signature] DATE 10/17/77

COPIES: WHITE GREEN Shift Foreman

CONFIDENTIAL
COUNSEL ONLY

01856

70-3

7 of 22

FUNCTIONAL ACCOUNT NO.		EQUIPMENT FILE NO.		MWO NO.	
				77-2256	
EQUIPMENT INSTRUMENT NAME AND NO.					
Pressure Electric Relief Valve					
MWO INITIATED BY:				MWO NO.	
☐ WRI ☐ AIR NO. ☐ NCR No.				☒ OTHER B. B. B.	
DESCRIPTION OF PROBLEM/MALFUNCTION					
Remove from Electric Relief Valve assembly, and disassemble to cause positive identification of defective assembly. Disassemble. Inspect assembly. and cause as instructed by District Engineer. Reassemble. Repair as required. Reassemble when instructed.					
WORK CLASSIFICATION:		☐ Normal ☐ Immediate ☐ Emergency ☒ Outage		☐ Preventive Maintenance	
☒ Routine ☐ Non-Routine		☒ Nuclear Safety Related/ASME ☐ Non-Nuclear Safety Related		Frequency	
				Scheduled For 11/12/77	
REP REQUIRED		CLEANLINESS INSPECTION REQUIRED		NPRD REQUIRED	
☒ Yes ☐ No		☐ Yes ☒ No		☐ Yes ☒ No	
PROCEDURE/INSTRUCTION		APPROVED BY MAINTENANCE/AC ENGINEER		DATE	
Number MP14A 02 Revision 0		<i>[Signature]</i>		11/12/77	
REVIEWED BY QUALITY CONTROL		DESIGNATED INSPECTOR (Name)		MIN. LEVEL	
<i>[Signature]</i>		Schultz/CC Section		E-M II	
SPECIAL INSTRUCTIONS		PERMISSION TO COMMENCE WORK		DATE	
Totally Test in Dist. To Starting Work					
ASSIGNED RESPONSIBILITY		11/13/77		10/13/77	
11. <i>[Signature]</i>		12. <i>[Signature]</i>			
DESCRIPTION OF WORK PERFORMED					
Relief Valve was removed and found to be sticking open about 1/2". Stem was checked and found to be 372 which gives 0.003" clearance in the guide. Disc was lipped. The main disc was checked for warpage. It was true and seating. The inlet line was cleaned to the block valve. The actuator actuator was adjusted to give the right valve - a 100% opening.					
TEST EQUIPMENT I.D. NO.		CALIBRATION DUE DATE		SPARE PARTS REQUIRED	
MM 4.1		3-3-79		☒ Yes ☐ No (List Part or P.O. or Etc.)	
MAINTENANCE COMPLETED AND INSPECTED PER REQUIREMENTS OF AC 1544 GC					
DESIGNATED INSPECTOR		DATE		RESPONSIBLE FOREMAN	
<i>[Signature]</i>		10/12/77		<i>[Signature]</i>	
TESTING COMPLETED & RETURNED TO SHIFT FOREMAN/FOREMAN CONTROL					
TEST NO.		SHIFT FOREMAN/FOREMAN		DATE	
<i>[Signature]</i>		<i>[Signature]</i>		10/17/77	
ACTION ITEMS/FOLLOW UP					
☐ NPRD Form Completed (if required) ☒ None Required					
☐ Initiated Followup MWO NO. ☐ Other					
☐ Initiated AIR/DVR NO.					
MWO REVIEWED AND APPROVED					
MAINTENANCE/AC ENGINEER <i>[Signature]</i>					
CONFIDENTIAL COUNSEL ONLY 10/17/77					
WHITE - Routed to be completed/procedure BLUE - Maintenance/AC Office GREEN - Shift Foreman YELLOW - Operations Engineer					

8 of 11

0186
7023

Pilot Whistler measurement is 0.372
Diode measurement is 0.375

Valve was tested at ~ 1100 psi 10 times and closed satisfactorily with no leakage noted.

Valve was also tested one time at 2150 psi and closed satisfactorily with no leakage noted.

Valve was also closed and closed once and
had two additional 0.5 second blows ^{at 1100 psi}
the 10 times above

B. J. J.
12/14/77

CONFIDENTIAL
COUNSEL ONLY

COPIES:

WHITE - Passed to be completed/procedure
BLUE - Shift Foreman
GREEN - MRC Office

YELLOW - Operations Engineer
PINK - Operations QA Engineer

9822

0187

2023

1127-787
726 215

REF ID: A660931

70-23 0188

ENGLI ALL OVER

[illegible]

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

TABLES OF FREQUENCY SCALED

TOTALS FOR ALL TABLES

FREQUENCY TABLES

0-6

1/64

1/32

1/16

±.005


TABLES 13°

FREQUENCY SURFACES V OR BETTER

ALL COLUMNS

1/64 MAX RADIUS CORNER

CROSBY WAVE & G.C.
VIREN, MA, MASS.
P.O.C (PILOT WAVE)
100-1-SN

[illegible]

620-0014




FIG. 1
ASSEMBLY OF PRESSURIZATION
VALVE STYLE HPV-SN

CONFIDENTIAL
COUNSEL ONLY

11 of 23

0189

7023