

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20545

FEB 11 1982

MEMORANDUM FOR: Robert M. Bernero, Director
Division of Risk Analysis

Richard W. Starostecki, Director
Division of Project and Resident Programs

Richard H. Vollmer, Director
Division of Engineering

Roger J. Mattson, Director
Division of Systems Integration

Stephen H. Hanauer, Director
Division of Safety Technology

Hugh L. Thompson, Jr., Acting Director
Division of Human Factors Safety

FROM: Gus C. Lainas, Assistant Director
for Safety Assessment, DL

SUBJECT: RESPONSE TO REPRESENTATIVE MORRIS UDALL'S LETTER OF
FEBRUARY 5, 1982

Enclosed is a copy of Representative Udall's letter sent to Chairman Palladino regarding various aspects of Ginna's steam generator tube rupture. It has been marked to delineate primary areas which you are requested to respond to. Please supply your responses to me by February 17, 1982. T. A. Ippolito, Chief ORAB, is coordinating this response.

Gus C. Lainas
Gus C. Lainas, Assistant Director
for Safety Assessment
Division of Licensing

Enclosure:
Letter dated 2/5/82

cc w/enclosure:
E. Case
D. Eisenhut
R. Haynes, RE: I
J. Funches
R. Minogue, RES
T. Ippolito
J. Lyons

CF
1000
202260144
DESIGNATED ORIGINAL

Certified By *lh*

8202260144 XA
10

WALDE - 8222

FEDERAL POWER COMMISSION
WASHINGTON, D.C.

WILLIAM H. HARRIS, JR., PRES.
FRANCIS S. COCHRAN, V. PRES.
D. BRUCE MCCLURE, CH. EXEC. V. PRES.
ROBERT J. MILLER, JR., EXEC. V. PRES.
WALTER H. CRAWFORD, JR., EXEC. V. PRES.
WILLIAM M. SULLIVAN, JR., EXEC. V. PRES.
WALTER W. SHAW, JR., EXEC. V. PRES.
ROBERT W. HAYES, JR., EXEC. V. PRES.
LARRY W. KILPATRICK, EXEC. V. PRES.
WALTER M. ROSS, JR., EXEC. V. PRES.
DAVID H. KAY, JR., EXEC. V. PRES.
JAMES L. DAVENPORT, EXEC. V. PRES.

February 5, 1982

CE
Tuller
A
D

The Honorable Nunzio Palladino
Chairman
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Chairman:

As a follow-on to the February 4 briefing, I would appreciate the Commission's answers to the following questions in addition to the information requested by Mr. Markey.

- NRR/RE:I 1. What is the primary significance of the Ginna incident? ^{45 DAY} REPORT
- NRR 2. What was the leak rate through the break as a function of time?
- NRR/RE:I 3. What triggered the steam generator tube rupture? ^{45 DAY} REPORT
- NRR 4. Had there been indications of leaking steam generator tubes prior to the rupture on January 25?
- RE:I 5. What was the cause of the PORV's apparent failure to close? Does the apparent failure of the PORV to close cause doubt about the adequacy of the industry's program to test such valves?
DF
- NRR/RE:I 6. What would the course of the incident have been had the PORV block valve failed to close partially or fully following failure of the PORV to close fully? ^{45 DAY} REPORT
- RE:I 7. Did the procedure for responding to a steam generator tube rupture contain instructions for actions to be taken in response to development of a steam bubble in the reactor pressure vessel?
- RE:I 8. Was there a need during the incident to take actions not specified in the plant's written operating and emergency procedures? Were the emergency procedures in place at Ginna consistent with Westinghouse guidelines as discussed in the January 28 memorandum from Mr. Speis to Dr. Mattson?
- RE:I 9. Had a water level measuring device been available, would it have assisted the operators in determining the size of the steam bubble in the pressure vessel and otherwise in bringing the plant to a stable condition?
Certified By [Signature] ^{45 DAY} REPORT

11. Is it generally expected that if a leak had developed in the steam generators, the operators would have been able to initiate the "feed and bleed" process described in Mr. Weiss' January 28 memorandum.

DST

12. How many steam generator tube ruptures per year of the Ginna magnitude or greater do you expect?

DST

13. What is the likelihood of several steam tube ruptures occurring at one time? What is the maximum number of simultaneous or near simultaneous steam generator tube ruptures that are considered design basis accidents following which the a can be brought to a safe shutdown condition by following plant operating and emergency procedures?

RES

14. Did WASH 1400 or more recent risk assessments determine the probability of occurrence of events in which one or more steam generator tube failures are followed by various combinations of PORV, block valve, and safety valve failures?

RE:I

15. How long did it take to reach cold shutdown? Is this a period longer than desirable? What was the reason for the period being longer than normal? What kinds of malfunctions during the extended cooldown period might have led to a significant release of radioactivity to the environment?

RE:I

16. Did any part of the reactor pressure vessel cool at a rate in excess of that stipulated in the plant technical specifications? { 45 DAY REPORT

RE:I

17. Was there a capability at Ginna to remotely vent the reactor pressure vessel high points? Does the Commission believe that conditions might develop in PWRs calling for the use of remotely controlled valves for the purpose of venting steam?


DST

RE:I

DHFS

18. At any point during the Ginna event, did the steam generator containing the ruptured tube control the primary system pressure? Are operators at Ginna and other PWRs trained with respect to actions to be taken when a steam generator controls primary system pressure?

Sincerely,


MORRIS R. UDALL
Chairman

23101C

2/17/82

91 89 87 85 83 81 79 77 75 73 71 69 67 65 63 61 59 57 55 53 51 49 47 45 43 41 39 37 35 33 31 29 27 25 23 21 19 17 15 13 11 9 7 5 3 1

92 90 88 86 84 82 80 78 76 74 72 70 68 66 64 62 60 58 56 54 52 50 48 46 44 42 40 38 36 34 32 30 28 26 24 22 20 18 16 14 12 10 8 6 4 2

COLUMNS

R41C65 } not adequately
 R41C64 } mapped yet
 R42C64
 R43C63
 R43C62
 R43C61
 R43C60
 R43C59

SHEAR TO 0.03 IN
 GAP BETWEEN
 LINER AND OUTER
 PERIMETER AROUND
 R44C58

NEWLY LOCATED (P/17)
 FOREIGN OBJECT - LOOKS
 LIKE A SMALLER PIECE OF
 ODD-WORKER FLOW RESTRICTOR


PIECE OF WIRE
 L SHAPED

FORGIB (PIECE OF
 TUBING)
 OBJECT

45
 44
 43
 42
 41
 40
 39
 38
 37
 36
 35
 34
 33
 32
 31
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

ROWS

R41C1 } not yet
 R7C1 } mapped
 R6C1
 R5C1
 R4C1
 R3C1




MANWAY

• PLUGGED
 X SLEEVED
 ○ PLUGGED THIS OUTSIDE

B 1/6 HOT LEG SIDE

NOZZLE

DS



2-16-82 WSK

2-16-82 DATA REVIEW "B" S/K HOT LEG






R1C92	OK	
R2C92	OK	
R3C92	OK	
R4C92	OK	
R5C92	OK	
R6C92	OK	
R7C92	OK	
R8C92	STARTED OUT WITH HOLE, SHOULD BE OK	A
R9C91	SCARS ON OD	B
R10C91	OD DAMAGE - WIPED AREA - SCRAPED	C
R11C91	HOLE AND DAMAGE	D
R12C91	HOLE AND DAMAGE	E
R13C90	SCARS ON OD	F
R14C90	OD DAMAGE - DEPRESSION	G
R15C90	OD DAMAGE AND HOLE	H
R16C89	LITTLE SCARS	I
R17C89	OD SCARS	J
R18C88	OK	
R19C88	OK	
R20C88	OK	
R21C87	OK	
R22C86	OK	
R23C86	OK	
R24C85	OK	
R25C85	OK	
R26C84	OK	
R27C83	OK	
R28C82	OK	
R29C82	OK	
R30C81	OK - PIECE OF TUBING ON TUBE SHEET	K
STAY PAD	OK	

2-16-82 DATA REVIEW "B" S/G HOT LEG.

R33C78	OK	
R34C77	OK	
→ R34C76	OK	
R35C76	OK	
→ R35C75	OK	
≡ R35C74	OK	
R36C74	OK	
→ R36C73	OK	
R37C73	OK	
→ R37C72	OK	
R38C72	OD DAMAGE - PLUGGED - OK	→ L
→ R38C71	OD DAMAGE - PLUGGED - OK	→ M
≡ R38C70	OK	→
R39C70	OD DAMAGE - PLUGGED - OK	→ N
→ R39C69	OD DAMAGE - PLUGGED - OK	→ O
≡ R39C68	OD DAMAGE - PLUGGED - OK	→ P
R40C68	OK - PLUGGED	→ Q
→ R40C67	OK - PLUGGED	→ R
R41C66	OK - PLUGGED - HUNG UP	→ S
→ R41C65		T
≡ R41C64		U
R42C64		V
→ R42C63		W
≡ R42C62		X
R43C61		Y
→ R43C60		Z
≡ R43C59		AA
R44C58	MANGLED	AB
→ R44C57	MANGLED - MISSING ?	AC
≡ R44C56	MANGLED	AD
≡ R44C55	MANGLED	AE






1

IMAGE EVALUATION TEST TARGET (MT-3)







1

IMAGE EVALUATION
TEST TARGET (MT-3)








1

IMAGE EVALUATION TEST TARGET (MT-3)



1

IMAGE EVALUATION TEST TARGET (MT-3)



2-16-82 DATA REVIEW "B" S/G H&L LEG.

R45C54	MANGLED TUBE	AF
R45C53	MANGLED TUBE.	AF
R45C52	PULLED TUBE.	AF
R45C51	MOTTLED (RIPPLED OD) - COLD WORKED?	AF
R45C50	OK	
R45C49	OK.	
R45C48	OK	
R45C47	OK - PLUGGED	
R45C46	OK - PLUGGED	
R45C45	OK	
R45C44	OK.	
R45C43	OK.	
R45C42	OK.	
R45C41		
R45C40	OK.	
R45C39	OK.	
⇒ R44C38	OK.	
⇒ R44C37	OK.	
→ R44C36	OK.	
R44C35	OK.	
⇒ R43C34	OK - PIECE OF WIRE →	AF
→ R43C33	OK.	
R43C32	OK.	
⇒ R42C31	OK.	
→ R42C30	OK.	
R42C29	OK.	
→ R41C28	OK.	
R41C27	OK.	
→ R40C26	OK.	
R40C25	OK.	
→ R39C24	OK.	

2-16-82 DATA REVIEW 'B' 3/6 HOLE

R39C23 OK
 R38C21 OK
 R37C20 OK
 R36C19 OK
 → R35C18 OK
 R35C17 OK
 R34C16 OK
 → R33C16 OK
 R32C15 OK

FOREIGN OBJECT (PIECE OF TUBING) BETWEEN R32C15 & STAY BAR ^{AK}

STAYBAR OK
 → R30C13 OK
 R30C12 OK
 R29C11 OK
 → R28C11 OK
 R27C10 OK
 R26C9 OK
 R25C8 OK
 → R24C8 OK
 R23C7 OK
 → R22C7 OK
 R21C6 OK
 R20C5 OK
 → R19C5 OK
 → R18C5 OK
 R17C4 OK
 → R16C4 OK
 R15C3 OK
 → R14C3 OK
 → R13C3 OK
 R12C2 PLUGGED AND OK

2-16-82 DATA REVIEW "B" S/G Hot Leg:

- R11C2 OK
- R10C2 OK
- R9C2 OK
- R8C1
- R7C1
- R6C1
- R5C1
- R4C1
- R3C1
- R2C1
- R1C1