Initial Telephone Report Date:	October 8, 1975	Date of Occurrence	10/8/75	
Initial Written Report Date:	October 8, 1975	Time of Occurrence:	1330	

OYSTER CREEK NUCLEAR GENERATING STATION FORKED RIVER. NEW JERSEY 08731

> Abnormal Occurrence Report No. 50-219/75/ 27

IDENTIFICATION

Violation of the Technical Specifications, paragraph3.1.1.0.3, OF OCCURRENCE: Low Reactor Pressure Core Spray Valve Permissive Pressure Switches RE 17B and D were found to trip at pressures less than the minimum required yalue of 285 psig. This event is considered to be an abnormal occurrence as defined in the Technical Specifications, paragraphs 1.15B and D.

CONDITIONS	P	R	I	0	R
TO OCCURREN	C	E	*		

X	Steady State Power Hot Standby Cold Shutdown Refueling Shutdown Routine Startup Operation	Routine Shutdown Operation Load Changes During Routine Power Operation Other (Specify)
Plant	Parameters: Power (thermal) - 582.6 Mwt Power (electrical) - 155 Mwe Recirc flow - 6.0 x 10 ⁴ Feed flow - 1.77 x 10 ⁶ lb./hr.	10.20.

DESCRIPTION OF OCCURRENCE:

On Wednesday, October 8, 1975 at approximately 1130 while performing quarterly surveillance testing on the four (4) Low Reactor Pressure Core Spray Valve Permissive Pressure Switches, it was discovered that RE 17B and D tripped at 275 psig and 277 psig, respectively. These values are less than the Technical Specification limit of 285 psig. Pressure switches RE 17B and D were immediately recalibrated.

8302240076 751017 PDR ADOCK 05000219

121661

The "as found" and "as left" switch settings were:

	"As Found" Settings	"As Left" Settings
RE17A	285 psig	285 psig
RE17B	275 psig	287 psig
RE17C	285 psig	285 psig
RE17D	277 psig	289 psig

PPARENT CAUSE F OCCURRENCE:

Design	Procedure		
Manufacture	Unusual Service Condition		
Installation/	Inc. Environmental		
Construction	Component Failure		
Operator	X Other (Specify)		

The cause of this occurrence is switch repeatability.

NALYSIS OF CCURRENCE: The Core Spray System Parallel Isolation Valves open when a low-low reactor water level and/or high drywell pressure condition exists in addition to a low reactor pressure condition (285 psig). The four (4) Low Reactor Pressure Core Spray Valve Permissive Pressure Switches sense the low reactor pressure condition and provide signals to the valve opening logic. Two (2) of these switches (RE 17A and B) are associated with Core Spray System 1 and the other two (2) switches (RE 17C and D) are associated with Core Spray System 2. A trip of one switch in each core spray system is required to effect parallel isolation valve opening in that system. A review of the "as found" switch settings indicates that parallel isolation valves in both core spray systems would have opened at reactor pressures 285 psig had a reactor low-low water level and/or high drywell pressure condition existed concurrently. The safety significance of this event is considered to be the loss of switch redundancy.

normal Occurrence port No., 50-219/75/27

DRRECTIVE ACTION:

Immediate corrective action involved the recalibration of pressure switches RE 17B and D.

AILURE DATA:

Manufacturer data pertinent to these switches are as

follows:

Manufacture:

Barksdale

Type: Range: Pressure Actuated Switch

50-1200 psig

Switch No.:

B2T-A12SS (RE 17B) B2T-A12SS (RE 17D)

Previous Abnormal Occurrences involving these switches:

(1) A.O. Report No. 50-219/75/12

Prepared by: J. E. Quintenz

Date: October 8, 1975

TU:

James P. O'Reilly Directorate of Regulatory Operations Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

FROM:

Jersey Central Power & Light Company Oyster Creek Nuclear Generating Station Docket #50-219 Forked River, New Jersey 08731

SUBJECT:

Abnormal Occurrence Report No. 50-219/75/ 27

The following is a preliminary report being submitted in compliance with the Technical Specifications, paragraph 6.6.2.

Proliminary Approval:

d. T. Carroll, Jr.

Date

CC: Mr. A. Giambusso

Emitial Telepho	ne Cetali	er 8. 1975	Date of Occurrence	10/8/75
Emitial Mritten Report Date:	00000	or 6, 1975	Time of Occurrence	: 1339
	ors	TER CREEK NUCLEA FORKED RIVER, N		
			Occurrence 0-219/75/_ET	
IDENTIFICATION OF OCCURRENCE:	Low Reacto 176 and D value of 2	or Pressure Core were found to to 265 psig. This of as defined in t	Spray Valve Pe rip at pressure event is consid	ations, paragraphs.1.1.D.3, rmissive Pressure Switches s less than the minimum requered to be an abnormal pecifications, paragraphs
CONDITIONS PRIOR	2			
TO OCCURRENCE:	<u>×</u>	Steady State Por Hot Standby Cold Shutdown Pafueling Shutdo Routine Startup Operation		Routine Shutdown Operation Load Changes During Poutine Power Operation Other (Specify)
	,	Parameters: Power (thermal) Power (electrica Recirc flow - 6. Feed flow - 1.77 Stack gas - 3090	1) - 155 Mwe 0 x 10 ⁴ x 10 ⁶ lb./hr.	

DESCRIPTION OF OCCURRENCE:

On Mednesday, October 8, 1975 at approximately 1130 while performit quarterly surveillance testing on the four (4) Low Reactor Pressur: Core Spray Valve Permissive Pressure Switches, it was discovered that RE 17B and D tripped at 275 psig and 277 psig, respectively. These values are less than the Technical Specification limit of 28! psig. Pressure switches RE 17B and D were immediately recalibrate:

razz Uccurrence it No. 50-219/75/27

The "as found" and "as left" switch settings were:

	"As Fuend" Settings		"As Left" Settings
RE17A	235 7512		285 psig
RE178	275 psig	446	287 psig
· GELTC	253 psig		265 psig
RE17D	277 psig		289 psig

CHOCKECE:

Design	Procedure		
Manufacture	Impous) Service Condition		
Installation/	Inc. Environmental		
Construction	Component Failure		
_02622330	X Palara (Specify)		

The cause of this occurrence is switch repeatability.

SIS OF

The Core Spray System Parallel Isolution Valves open when a low-low reactor water level and/or high drywell pressure condition exists in addition to a law reactor pressure condition (285 psis). The from [4] low Reactor Pressure Core Spray Valve Permissive Pressure Switches sense the law reactor pressure condition and gravide signals to the valve opening logic. Two (2) of these switches (RE 17A and E) are associated with fore Spray System 1 and the other two (2) switches (RE 17C and D) are associated with Core Spray System I. A trip of one switch in each core spray system is required to effect parallel isolation valve opening in that system. A review of the "as found" switch settings indicates that parallel isolation valves in both core spray systems would have opened at reactor pressures 285 psig had a reactor low-low water level and/or high drywell pressure. condition existed concurrently. The safety significance of this event is considered to be the loss of switch redundance.

real Occurrence of No. 58-219/75/27

!CTIVE ACTION:

Introducte corrective action impossed the recalibration of pressure switches RE 178 and Da.

TRE DATA:

Manufacturer data pertinent to these switches are as follows:

MoonSecture: Type: Rompe: Smitch Mo.: Furtherador Foreserve Actuated Switch SO-LBOS paig BIT-ALIBS (RE 178) BIT-ALIBS (RE 170)

Previous Abnormal Occurrences Esselving these switches:
(1) 8.0. Report No. 50-219/75/12

1805 by: J. E. Quintens

Date: October 8, 1975