

TO:

James P. O'Reilly  
Directorate of Regulatory Operations  
Region I  
631 Park Avenue ✓  
King of Prussia, Pennsylvania 19406

FROM:

Jersey Central Power & Light Company  
Oyster Creek Nuclear Generating Station Docket #50-219  
Forked River, New Jersey 08731

SUBJECT:

Abnormal Occurrence Report No. 50-219/75/ 22

The following is a preliminary report being  
submitted in compliance with the Technical  
Specifications, paragraph 6.6.2.

Preliminary Approval:



J. T. Carroll, Jr.

Date

CC: Mr. A. Giambusso

8302250155 750811  
PDR ADOCK 05000219  
S PDR

Initial Telephone  
Report Date: 8/11/75

Date of  
Occurrence: 8/10/75

Initial Written  
Report Date: 8/11/75

Time of  
Occurrence: 1435

OYSTER CREEK NUCLEAR GENERATING STATION  
FORKED RIVER, NEW JERSEY 08731

Abnormal Occurrence  
Report No. 50-219/74/22

IDENTIFICATION OF OCCURRENCE: Violation of the Technical Specifications, paragraph 3.6.A.3, failure of the stack gas sample system to continuously monitor stack releases while the reactor was in an unisolated condition.

This event is considered to be an abnormal occurrence as defined in the Technical Specifications, paragraph 1.15B.

CONDITIONS PRIOR  
TO OCCURRENCE:

<input checked="" type="checkbox"/> Steady State Power	<input type="checkbox"/> Routine Shutdown
<input type="checkbox"/> Hot Standby	<input type="checkbox"/> Operation
<input type="checkbox"/> Cold Shutdown	<input type="checkbox"/> Load Changes During
<input type="checkbox"/> Refueling Shutdown	<input type="checkbox"/> Routine Power Operation
<input type="checkbox"/> Routine Startup	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Operation	

Power:	Core, 1675 MWt
	Electric, 550 MWe
Flow:	Recirculation, $13.5 \times 10^4$ gpm
	Feed, $6.55 \times 10^6$ lb/hr.
Reactor Pressure:	1020 psig
Stack Gas:	10,200 $\mu$ ci/sec

DESCRIPTION OF OCCURRENCE: At 1435 on August 10, 1975 a stack gas sample line low flow alarm was received in the Control Room. An operator was dispatched to check the Stack Gas Sample Pump at which time, Stack Gas Sample Pump A was found not running. The operator reset the thermal overload which started Stack Gas Sample Pump A at 1437. The total amount of time the Stack Gas Sample Pump was out of service was approximately two (2) minutes.

PARENT CASE  
OCURRENCE:

Design  
 Manufacture  
 Installation/  
 Construction  
 Operator

Procedure  
 Unusual Service Condition  
 Inc. Environmental  
 Component Failure  
 Other (Specify)  
The cause of this  
occurrence is under investi-  
gation.

ANALYSIS OF A review of the stack gas radiation monitor recorder traces showed  
OCURRENCE: the levels of both monitor channels to be relatively constant  
(at 400cpsA) with no spiking before and after the pump trip. In a further  
250cpsB  
effort to determine if excessive stack releases might have occurred during the  
proximate two(2) minute period that the Stack Gas Sample Pump was not  
operating, recorder traces of radiation monitoring systems associated with two  
seous streams released through the stack were reviewed. Off Gas radiation  
monitor recorder traces showed that the levels of both monitor channels were  
relatively constant (at approximately  $1.25 \times 10^3$  nr/hr) with no spiking for a  
period of approximately 60 minutes prior to this event. Sixty(60) minutes is  
the Off Gas System holdup time prior to releasing to the stack. In addition,  
a review of the Reactor Building Ventilation Exhaust radiation monitor  
recorder traces showed that at the time of this event, the levels of both  
monitor channels were relatively constant (at approximately 1.5 nr/hr) with  
no spiking. Based on these considerations and the very short period of time  
at the stack gas sample pump was not operating, the safety significance of  
this event is considered to be minimal.

CORRECTIVE ACTION: The thermal overload protection was reset. After verifying that  
Stack Gas Sample Pump A was running with no abnormal conditions  
present, Stack Gas Sample Pump B was put into service and Stack Gas Sample  
Pump A was taken out of service.

FAILURE DATA: Previous abnormal occurrences involving the Stack Gas Sample Pumps are

- |    |                                |         |
|----|--------------------------------|---------|
| 1. | Abnormal Occurrence Report No. | 74/53   |
| 2. | "                              | " 74/54 |
| 3. | "                              | " 74/57 |
| 4. | "                              | " 74/61 |
| 5. | "                              | " 75/6  |

Prepared by:

James E. Gentry

Date:

8/11/75

Mr. James P. O'Reilly

- 2 -

August 11, 1975

E. CORRECTIVE ACTION

The load was removed from the plant at 4:15 a.m., on August 11, 1975, and plant cooldown was commenced at 11:10 a.m., in preparation for replacement of the faulty seal.

F. FAILURE DATA

To be addressed in the final report.

INVESTIGATOR:



K. Denton

cc: Director of Office of Nuclear Reactor Regulation