

NUCLEAR ENERGY INFORMATION
REGION III
790 RODSVELT ROAD
GLEN ELLYN, ILLINOIS 60137

January 3, 1979

Docket No. 50-500/501
50-520/320

MEMORANDUM FOR: J. F. Streeter, Chief, Nuclear Support Section 1
FROM: J. S. Creswell, Reactor Inspector
SUBJECT: CONVEYING NEW INFORMATION TO LICENSING BOARDS -
DAVIS-BESSE UNITS 2 & 3 AND MIDLAND UNITS 1 & 2

During the course of my inspections at Davis-Besse, certain issues have come to my attention which I am submitting for consideration for forwarding to the Atomic Safety and Licensing Board which has proceedings pending for the aforementioned facilities. This submittal is made pursuant to Regional Procedure 1530A (November 16, 1978), step 3 and information supplied to me per step 1. The issues for consideration are:

1. During a recent inspection at Davis-Besse Unit 1 information has been attained which indicates that at certain conditions of reactor coolant viscosity (as a function of temperature) core lifting may occur. The licensee informed the Inspector that this issue involves other B&W facilities. The Davis-Besse PSAR states in Section 4.4.3.7:

The hydraulic force on the fuel assembly receiving the most flow is shown as a function of system flow in Figure 4-39. Additional forces acting on the fuel assembly are the assembly weight and a hold down spring force, which resulted in a net downward force at all times during normal station operation.

The licensee states that there is a 500°F interlock for the starting of the fourth reactor coolant pump. However, no Technical Specification requires that the pump be started at or above this temperature. A concern regarding this matter would be if assemblies moved upward into a position such that control rod movement would be hindered.

2. Inspection Report 50-346/78-06, paragraph 4, reported reactivity - power oscillations in the Davis-Besse core. These oscillations have also occurred at Oconee and are attributed to steam generator level oscillations. B&W report BAW-10007 states in AP.1:

January 3, 1972

The OTSG laboratory model test results indicated that periodic oscillations in steam pressure, steam flow, and steam generator primary outlet temperatures could occur under certain conditions.

It was shown that the oscillations were of the type associated with the relationships between feedwater housing chamber pressure drop and tube nest pressure drop, which are eliminated or reduced to levels of no consequence (no feedback to reactor system) by adjustment of the tube nest inlet resistance. As a result of the tests, an adjustable orifice has been installed in the downcomer section of the steam generators to provide for adjustment of the tube nest inlet resistance and to provide the means for elimination of oscillations if they should develop during the operating lifetime of the generators. The initial orifice setting is chosen conservatively to minimize the need for further adjustment during the startup test program.

We also note that the effect on the in-core detector system for monitoring core parameters during the oscillations is not clear.

3. Inspection and Enforcement Report 30-346/73-06 documented that pressurizer level had gone offscale for approximately five minutes during the November 29, 1977 loss of offsite power event. There are some indications that other B&W plants may have problems maintaining pressurizer level initiations during transients. In addition, under certain conditions such as loss of feedwater at 100% power with the reactor coolant pumps running the pressurizer may void completely. A special analysis has been performed concerning this event. This analysis is attached as Enclosure 1. Because of pressurizer level maintenance problems the sizing of the pressurizer may require further review..

Also noted during the event was the fact that Tcold went offscale (less than 520°F). In addition, it was noted that the makeup flow monitoring is limited to less than 160 gpm and that makeup flow may be substantially greater than this value. This information should be examined in light of the requirements of GDC 13.

4. A memo from B&W regarding control rod drive system trip breaker maintenance is attached as Enclosure 2. This memo should be evaluated in terms of shutdown margin maintenance and ATWS considerations particularly in light of large positive moderator coefficients allowable with B&W facilities.

... Inspector

January 8, 1979

5. Inspection and Enforcement Report 50-34876-17, paragraph 6 refers to inspection findings regarding the capability of the incore detector system to determine worst case thermal conditions. The reactor can be operated per the Technical Specifications with the center incore string out of service. If the peak power limitation is in the center of the core (this has been the case at Davis-Besse), factors are not applied to conservatively monitor values such as \dot{F}_Q and $F_{delta H}$.
6. Enclosure 3 describes an event that occurred at a BSN facility which resulted in a severe thermal transient and extreme difficulty in controlling the plant. The aforementioned facilities should be reviewed in light of this information for possible safety implications.

J. S. Creswell
Inspector

Enclosures: As stated

cc w/c enclosures:
G. Fiorelli
R. C. Kaep
T. N. Tambling