

b7C & b7D

Those on Attached List

MONTHLY LICENSED EVENT REPORTS (MRE) FILE LISTINGS

The enclosed MRE computer listings provide information on certain licensee event reports entered into the file during the month of November. The two listings provided are as follows:

1. MRE output on MRE events sorted by cause, facility, and event date.
2. MRE output on events involving personnel error sorted by facility and event date.

If you desire additional information or special searches, please do not hesitate to contact us.

J. A. Kirk, Acting Director
Regulatory Info. System Division
Office of Management Information
and Program Control

Inclusive
As stated

8307070191 790830
PDR ADOCK 05000289
S HOL

01018
CROSS SECTION NOT PROVIDED
CIVILIAN CIVILIC-J
CIVILIAN INDUSTRIAL COMMISIONER
SUCH INFORMATION NOT APPLICABLE
DURING OPERATION SYS + CONFERECE
ROUTINE INSPECTION
FABRICKS INDUSTRIAL

05000002
010177
010182

010177
SILENT STATE OPERATION
11-12A1 IN HOUR 1 WORKING HOURS DATED, EVC PRESSURE TEL. 010177, 10-02
IN. BOTTLE GLU. CAUSES TO START CONTRARY TO TECH SPEC.
IS AVAILABLE & OPERABLE. FIRST TIME OCCURRENCE. CHIEF FAILURE, 7P-12A1
BREAKER VERIFICATION SP-321 PLATFORM. 20 ENDS, DIESEL GENERATOR 24,
PLAUSIBLE IN 7 HOURS.

L055 OF DIESEL START PERMISSIVE DUE TO HIGH LINE OIL PRESSURE. AVAIL GAs
TO HIGH HE HAD TO REPEAT & HAS NOT REPEATED TO THIS DATE.

01018
CAUSE SECTION NOT PROVIDED
CIVILIAN CIVILIC-J
BATTERIES + CHARGERS
SUCH INFORMATION NOT APPLICABLE
PC MISSING FROM SYS + CONFERECE
ROUTINE INSPECTION
FABRICKS INDUSTRIAL DIV

010177
010180

010177
SILENT STATE OPERATION
11-12A1 IN 24 HOURS 1977, HOURS 1-2 BATTERIES BLOWN OUT. REASON:
HIGH CAPACITY OF QUARTERLY & HEAVILY STRUCTURE PROBLEMS.
IN A CONDITION CONTRARY TO 1.5. 3-A-1-1-A. ELECTRICITY HAS BEEN DOWN 100%
IN PAST. GDU. THIRD A FOURTH OCCURRENCE OF THIS.
PERMITABLE UP/DOWN 24 HOURS EACH TIME.

L055 OF ELECTROLYTE DUE TO BATTERIES BEING IN NO LOAD CONDITIONS
H2, RECOMMENDATION TO INCREASE FLOAT VOLTAGE .05 VOLTS WILL BE SUBMITTED
. IN PRECISE RETURN DATE.

01018
NOT APPLICABLE
DAVIS-BELG-J
INSTRUMENTATION + EQUIPMENT
OTHER
HIGHER RISK SYS FOR SAFETY
ROUTINE CYCLE
CONSOLIDATED CONTROLS COMP.

010174
010177
010180

010177
ROUTINE SILENT STATE OPERATION
HALF DAY OF BOTTLE & FLUIDATION BOTTLE SYSTEM DUE TO THE
EVC CONTACT SYSTEM BLOWN & PRESSURE. CAUSES PRESSURE FROM BOTTLE 10
LBS HIGH & VALVE FAILED TO CLOSE. CAUSES REDUCTION IN EVC PRESSURE.
LEGS HIGH EXCEEDED FOR 5 1.5. 3-A-1-1-A, 3-A-5, 3-A-6, 3-A-7, 3-A-8, 3-A-9.

H2, TRIP CIRCUIT FROM SILECS CHAMBER 2, WHICH CAUSES VALVE FAULTS.
H2, CAUSE OF THIS HALF DAY HAS NOT BEEN POSITIVELY DETERMINED AND
AN INVESTIGATIVE INVESTIGATION HAS NEVER BEEN CONDUCTED AT TECHNICAL GS.

OPERATING UNITS STATUS REPORT

DATA AS OF 10-31-77

NUREG 002C
VOL. 1 NO.
NOVEMBER
1977
NATIONAL ENERGY INFORMATION

LICENSED OPERATING REACTORS

DATA FOR DECISIONS

- Department of Energy
- Nuclear Regulatory Commission

UNIVERSITY

FACILITY DATA

NAC POWER RESTRICTIONS: white

INSPECTION STATUS

Facility Data		Enforcement Status		Inspection Status		Reports Received from Licensee	
Facility Description	Ground floor	None	Date of last inspection	09/12/01	Type of report	Report	None
1. Location being monitored	Burnham, 19 miles		2. Facility Address, County	1018			
3. Type of Reactor			4. Last Report				
5. Current Power Level (Mw)	1112		6. Date of last inspection	09/12/01	7. Date of last report	09/12/01	8. Date of last inspection
7. Current Thermal Rating (Mw)	961		8. Last Report	09/12/01	9. Last Report	09/12/01	10. Last Report
9. Date of last audit	9/10		11. Last Report	09/12/01	12. Last Report	09/12/01	13. Last Report
12. Date of Commercial Operation	9/10		14. Last Report	09/12/01	15. Last Report	09/12/01	16. Last Report
13. Current Condition	Normal		17. Last Report	09/12/01	18. Last Report	09/12/01	19. Last Report
14. Condition Existing When Known	Normal		20. Last Report	09/12/01	21. Last Report	09/12/01	22. Last Report
23. Safety & Emergency Information			23. Last Report	09/12/01	24. Last Report	09/12/01	25. Last Report
26. License			26. Last Report	09/12/01	27. Last Report	09/12/01	28. Last Report
29. Current Admin.	From: Mr. Bill Wilson, Sr., Title: Vice Pres.		30. Inspection Status	09/12/01	31. Last Report	09/12/01	32. Last Report
32. Corporate Contact	Frank Baum, VP - Phone: 511-3000		33. Last Report	09/12/01	34. Last Report	09/12/01	35. Last Report
34. Nuclear Safety Agency	Resident Env.		36. Inspection Status	09/12/01	37. Last Report	09/12/01	38. Last Report
38. Nuclear Safety System	Resident Env.		39. Last Report	09/12/01	40. Last Report	09/12/01	41. Last Report
40. Last Inspector	John		42. Last Report	09/12/01	43. Last Report	09/12/01	44. Last Report
44. Reporting Information			45. Last Report	09/12/01	46. Last Report	09/12/01	47. Last Report
48. 10 Major responsible			48. Last Report	09/12/01	49. Last Report	09/12/01	50. Last Report
51. 11 Branch Chief	Bill		51. Last Report	09/12/01	52. Last Report	09/12/01	53. Last Report
53. 12 Senior Inspector			54. Last Report	09/12/01	55. Last Report	09/12/01	56. Last Report
56. 13 Power and Resources			57. Last Report	09/12/01	58. Last Report	09/12/01	59. Last Report
59. 14 Licensing			60. Last Report	09/12/01	61. Last Report	09/12/01	62. Last Report
62. 15 Director	W.H.S.		63. Last Report	09/12/01	64. Last Report	09/12/01	65. Last Report
65. 16 General Manager			66. Last Report	09/12/01	67. Last Report	09/12/01	68. Last Report
68. 17 General Manager/Chief of Staff			69. Last Report	09/12/01	70. Last Report	09/12/01	71. Last Report

Reviewed by NIPC OIC: John Riebe DATE: 07/17/02Reviewed by NRR DOR: J.E. [initials] DATE: 07/17/02

OPERATING UNITS STATUS REPORT

DATA AS OF 11-30-77

NUREG 0020
VOL. 1 NO. 1
DECEMBER

NUCLEAR REGULATORY COMMISSION
U.S. GOVERNMENT PRINTING OFFICE: 1977 50-770-104-10

LICENSED OPERATING REAC
DATA FOR DECISIONS

- Department Of Energy
- Nuclear Regulatory Commission

FACILITY DATA

SRC POWER RESTRICTIONS: None

INSPECTION STATUS

ENFORCEMENT STATUS

Facility Description	Building Number 18-A-B-C	Date of Inspection	10/19/01	Date of Report	10/22/01	Report to	State of Alaska
1. Environmental Impact Assessment	None						
2. Energy Reliability Council	None						
3. Type of Power	residential						
4. Standard Power Grid Status	100%						
5. Orange Book of New Plant Model	20%						
6. Grid Allocated Generating	8%						
7. Grid of Commercial Operation	11/18/01						
8. Customer Contact Method	Telephone						
9. Customer Contact Person Name	John Doe						
10. Company Contact Person Name	John Doe						
11. Company Information							
12. Themes							
13. Envelope Address	1234 Power Rd, Matanuska, Alaska 99635						
14. Facility Contact	John Doe, Phone 999-1234						
15. Authorized Signatures							
16. Nuclear License Holder System	Edwards & Associates Inc.						
17. Construction	Initial Site Plan A						
Reporting Information							
18. HI Region responsible	HI						
19. HI Branch Chief	E. Johnson						
20. HI Branch Inspector	B. C. King						
21. HI Project Inspector	B. R. King						
22. Shoring Product Manager	B. C. King						
23. District Manager	W. M. King						
24. State Number/Office of Power	123456789						

REPORTS RECEIVED FROM LICENSEE

	Report Date	Date of Report	To whom	Comments
1. Results of operations visit on September 1st, 2001. In the plant there were several deficiencies in a number of areas. These deficiencies were addressed by the licensee. These deficiencies included water treatment system, fire protection and facility equipment. The operator stated that the facility was in good condition. Despite modifications made, there were still facility items which were not functioning properly and the power plant's operation functioned as planned.	09-19-01-02 10/01/01	10/01/01	to DNR Report	Testing results in fire protection system are being reviewed.
2. Results of inspection dated 10/18/01. In the plant there were several deficiencies in a number of areas. These deficiencies were addressed by the licensee. These deficiencies included water treatment system, fire protection and facility equipment. The operator stated that the facility was in good condition. Despite modifications made, there were still facility items which were not functioning properly and the power plant's operation functioned as planned.	09-20-01-10 10/01/01	10/01/01	to DNR Report	Inspections are due to facility generator failure due to defective electrical switch.
3. Results of inspection dated 10/18/01. In the plant there were several deficiencies in a number of areas. These deficiencies were addressed by the licensee. These deficiencies included water treatment system, fire protection and facility equipment. The operator stated that the facility was in good condition. Despite modifications made, there were still facility items which were not functioning properly and the power plant's operation functioned as planned.	09-20-01-11 10/01/01	10/01/01	to DNR Report	Inspections of facility system are being reviewed.
4. Results of inspection dated 10/18/01. In the plant there were several deficiencies in a number of areas. These deficiencies were addressed by the licensee. These deficiencies included water treatment system, fire protection and facility equipment. The operator stated that the facility was in good condition. Despite modifications made, there were still facility items which were not functioning properly and the power plant's operation functioned as planned.	09-20-01-12 10/01/01	10/01/01	to DNR Report	Inspections of facility system are being reviewed.

Received by MIPC OIC: L. B. King DATE: 10/22/01
 Received by NRR DOR: J. G. King DATE: 10/22/01

See Continuation on Page 8 TA

UNITED
NUCL
REGUL
COMMIT

CURRENT EVENTS

POWER REACTORS

THIS COMPILATION OF SELECTED EVENTS IS PREPARED TO DISSEMINATE INFORMATION ON OPERATING EXPERIENCE AT NUCLEAR POWER PLANTS IN A TIMELY MANNER AND AS OF A FIXED DATE. THESE EVENTS ARE SELECTED FROM PUBLIC INFORMATION SOURCES. NRC HAS, OR IS TAKING CONTINUOUS ACTION ON THESE ISSUES AS APPLICABLE, FROM AN INSPECTION AND ENFORCEMENT, LICENSING AND GENERIC REVIEW STANDPOINT.

1 SEPTEMBER - 31 OCTOBER 1977
(PUBLISHED DECEMBER 1977)

P-100
EXHIBIT 5
7/2/78 FOR IDENTIFICATION
S. Meier

OPERATOR ERROR

On January 11, 1977 while the Fort Calhoun Station Unit 1 was operating, water from the Refueling Water Storage Tank was pumped into the containment through the containment spray header due to an operator error.

During the performance of a quarterly test of the safety injection and containment spray pumps, the operator noticed an increase in the containment sump level approximately ten minutes after the low pressure safety injection pump had been started. Approximately 3300 gallons of water had been pumped to the containment. About one minute later the ventilation isolation actuation signal was received. At this time the operator realized he had failed to follow the surveillance procedures and had left the discharge valve of the low head safety injection pump open. He immediately secured the pump.

The Reactor Coolant System was checked for leakage and containment entry was made approximately one hour later. Inspection revealed that a discharge from the containment spray nozzles had occurred. A few minutes later power reduction was started. A second containment entry was made about an hour later, after containment air samples confirmed that a full face mask would provide adequate respiratory protection for the levels of radioactivity in the building. A detailed inspection revealed no serious deficiencies and no electrical grounds; the power reduction was terminated at a power level of 63%.

Although the operator had not followed the procedure and the discharge valve was open, the containment spray header isolation valve (HCV-345)

and the low pressure safety injection to containment spray header cross-connect valve (HCV-335) should have prevented the event. The electric/pneumatic converter on HCV-345 had failed and both red and green position indication lights were on, indicating the valve was partially open. Prior to the event the auxiliary building equipment operator had taken local control of the valve in an attempt to completely close the valve. After about 1/2 inch of stem travel, the operator removed the valve pin and the valve went back to its previous position as demanded by the valve positioner. The third valve (HCV-31) in the incident had a leakage problem that had been previously identified but no corrective action had been taken.

The pneumatic relay on valve HCV-345 was replaced and valve HCV-335 repaired. Valve HCV-344 and HCV-345 are now required to be placed in the test mode prior to operating the low pressure safety injection pump or contain spray pump for testing. This mode along with verification of an annunciation will ensure that both of these valves are in the fully closed position prior to pump operation.

VALVE MALFUNCTIONS

1. Primary System Depressurization

On September 24, 1977, Davis Besse Nuclear Power Station Unit No. 1 experienced a depressurization when a pressurizer power relief valve failed in the open position. The Reactor Coolant System (RCS) pressure was reduced from 2255 psig to 675 psig in approximately twenty-one (21) minutes. At the beginning of this event, steam was being bypassed to the condenser and the reactor thermal power was at 263 MW, or 9.5%. Electricity was not being generated. The following systems malfunctioned during the transient:

- a. Steam and Feedwater Rupture Control System (SFRCS).
- b. Pressurizer Pilot Actuated Relief Valve.
- c. No. 2 Steam Generator Auxiliary Feed Pump Turbine Governor.

The event was initiated at 2134 hours, when a spurious "half-trip" occurred in the SFRCS, resulting in closure of the No. 2 Feedwater Startup Valve and loss of flow to No. 2 Steam Generator. Approximately one minute later, low level in the No. 2 Steam Generator caused a full SFRCS trip, closing the Main Steam Isolation Valves.

(MSIV). The loss of heat sink for the reactor caused the RCS temperature, pressure, and pressurizer level to rise.

The RCS pressure increased to the pilot actuated relief valve setpoint (2255 psig) and the valve cycled open and closed nine times in rapid succession, failing to close on the tenth opening. Meanwhile, the reactor operator observed the pressurizer level increase and manually tripped the reactor about one minute after MSIV closure (two minutes into the transient). At this point the RCS pressure was approximately 2000 psig and decreasing while the pressurizer level had reached its maximum initial rise of about 310 inches. The RCS pressure continued to decrease due to the open relief valve and upon reaching 1520 psig approximately three minutes into the transient, actuated Safety Features including high pressure (water) injection and containment isolation.

Approximately five minutes into the transient the rupture disc on the pressurizer quench tank, which was receiving the RCS blowdown, burst. Bursting of the rupture disc was aggravated by the actuation of containment isolation, which had isolated the quench tank cooling system, resulting in expedited pressurization of the quench tank.

The RCS continued to blow down through the open pressurizer power relief valve and the quench tank rupture disc opening until primary coolant saturation pressure was reached, about six minutes into the transient. The formation of steam in the RCS caused an insurge of water into the pressurizer. This insurge and the high pressure water injection then restored the pressurizer level to about 310 inches after nine minutes into the transient.

Approximately thirteen minutes into the transient, the secondary side of the No. 2 Steam Generator went dry. About fourteen minutes into the transient, the operators noticed the low level condition and found that the auxiliary feed pump was operating at reduced speed. Manual control of the auxiliary feed pump was started and water level restored to the No. 2 Steam Generator.

At approximately 21 minutes into the transient, the operators discovered that the pressurizer power relief valve was stuck open. Blowdown via this valve was stopped by closing the block valve, thus terminating the reactor vessel depressurization. The RCS pressure recovered to normal and cooldown of the system followed.

The reason for the spurious "half-trip" of the SPRCS has not yet been determined. An extensive investigation revealed several loose connections at terminal boards, but nothing conclusive.

Investigation finds the failure of the pressurizer pilot actuated relief valve revealed that a "close" relay was missing from the control circuit. This missing relay would normally provide a "seal-in" circuit which would hold the valve open until the pressure dropped to 2205 psig. Without the relay the power relief valve cycled open and closed each time the pressure of the RCS went above or below 2255 psig. The rapid cycling of the valve caused a failure of the pilot valve stem, and this failure caused the power relief valve to remain open.

It was determined that the auxiliary feed pump did not go to full speed because of "binding" in the turbine governor.

The transient was analyzed by the NSSS vendor and determined to be within the design parameters analyzed for a rapid depressurization.

With exception of the above noted malfunctions, the plant functioned as designed and there was no threat to the health and safety of a general public.²⁻³

2. Feedwater Isolation Valves

On two occasions in July, at the Trojan nuclear plant, a hydraulic feedwater isolation valve failed to close upon receipt of a close signal. All other equipment required to operate, functioned normally.

The first failure, July 6, 1977, had been attributed to an improperly assembled solenoid in the hydraulic actuator. Investigation of the second failure indicated that both events were due to a lack of sufficient hydraulic pressure.

Failure of the valve to close was caused by the pressure regulator leaking and failing to close down to regulate the pressure. This caused the hydraulic system on the valve to be drained down to a point that the valve would not operate. Inspection of the regulator revealed that a locking screw on the regulator adjusting knob was loose and would allow the knob to vibrate to any position. With the regulator improperly set it would not close down to regulate pressure and would allow the hydraulic fluid to drain. This before the hydraulic operator could function. A similar problem was discovered on two other valves, although the maledjustment was not sufficient to prevent these valves from operating.

13

ATOMIC ENERGY CLEARING HOUSE

1946. U. S. PAT. OFF. 1

PUBLISHED BY

CONGRESSIONAL INFORMATION BUREAU, INC.

DAILY NEWS SERVICE SINCE 1897

COLORADO BUILDING

FOURTEENTH AND G STREETS, NINETEENTH

WASHINGTON, D. C. 20005

ROBERT P. CAZALAS
PRESIDENT

GROVER C. BOYDSTON
EDITOR

Vol. 24

January 9, 1978

METROPOLITAN PRESS
GENERAL AGENTS

----- THIS WEEK'S ISSUE -----
NRC will hold public hearing on proposed clearance program
for some employees in commercial nuclear industry.....Page 1
Pres. Carter and Shah of Iran agreed on nuclear safeguards
that will allow U.S. to sell 6 to 8 reactors to Iran -
Pres. agreed U.S. will supply fuel and heavy water to
India's Tarapur reactor.....Page 2
Secret file on "possible illicit diversion of material from
NUMEC does exist," declassified NRC documents reveal.....Page 2
Atomic Safety and Licensing Appeal Board reversed Licensing
Board's decision that Midland nuclear plant license would
not create situation inconsistent with antitrust laws.....Page 6
Strontium-90 and cesium-137 levels in milk are due to nuclear
weapons fallout, not to nuclear plant releases, NU report..Page 11
Domestic uranium mill output increased about 10 per cent
over that of 1976, Bureau of Mines, Dept. of Interior.....Page 16
NRC's report of Current Events for Power Reactors for the
period September 1-October 31, 1977.....Page 17
NRC has issued construction permit for Tyrone Energy Park
in Wisconsin.....Page 22
NRC Public Document Room -
Inspections.....Page 23
Licensing.....Page 28
Recent industry announcements.....Page 31
Reportable occurrence reports for November 1977 (continued)....Page 42

NRC WILL HOLD PUBLIC HEARING ON PROPOSED CLEARANCE PROGRAM FOR SOME EMPLOYEES IN COMMERCIAL NUCLEAR INDUSTRY. Proposed changes to NRC regulations upgrading its safeguards program would apply to personnel who have access to or control over certain quantities of special nuclear material (high enriched uranium, plutonium and uranium-233), or access to protected areas of facilities such as nuclear power plants and fuel reprocessing plants.

The date and location of the hearing will be announced later.

The Commission will specifically seek comments of individuals and groups on such matters as:

(1) The advantages and disadvantages of alternative programs, such as psychological testing administered by licensees under standards established by the Commission, and alternative safeguards measures not involving investigation or testing of licensee employees.

(2) The extent to which the clearance program meets the performance requirements for protecting nuclear power reactors, particularly toward meeting the postulated threat of internal conspiracy.

(3) The desirability of applying the rule to university research and training reactors subject to Part 73 (physical protection of plants and materials) of NRC regulations.

(4) Impact of the proposed clearance program on transportation of special nuclear material.

Persons who wish to present oral or written statements on the proposed clearance program, announced by the NRC last March, must submit their name and name of their organization, if any, to the Secretary of the Commission, Washington, D.C. 20585, by January 27.

to stocks, although restrictions on the enrichment of foreign uranium for domestic use were partially lifted. All restrictions were to be lifted by 1983.

During the same 9-month period, 123 tons of uranium compounds, including metals and alloys, valued at \$2.9 million and 882 tons of uranium concentrate valued at \$59.0 million were exported. The value of exported special nuclear materials, principally enriched uranium, for the first 10 months was \$391 million.

- 6 - 6 - 6 - 6 - 6 -

NRC'S REPORT OF CURRENT EVENTS FOR POWER REACTORS FOR THE PERIOD SEPTEMBER 1-OCTOBER 31, 1977, published December 1977, is presented below:

OPERATOR ERROR

On January 11, 1977 while the Fort Calhoun Station Unit 1 was operating, water from the Refueling Water Storage Tank was pumped into the containment through the containment spray header due to an operator error.

During the performance of a quarterly test of the safety injection and containment spray pumps, the operator noticed an increase in the containment sump level approximately ten minutes after the low pressure safety injection pump had been started. Approximately 3300 gallons of water had been pumped to the containment. About one minute later the ventilation isolation actuation signal was received. At this time the operator realized he had failed to follow the surveillance procedures and had left the discharge valve of the low head safety injection pump open. He immediately secured the pump.

The Reactor Coolant System was checked for leakage and containment entry was made approximately one hour later. Inspection revealed that a discharge from the containment spray nozzles had occurred. A few minutes later power reduction was started. A second containment entry was made about an hour later, after containment air samples confirmed that a full face mask would provide adequate respiratory protection for the levels of radioactivity in the building. A detailed inspection revealed no serious deficiencies and no electrical grounds; the power reduction was terminated at a power level of 83%.

Although the operator had not followed the procedure and the discharge valve was open, the containment spray header isolation valve (HCV-345) and the low pressure safety injection to containment spray header cross-connect valve (HCV-335) should have prevented the event. The electric/pneumatic converter on HCV-345 had failed and both red and green position indication lights were on, indicating the valve was partially open. Prior to the event the auxiliary Building Equipment Operator had taken local control of the valve in an attempt to completely close the valve. After about 1/2 inch of stem travel, the operator removed the valve pin and the valve went back to its previous position as demanded by the valve positioner. The third valve (HCV-335) in the incident had a leakage problem that had been previously identified but no corrective action had been taken.

The pneumatic relay on valve HCV-345 was replaced and valve HCV-335 repaired. Valve HCV-344 and HCV-345 are now required to be placed in the test mode prior to operating the low pressure safety injection pump or contain spray pump for testing. This mode along with verification of an annunciator will ensure that both of these valves are in the fully closed position prior to pump operation.

VALVE MALFUNCTIONS

1. Primary System Depressurization

On September 24, 1977, Davis Besse Nuclear Power Station Unit No. 1 experienced a depressurization when a pressurizer power relief valve failed in the open position. The Reactor Coolant System (RCS) pressure was reduced from 1155 psig to 875 psig in approximately twenty-one (21) minutes. At the beginning of this event, steam was being bypassed to the condenser and, the reactor thermal power was at 263 MW, at 9.5L. Electricity was not being generated. The following systems malfunctioned during the transient:

- a. Steam and Feedwater Rupture Control System (SFRCS).
- b. Pressurizer Pilot Actuated Relief Valve.
- c. No. 2 Steam Generator Auxiliary Feed Pump Turbine Governor.

APPENDIX D (continued)

The reactor vessel was at full power, and a previous "half-trip" occurred, in the S-75, ... 11:10 AM. At 11:15 AM of the No. 1 Reactor Startup Valve and loss of flow to No. 2 Steam Generator. Approximately one minute later, low level in the No. 2 Steam Generator caused a full water trip, closing the Main Steam Isolation Valves (MSIV). The loss of heat sink for the reactor caused the RCS temperature, pressure, and pressurizer level to rise.

The RCS pressure increased to the pilot actuated relief valve setpoint (2255 psig) and the valve cycled open and closed nine times in rapid succession, failing to close on the tenth opening. Meanwhile, the reactor operator observed the pressurizer level fluctuate and manually tripped the reactor about one minute after MSIV closure (two minutes into the transient). At this point the RCS pressure was approximately 2000 psig and decreasing while the pressurizer level had reached its maximum initial rise of about 310 inches. The RCS pressure continued to decrease due to the open relief valve and upon reaching 1610 psig approximately three minutes into the transient, activated safety features including high pressure (water) injection and containment isolation.

Approximately five minutes into the transient the rupture disc on the pressurizer vent line, which was receiving the RCS blowdown, burst. Venting of the ruptured line was suppressed by the activation of containment isolation, which had isolated the quench tank cooling system, preventing an uncontrolled pressurization of the quench tank.

The RCS continued to blow down through the open pressurizer power relief valve and the quench tank rupture disc opening until primary coolant saturation pressure was reached, about six minutes into the transient. The formation of steam in the RCS caused an surge of water into the pressurizer. This surge and the high pressure water injection then restored pressurizer level to about 310 inches after two minutes into the transient.

Approximately thirteen minutes into the transient, the secondary side of the No. 2 Steam Generator went dry. About fourteen minutes into the transient, the operators noticed the low level condition and found that the auxiliary feed pump was operating at reduced speed. Manual control of the auxiliary feed pump was started and water level restored to the No. 2 Steam Generator.

At approximately 11 minutes into the transient, the operators discovered that the pressurizer power relief valve was stuck open. Blowdown via this valve was stopped by closing the block valve, thus terminating the reactor vessel depressurization. The RCS pressure returned to normal and cooldown of the system followed.

The reason for this spurious "half-trip" of the SACS has not yet been determined. An extensive investigation revealed several loose connections at terminal boards, but nothing conclusive.

Investigation into the failure of the pressurizer pilot actuated relief valve revealed that a "close" relay was missing from the control circuit. This missing relay would normally provide a "latch-in" circuit which would hold the valve open until the pressure dropped to 2105 psig. Without the relay the power relief valve cycled open and closed each time the pressure of the RCS went above or below 2255 psig. The rapid cycling of the valve caused a failure of the pilot valve stem, and this failure caused the power relief valve to stick open.

It was determined that the auxiliary feed pump did not go to full speed because of "binding" in the turbine governor.

The binding was stabilized by the PSS and determined to be within the design performance envelope, despite rapid depressurization.

With exception of the above rated malfunctions, the plant functioned as designed and went back to the health and safety of the general public.

2. Reactor Isolation Valves

On the occasions in July, 1977, at the Florida nuclear plants, a hydraulic feedback loop caused the reactor isolation valves to stick in either an open or a closed position. All other equipment operated normally.

The first failure, July 6, 1977, had been attributed to an apparently loose cable hold in the hydraulic actuator. Investigation of the second failure indicated that both the actuator and the line of the valve hydraulic pressure.