



Tennessee Valley Authority, Post Office Box 2000, Seaford, Tennessee 37370

J. L. Wilson
Vice President, Sequoyah Nuclear Plant

March 11, 1992


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - LICENSEE EVENT REPORT
(LER) 50-328/92001

The enclosed LER provides details concerning an automatic reactor trip during power operation and two subsequent reactor trip actuations, of which one was coincident with an auxiliary feedwater start and feedwater isolation, while shutdown. These events are being reported in accordance with 10 CFR 50.73(a)(2)(iv) as conditions that resulted in manual or automatic actuation of engineered safety features, including the reactor protection system.

Sincerely,


J. L. Wilson

Enclosure
cc: See page 2

9203190270 920311
PDR ADOCK 05000328
S PDR

JE22

U.S. Nuclear Regulatory Commission
Page 2
March 11, 1992

cc (Enclosure):

INPO Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. D. E. LaBarge, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379

Mr. B. A. Wilson, Project Chief
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)	
		SEQUENTIAL	REVISION		
	YEAR	NUMBER	NUMBER		
Sequoyah Nuclear Plant Unit 2	105010131218	912	0011	00	01201019

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. PLANT CONDITIONS

Event No. 1

Unit 2 was in power operations at approximately 89 percent reactor thermal power.

Event Nos. 2 and 3

Unit 2 was in Mode 3, hot standby, with the reactor coolant system at no-load temperature and pressure.

II. DESCRIPTION OF EVENT

A. Event:

1. Event No. 1 (Automatic Turbine and Reactor Trip)

On February 10, 1992, at 0528 EST, the Unit 2 reactor tripped as a result of a turbine trip. The operators received no prior indications that a turbine and/or reactor trip was imminent prior to the turbine first out "turbine overspeed" alarm annunciation. The turbine speed indicator was noted at 1800 revolutions per minute by the shift operations supervisor within a minute after the trip. Additionally, no grid anomaly was observed. The turbine trip precipitated the reactor trip.

2. Event No. 2 (Automatic Reactor Trip, Feedwater Isolation (FWI), and Auxiliary Feedwater (AFW) Start)

On February 10, 1992, at 0949 EST, the Unit 2 reactor trip breaker automatically opened and an engineered safety feature (ESF) signal occurred during performance of a reactor trip breaker (RTB) cycling test. In accordance with procedure requirements, a temporary jumper was installed across terminals in the solid state protection system (SSPS) cabinets to prevent FWI when cycling the RTB during the test. The temporary jumper consisted of a rubber-sleeved alligator clip, with a integral banana plug jack. This clip was connected to a lead with a banana plug on one end and a alligator clip on the other end. During installation of the rubber-sleeved alligator clip, the rubber sleeve was pulled back to facilitate positive attachment of the alligator clip to the terminal. It was not recognized that electrical separation of the banana plug had resulted. At the time of the test, the power range negative rate trip signal had not been cleared from the previous reactor trip (Event No. 1). The assistant shift operations supervisor (ASOS) assumed that procedurally-installed jumpers would prevent trip actuation as well as a FWI. The ASOS proceeded to perform the RTB test by closing the RTB. The RTB immediately reopened because of the uncleared trip signal and

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)	
		SEQUENTIAL	REVISION		
Sequoyah Nuclear Plant Unit 2		YEAR	NUMBER	NUMBER	
		19 12	-- 0 0 1	-- 0 0 1	3 OF 9

TEXT (If more space is required, use additional NRC Form 366A's) (17)

simultaneously an unplanned ESF actuation was initiated (FWI and APW start). Cycling of the RTB tripped the operating main feed pump (Pump "A") and started the steam-driven APW pump; the motor-driven APW pumps were in operation before this event. The trip signal was cleared and the temporary jumper lead, banana plug end, was connected to a gripper type connector. The test was completed the same day with no further complications or adverse actions.

3. Event No. 3 (Manually Initiated Reactor Trip)

On February 10, 1992, at 2110 EST, while in hot standby, the Unit 2 reactor was manually tripped. During unit startup, an operator was withdrawing each shutdown bank and comparing the rod position indicator (RPI) with the demand step counter for the respective bank. While withdrawing Shutdown Bank "D", the operator observed that the group demand step counter was reading significantly more than two steps out from the RPI. Technical specification Limiting Condition for Operation (LCO) 3.1.3.3 was entered. In accordance with the LCO action statement, the reactor trip breakers were immediately opened.

B. Inoperable Structures, Components, or Systems That Contributed to the Event:

None.

C. Dates and Approximate Times of Major Occurrences:

- February 10, 1992 at 0525 EST The unit was stable in power operation at 89.3 percent power, Mode 1, it came down for the Unit 2 Cycle 5 refueling outage.
- February 10, 1992 at 0528 EST The turbine trip, followed by a reactor trip.
- February 10, 1992 at 0757 EST The unit was stable, maintained in hot standby, Mode 3.
- February 10, 1992 at 0949 EST A reactor trip and ESF actuation occurred during performance of a reactor trip breaker test.
- February 10, 1992 at 2103 EST Operator started withdrawing shutdown bank "D" in the process of unit startup.
- February 10, 1992 at 2110 EST Operators manually tripped the reactor in accordance with the action statement of LCO 3.1.3.3 after noting that the rod position indicators and the group demand counters deviated by more than two steps.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)						
		YEAR	NUMBER	REVISION	NUMBER	NUMBER	NUMBER	NUMBER				
Sequoyah Nuclear Plant Unit 2	050003181912	--	0	0	1	--	0	0	0	410	0	9

TEXT (If more space is required, use additional NRC Form 366A's) (17)

D. Other Systems or Secondary Functions Affected:

1. Event Nos. 1 and 3

As designed, the reactor tripped in each event. Other systems performed as expected.

2. Event No. 2

A reactor trip, FWI, and an AFW start occurred while testing the RTBs. All control rods were already on the bottom at the time of the event. The FWI and AFW start occurred when a jumper, that had been placed to preclude a FWI signal, became disengaged before breaker cycling. The open RTBs combined with T_{avg} of less than 554 degrees Fahrenheit, completed the logic to initiate the signal. The main feed pump (Pump "A") tripped and the steam-driven AFW pump started. The motor-driven AFW pumps were in operation before the event.

E. Method of Discovery:

1. The turbine and/or reactor trip was annunciated on the control room panels.
2. The trip signal, AFW start, and FWI were annunciated on the control room panels.
3. Operator initiated the trip during unit startup when withdrawing the shutdown bank "D" control rods.

F. Operator Actions:

1. Event No. 1

The control room staff responded as prescribed by emergency procedures. They promptly diagnosed the plant condition and took actions necessary to stabilize the unit in a safe condition and maintained the unit in hot standby.

2. Event No. 2

The control room staff restored feedwater operation, secured the steam-driven auxiliary feedwater pump, and reset the negative rate trip signal.

3. Event No. 3

Operators manually tripped the reactor.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		SEQUENTIAL	REVISION		
Sequoyah Nuclear Plant Unit 2		YEAR	NUMBER	NUMBER	
		050003	18	92	1001

TEXT (If more space is required, use additional NRC Form 366A's) (17)

G. Safety System Responses:

1. Event Nos. 1 and 3

Safety systems and plant parameters performed as expected.

2. Event No. 2

The plant equipment associated with FWI responded in accordance with design. The plant was in a stable condition with main feed pump (MFP) "A" recirculating to the hotwell and motor driven AFW pumps were feeding the steam generators. The FWI tripped the MFP "A" and started the steam-driven AFW pump. The steam-driven AFW pump was secured shortly thereafter. The RTB opened as designed due to the rate trip already being present. Rods were already on bottom. The event did not result in any system transient or equipment anomalous operation.

III. CAUSE OF THE EVENT

A. Immediate Cause:

1. Automatic Turbine and Reactor Trip

The reactor trip was precipitated by a turbine trip. The turbine tripped because of low auto stop oil pressure.

2. Automatic Reactor Trip, FWI and AFW Start

The negative rate trip signal was not cleared before performance of the RTB test and loss of electrical continuity in the temporary jumper.

3. Manually Initiated Reactor Trip

Operator action as prescribed by technical specifications.

B. Root Cause:

1. Automatic Turbine and Reactor Trip

Malfunction of a solenoid valve in the auto stop oil portion of the turbine electro-hydraulic control system.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)			
		YEAR	NUMBER	REVISION	NUMBER	OF	TOTAL		
Sequoyah Nuclear Plant Unit 2	1051000328	1982	001	0	0	6	0	9	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

2. Automatic Reactor Trip, FWI, and AFW Start

The assistant shift Operations supervisor proceeded with the RTB test without clearing the negative rate trip signal because of an assumption that the installed jumpers would bypass all trip signals.

The previous corrective action of placing the procedure on hold until it was revised to identify the type of jumper to be used was not implemented. This action resulted from the use of a jumper with alligator clip ends where one of the alligator clips became disengaged from the terminal prior to cycling the RTB.

3. Manually Initiated Reactor Trip

The demand step counter failed due to mechanical binding of the reset mechanism in the mid-travel position. No visible foreign material was found in the mechanism. Cause of the specific failure is unknown.

C. Contributing Factors:

1. Event No. 1

The solenoid failure is suspected to have resulted from pilot valve seat failure. This failure appears to be a result of material incompatibility with the working fluid (oil) and heat generated by the energized solenoid.

2. Event No. 2

The ASOS assumed that the jumpers installed for the RTB test bypassed all trip signals. The ASOS was aware that the negative rate trip signal was still present from the reactor trip earlier that morning (Event No. 1). Operators are trained to not close breakers with trip signals present; however, the ASOS believed the signal to be bypassed.

3. Event No. 3

None.

IV. ANALYSIS OF EVENT

Plant response during and after the trips was consistent with responses described in the final safety analysis report and accordingly, the events did not adversely affect the health and safety of the public.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	NUMBER	NUMBER			
Sequoyah Nuclear Plant Unit 2	105000328	92	01	1	0	0	7 of 9

TEXT (If more space is required, use additional NRC Form 366A's) (17)

V. CORRECTIVE ACTION

A. Immediate Corrective Actions

1. Automatic Turbine and Reactor Trip

The control room staff responded as prescribed by emergency procedures. They promptly diagnosed the plant conditions and took actions necessary to stabilize the unit in a safe condition.

2. Automatic Reactor Trip, FWI and AFW Start

The control room staff restored feedwater operation and secured the steam-driven AFW pump.

3. Manually Initiated Turbine Trip

Operators manually tripped the reactor and verified all rods at the bottom by use of control room indicators.

B. Corrective Action to Prevent Recurrence

1. Automatic Turbine and Reactor Trip

- a. The malfunctioned solenoid valve was replaced. Postmaintenance tests were performed on the replacement valve. The tests consisted of visual inspection for oil leaks under pressure and electrical functional test to verify operability.
- b. An evaluation will be performed to determine the solenoid valve's failure mechanism. This evaluation will address generic applicability and determination of appropriate action to resolve the potential for solenoid valve failure.

2. Automatic Reactor Trip, FWI and AFW Start

- a. The surveillance instruction (SI) used to perform the test was revised to ensure reactor trip signals have been cleared before test performance and to ensure appropriate jumpers are used.
- b. Use of jumpers in Instrument Maintenance procedures will be evaluated to ensure actions are taken to provide good jumper connections. The intent is to identify locations for installation of banana lug terminals (or equivalent) to provide a positive means of jumpering the connections commonly used.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)
		SEQUENTIAL	REVISION	YEAR	NUMBER	
Sequoyah Nuclear Plant Unit 2						
	015101013 12 18 19 12	--	0	0	1	--
			0	0	0	8 OF 0 9

TEXT (If more space is required, use additional NRC Form 366A's) (17)

c. The operator was counseled about the event and the lessons learned will be reviewed for inclusion in operator training.

3. Manually Initiated Reactor Trip

The malfunctioned shutdown bank "D" group demand step counter was replaced. The replacement counter was verified as functional.

VI. ADDITIONAL INFORMATION

A. Failed Components

1. Automatic Turbine and/or Reactor Trip

Automatic Switch Company pilot operated solenoid valve, Model No. WPHCX8223A1011909, 1/2" national pipe thread end connections, 3/8" main orifice size and a 250V direct current coil.

2. Automatic Reactor Trip, FWI and AFW Start

None.

3. Manual Initiated Reactor Trip

Step counter manufactured by Whittaker Corp., Electronic Resources Division, Model No. 127FD100AS/S, Serial No. 20475.

B. Previous Similar Events

1. Turbine and/or Reactor Trip

This event is the first occurrence resulting from a malfunctioned EHC solenoid valve. There have been three LERs previously written as a result of EHC system problems (SQN 328/84015, 85004, and 91001), previous corrective actions would not prevent this event.

2. Automatic Reactor Trip, FWI and AFW Start

This is the second event as a result of jumper disengagement from a terminal during RTB posttrip testing. The previously written LER is SQN 327/89035. No previous events were identified where RTR cycling was attempted with an uncleared trip signal. Previous corrective actions may have prevented the ESF actuation if the test procedure was revised to ensure proper jumper use. However, previous corrective actions would not prevent RTB operation with an uncleared trip signal present.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)			
Sequoyah Nuclear Plant Unit 2			SEQUENTIAL	REVISION					
		YEAR	NUMBER	NUMBER					
	0500013 12 18 19 12	0	0	1	0	0	0	9	0 9

TEXT (If more space is required, use additional NRC Form 366A's) (17)

3. Manually Initiated Reactor Trip

This is the second event as a result of a malfunctioned demand step counter. The previous event described by LER SQN 328/88013 was caused by debris in the counter mechanism. Previous corrective actions would not prevent this event.

VII. COMMITMENTS

1. An evaluation will be performed to determine the solenoid valve's failure mechanism. This evaluation will address generic applicability and determination of appropriate action to resolve the potential for solenoid valve failure by May 11, 1992.
2. Event No. 2 will be reviewed by the operator training staff and Operations personnel will be informed of the lesson learned by March 25, 1992.